



Status Report

HAWKER 900XP

S/N HA-0161 N61HQ

OWNER: NEW KPC HOLDCO, LLC
ADDRESS: 6400 N. ANDREWS AVENUE, SUITE 490
FORT LAUDERDALE FL 33309
OFFICE: 561-756-5438
FAX:

OPERATOR: WORLDWIDE SPORTS ENTERPRISE, LLC
ADDRESS: C/O RAMJET AVIATION, INC
FT. LAUDERDALE FL 33315
OFFICE: 954-359-0260
FAX:

OPERATOR: WORLDWIDE SPORTS ENTERPRISE, LLC
ADDRESS: 6400 NORTH ANDREWS AVENUE
FT. LAUDERDALE FL 33309
OFFICE: 561-756-5438
FAX:

ANALYST: GLEN WATSON
EMAIL: GWATSON@CAMPSYSTEMS.COM

+1-316-462-2438 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT SERIAL/REGNO: HA-0161/N61HQ MODEL: HAWKER 900XP MANUFACTURER: TEXTRON AVIATION INC.

CERTIFICATION DATE: 16-MAR-2010

LAST ACTUALS:
3908.4 A/C HRS as of 25-JUL-2024
1492 AFL as of 25-JUL-2024
3746 APH as of 03-JUL-2024

APU SERIAL/PART: P-1179/3800304-1 MODEL: GTCP36-150(W) MANUFACTURER: HONEYWELL

INSTALLED ON: 05-MAY-2010
0 APU HRS 0 A/C HRS
0 APUS

LAST ACTUALS:
3764 APU HRS as of 03-JUL-2024
0 APUS as of 11-JUL-2024

ENGINE NO. 1 SERIAL/PART: P122372/3060090-1 MODEL: TFE731-50R-1H MANUFACTURER: HONEYWELL

INSTALLED ON: 19-DEC-2017
2853.82 ENG. HRS 2886.88 A/C HRS
1031 ENC

LAST ACTUALS:
3895.3 ENG. HRS as of 25-JUL-2024
1478 ENC as of 25-JUL-2024

ENGINE NO. 2 SERIAL/PART: P122371/3060090-1 MODEL: TFE731-50R-1H MANUFACTURER: HONEYWELL

INSTALLED ON: 19-DEC-2017
2853.82 ENG. HRS 2886.88 A/C HRS
1031 ENC

LAST ACTUALS:
3895.3 ENG. HRS as of 25-JUL-2024
1478 ENC as of 25-JUL-2024



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition              |
|--|---|-----------|----------|----------|---------------------------|-----------|-----------|--------------------------|
| ATA 00 - INFORMATION                   |   |           |          |          |                           |           |           |                          |
| A010-161102                            | APU - REVIEW SERVICE INFORMATION LETTER APU-56 (D199709000077) REVISION 2             |           |          |          |                           |           |           | Service ATA:00           |
|  | MOS/MSC   | 10-Mar-17 | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|  | HRS   |           |          |          |                           |           |           |                          |
|  | APUS  |           |          |          |                           |           |           |                          |
|  | PROC. REF: RCF A010-161102  |           |          |          |                           |           |           |                          |
| A010-180112                            | APU - REVIEW HONEYWELL GTCP 36-150(F) APU-49 SIL REV 10                               |           |          |          |                           |           |           | Service ATA:00           |
|  | MOS/MSC   | EFF       | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|  | HRS   |           |          |          |                           |           |           |                          |
|  | APUS  |           |          |          |                           |           |           |                          |
|  | PROC. REF: RCF APU-SIL-49   |           |          |          |                           |           |           |                          |
| ADS-B OUT STATUS                       | AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT COMPLIANT                      |           |          |          |                           |           |           | Component ATA:00         |
| PN:CONFIRMATION FROM FLIGHT AWARE DATA | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |                          |
| SN:UNKNOWN                             | HRS   | 0         |          | TSN 0    |                           |           |           |                          |
|  | AFL   | 0         |          | TSN 0    |                           |           |           |                          |
| BCXP-151102                            | REVIEW HAWKER 900XP MAINTENANCE MANUAL ADDENDA REV 8 SEPT, 2015-RCF                   |           |          |          |                           |           |           | Service ATA:00           |
|  | MOS/MSC   | EFF       | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|  | HRS   |           |          |          |                           |           |           |                          |
|  | AFL   |           |          |          |                           |           |           |                          |
|  | PROC. REF: RCF BCXP   |           |          |          |                           |           |           |                          |
| BCXP-151106                            | REVIEW HAWKER 750/800XP/850XP/900XP AFMS REV 30 DATED SEPTEMBER 1, 2015- RCF          |           |          |          |                           |           |           | Service ATA:00           |
|  | MOS/MSC   |           | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|  | HRS   |           |          |          |                           |           |           |                          |
|  | AFL   |           |          |          |                           |           |           |                          |
|  | PROC. REF: RCF BCXP   |           |          |          |                           |           |           |                          |
| BCXP-160322                            | REVIEW HAWKER 750/800XP/850XP/900XP AFMS REV 31 DATED MARCH 1, 2016 -CAMP CHANGE FORM |           |          |          |                           |           |           | Service ATA:00           |
|  | MOS/MSC   | 23-Jun-16 | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|  | HRS   |           |          |          |                           |           |           |                          |
|  | AFL   |           |          |          |                           |           |           |                          |
|  | PROC. REF: RCF BCXP   |           |          |          |                           |           |           |                          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



## Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN              | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition               |        |
|----------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|---------------------------|--------|
| ATA 00 - INFORMATION |  |           |          |          |                           |           |           |                           |        |
| BCXP-160901          | REVIEW HAWKER 750/800XP/850XP/900XP AFMS REVISION 32 DATED SEP.16 REVISION SUMMARY CHANGE FORM           |           |          |          |                           |           |           | Service                   | ATA:00 |
|                      | MOS/MSC  | 13-Mar-17 | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS  |        |
|                      | HRS  |           |          |          |                           |           |           |                           |        |
|                      | AFL  |           |          |          |                           |           |           |                           |        |
|                      |  |           |          |          | PROC. REF: RCF BCXP       |           |           |                           |        |
| BCXP-170227          | REVIEW REVISION CHANGE SUMMARY FORM FOR CONCORDE BATTERY REV B DATED FEBRUARY 27, 2017                   |           |          |          |                           |           |           | Service                   | ATA:00 |
|                      | MOS/MSC  |           | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS  |        |
|                      | HRS  |           |          |          |                           |           |           |                           |        |
|                      | AFL  |           |          |          |                           |           |           |                           |        |
|                      |  |           |          |          | PROC. REF: RCF BCXP       |           |           |                           |        |
| BCXP-170711          | REVIEW HAWKER 750/800XP/850XP/900XP AFMS AUDIT SUMMARY CHANGE FORM                                       |           |          |          |                           |           |           | Service                   | ATA:00 |
|                      | MOS/MSC  |           | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS  |        |
|                      | HRS  |           |          |          |                           |           |           |                           |        |
|                      | AFL  |           |          |          |                           |           |           |                           |        |
|                      |  |           |          |          | PROC. REF: RCF BCXP       |           |           |                           |        |
| BCXP-190624          | REVIEW AUDIT SUMMARY CHANGE FORM - TASK CODE CHANGE  |           |          |          |                           |           |           | Service                   | ATA:00 |
|                      | MOS/MSC  |           | -        |          |                           |           |           | AUDIT SUMMARY CHANGE FORM |        |
|                      | HRS  |           |          |          |                           |           |           |                           |        |
|                      | AFL  |           |          |          |                           |           |           |                           |        |
|                      |  |           |          |          | PROC. REF: RCF BCXP       |           |           |                           |        |
| BCXP-201207          | REVIEW AUDIT SUMMARY CHANGE FORM - ADDITION OF PART NUMBER TASKS FOR FDR ULB BATTERY AND CVR ULB BATTERY |           |          |          |                           |           |           | Service                   | ATA:00 |
|                      | MOS/MSC  | 29-Dec-20 | -        |          |                           |           |           | AUDIT SUMMARY CHANGE FORM |        |
|                      | HRS  |           |          |          |                           |           |           |                           |        |
|                      | AFL  |           |          |          |                           |           |           |                           |        |
|                      |  |           |          |          | PROC. REF: RCF BCXP       |           |           |                           |        |
| E004-170718          | NO. 1 ENGINE - REVIEW HONEYWELL TFE731-20/-40/-60 LMM,TR 70-4  |           |          |          |                           |           |           | Service                   | ATA:00 |
|                      | MOS/MSC  | EFF       | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS  |        |
|                      | HRS  |           |          |          |                           |           |           |                           |        |
|                      | ENC  |           |          |          |                           |           |           |                           |        |
|                      |  |           |          |          | PROC. REF: RCF E004       |           |           |                           |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN              | Unit                  | C/W                               | Interval                            | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition                                |
|----------------------|-----------------------|-----------------------------------|-------------------------------------|----------|---------------------------|-----------|-----------|--|
| ATA 00 - INFORMATION |                       |                                   |                                     |          |                           |           |           |  |
| E004-170718          | NO. 2 ENGINE - REVIEW | HONEYWELL                         | TFE731-20/-40/-60 LMM,TR 70-4       |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE FORMS |
|                      | MOS/MSC               | EFF                               | -                                   |          |                           |           |           |  |
|                      | HRS                   |                                   |                                     |          |                           |           |           |  |
|                      | ENC                   |                                   |                                     |          |                           |           |           |  |
|                      |                       |                                   |                                     |          |                           |           |           | PROC. REF: RCF E004                        |
| E004-170913          | NO. 1 ENGINE - REVIEW | HONEYWELL                         | TFE731-20/-40/-60 LMM, 12 TR 72-235 |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE FORMS |
|                      | MOS/MSC               | EFF                               | -                                   |          |                           |           |           |  |
|                      | HRS                   |                                   |                                     |          |                           |           |           |  |
|                      | ENC                   |                                   |                                     |          |                           |           |           |  |
|                      |                       |                                   |                                     |          |                           |           |           | PROC. REF: RCF E004                        |
| E004-170913          | NO. 2 ENGINE - REVIEW | HONEYWELL                         | TFE731-20/-40/-60 LMM, 12 TR 72-235 |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE FORMS |
|                      | MOS/MSC               | EFF                               | -                                   |          |                           |           |           |  |
|                      | HRS                   |                                   |                                     |          |                           |           |           |  |
|                      | ENC                   |                                   |                                     |          |                           |           |           |  |
|                      |                       |                                   |                                     |          |                           |           |           | PROC. REF: RCF E004                        |
| E004-180118          | NO. 1 ENGINE - REVIEW | TFE731-20/-40/-50/-60 LMM REV 13  |                                     |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE FORMS |
|                      | MOS/MSC               | EFF                               | -                                   |          |                           |           |           |  |
|                      | HRS                   |                                   |                                     |          |                           |           |           |  |
|                      | ENC                   |                                   |                                     |          |                           |           |           |  |
|                      |                       |                                   |                                     |          |                           |           |           | PROC. REF: RCF E004                        |
| E004-180118          | NO. 2 ENGINE - REVIEW | TFE731-20/-40/-50/-60 LMM REV 13  |                                     |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE FORMS |
|                      | MOS/MSC               | EFF                               | -                                   |          |                           |           |           |  |
|                      | HRS                   |                                   |                                     |          |                           |           |           |  |
|                      | ENC                   |                                   |                                     |          |                           |           |           |  |
|                      |                       |                                   |                                     |          |                           |           |           | PROC. REF: RCF E004                        |
| E004-180802          | NO. 1 ENGINE - REVIEW | TFE731-20/-40/-50/-60 LMM TR 5-17 |                                     |          |                           |           |           | Service ATA:00<br>REQUIREMENT CHANGE FORMS |
|                      | MOS/MSC               | EFF                               | -                                   |          |                           |           |           |  |
|                      | HRS                   |                                   |                                     |          |                           |           |           |  |
|                      | ENC                   |                                   |                                     |          |                           |           |           |  |
|                      |                       |                                   |                                     |          |                           |           |           | PROC. REF: RCF E004-180802                 |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN              | Unit  | C/W | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C  | Max Limit | Remaining | Disposition              |
|----------------------|---|-----|----------|----------|----------------------------|-----------|-----------|--------------------------|
| ATA 00 - INFORMATION |   |     |          |          |                            |           |           |                          |
| E004-180802          | NO. 2 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM TR 5-17 |     |          |          |                            |           |           | Service ATA:00           |
|                      | MOS/MSC   | EFF | -        |          |                            |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |     |          |          |                            |           |           |                          |
|                      | ENC   |     |          |          |                            |           |           |                          |
|                      |   |     |          |          | PROC. REF: RCF E004-180802 |           |           |                          |
| E004-191206          | NO. 1 ENGINE - REVIEW TFE731-20/40/50/60 LMM TR 79-8    |     |          |          |                            |           |           | Service ATA:00           |
|                      | MOS/MSC   | EFF | -        |          |                            |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |     |          |          |                            |           |           |                          |
|                      | ENC   |     |          |          |                            |           |           |                          |
|                      |   |     |          |          | PROC. REF: RCF E004        |           |           |                          |
| E004-191206          | NO. 2 ENGINE - REVIEW TFE731-20/40/50/60 LMM TR 79-8    |     |          |          |                            |           |           | Service ATA:00           |
|                      | MOS/MSC   | EFF | -        |          |                            |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |     |          |          |                            |           |           |                          |
|                      | ENC   |     |          |          |                            |           |           |                          |
|                      |   |     |          |          | PROC. REF: RCF E004        |           |           |                          |
| E004-191209          | NO. 1 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM TR 5-18 |     |          |          |                            |           |           | Service ATA:00           |
|                      | MOS/MSC   | EFF | -        |          |                            |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |     |          |          |                            |           |           |                          |
|                      | ENC   |     |          |          |                            |           |           |                          |
|                      |   |     |          |          | PROC. REF: RCF E004        |           |           |                          |
| E004-191209          | NO. 2 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM TR 5-18 |     |          |          |                            |           |           | Service ATA:00           |
|                      | MOS/MSC   | EFF | -        |          |                            |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |     |          |          |                            |           |           |                          |
|                      | ENC   |     |          |          |                            |           |           |                          |
|                      |   |     |          |          | PROC. REF: RCF E004        |           |           |                          |
| E004-201001          | NO. 1 ENGINE - REVIEW TFE731-20/40/50/60 LMM TR 72-245  |     |          |          |                            |           |           | Service ATA:00           |
|                      | MOS/MSC   | EFF | -        |          |                            |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |     |          |          |                            |           |           |                          |
|                      | ENC   |     |          |          |                            |           |           |                          |
|                      |   |     |          |          | PROC. REF: RCF E004        |           |           |                          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN              | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition              |
|----------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|--------------------------|
| ATA 00 - INFORMATION |   |           |          |          |                           |           |           |                          |
| E004-201001          | NO. 2 ENGINE - REVIEW TFE731-20/40/50/60 LMM TR 72-245    |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC   | EFF       | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |           |          |          |                           |           |           |                          |
|                      | ENC   |           |          |          |                           |           |           |                          |
|                      |   |           |          |          | PROC. REF: RCF E004       |           |           |                          |
| E004-201102          | NO. 1 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM TR 79-9   |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC   | 29-Dec-20 | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |           |          |          |                           |           |           |                          |
|                      | ENC   |           |          |          |                           |           |           |                          |
|                      |   |           |          |          | PROC. REF: RCF E004       |           |           |                          |
| E004-201102          | NO. 2 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM TR 79-9   |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC   | 29-Dec-20 | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |           |          |          |                           |           |           |                          |
|                      | ENC   |           |          |          |                           |           |           |                          |
|                      |   |           |          |          | PROC. REF: RCF E004       |           |           |                          |
| E004-201221          | NO. 1 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM TR 72-244 |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC   | 21-Jan-21 | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |           |          |          |                           |           |           |                          |
|                      | ENC   |           |          |          |                           |           |           |                          |
|                      |   |           |          |          | PROC. REF: RCF E004       |           |           |                          |
| E004-201221          | NO. 2 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM TR 72-244 |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC   | 21-Jan-21 | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |           |          |          |                           |           |           |                          |
|                      | ENC   |           |          |          |                           |           |           |                          |
|                      |   |           |          |          | PROC. REF: RCF E004       |           |           |                          |
| E004-210506          | NO. 1 ENGINE - REVIEW TFE731-20/40/50/60 LMM TR 79-11     |           |          |          |                           |           |           | Service ATA:00           |
|                      | MOS/MSC   | EFF       | -        |          |                           |           |           | REQUIREMENT CHANGE FORMS |
|                      | HRS   |           |          |          |                           |           |           |                          |
|                      | ENC   |           |          |          |                           |           |           |                          |
|                      |   |           |          |          | PROC. REF: RCF E004       |           |           |                          |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit  | C/W       | Interval      | TSX/Adj.                              | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition              |        |
|--|---|-----------|---------------|---------------------------------------|---------------------------|-----------|-------------|--------------------------|--------|
| <b>ATA 00 - INFORMATION</b>                    |   |           |               |                                       |                           |           |             |                          |        |
| E004-210506                                    | NO. 2 ENGINE - REVIEW TFE731-20/40/50/60 LMM TR 79-11 |           |               |                                       |                           |           |             | Service                  | ATA:00 |
|  | MOS/MSC   | EFF       | -             |                                       |                           |           |             | REQUIREMENT CHANGE FORMS |        |
|  | HRS   |           |               |                                       |                           |           |             |                          |        |
|  | ENC   |           |               |                                       |                           |           |             |                          |        |
|  |   |           |               | PROC. REF: RCF E004                   |                           |           |             |                          |        |
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b> |   |           |               |                                       |                           |           |             |                          |        |
| 050001   | INSPECTION PRE-FLIGHT                                 |           |               |                                       |                           |           |             | Service                  | ATA:05 |
|  | MOS/MSC   | 13-Mar-24 | A/R           |                                       |                           |           |             |                          |        |
|  | HRS   | 3890.9    |               |                                       |                           |           |             |                          |        |
| WC#: 05.T01                                    | AFL   | 1481      |               |                                       |                           |           |             |                          |        |
|  |   |           |               | PROC. REF: AMS 5-20-01, AFMS 05-00-00 |                           |           |             |                          |        |
| 050005   | INSPECTION POST FLIGHT                                |           |               |                                       |                           |           |             | Service                  | ATA:05 |
|  | MOS/MSC   | 20-Jun-22 | A/R           |                                       |                           |           |             |                          |        |
|  | HRS   | 3511.6    |               |                                       |                           |           |             |                          |        |
| WC#: 05.T02                                    | AFL   | 1288      |               |                                       |                           |           |             |                          |        |
|  |   |           |               | PROC. REF: AFMS 05-00-00, AMS 5-20-02 |                           |           |             |                          |        |
| 050110   | INSPECTION B1-B12 COMPLETE                            |           |               |                                       |                           |           |             | Package                  | ATA:05 |
|  | MOS   | 03-Aug-21 |               |                                       |                           |           |             |                          |        |
|  | HRS   | 3405      | 800 (+40/-10) |                                       | 4205                      | 4245      | 296.6 (+40) |                          |        |
|  | AFL   | 1243      |               |                                       |                           |           |             |                          |        |
|  |   |           |               | PROC. REF: AMS 5-21-00                |                           |           |             | PKG:91                   |        |
| 050141 <sup>S</sup>                            | INSPECT AREA F1-800 HOURS                             |           |               |                                       |                           |           |             | Service                  | ATA:05 |
|  | MOS   | 03-Aug-21 |               |                                       |                           |           |             |                          |        |
|  | HRS   | 3405      | 800 (+40/-10) |                                       |                           |           |             |                          |        |
| WC#: 05.203                                    | AFL   | 1243      |               |                                       |                           |           |             |                          |        |
|  |   |           |               | PROC. REF: AMS 5-00-00                |                           |           |             | PKG:9,91                 |        |
| 050171 <sup>S</sup>                            | INSPECT AREA F3 ABOVE FLOOR-800 HOURS                 |           |               |                                       |                           |           |             | Service                  | ATA:05 |
|  | MOS   | 03-Aug-21 |               |                                       |                           |           |             |                          |        |
|  | HRS   | 3405      | 800 (+40/-10) |                                       |                           |           |             |                          |        |
| WC#: 05.206                                    | AFL   | 1243      |               |                                       |                           |           |             |                          |        |
|  |   |           |               | PROC. REF: AMS 5-00-00                |                           |           |             | PKG:12,91                |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit                         | C/W       | Interval       | TSX/Adj.               | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|--|------------------------------|-----------|----------------|------------------------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b> |                              |           |                |                        |                           |           |             |             |        |
| 050181 <sup>S</sup>                            | INSPECT AREA F4-800 HOURS    |           |                |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                          | 03-Aug-21 |                |                        |                           |           |             |             |        |
|  | HRS                          | 3405      | 800 (+40/-10)  |                        |                           |           |             |             |        |
| WC#: 05.207                                    | AFL                          | 1243      |                |                        |                           |           |             |             |        |
|  |                              |           |                | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:13,91   |        |
| 050191 <sup>S</sup>                            | INSPECT AREA T1-800 HOURS    |           |                |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                          | 03-Aug-21 |                |                        |                           |           |             |             |        |
|  | HRS                          | 3405      | 800 (+40/-10)  |                        |                           |           |             |             |        |
| WC#: 05.208                                    | AFL                          | 1243      |                |                        |                           |           |             |             |        |
|  |                              |           |                | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:14,91   |        |
| 050201 <sup>S</sup>                            | INSPECT AREA W1-800 HOURS    |           |                |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                          | 03-Aug-21 |                |                        |                           |           |             |             |        |
|  | HRS                          | 3405      | 800 (+40/-10)  |                        |                           |           |             |             |        |
| WC#: 05.209                                    | AFL                          | 1243      |                |                        |                           |           |             |             |        |
|  |                              |           |                | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:15,91   |        |
| 050211 <sup>S</sup>                            | INSPECT AREA W2-800 HOURS    |           |                |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                          | 03-Aug-21 |                |                        |                           |           |             |             |        |
|  | HRS                          | 3405      | 800 (+40/-10)  |                        |                           |           |             |             |        |
| WC#: 05.210                                    | AFL                          | 1243      |                |                        |                           |           |             |             |        |
|  |                              |           |                | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:16,91   |        |
| 050221 <sup>S</sup>                            | INSPECT AREA M1/M2-800 HOURS |           |                |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                          | 03-Aug-21 |                |                        |                           |           |             |             |        |
|  | HRS                          | 3405      | 800 (+40/-10)  |                        |                           |           |             |             |        |
| WC#: 05.211                                    | AFL                          | 1243      |                |                        |                           |           |             |             |        |
|  |                              |           |                | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:17,91   |        |
| 050231 <sup>S</sup>                            | INSPECT AREA G-800 HOURS     |           |                |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                          | 03-Aug-21 |                |                        |                           |           |             |             |        |
|  | HRS                          | 3405      | 800 (+40/-10)  |                        |                           |           |             |             |        |
| WC#: 05.212                                    | AFL                          | 1243      |                |                        |                           |           |             |             |        |
|  |                              |           |                | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:18,91   |        |
| 050240   | INSPECTION C1-C12 COMPLETE   |           |                |                        |                           |           |             | Package     | ATA:05 |
|  | MOS                          | 06-Jun-18 |                |                        |                           |           |             |             |        |
|  | HRS                          | 2965.25   | 1600 (+50/-50) |                        | 4565.25                   | 4615.25   | 656.9 (+50) |             |        |
|  | AFL                          | 1073      |                |                        |                           |           |             |             |        |
|  |                              |           |                | PROC. REF: AMS 5-22-00 |                           |           |             | PKG:92      |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit                                    | C/W       | Interval       | TSX/Adj.               | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--|---|-----------|----------------|------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b> |   |           |                |                        |                           |           |           |             |        |
| 050271 <sup>S</sup>                            | INSPECT AREA F1-1600 HOURS              |           |                |                        |                           |           |           | Service     | ATA:05 |
|  | MOS                                     | 06-Jun-18 |                |                        |                           |           |           |             |        |
|  | HRS                                     | 2965.25   | 1600 (+50/-50) |                        |                           |           |           |             |        |
| WC#: 05.303                                    | AFL                                     | 1073      |                |                        |                           |           |           |             |        |
|  |   |           |                | PROC. REF: AMS 5-00-00 |                           |           |           | PKG:21,92   |        |
| 050281 <sup>S</sup>                            | INSPECT AREA F2-1600 HOURS              |           |                |                        |                           |           |           | Service     | ATA:05 |
|  | MOS                                     | 06-Jun-18 |                |                        |                           |           |           |             |        |
|  | HRS                                     | 2965.25   | 1600 (+50/-50) |                        |                           |           |           |             |        |
| WC#: 05.304                                    | AFL                                     | 1073      |                |                        |                           |           |           |             |        |
|  |   |           |                | PROC. REF: AMS 5-00-00 |                           |           |           | PKG:22,92   |        |
| 050291 <sup>S</sup>                            | INSPECT AREA F3 UNDERFLOOR-1600 HOURS   |           |                |                        |                           |           |           | Service     | ATA:05 |
|  | MOS                                     | 06-Jun-18 |                |                        |                           |           |           |             |        |
|  | HRS                                     | 2965.25   | 1600 (+50/-50) |                        |                           |           |           |             |        |
| WC#: 05.305                                    | AFL                                     | 1073      |                |                        |                           |           |           |             |        |
|  |   |           |                | PROC. REF: AMS 5-00-00 |                           |           |           | PKG:23,92   |        |
| 050301 <sup>S</sup>                            | INSPECT AREA F3- ABOVE FLOOR-1600 HOURS |           |                |                        |                           |           |           | Service     | ATA:05 |
|  | MOS                                     | 06-Jun-18 |                |                        |                           |           |           |             |        |
|  | HRS                                     | 2965.25   | 1600 (+50/-50) |                        |                           |           |           |             |        |
| WC#: 05.306                                    | AFL                                     | 1073      |                |                        |                           |           |           |             |        |
|  |   |           |                | PROC. REF: AMS 5-00-00 |                           |           |           | PKG:24,92   |        |
| 050311 <sup>S</sup>                            | INSPECT AREA F4-1600 HOURS              |           |                |                        |                           |           |           | Service     | ATA:05 |
|  | MOS                                     | 06-Jun-18 |                |                        |                           |           |           |             |        |
|  | HRS                                     | 2965.25   | 1600 (+50/-50) |                        |                           |           |           |             |        |
| WC#: 05.307                                    | AFL                                     | 1073      |                |                        |                           |           |           |             |        |
|  |   |           |                | PROC. REF: AMS 5-00-00 |                           |           |           | PKG:25,92   |        |
| 050321 <sup>S</sup>                            | INSPECT AREA T1-1600 HOURS              |           |                |                        |                           |           |           | Service     | ATA:05 |
|  | MOS                                     | 06-Jun-18 |                |                        |                           |           |           |             |        |
|  | HRS                                     | 2965.25   | 1600 (+50/-50) |                        |                           |           |           |             |        |
| WC#: 05.308                                    | AFL                                     | 1073      |                |                        |                           |           |           |             |        |
|  |   |           |                |                        |                           |           |           | PKG:26,92   |        |
| 050331 <sup>S</sup>                            | INSPECT AREA W1-1600 HOURS              |           |                |                        |                           |           |           | Service     | ATA:05 |
|  | MOS                                     | 06-Jun-18 |                |                        |                           |           |           |             |        |
|  | HRS                                     | 2965.25   | 1600 (+50/-50) |                        |                           |           |           |             |        |
| WC#: 05.309                                    | AFL                                     | 1073      |                |                        |                           |           |           |             |        |
|  |   |           |                | PROC. REF: AMS 5-00-00 |                           |           |           | PKG:27,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit                                   | C/W       | Interval        | TSX/Adj.               | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition |        |
|--|--|-----------|-----------------|------------------------|---------------------------|-----------|---------------|-------------|--------|
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b> |  |           |                 |                        |                           |           |               |             |        |
| 050341 <sup>S</sup>                            | INSPECT AREA W2-1600 HOURS             |           |                 |                        |                           |           |               | Service     | ATA:05 |
|  | MOS                                    | 06-Jun-18 |                 |                        |                           |           |               |             |        |
|  | HRS                                    | 2965.25   | 1600 (+50/-50)  |                        |                           |           |               |             |        |
| WC#: 05.310                                    | AFL                                    | 1073      |                 |                        |                           |           |               |             |        |
|  |  |           |                 | PROC. REF: AMS 5-00-00 |                           |           |               | PKG:28,92   |        |
| 050351 <sup>S</sup>                            | INSPECT AREA M1/M2-1600 HOURS          |           |                 |                        |                           |           |               | Service     | ATA:05 |
|  | MOS                                    | 06-Jun-18 |                 |                        |                           |           |               |             |        |
|  | HRS                                    | 2965.25   | 1600 (+50/-50)  |                        |                           |           |               |             |        |
| WC#: 05.311                                    | AFL                                    | 1073      |                 |                        |                           |           |               |             |        |
|  |  |           |                 | PROC. REF: AMS 5-00-00 |                           |           |               | PKG:29,92   |        |
| 050361 <sup>S</sup>                            | INSPECT AREA G-1600 HOURS              |           |                 |                        |                           |           |               | Service     | ATA:05 |
|  | MOS                                    | 06-Jun-18 |                 |                        |                           |           |               |             |        |
|  | HRS                                    | 2965.25   | 1600 (+50/-50)  |                        |                           |           |               |             |        |
| WC#: 05.312                                    | AFL                                    | 1073      |                 |                        |                           |           |               |             |        |
|  |  |           |                 | PROC. REF: AMS 5-00-00 |                           |           |               | PKG:30,92   |        |
| 050370   | INSPECTION D1-D12 COMPLETE             |           |                 |                        |                           |           |               | Package     | ATA:05 |
|  | MOS                                    | 06-Jun-18 |                 |                        |                           |           |               |             |        |
|  | HRS                                    | 2965.25   | 3200 (+150/-50) |                        | 6165.25                   | 6315.25   | 2256.9 (+150) |             |        |
|  | AFL                                    | 1073      |                 |                        |                           |           |               |             |        |
|  |  |           |                 | PROC. REF: AMS 5-23-00 |                           |           |               | PKG:93      |        |
| 050411 <sup>S</sup>                            | INSPECT AREA F2-3200 HOURS             |           |                 |                        |                           |           |               | Service     | ATA:05 |
|  | MOS                                    | 06-Jun-18 |                 |                        |                           |           |               |             |        |
|  | HRS                                    | 2965.25   | 3200 (+150/-50) |                        |                           |           |               |             |        |
| WC#: 05.404                                    | AFL                                    | 1073      |                 |                        |                           |           |               |             |        |
|  |  |           |                 | PROC. REF: AMS 5-00-00 |                           |           |               | PKG:34,93   |        |
| 050431 <sup>S</sup>                            | INSPECT AREA F3 ABOVE FLOOR-3200 HOURS |           |                 |                        |                           |           |               | Service     | ATA:05 |
|  | MOS                                    | 06-Jun-18 |                 |                        |                           |           |               |             |        |
|  | HRS                                    | 2965.25   | 3200 (+150/-50) |                        |                           |           |               |             |        |
| WC#: 05.406                                    | AFL                                    | 1073      |                 |                        |                           |           |               |             |        |
|  |  |           |                 | PROC. REF: AMS 5-00-00 |                           |           |               | PKG:36,93   |        |
| 050441 <sup>S</sup>                            | INSPECT AREA F4-3200 HOURS             |           |                 |                        |                           |           |               | Service     | ATA:05 |
|  | MOS                                    | 06-Jun-18 |                 |                        |                           |           |               |             |        |
|  | HRS                                    | 2965.25   | 3200 (+150/-50) |                        |                           |           |               |             |        |
| WC#: 05.407                                    | AFL                                    | 1073      |                 |                        |                           |           |               |             |        |
|  |  |           |                 | PROC. REF: AMS 5-00-00 |                           |           |               | PKG:37,93   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit                       | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |           |
|--|----------------------------|-----------|-----------------|----------|---------------------------|-----------|-------------|-------------|-----------|
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b> |                            |           |                 |          |                           |           |             |             |           |
| 050491 <sup>S</sup>                            | INSPECT AREA G-3200 HOURS  |           |                 |          |                           |           |             | Service     | ATA:05    |
|  | MOS                        | 06-Jun-18 |                 |          |                           |           |             |             |           |
|  | HRS                        | 2965.25   | 3200 (+150/-50) |          |                           |           |             |             |           |
| WC#: 05.412                                    | AFL                        | 1073      |                 |          |                           |           |             |             |           |
|  | PROC. REF: AMS 5-00-00     |           |                 |          |                           |           |             |             | PKG:42,93 |
| 050500   | INSPECTION E1-E12 COMPLETE |           |                 |          |                           |           |             | Package     | ATA:05    |
|  | MOS                        | 25-Jul-24 | 12 (+1m/-1m)    | Adj -32d | 23-Jun-25                 | 23-Jul-25 | 329 d (+30) |             |           |
|  | HRS                        | 3908.4    |                 |          |                           |           |             |             |           |
|  | AFL                        | 1492      |                 |          |                           |           |             |             |           |
|  | PROC. REF: AMS 5-24-00     |           |                 |          |                           |           |             |             | PKG:94    |
| 050571 <sup>S</sup>                            | INSPECT AREA F4-12 MONTHS  |           |                 |          |                           |           |             | Service     | ATA:05    |
|  | MOS                        | 25-Jul-24 | 12 (+1m/-1m)    |          |                           |           |             |             |           |
|  | HRS                        | 3908.4    |                 |          |                           |           |             |             |           |
| WC#: 05.506                                    | AFL                        | 1492      |                 |          |                           |           |             |             |           |
|  | PROC. REF: AMS 5-00-00     |           |                 |          |                           |           |             |             | PKG:49,94 |
| 050630   | INSPECTION F1-F12 COMPLETE |           |                 |          |                           |           |             | Package     | ATA:05    |
|  | MOS                        | 25-Jul-24 | 24 (+2m/-2m)    | Adj -35d | 20-Jun-26                 | 20-Aug-26 | 691 d (+61) |             |           |
|  | HRS                        | 3908.4    |                 |          |                           |           |             |             |           |
|  | AFL                        | 1492      |                 |          |                           |           |             |             |           |
|  | PROC. REF: AMS 5-25-00     |           |                 |          |                           |           |             |             | PKG:95    |
| 050661 <sup>S</sup>                            | INSPECT AREA F1-24 MONTHS  |           |                 |          |                           |           |             | Service     | ATA:05    |
|  | MOS                        | 25-Jul-24 | 24 (+2m/-2m)    |          |                           |           |             |             |           |
|  | HRS                        | 3908.4    |                 |          |                           |           |             |             |           |
| WC#: 05.603                                    | AFL                        | 1492      |                 |          |                           |           |             |             |           |
|  | PROC. REF: AMS 5-00-00     |           |                 |          |                           |           |             |             | PKG:57,95 |
| 050671 <sup>S</sup>                            | INSPECT AREA F2-24 MONTHS  |           |                 |          |                           |           |             | Service     | ATA:05    |
|  | MOS                        | 25-Jul-24 | 24 (+2m/-2m)    |          |                           |           |             |             |           |
|  | HRS                        | 3908.4    |                 |          |                           |           |             |             |           |
| WC#: 05.604                                    | AFL                        | 1492      |                 |          |                           |           |             |             |           |
|  | PROC. REF: AMS 5-00-00     |           |                 |          |                           |           |             |             | PKG:58,95 |
| 050691 <sup>S</sup>                            | INSPECT AREA F3-24 MONTHS  |           |                 |          |                           |           |             | Service     | ATA:05    |
|  | MOS                        | 25-Jul-24 | 24 (+2m/-2m)    |          |                           |           |             |             |           |
|  | HRS                        | 3908.4    |                 |          |                           |           |             |             |           |
| WC#: 05.606                                    | AFL                        | 1492      |                 |          |                           |           |             |             |           |
|  | PROC. REF: AMS 5-00-00     |           |                 |          |                           |           |             |             | PKG:60,95 |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit                      | C/W       | Interval     | TSX/Adj.               | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|--|---------------------------|-----------|--------------|------------------------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b> |                           |           |              |                        |                           |           |             |             |        |
| 050701 <sup>S</sup>                            | INSPECT AREA F4-24 MONTHS |           |              |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                       | 25-Jul-24 | 24 (+2m/-2m) |                        |                           |           |             |             |        |
|  | HRS                       | 3908.4    |              |                        |                           |           |             |             |        |
| WC#: 05.607                                    | AFL                       | 1492      |              |                        |                           |           |             |             |        |
|  |                           |           |              | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:61,95   |        |
| 050721 <sup>S</sup>                            | INSPECT AREA W1-24 MONTHS |           |              |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                       | 25-Jul-24 | 24 (+2m/-2m) |                        |                           |           |             |             |        |
|  | HRS                       | 3908.4    |              |                        |                           |           |             |             |        |
| WC#: 05.609                                    | AFL                       | 1492      |              |                        |                           |           |             |             |        |
|  |                           |           |              | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:63,95   |        |
| 050731 <sup>S</sup>                            | INSPECT AREA W2-24 MONTHS |           |              |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                       | 25-Jul-24 | 24 (+2m/-2m) |                        |                           |           |             |             |        |
|  | HRS                       | 3908.4    |              |                        |                           |           |             |             |        |
| WC#: 05.610                                    | AFL                       | 1492      |              |                        |                           |           |             |             |        |
|  |                           |           |              | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:64,95   |        |
| 050751 <sup>S</sup>                            | INSPECT AREA G-24 MONTHS  |           |              |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                       | 25-Jul-24 | 24 (+2m/-2m) |                        |                           |           |             |             |        |
|  | HRS                       | 3908.4    |              |                        |                           |           |             |             |        |
| WC#: 05.612                                    | AFL                       | 1492      |              |                        |                           |           |             |             |        |
|  |                           |           |              | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:66,95   |        |
| 050760   | INSPECTION G COMPLETE     |           |              |                        |                           |           |             | Package     | ATA:05 |
|  | MOS                       | 20-Jun-22 | 48 (+2m/-2m) |                        | 20-Jun-26                 | 20-Aug-26 | 691 d (+61) |             |        |
|  | HRS                       | 3511.6    |              |                        |                           |           |             |             |        |
|  | AFL                       | 1288      |              |                        |                           |           |             |             |        |
|  |                           |           |              | PROC. REF: AMS 5-26-00 |                           |           |             | PKG:96      |        |
| 050761 <sup>S</sup>                            | INSPECT AREA F1-48 MONTHS |           |              |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                       | 20-Jun-22 | 48 (+2m/-2m) |                        |                           |           |             |             |        |
|  | HRS                       | 3511.6    |              |                        |                           |           |             |             |        |
| WC#: 05.703                                    | AFL                       | 1288      |              |                        |                           |           |             |             |        |
|  |                           |           |              | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:96      |        |
| 050762 <sup>S</sup>                            | INSPECT AREA F2-48 MONTHS |           |              |                        |                           |           |             | Service     | ATA:05 |
|  | MOS                       | 20-Jun-22 | 48 (+2m/-2m) |                        |                           |           |             |             |        |
|  | HRS                       | 3511.6    |              |                        |                           |           |             |             |        |
| WC#: 05.704                                    | AFL                       | 1288      |              |                        |                           |           |             |             |        |
|  |                           |           |              | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:96      |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit  | C/W       | Interval      | TSX/Adj.               | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|--|---|-----------|---------------|------------------------|---------------------------|-----------|-------------|----------------|
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b> |   |           |               |                        |                           |           |             |                |
| 050763 <sup>S</sup>                            | INSPECT AREA F3-48 MONTHS                                   |           |               |                        |                           |           |             | Service ATA:05 |
|  | MOS   | 20-Jun-22 | 48 (+2m/-2m)  |                        |                           |           |             |                |
|  | HRS   | 3511.6    |               |                        |                           |           |             |                |
| WC#: 05.705                                    | AFL   | 1288      |               |                        |                           |           |             |                |
|  |   |           |               | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:96         |
| 050764 <sup>S</sup>                            | INSPECT AREA F4-48 MONTHS                                   |           |               |                        |                           |           |             | Service ATA:05 |
|  | MOS   | 20-Jun-22 | 48 (+2m/-2m)  |                        |                           |           |             |                |
|  | HRS   | 3511.6    |               |                        |                           |           |             |                |
| WC#: 05.707                                    | AFL   | 1288      |               |                        |                           |           |             |                |
|  |   |           |               | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:96         |
| 050765 <sup>S</sup>                            | INSPECT AREA T1-48 MONTHS                                   |           |               |                        |                           |           |             | Service ATA:05 |
|  | MOS   | 20-Jun-22 | 48 (+2m/-2m)  |                        |                           |           |             |                |
|  | HRS   | 3511.6    |               |                        |                           |           |             |                |
| WC#: 05.708                                    | AFL   | 1288      |               |                        |                           |           |             |                |
|  |   |           |               | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:96         |
| 050766 <sup>S</sup>                            | INSPECT AREA W1/W2-48 MONTHS                                |           |               |                        |                           |           |             | Service ATA:05 |
|  | MOS   | 20-Jun-22 | 48 (+2m/-2m)  |                        |                           |           |             |                |
|  | HRS   | 3511.6    |               |                        |                           |           |             |                |
| WC#: 05.709                                    | AFL   | 1288      |               |                        |                           |           |             |                |
|  |   |           |               | PROC. REF: AMS 5-00-00 |                           |           |             | PKG:96         |
| 050771   | INSPECTION 400 HOUR DETAILED WALK-AROUND                    |           |               |                        |                           |           |             | Service ATA:05 |
|  | MOS   | 13-Mar-24 |               |                        |                           |           |             |                |
|  | HRS   | 3890.9    | 400 (+40/-10) |                        | 4290.9                    | 4330.9    | 382.5 (+40) |                |
| WC#: 05.100                                    | AFL   | 1481      |               |                        |                           |           |             |                |
|  |   |           |               | PROC. REF: AMS 5-20-07 |                           |           |             |                |
| 055005   | ACCOMPLISH INSPECTIONS AFTER AN OVERWEIGHT OR HEAVY LANDING |           |               |                        |                           |           |             | Service ATA:05 |
|  | MOS/MSC   | 16-Mar-10 | A/R           |                        |                           |           |             |                |
|  | HRS   | 0         |               |                        |                           |           |             |                |
| WC#: 05.710                                    | AFL   | 0         |               |                        |                           |           |             |                |
|  |   |           |               | PROC. REF: AMS 5-50-01 |                           |           |             |                |
| 055010   | ACCOMPLISH INSPECTIONS AFTER FLIGHT IN HEAVY TURBULENCE     |           |               |                        |                           |           |             | Service ATA:05 |
|  | MOS/MSC   | 16-Mar-10 | A/R           |                        |                           |           |             |                |
|  | HRS   | 0         |               |                        |                           |           |             |                |
| WC#: 05.711                                    | AFL   | 0         |               |                        |                           |           |             |                |
|  |   |           |               | PROC. REF: AMS 5-50-02 |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b> |  |           |          |          |                           |           |           |             |        |
| 055015   | <b>ACCOMPLISH INSPECTIONS AFTER A LIGHTNING STRIKE</b>   |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC  | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 05.712                                    | AFL  | 0         |          |          |                           |           |           |             |        |
|  | PROC. REF: AMS 5-50-03   |           |          |          |                           |           |           |             |        |
| 055035   | <b>ACCOMPLISH INSPECTIONS AFTER A COLD SOAK BELOW -40 DEGREE C</b>                                   |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC  | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 05.713                                    | AFL  | 0         |          |          |                           |           |           |             |        |
|  | PROC. REF: AMM 27-33-00, AMS 5-50-06   |           |          |          |                           |           |           |             |        |
| 055040   | <b>ACCOMPLISH INSPECTIONS AFTER MISUSE OF REVERSE THRUST</b>   |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC  | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 05.714                                    | AFL  | 0         |          |          |                           |           |           |             |        |
|  | PROC. REF: AMS 5-50-04   |           |          |          |                           |           |           |             |        |
| 055045   | <b>ACCOMPLISH INSPECTIONS AFTER LANDING GEAR VIBRATION</b>   |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC  | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 05.715                                    | AFL  | 0         |          |          |                           |           |           |             |        |
|  | PROC. REF: AMS 5-50-05   |           |          |          |                           |           |           |             |        |
| 055050   | <b>ACCOMPLISH INSPECTIONS AFTER LANDING OR ABORTED TAKE-OFF IN DEEP WATER PUDDLES, SLUSH OR SNOW</b> |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC  | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 05.716                                    | AFL  | 0         |          |          |                           |           |           |             |        |
|  | PROC. REF: AMS 5-50-07   |           |          |          |                           |           |           |             |        |
| 055060   | <b>ACCOMPLISH INSPECTIONS AFTER AN EMERGENCY STOP</b>  |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC  | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 05.717                                    | AFL  | 0         |          |          |                           |           |           |             |        |
|  | PROC. REF: AMM 32-40-114, AMS 5-50-08  |           |          |          |                           |           |           |             |        |
| 055065   | <b>ACCOMPLISH INSPECTIONS AFTER ABNORMAL APU CONDITIONS</b>  |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC  | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 05.718                                    | AFL  | 0         |          |          |                           |           |           |             |        |
|  | PROC. REF: AMS 5-50-09   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b>     |   |           |          |          |                           |           |           |             |        |
| 055070   | <b>ACCOMPLISH INSPECTIONS AFTER FLAP OVERSPEED</b>  |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC   | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS   | 0         |          |          |                           |           |           |             |        |
| WC#: 05.719  | AFL   | 0         |          |          |                           |           |           |             |        |
| PROC. REF: AMM 27-50-02, AMM 27-50-02, AMS 5-50-10 |   |           |          |          |                           |           |           |             |        |
| 055075   | <b>ACCOMPLISH INSPECTIONS AFTER EXPOSURE TO VOLCANIC ASH</b>                              |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC   | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS   | 0         |          |          |                           |           |           |             |        |
| WC#: 05.720  | AFL   | 0         |          |          |                           |           |           |             |        |
| PROC. REF: AMS 5-50-11                             |   |           |          |          |                           |           |           |             |        |
| 055080   | <b>ACCOMPLISH INSPECTIONS FOR HYDRAULIC CONTAMINATION OF THE CABIN VENTILATION SYSTEM</b> |           |          |          |                           |           |           | Service     | ATA:05 |
|  | MOS/MSC   | 16-Mar-10 | A/R      |          |                           |           |           |             |        |
|  | HRS   | 0         |          |          |                           |           |           |             |        |
|  | AFL   | 0         |          |          |                           |           |           |             |        |
| PROC. REF: AMS 5-50-12                             |   |           |          |          |                           |           |           |             |        |
| 057110   | <b>NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION</b>  |           |          |          |                           |           |           | Package     | ATA:05 |
|  | MOS   | 13-Mar-24 |          |          |                           |           |           |             |        |
|  | HRS   | 3877.8    | 250      |          | (4127.8)<br>4140.9        |           | 232.5     |             |        |
|  | ENC   | 1467      |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                          |   |           |          |          |                           |           |           |             |        |
| 057110   | <b>NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION</b>  |           |          |          |                           |           |           | Package     | ATA:05 |
|  | MOS   | 13-Mar-24 |          |          |                           |           |           |             |        |
|  | HRS   | 3877.8    | 250      |          | (4127.8)<br>4140.9        |           | 232.5     |             |        |
|  | ENC   | 1467      |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                          |   |           |          |          |                           |           |           |             |        |
| 057120   | <b>NO. 1 ENGINE - 500 TO 650 HOUR INSPECTION</b>  |           |          |          |                           |           |           | Package     | ATA:05 |
|  | MOS   | 14-May-20 |          |          |                           |           |           |             |        |
|  | HRS   | 3324.5    | 650      |          | (3974.5)<br>3987.6        |           | 79.2      |             |        |
|  | ENC   | 1210      |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                          |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                 | Unit  | C/W                       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---|---------------------------|----------|----------|---------------------------|-----------|-----------|-------------|
| ATA 05 - TIME LIMITS/MAINTENANCE CHECKS |   |                           |          |          |                           |           |           |             |
| 057120                                  | NO. 2 ENGINE - 500 TO 650 HOUR INSPECTION   |                           |          |          |                           |           |           |             |
|   | MOS   | 14-May-20                 |          |          |                           |           |           |             |
|   | HRS   | 3324.5                    | 650      |          | (3974.5)<br>3987.6        |           | 79.2      |             |
|   | ENC   | 1210                      |          |          |                           |           |           |             |
|   |   | PROC. REF: GENERIC NO REF |          |          |                           |           |           |             |
| 057125                                  | NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION   |                           |          |          |                           |           |           |             |
|   | MOS   | 20-Jun-22                 |          |          |                           |           |           |             |
|   | HRS   | 3498.5                    | 850      |          | (4348.5)<br>4361.6        |           | 453.2     |             |
|   | ENC   | 1274                      |          |          |                           |           |           |             |
|   |   | PROC. REF: GENERIC NO REF |          |          |                           |           |           |             |
| 057125                                  | NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION   |                           |          |          |                           |           |           |             |
|   | MOS   | 20-Jun-22                 |          |          |                           |           |           |             |
|   | HRS   | 3498.5                    | 850      |          | (4348.5)<br>4361.6        |           | 453.2     |             |
|   | ENC   | 1274                      |          |          |                           |           |           |             |
|   |   | PROC. REF: GENERIC NO REF |          |          |                           |           |           |             |
| 057130                                  | NO. 1 ENGINE - 1000 TO 1300 HOUR INSPECTION |                           |          |          |                           |           |           |             |
|   | MOS   | 04-Dec-17                 |          |          |                           |           |           |             |
|   | HRS   | 2853.82                   | 1300     |          | (4153.82)<br>4166.92      |           | 258.5     |             |
|   | ENC   | 1031                      |          |          |                           |           |           |             |
|   |   | PROC. REF: GENERIC NO REF |          |          |                           |           |           |             |
| 057130                                  | NO. 2 ENGINE - 1000 TO 1300 HOUR INSPECTION |                           |          |          |                           |           |           |             |
|   | MOS   | 28-Nov-17                 |          |          |                           |           |           |             |
|   | HRS   | 2853.82                   | 1300     |          | (4153.82)<br>4166.92      |           | 258.5     |             |
|   | ENC   | 1031                      |          |          |                           |           |           |             |
|   |   | PROC. REF: GENERIC NO REF |          |          |                           |           |           |             |
| 057135                                  | NO. 1 ENGINE - 1500 TO 1650 HOUR INSPECTION |                           |          |          |                           |           |           |             |
|   | MOS   | 04-Dec-17                 |          |          |                           |           |           |             |
|   | HRS   | 2853.82                   | 1650     |          | (4503.82)<br>4516.92      |           | 608.5     |             |
|   | ENC   | 1031                      |          |          |                           |           |           |             |
|   |   | PROC. REF: GENERIC NO REF |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit  | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition    |
|--|---|-----------|---------------|----------|---------------------------|-----------|-------------|----------------|
| <b>ATA 05 - TIME LIMITS/MAINTENANCE CHECKS</b> |   |           |               |          |                           |           |             |                |
| 057135   | NO. 2 ENGINE - 1500 TO 1650 HOUR INSPECTION |           |               |          |                           |           |             | Package ATA:05 |
|  | MOS   | 28-Nov-17 |               |          |                           |           |             |                |
|  | HRS   | 2853.82   | 1650          |          | (4503.82)<br>4516.92      |           | 608.5       |                |
|  | ENC   | 1031      |               |          |                           |           |             |                |
| PROC. REF: GENERIC NO REF                      |   |           |               |          |                           |           |             | PKG:5          |
| <b>ATA 08 - LEVELING AND WEIGHING</b>          |   |           |               |          |                           |           |             |                |
| 080001 <sup>U S</sup>                          | PERFORM WEIGHT AND BALANCE OF AIRCRAFT      |           |               |          |                           |           |             | Service ATA:08 |
|  | MOS   | 19-Aug-22 | 36            |          |                           |           |             |                |
|  | HRS   | 3555.1    |               |          |                           |           |             |                |
|  | AFL   | 1314      |               |          |                           |           |             |                |
| <b>ATA 12 - SERVICING</b>                      |   |           |               |          |                           |           |             |                |
| 120001   | LUBRICATE AREA G-200 HOURS                  |           |               |          |                           |           |             | Service ATA:12 |
|  | MOS   | 12-Feb-24 |               |          |                           |           |             |                |
|  | HRS   | 3881.4    | 200 (+40/-10) |          | 4081.4                    | 4121.4    | 173 (+40)   |                |
| WC#: 12.001                                    | AFL   | 1476      |               |          |                           |           |             |                |
| PROC. REF: AMS 5-20-11                         |   |           |               |          |                           |           |             |                |
| 120003   | LUBRICATE AREA F1-400 HOURS                 |           |               |          |                           |           |             | Service ATA:12 |
|  | MOS   | 13-Mar-24 |               |          |                           |           |             |                |
|  | HRS   | 3890.9    | 400 (+40/-10) |          | 4290.9                    | 4330.9    | 382.5 (+40) |                |
| WC#: 12.003                                    | AFL   | 1481      |               |          |                           |           |             |                |
| PROC. REF: AMS 5-20-11                         |   |           |               |          |                           |           |             |                |
| 120004   | LUBRICATE AREA T1-400 HOURS                 |           |               |          |                           |           |             | Service ATA:12 |
|  | MOS   | 13-Mar-24 |               |          |                           |           |             |                |
|  | HRS   | 3890.9    | 400 (+40/-10) |          | 4290.9                    | 4330.9    | 382.5 (+40) |                |
| WC#: 12.004                                    | AFL   | 1481      |               |          |                           |           |             |                |
| PROC. REF: AMS 5-20-11                         |   |           |               |          |                           |           |             |                |
| 120007   | LUBRICATE AREA W1/W2-400 HOURS              |           |               |          |                           |           |             | Service ATA:12 |
|  | MOS   | 13-Mar-24 |               |          |                           |           |             |                |
|  | HRS   | 3890.9    | 400 (+40/-10) |          | 4290.9                    | 4330.9    | 382.5 (+40) |                |
| WC#: 12.007                                    | AFL   | 1481      |               |          |                           |           |             |                |
| PROC. REF: AMM 28-10-44, AMS 5-20-11           |   |           |               |          |                           |           |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN             | Unit                                      | C/W       | Interval       | TSX/Adj.                             | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------|---|-----------|----------------|--------------------------------------|---------------------------|-----------|-----------|-------------|--------|
| ATA 12 - SERVICING  |   |           |                |                                      |                           |           |           |             |        |
| 120012 <sup>S</sup> | LUBRICATE AREA F3 (ABOVE FLOOR)-800 HOURS |           |                |                                      |                           |           |           | Service     | ATA:12 |
|                     | MOS                                       | 03-Aug-21 |                |                                      |                           |           |           |             |        |
|                     | HRS                                       | 3405      | 800 (+40/-10)  |                                      |                           |           |           |             |        |
| WC#: 12.012         | AFL                                       | 1243      |                |                                      |                           |           |           |             |        |
|                     |   |           |                | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:12,91   |        |
| 120013 <sup>S</sup> | LUBRICATE AREA F4-800 HOURS               |           |                |                                      |                           |           |           | Service     | ATA:12 |
|                     | MOS                                       | 03-Aug-21 |                |                                      |                           |           |           |             |        |
|                     | HRS                                       | 3405      | 800 (+40/-10)  |                                      |                           |           |           |             |        |
| WC#: 12.009         | AFL                                       | 1243      |                |                                      |                           |           |           |             |        |
|                     |   |           |                | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:13,91   |        |
| 120015 <sup>S</sup> | LUBRICATE AREA W1-800 HOURS               |           |                |                                      |                           |           |           | Service     | ATA:12 |
|                     | MOS                                       | 03-Aug-21 |                |                                      |                           |           |           |             |        |
|                     | HRS                                       | 3405      | 800 (+40/-10)  |                                      |                           |           |           |             |        |
| WC#: 12.015         | AFL                                       | 1243      |                |                                      |                           |           |           |             |        |
|                     |   |           |                | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:15,91   |        |
| 120016 <sup>S</sup> | LUBRICATE AREA W2-800 HOURS               |           |                |                                      |                           |           |           | Service     | ATA:12 |
|                     | MOS                                       | 03-Aug-21 |                |                                      |                           |           |           |             |        |
|                     | HRS                                       | 3405      | 800 (+40/-10)  |                                      |                           |           |           |             |        |
| WC#: 12.016         | AFL                                       | 1243      |                |                                      |                           |           |           |             |        |
|                     |   |           |                | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:16,91   |        |
| 120018 <sup>S</sup> | LUBRICATE AREA G-800 HOURS                |           |                |                                      |                           |           |           | Service     | ATA:12 |
|                     | MOS                                       | 03-Aug-21 |                |                                      |                           |           |           |             |        |
|                     | HRS                                       | 3405      | 800 (+40/-10)  |                                      |                           |           |           |             |        |
| WC#: 12.018         | AFL                                       | 1243      |                |                                      |                           |           |           |             |        |
|                     |   |           |                | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:18,91   |        |
| 120019 <sup>S</sup> | LUBRICATE AREA F1-1600 HOURS              |           |                |                                      |                           |           |           | Service     | ATA:12 |
|                     | MOS                                       | 06-Jun-18 |                |                                      |                           |           |           |             |        |
|                     | HRS                                       | 2965.25   | 1600 (+50/-50) |                                      |                           |           |           |             |        |
| WC#: 12.013         | AFL                                       | 1073      |                |                                      |                           |           |           |             |        |
|                     |   |           |                | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:21,92   |        |
| 120020 <sup>S</sup> | LUBRICATE AREA F2-1600 HOURS              |           |                |                                      |                           |           |           | Service     | ATA:12 |
|                     | MOS                                       | 06-Jun-18 |                |                                      |                           |           |           |             |        |
|                     | HRS                                       | 2965.25   | 1600 (+50/-50) |                                      |                           |           |           |             |        |
| WC#: 12.020         | AFL                                       | 1073      |                |                                      |                           |           |           |             |        |
|                     |   |           |                | PROC. REF: AMM 32-66-00, AMS 5-20-11 |                           |           |           | PKG:22,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit                                      | C/W       | Interval        | TSX/Adj.                             | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|---|-----------|-----------------|--------------------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 12 - SERVICING</b> |   |           |                 |                                      |                           |           |           |             |        |
| 120021 <sup>S</sup>       | LUBRICATE AREA F3 (UNDERFLOOR)-1600 HOURS |           |                 |                                      |                           |           |           | Service     | ATA:12 |
|                           | MOS                                       | 06-Jun-18 |                 |                                      |                           |           |           |             |        |
|                           | HRS                                       | 2965.25   | 1600 (+50/-50)  |                                      |                           |           |           |             |        |
| WC#: 12.021               | AFL                                       | 1073      |                 |                                      |                           |           |           |             |        |
|                           |   |           |                 | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:23,92   |        |
| 120022 <sup>S</sup>       | LUBRICATE AREA F3-1600 HOURS              |           |                 |                                      |                           |           |           | Service     | ATA:12 |
|                           | MOS                                       | 06-Jun-18 |                 |                                      |                           |           |           |             |        |
|                           | HRS                                       | 2965.25   | 1600 (+50/-50)  |                                      |                           |           |           |             |        |
| WC#: 12.022               | AFL                                       | 1073      |                 |                                      |                           |           |           |             |        |
|                           |   |           |                 | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:24,92   |        |
| 120023 <sup>S</sup>       | LUBRICATE AREA F4-1600 HOURS              |           |                 |                                      |                           |           |           | Service     | ATA:12 |
|                           | MOS                                       | 06-Jun-18 |                 |                                      |                           |           |           |             |        |
|                           | HRS                                       | 2965.25   | 1600 (+50/-50)  |                                      |                           |           |           |             |        |
| WC#: 12.023               | AFL                                       | 1073      |                 |                                      |                           |           |           |             |        |
|                           |   |           |                 | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:25,92   |        |
| 120024 <sup>S</sup>       | LUBRICATE AREA T1-1600 HOURS              |           |                 |                                      |                           |           |           | Service     | ATA:12 |
|                           | MOS                                       | 06-Jun-18 |                 |                                      |                           |           |           |             |        |
|                           | HRS                                       | 2965.25   | 1600 (+50/-50)  |                                      |                           |           |           |             |        |
| WC#: 12.024               | AFL                                       | 1073      |                 |                                      |                           |           |           |             |        |
|                           |   |           |                 | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:26,92   |        |
| 120025 <sup>S</sup>       | LUBRICATE AREA W1-1600 HOURS              |           |                 |                                      |                           |           |           | Service     | ATA:12 |
|                           | MOS                                       | 06-Jun-18 |                 |                                      |                           |           |           |             |        |
|                           | HRS                                       | 2965.25   | 1600 (+50/-50)  |                                      |                           |           |           |             |        |
| WC#: 12.025               | AFL                                       | 1073      |                 |                                      |                           |           |           |             |        |
|                           |   |           |                 | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:27,92   |        |
| 120026 <sup>S</sup>       | LUBRICATE AREA W2-1600 HOURS              |           |                 |                                      |                           |           |           | Service     | ATA:12 |
|                           | MOS                                       | 06-Jun-18 |                 |                                      |                           |           |           |             |        |
|                           | HRS                                       | 2965.25   | 1600 (+50/-50)  |                                      |                           |           |           |             |        |
| WC#: 12.026               | AFL                                       | 1073      |                 |                                      |                           |           |           |             |        |
|                           |   |           |                 | PROC. REF: AMS 5-20-11               |                           |           |           | PKG:28,92   |        |
| 120030 <sup>S</sup>       | LUBRICATE AREA F2-3200 HOURS              |           |                 |                                      |                           |           |           | Service     | ATA:12 |
|                           | MOS                                       | 06-Jun-18 |                 |                                      |                           |           |           |             |        |
|                           | HRS                                       | 2965.25   | 3200 (+150/-50) |                                      |                           |           |           |             |        |
| WC#: 12.030               | AFL                                       | 1073      |                 |                                      |                           |           |           |             |        |
|                           |   |           |                 | PROC. REF: AMM 32-66-00, AMS 5-20-11 |                           |           |           | PKG:34,93   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                       | Unit  | C/W       | Interval      | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---|---|-----------|---------------|-------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 12 - SERVICING</b>                     |   |           |               |                         |                           |           |           |             |        |
| 120049 <sup>S</sup>                           | LUBRICATE AREA F1-24 MONTHS                         |           |               |                         |                           |           |           | Service     | ATA:12 |
|   | MOS   | 25-Jul-24 | 24 (+2m/-2m)  |                         |                           |           |           |             |        |
|   | HRS   | 3908.4    |               |                         |                           |           |           |             |        |
| WC#: 12.049                                   | AFL   | 1492      |               |                         |                           |           |           |             |        |
|   |   |           |               | PROC. REF: AMS 5-20-11  |                           |           |           | PKG:57,95   |        |
| 120050 <sup>S</sup>                           | LUBRICATE AREA F2-24 MONTHS                         |           |               |                         |                           |           |           | Service     | ATA:12 |
|   | MOS   | 25-Jul-24 | 24 (+2m/-2m)  |                         |                           |           |           |             |        |
|   | HRS   | 3908.4    |               |                         |                           |           |           |             |        |
| WC#: 12.050                                   | AFL   | 1492      |               |                         |                           |           |           |             |        |
|   |   |           |               | PROC. REF: AMS 5-20-11  |                           |           |           | PKG:58,95   |        |
| <b>ATA 20 - STANDARD PRACTICES - AIRFRAME</b> |   |           |               |                         |                           |           |           |             |        |
| 200001 <sup>S</sup>                           | BONDING CHECK CONTROL SURFACES                      |           |               |                         |                           |           |           | Service     | ATA:20 |
|   | MOS   | 03-Aug-21 |               |                         |                           |           |           |             |        |
|   | HRS   | 3405      | 800 (+40/-10) |                         |                           |           |           |             |        |
| WC#: 20.010                                   | AFL   | 1243      |               |                         |                           |           |           |             |        |
|   |   |           |               |                         |                           |           |           | PKG:7,91    |        |
| 200002 <sup>S</sup>                           | FUNCTIONAL TEST REFUEL POINT EARTHING STUDS (3 OFF) |           |               |                         |                           |           |           | Service     | ATA:20 |
|   | MOS   | 03-Aug-21 |               |                         |                           |           |           |             |        |
|   | HRS   | 3405      | 800 (+40/-10) |                         |                           |           |           |             |        |
| WC#: 20.020                                   | AFL   | 1243      |               |                         |                           |           |           |             |        |
|   |   |           |               |                         |                           |           |           | PKG:7,91    |        |
| 200003 <sup>S</sup>                           | CHECK RADIO RACKING, ELECTRICAL-BONDING             |           |               |                         |                           |           |           | Service     | ATA:20 |
|   | MOS   | 20-Jun-22 | 48 (+2m/-2m)  |                         |                           |           |           |             |        |
|   | HRS   | 3511.6    |               |                         |                           |           |           |             |        |
| WC#: 20.030                                   | AFL   | 1288      |               |                         |                           |           |           |             |        |
|   |   |           |               | PROC. REF: AMM 24-01-00 |                           |           |           | PKG:96      |        |
| <b>ATA 21 - AIR CONDITIONING</b>              |   |           |               |                         |                           |           |           |             |        |
| 210002 <sup>S</sup>                           | CHECK/TEST RAM AIR VALVE/DUMP VALVE/VENT VALVE      |           |               |                         |                           |           |           | Service     | ATA:21 |
|   | MOS   | 03-Aug-21 |               |                         |                           |           |           |             |        |
|   | HRS   | 3405      | 800 (+40/-10) |                         |                           |           |           |             |        |
| WC#: 21.075                                   | AFL   | 1243      |               |                         |                           |           |           |             |        |
|   |   |           |               |                         |                           |           |           | PKG:7,91    |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit   | C/W       | Interval       | TSX/Adj.                              | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|----------------------------------|--|-----------|----------------|---------------------------------------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 21 - AIR CONDITIONING</b> |  |           |                |                                       |                           |           |             |             |        |
| 210003 <sup>S</sup>              | BENCH CHECK ENVIRONMENTAL CONTROL SYSTEM   |           |                |                                       |                           |           |             | Service     | ATA:21 |
|                                  | MOS  | 03-Aug-21 |                |                                       |                           |           |             |             |        |
|                                  | HRS  | 3405      | 800 (+40/-10)  |                                       |                           |           |             |             |        |
| WC#: 21.110                      | AFL  | 1243      |                |                                       |                           |           |             |             |        |
|                                  |  |           |                | PROC. REF: AMM 21-10-78               |                           |           |             | PKG:7,91    |        |
| 210004 <sup>S</sup>              | CHECK MANUAL CABIN ALTITUDE CONTROL VALVE  |           |                |                                       |                           |           |             | Service     | ATA:21 |
|                                  | MOS  | 03-Aug-21 |                |                                       |                           |           |             |             |        |
|                                  | HRS  | 3405      | 800 (+40/-10)  |                                       |                           |           |             |             |        |
| WC#: 21.270                      | AFL  | 1243      |                |                                       |                           |           |             | PKG:10,91   |        |
| 210005 <sup>S</sup>              | CHECK COOLING TURBINE EXHAUST DUCT DRAIN   |           |                |                                       |                           |           |             | Service     | ATA:21 |
|                                  | MOS  | 03-Aug-21 |                |                                       |                           |           |             |             |        |
|                                  | HRS  | 3405      | 800 (+40/-10)  |                                       |                           |           |             |             |        |
| WC#: 21.260                      | AFL  | 1243      |                |                                       |                           |           |             | PKG:13,91   |        |
| 210006                           | INSPECT WATER SEPARATOR FOR SATISFACTORY CONDITION   |           |                |                                       |                           |           |             | Service     | ATA:21 |
|                                  | MOS  | 13-Mar-24 |                |                                       |                           |           |             |             |        |
|                                  | HRS  | 3890.9    | 400 (+10%)     |                                       | 4290.9                    | 4330.9    | 382.5 (+40) |             |        |
| WC#: 21.221                      | AFL  | 1481      |                |                                       |                           |           |             |             |        |
|                                  |  |           |                | PROC. REF: AMM 21-10-95, AMM 21-10-95 |                           |           |             |             |        |
| 210007                           | INSPECT WATER SEPARATOR WATER DRAIN, WATER DRAIN PIPELINE, HP LINE TO WATER INJECTOR NOZZLE AND WATER INJECTOR NOZZLE ARE FREE FROM BLOCKAGES AND OBSTRUCTIONS |           |                |                                       |                           |           |             | Service     | ATA:21 |
|                                  | MOS  | 13-Mar-24 |                |                                       |                           |           |             |             |        |
|                                  | HRS  | 3890.9    | 400 (+10%)     |                                       | 4290.9                    | 4330.9    | 382.5 (+40) |             |        |
| WC#: 21.280                      | AFL  | 1481      |                |                                       |                           |           |             |             |        |
|                                  |  |           |                | PROC. REF: AMM 21-10-95               |                           |           |             |             |        |
| 210008 <sup>S</sup>              | VISUALLY INSPECT CABIN PRESSURE OUTFLOW/SAFETY VALVE CONTROLLER  |           |                |                                       |                           |           |             | Service     | ATA:21 |
|                                  | MOS  | 06-Jun-18 |                |                                       |                           |           |             |             |        |
|                                  | HRS  | 2965.25   | 1600 (+50/-50) |                                       |                           |           |             |             |        |
| WC#: 21.118                      | AFL  | 1073      |                |                                       |                           |           |             | PKG:22,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit  | C/W       | Interval        | TSX/Adj.                              | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------------|---|-----------|-----------------|---------------------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 21 - AIR CONDITIONING</b> |   |           |                 |                                       |                           |           |           |             |        |
| 210009 <sup>S</sup>              | CHECK PRESSURIZATION CONTROL VENTURI SCREEN       |           |                 |                                       |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 06-Jun-18 |                 |                                       |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 1600 (+50/-50)  |                                       |                           |           |           |             |        |
| WC#: 21.275                      | AFL   | 1073      |                 |                                       |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-30-65               |                           |           |           | PKG:24,92   |        |
| 210010 <sup>S</sup>              | CLEAN PRESSURE REGULATOR FILTER SCREENS           |           |                 |                                       |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 20-Jun-22 | 48 (+2m/-2m)    |                                       |                           |           |           |             |        |
|                                  | HRS   | 3511.6    |                 |                                       |                           |           |           |             |        |
| WC#: 21.155                      | AFL   | 1288      |                 |                                       |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-30-55               |                           |           |           | PKG:96      |        |
| 210011 <sup>S</sup>              | CLEAN/FUNCTIONAL TEST OUTFLOW/SAFETY VALVES       |           |                 |                                       |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 20-Jun-22 | 48 (+2m/-2m)    |                                       |                           |           |           |             |        |
|                                  | HRS   | 3511.6    |                 |                                       |                           |           |           |             |        |
| WC#: 21.120                      | AFL   | 1288      |                 |                                       |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-30-25, AMM 21-30-25 |                           |           |           | PKG:96      |        |
| 210012 <sup>S</sup>              | INSPECT AIR CONDITIONING DUCTS                    |           |                 |                                       |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 06-Jun-18 |                 |                                       |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 1600 (+50/-50)  |                                       |                           |           |           |             |        |
| WC#: 21.250                      | AFL   | 1073      |                 |                                       |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-10-15               |                           |           |           | PKG:25,92   |        |
| 210013 <sup>S</sup>              | INSPECT RAM AIR DUCT                              |           |                 |                                       |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 06-Jun-18 |                 |                                       |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 1600 (+50/-50)  |                                       |                           |           |           |             |        |
| WC#: 21.255                      | AFL   | 1073      |                 |                                       |                           |           |           |             |        |
|                                  |   |           |                 |                                       |                           |           |           | PKG:25,92   |        |
| 210014 <sup>S</sup>              | INSPECT CABIN AIR FILTERS (PRESSURIZATION SYSTEM) |           |                 |                                       |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 20-Jun-22 | 48 (+2m/-2m)    |                                       |                           |           |           |             |        |
|                                  | HRS   | 3511.6    |                 |                                       |                           |           |           |             |        |
| WC#: 21.310                      | AFL   | 1288      |                 |                                       |                           |           |           |             |        |
|                                  |   |           |                 |                                       |                           |           |           | PKG:96      |        |
| 210015 <sup>S</sup>              | INSPECT SILENCER DUCT/SOUNDPROOFING               |           |                 |                                       |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 06-Jun-18 |                 |                                       |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 3200 (+150/-50) |                                       |                           |           |           |             |        |
| WC#: 21.015                      | AFL   | 1073      |                 |                                       |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-10-15               |                           |           |           | PKG:37,93   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit  | C/W       | Interval        | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------------|---|-----------|-----------------|---|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 21 - AIR CONDITIONING</b> |   |           |                 |   |                           |           |           |             |        |
| 210016 <sup>S</sup>              | BENCH CHECK SYSTEM OVERHEAT TEMPERATURE SWITCH  |           |                 |   |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 06-Jun-18 |                 |   |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 3200 (+150/-50) |   |                           |           |           |             |        |
| WC#: 21.195                      | AFL   | 1073      |                 |   |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-60-85                             |                           |           |           | PKG:37,93   |        |
| 210018 <sup>S</sup>              | FUNCTIONAL TEST ALTITUDE SWITCH, CABIN DEPRESSURIZATION WARNING   |           |                 |   |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 20-Jun-22 | 48 (+2m/-2m)    |   |                           |           |           |             |        |
|                                  | HRS   | 3511.6    |                 |   |                           |           |           |             |        |
| WC#: 21.135                      | AFL   | 1288      |                 |   |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-30-70                             |                           |           |           | PKG:96      |        |
| 210019 <sup>S</sup>              | INSPECT CABIN SUPPLY NON-RETURN VALVE   |           |                 |   |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 06-Jun-18 |                 |   |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 3200 (+150/-50) |   |                           |           |           |             |        |
| WC#: 21.065                      | AFL   | 1073      |                 |   |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-10-107                            |                           |           |           | PKG:37,93   |        |
| 210020 <sup>S</sup>              | FUNCTIONAL TEST ELECTRICALLY ACTUATED AUXILIARY HEATING VALVE   |           |                 |   |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 06-Jun-18 |                 |   |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 1600 (+50/-50)  |   |                           |           |           |             |        |
| WC#: 21.180                      | AFL   | 1073      |                 |   |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-60-105                            |                           |           |           | PKG:19,92   |        |
| 210021 <sup>S</sup>              | INSPECT/CHECK APU SUPPLY, AUXILIARY SUPPLY, RAM AIR SUPPLY AND MAIN ENGINE SUPPLY CHECK/NON-RETURN VALVES |           |                 |   |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 06-Jun-18 |                 |   |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 3200 (+150/-50) |   |                           |           |           |             |        |
| WC#: 21.030                      | AFL   | 1073      |                 |   |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-10-165                            |                           |           |           | PKG:37,93   |        |
| 210022                           | CHECK TORQUE AIR CONDITIONING DUCTS   |           |                 |   |                           |           |           | Service     | ATA:21 |
|                                  | MOS/MSC   | 13-Mar-24 | O/C             |   |                           |           |           |             |        |
|                                  | HRS   | 3890.9    |                 |   |                           |           |           |             |        |
| WC#: 21.010                      | AFL   | 1481      |                 |   |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-10-87, AMM 21-10-15, AMM 21-10-95 |                           |           |           |             |        |
| 210024 <sup>S</sup>              | CLEAN/REPLACE LOW LIMIT TEMPERATURE CONTROL VALVE FILTER  |           |                 |   |                           |           |           | Service     | ATA:21 |
|                                  | MOS   | 03-Aug-21 |                 |   |                           |           |           |             |        |
|                                  | HRS   | 3405      | 800 (+40/-10)   |   |                           |           |           |             |        |
| WC#: 21.290                      | AFL   | 1243      |                 |   |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 21-60-61                             |                           |           |           | PKG:13,91   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition             |        |
|----------------------------------|--|-----------|----------------|----------|---------------------------|-----------|-----------|-------------------------|--------|
| <b>ATA 21 - AIR CONDITIONING</b> |  |           |                |          |                           |           |           |                         |        |
| 210025 <sup>S</sup>              | INSPECT PATS APU GTCP36-150W BLEED AIR SYSTEM              |           |                |          |                           |           |           | Service                 | ATA:21 |
|                                  | MOS  | 06-Jun-18 |                |          |                           |           |           |                         |        |
|                                  | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |           |                         |        |
| WC#: 21.035                      | AFL  | 1073      |                |          |                           |           |           |                         |        |
|                                  |  |           |                |          |                           |           |           | PKG:25,92               |        |
| 210026                           | REPLACE DIGITAL PRESSURIZATION CABIN AIR FILTER ELEMENT    |           |                |          |                           |           |           | Service                 | ATA:21 |
|                                  | MOS/MSC  | 05-May-10 | N/R            |          |                           |           |           |                         |        |
|                                  | HRS  | 0         |                |          |                           |           |           |                         |        |
| WC#: 21.322                      | AFL  | 0         |                |          |                           |           |           |                         |        |
| 210027                           | CLEAN ELECTROPNEUMATIC OUTFLOW VALVE                       |           |                |          |                           |           |           | Service                 | ATA:21 |
|                                  | MOS/MSC  | 05-May-10 | N/R            |          |                           |           |           |                         |        |
|                                  | HRS  | 0         |                |          |                           |           |           |                         |        |
| WC#: 21.323                      | AFL  | 0         |                |          |                           |           |           |                         |        |
|                                  |  |           |                |          |                           |           |           | PROC. REF: AMM 21-31-10 |        |
| 210028                           | TEST ELECTROPNEUMATIC OUTFLOW VALVE (EOV) PRESSURE LIMITER |           |                |          |                           |           |           | Service                 | ATA:21 |
|                                  | MOS/MSC  | 05-May-10 | N/R            |          |                           |           |           |                         |        |
|                                  | HRS  | 0         |                |          |                           |           |           |                         |        |
| WC#: 21.324                      | AFL  | 0         |                |          |                           |           |           |                         |        |
|                                  |  |           |                |          |                           |           |           | PROC. REF: AMM 21-31-00 |        |
| 210029                           | INSPECTION/CHECK ELECTROPNEUMATIC OUTFLOW VALVES           |           |                |          |                           |           |           | Service                 | ATA:21 |
|                                  | MOS/MSC  | 16-Mar-10 | N/R            |          |                           |           |           |                         |        |
|                                  | HRS  | 0         |                |          |                           |           |           |                         |        |
| WC#: 21.325                      | AFL  | 0         |                |          |                           |           |           |                         |        |
|                                  |  |           |                |          |                           |           |           | PROC. REF: AMM 21-31-10 |        |
| 211013                           | LEFT SWITCHES BLEED AIR OVER TEMPERATURE TEST              |           |                |          |                           |           |           | Service                 | ATA:21 |
|                                  | MOS  | 31-Dec-19 | 60             |          | 31-Dec-24                 |           | 155 d     |                         |        |
|                                  | HRS  | 3327.28   |                |          |                           |           |           |                         |        |
| WC#: 21.265                      | AFL  | 1211      |                |          |                           |           |           |                         |        |
| 211014                           | RIGHT SWITCHES BLEED AIR OVER TEMPERATURE TEST             |           |                |          |                           |           |           | Service                 | ATA:21 |
|                                  | MOS  | 31-Dec-19 | 60             |          | 31-Dec-24                 |           | 155 d     |                         |        |
|                                  | HRS  | 3327.28   |                |          |                           |           |           |                         |        |
| WC#: 21.265                      | AFL  | 1211      |                |          |                           |           |           |                         |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit    | C/W                                    | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|----------------------------------|---------|--|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 21 - AIR CONDITIONING</b> |         |  |          |          |                           |           |           |                  |               |
| <b>211019</b>                    |         | <b>APU SHUTOFF VALVE</b>               |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:PN                            | MOS/MSC | 16-Mar-10                              | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:UNKNOWN                       | HRS     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
| WC#: 21.020                      | AFL     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM 21-10-195         |         |  |          |          |                           |           |           |                  |               |
| <b>211031</b>                    |         | <b>APU BLEED AIR NON-RETURN VALVE</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:109812-9                      | MOS/MSC | 26-May-09                              | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:4921                          | HRS     |  |          |          | TSN 0                     |           |           |                  |               |
| WC#: 21.025                      | AFL     |  |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |           |                  |               |
| <b>211088</b>                    |         | <b>NO. 1 AIR DISTRIBUTION ACTUATOR</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:1092TH100-47                  | MOS/MSC | 16-Mar-10                              | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:5207D                         | HRS     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
|                                  | AFL     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |           |                  |               |
| <b>211089</b>                    |         | <b>NO. 2 AIR DISTRIBUTION ACTUATOR</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:1092TH100-47                  | MOS/MSC | 16-Mar-10                              | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:5579D                         | HRS     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
|                                  | AFL     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |           |                  |               |
| <b>211090</b>                    |         | <b>NO. 3 AIR DISTRIBUTION ACTUATOR</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:1092TH100-47                  | MOS/MSC | 16-Mar-10                              | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:5513D                         | HRS     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
|                                  | AFL     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |           |                  |               |
| <b>211091</b>                    |         | <b>NO. 4 AIR DISTRIBUTION ACTUATOR</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:1092TH100-47                  | MOS/MSC | 16-Mar-10                              | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:5614D                         | HRS     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
|                                  | AFL     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |           |                  |               |
| <b>211092</b>                    |         | <b>NO. 5 AIR DISTRIBUTION ACTUATOR</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:1092TH100-47                  | MOS/MSC | 16-Mar-10                              | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:4954D                         | HRS     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
|                                  | AFL     | 0                                      |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 21 - AIR CONDITIONING</b> |  |           |          |          |                           |           |           |             |        |
| 212001                           | LEFT MAIN AIR VALVE                          |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:321292-1                      | MOS/MSC                                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3160                          | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 21.040                      | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 21-10-25          |  |           |          |          |                           |           |           |             |        |
| 212002                           | RIGHT MAIN AIR VALVE                         |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:HTE250072-1                   | MOS/MSC                                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:12092069                      | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 21.045                      | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 21-10-24          |  |           |          |          |                           |           |           |             |        |
| 212008                           | PRESSURE REGULATOR VALVE                     |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:3215086-3                     | MOS/MSC                                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:951                           | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 21.295                      | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 21-10-76          |  |           |          |          |                           |           |           |             |        |
| 212026                           | NO. 1 ENGINE BLEED AIR NON-RETURN VALVE      |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:HTE4168                       | MOS/MSC                                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:7091602                       | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 21.050                      | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF        |  |           |          |          |                           |           |           |             |        |
| 212027                           | NO. 2 ENGINE BLEED AIR NON-RETURN VALVE      |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:HTE4168                       | MOS/MSC                                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:7091604                       | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 21.050                      | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF        |  |           |          |          |                           |           |           |             |        |
| 212050                           | AUXILIARY HEATING BLEED AIR NON-RETURN VALVE |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:PN                            | MOS/MSC                                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                       | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 21.055                      | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF        |  |           |          |          |                           |           |           |             |        |
| 212062                           | LEFT (HP/LP) MIXING VALVE                    |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:PN                            | MOS/MSC                                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                       | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 21.060                      | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 21-10-35          |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit    | C/W                                    | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|----------------------------------|---------|--|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 21 - AIR CONDITIONING</b> |         |  |          |          |                           |           |           |                  |               |
| <b>212063</b>                    |         | <b>RIGHT (HP/LP) MIXING VALVE</b>      |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:PN                            | MOS/MSC | 16-Mar-10                              | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                       | HRS     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| WC#: 21.060                      | AFL     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 21-10-35          |         |  |          |          |                           |           |           |                  |               |
| <b>212074</b>                    |         | <b>MAIN SUPPLY NON-RETURN VALVE</b>    |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:PN                            | MOS     | 16-Mar-10                              |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN:UNKNOWN                       | HRS     | 0                                      | 12000    | TSN 0    | 12000                     |           | 8091.6    |                  |               |
| WC#: 21.245                      | AFL     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 21-10-107         |         |  |          |          |                           |           |           |                  |               |
| <b>212082</b>                    |         | <b>BLEED AIR CHECK VALVE</b>           |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:HTE4405                       | MOS/MSC | 16-Mar-10                              | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:40080401                      | HRS     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| WC#: 21.070                      | AFL     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |           |                  |               |
| <b>212086</b>                    |         | <b>RAM AIR NON-RETURN VALVE</b>        |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:321262-1                      | MOS/MSC | 16-Mar-10                              | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:1821                          | HRS     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| WC#: 21.075                      | AFL     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 21-10-165         |         |  |          |          |                           |           |           |                  |               |
| <b>212098</b>                    |         | <b>RAM AIR SUPPLY NON-RETURN VALVE</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:123190-1                      | MOS/MSC | 16-Mar-10                              | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:7952                          | HRS     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| WC#: 21.080                      | AFL     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 21-10-165         |         |  |          |          |                           |           |           |                  |               |
| <b>212103</b>                    |         | <b>TEMPERATURE DUCT SWITCH</b>         |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:PN                            | MOS/MSC | 16-Mar-10                              | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                       | HRS     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| WC#: 21.085                      | AFL     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |           |                  |               |
| <b>212122</b>                    |         | <b>UPPER CHECK VALVE</b>               |          |          |                           |           |           | <b>Component</b> | <b>ATA:21</b> |
| PN:130156-2                      | MOS/MSC | 16-Mar-10                              | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:89-A1243                      | HRS     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| WC#: 21.095                      | AFL     | 0                                      |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |                         |
|---------------------------------------|---------|---|----------|----------|---------------------------|-----------|-----------|-------------|-------------------------|
| <b>ATA 21 - AIR CONDITIONING</b>      |         |   |          |          |                           |           |           |             |                         |
| <b>212123</b>                         |         | <b>LOWER CHECK VALVE</b>                                  |          |          |                           |           |           |             | <b>Component ATA:21</b> |
| PN:130156-2                           | MOS/MSC | 16-Mar-10   | O/C      |          | TSN 0                     |           |           |             |                         |
| SN:89-A1246                           | HRS     | 0   |          |          | TSN 0                     |           |           |             |                         |
| WC#: 21.095                           | AFL     | 0   |          |          | TSN 0                     |           |           |             |                         |
| PROC. REF: GENERIC NO REF             |         |   |          |          |                           |           |           |             |                         |
| <b>212146</b>                         |         | <b>CABIN RECIRCULATING FAN</b>                            |          |          |                           |           |           |             | <b>Component ATA:21</b> |
| PN:0901-2                             | MOS/MSC | 16-Mar-10   | O/C      |          | TSN 0                     |           |           |             |                         |
| SN:999                                | HRS     | 0   |          |          | TSN 0                     |           |           |             |                         |
| WC#: 21.100                           | AFL     | 0   |          |          | TSN 0                     |           |           |             |                         |
| PROC. REF: GENERIC NO REF             |         |   |          |          |                           |           |           |             |                         |
| <b>213001</b>                         |         | <b>NO. 1 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE</b> |          |          |                           |           |           |             | <b>Component ATA:21</b> |
| PN:B01A2-14128A                       | MOS/MSC | 16-Mar-10   | O/C      |          | TSN 0                     |           |           |             |                         |
| SN:HAY0698                            | HRS     | 0   |          |          | TSN 0                     |           |           |             |                         |
| WC#: 21.105                           | AFL     | 0   |          |          | TSN 0                     |           |           |             |                         |
| PROC. REF: GENERIC NO REF             |         |   |          |          |                           |           |           |             |                         |
| <b>213002</b>                         |         | <b>NO. 2 ENGINE HIGH PRESSURE BLEED AIR SHUTOFF VALVE</b> |          |          |                           |           |           |             | <b>Component ATA:21</b> |
| PN:B01A2-14128A                       | MOS/MSC | 16-Mar-10   | O/C      |          | TSN 0                     |           |           |             |                         |
| SN:HAY0643                            | HRS     | 0   |          |          | TSN 0                     |           |           |             |                         |
| WC#: 21.105                           | AFL     | 0   |          |          | TSN 0                     |           |           |             |                         |
| PROC. REF: GENERIC NO REF             |         |   |          |          |                           |           |           |             |                         |
| <b>213019</b>                         |         | <b>OUTFLOW/SAFETY VALVE CONTROLLER</b>                    |          |          |                           |           |           |             | <b>Component ATA:21</b> |
| PN:130530-5                           | MOS/MSC | 16-Mar-10   | O/C      |          | TSN 0                     |           |           |             |                         |
| SN:99-C0419                           | HRS     | 0   |          |          | TSN 0                     |           |           |             |                         |
| WC#: 21.115                           | AFL     | 0   |          |          | TSN 0                     |           |           |             |                         |
| PROC. REF: AMM 21-30-16               |         |   |          |          |                           |           |           |             |                         |
| <b>213031</b>                         |         | <b>LEFT OUTFLOW VALVE</b>                                 |          |          |                           |           |           |             | <b>Component ATA:21</b> |
| PN:103278-18                          | MOS/MSC | 16-Mar-10   | O/C      |          | TSN 0                     |           |           |             |                         |
| SN:109-G0428                          | HRS     | 0   |          |          | TSN 0                     |           |           |             |                         |
| WC#: 21.120                           | AFL     | 0   |          |          | TSN 0                     |           |           |             |                         |
| PROC. REF: AMM 21-30-25, AMM 21-31-10 |         |   |          |          |                           |           |           |             |                         |
| <b>213032</b>                         |         | <b>RIGHT OUTFLOW VALVE</b>                                |          |          |                           |           |           |             | <b>Component ATA:21</b> |
| PN:103278-13                          | MOS/MSC | 16-Mar-10   | O/C      |          | TSN 0                     |           |           |             |                         |
| SN:89-A1079                           | HRS     | 0   |          |          | TSN 0                     |           |           |             |                         |
| WC#: 21.120                           | AFL     | 0   |          |          | TSN 0                     |           |           |             |                         |
| PROC. REF: AMM 21-30-25, AMM 21-31-10 |         |   |          |          |                           |           |           |             |                         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 21 - AIR CONDITIONING</b>                            |         |           |          |          |                           |           |           |             |
| <b>213035 2" BUTTERFLY VALVE Component ATA:21</b>           |         |           |          |          |                           |           |           |             |
| PN:AWE113-13A   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:HAY0338  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 21.320   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF                                   |         |           |          |          |                           |           |           |             |
| <b>213067 CABIN ALTITUDE CONTROL VALVE Component ATA:21</b> |         |           |          |          |                           |           |           |             |
| PN:131004-2   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:1286655  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 21.125   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 21-30-95                                     |         |           |          |          |                           |           |           |             |
| <b>213073 MECHANICAL DUMP VALVE Component ATA:21</b>        |         |           |          |          |                           |           |           |             |
| PN:HTE940008  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:54080789   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 21.130   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 21-30-136                                    |         |           |          |          |                           |           |           |             |
| <b>213097 ALTIMETER PRESSURE SWITCH Component ATA:21</b>    |         |           |          |          |                           |           |           |             |
| PN:140-380024-7   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:J056815  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 21.135   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF                                   |         |           |          |          |                           |           |           |             |
| <b>213098 ALTIMETER PRESSURE SWITCH Component ATA:21</b>    |         |           |          |          |                           |           |           |             |
| PN:140-380024-11  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:K050136  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 21.300   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF                                   |         |           |          |          |                           |           |           |             |
| <b>213109 VENTURI Component ATA:21</b>                      |         |           |          |          |                           |           |           |             |
| PN:131052-1   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:99-4525  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 21.140   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 21-30-105                                    |         |           |          |          |                           |           |           |             |
| <b>213115 FAN OPERATED VENTURI Component ATA:21</b>         |         |           |          |          |                           |           |           |             |
| PN:132322-3-1   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:109-A0965  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 21.145   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 21-30-65                                     |         |           |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition |               |
|----------------------------------|---------|--|----------|----------|---------------------------|-----------|------------------|-------------|---------------|
| <b>ATA 21 - AIR CONDITIONING</b> |         |  |          |          |                           |           |                  |             |               |
| <b>213121</b>                    |         | <b>LEFT PNEUMATIC VALVE</b>                  |          |          |                           |           | <b>Component</b> |             | <b>ATA:21</b> |
| PN:107312-4-1                    | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:119-13448                     | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 21.150                      | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 21-30-35          |         |  |          |          |                           |           |                  |             |               |
| <b>213122</b>                    |         | <b>RIGHT PNEUMATIC VALVE</b>                 |          |          |                           |           | <b>Component</b> |             | <b>ATA:21</b> |
| PN:107312-4-1                    | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:119-13449                     | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 21.150                      | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 21-30-35          |         |  |          |          |                           |           |                  |             |               |
| <b>213133</b>                    |         | <b>LEFT ABSOLUTE PRESSURE CONTROL</b>        |          |          |                           |           | <b>Component</b> |             | <b>ATA:21</b> |
| PN:102466-13                     | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:88-G0020                      | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 21.155                      | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 21-30-55          |         |  |          |          |                           |           |                  |             |               |
| <b>213134</b>                    |         | <b>RIGHT ABSOLUTE PRESSURE CONTROL</b>       |          |          |                           |           | <b>Component</b> |             | <b>ATA:21</b> |
| PN:102466-13                     | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:88-G0034                      | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 21.155                      | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 21-30-55          |         |  |          |          |                           |           |                  |             |               |
| <b>213157</b>                    |         | <b>JET PUMP</b>                              |          |          |                           |           | <b>Component</b> |             | <b>ATA:21</b> |
| PN:131150-1-1                    | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:89-3615                       | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 21.160                      | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 21-30-45          |         |  |          |          |                           |           |                  |             |               |
| <b>213169</b>                    |         | <b>CABIN DIFFERENTIAL PRESSURE INDICATOR</b> |          |          |                           |           | <b>Component</b> |             | <b>ATA:21</b> |
| PN:PN                            | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                       | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 21.165                      | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |                  |             |               |
| <b>213181</b>                    |         | <b>GROUND PRESSURE CONNECTOR</b>             |          |          |                           |           | <b>Component</b> |             | <b>ATA:21</b> |
| PN:PN                            | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                       | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 21.170                      | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 21-30-85          |         |  |          |          |                           |           |                  |             |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining               | Disposition |  |
|----------------------------------|---------|--|----------|----------|---------------------------|-----------|-------------------------|-------------|--|
| <b>ATA 21 - AIR CONDITIONING</b> |         |  |          |          |                           |           |                         |             |  |
| <b>216001</b>                    |         | <b>CABIN TEMPERATURE CONTROL VALVE</b>       |          |          |                           |           | <b>Component ATA:21</b> |             |  |
| PN:104968                        | MOS/MSC | 16-Mar-10                                    | O/C      |          | TSN 0                     |           |                         |             |  |
| SN:1915                          | HRS     | 0  |          |          | TSN 0                     |           |                         |             |  |
| WC#: 21.175                      | AFL     | 0  |          |          | TSN 0                     |           |                         |             |  |
| PROC. REF: AMM 21-60-57          |         |  |          |          |                           |           |                         |             |  |
| <b>216025</b>                    |         | <b>AUXILIARY HEATING VALVE</b>               |          |          |                           |           | <b>Component ATA:21</b> |             |  |
| PN:104568                        | MOS/MSC | 16-Mar-10                                    | O/C      |          | TSN 0                     |           |                         |             |  |
| SN:13821                         | HRS     | 0  |          |          | TSN 0                     |           |                         |             |  |
| WC#: 21.180                      | AFL     | 0  |          |          | TSN 0                     |           |                         |             |  |
| PROC. REF: AMM 21-60-105         |         |  |          |          |                           |           |                         |             |  |
| <b>216055</b>                    |         | <b>CABIN TEMPERATURE (CONTROLLER) SENSOR</b> |          |          |                           |           | <b>Component ATA:21</b> |             |  |
| PN:607148-1                      | MOS/MSC | 16-Mar-10                                    | O/C      |          | TSN 0                     |           |                         |             |  |
| SN:607148-11116                  | HRS     | 0  |          |          | TSN 0                     |           |                         |             |  |
| WC#: 21.185                      | AFL     | 0  |          |          | TSN 0                     |           |                         |             |  |
| PROC. REF: MMA 21-60-05          |         |  |          |          |                           |           |                         |             |  |
| <b>216073</b>                    |         | <b>CABIN TEMPERATURE CONTROLLER</b>          |          |          |                           |           | <b>Component ATA:21</b> |             |  |
| PN:617452-4                      | MOS/MSC | 27-May-11                                    | O/C      |          | TSN 0                     |           |                         |             |  |
| SN:038C-1214                     | HRS     | 469.5  |          |          | TSN 0                     |           |                         |             |  |
| WC#: 21.190                      | AFL     | 183  |          |          | TSN 0                     |           |                         |             |  |
| PROC. REF: AMM 21-60-67          |         |  |          |          |                           |           |                         |             |  |
| <b>216097</b>                    |         | <b>TEMPERATURE DUCT SELECTOR</b>             |          |          |                           |           | <b>Component ATA:21</b> |             |  |
| PN:PN                            | MOS/MSC | 16-Mar-10                                    | O/C      |          | TSN 0                     |           |                         |             |  |
| SN:UNKNOWN                       | HRS     | 0  |          |          | TSN 0                     |           |                         |             |  |
| WC#: 21.195                      | AFL     | 0  |          |          | TSN 0                     |           |                         |             |  |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |                         |             |  |
| <b>216115</b>                    |         | <b>COLD AIR UNIT PACK</b>                    |          |          |                           |           | <b>Component ATA:21</b> |             |  |
| PN:2214070-5                     | MOS/MSC | 16-Mar-10                                    | O/C      |          | TSN 0                     |           |                         |             |  |
| SN:909                           | HRS     | 0  |          |          | TSN 0                     |           |                         |             |  |
| WC#: 21.200                      | AFL     | 0  |          |          | TSN 0                     |           |                         |             |  |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |                         |             |  |
| <b>216121</b>                    |         | <b>MODULATING VALVE</b>                      |          |          |                           |           | <b>Component ATA:21</b> |             |  |
| PN:978836-5-1                    | MOS/MSC | 16-Mar-10                                    | O/C      |          | TSN 0                     |           |                         |             |  |
| SN:1288                          | HRS     | 0  |          |          | TSN 0                     |           |                         |             |  |
| WC#: 21.210                      | AFL     | 0  |          |          | TSN 0                     |           |                         |             |  |
| PROC. REF: GENERIC NO REF        |         |  |          |          |                           |           |                         |             |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------------|--------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 21 - AIR CONDITIONING</b> |                                |           |          |          |                           |           |           |             |        |
| 216127                           | CONTROL SENSOR                 |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:1150642-3                     | MOS/MSC                        | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:115064211583                  | HRS                            | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 21.215                      | AFL                            | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 21-60-60          |                                |           |          |          |                           |           |           |             |        |
| 216135                           | TOTAL TEMPERATURE SENSOR       |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:102ER1EC                      | MOS/MSC                        | 20-Sep-12 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:B7607                         | HRS                            | 1134.92   |          | TSN 0    |                           |           |           |             |        |
| WC#: 21.305                      | AFL                            | 414       |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF 1          |                                |           |          |          |                           |           |           |             |        |
| 217001                           | WATER SEPARATOR                |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:25VF1351-131                  | MOS/MSC                        | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:1924                          | HRS                            | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 21.220                      | AFL                            | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 21-10-95          |                                |           |          |          |                           |           |           |             |        |
| 217014                           | CABIN TRIPLE INDICATOR         |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:51010-1113                    | MOS/MSC                        | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:508787A                       | HRS                            | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 21.225                      | AFL                            | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 21-30-90          |                                |           |          |          |                           |           |           |             |        |
| 217023                           | PRESSURE SWITCH                |           |          |          |                           |           |           | Component   | ATA:21 |
| PN:HTE690090                     | MOS/MSC                        | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:6091267                       | HRS                            | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 21.235                      | AFL                            | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 21-10-39          |                                |           |          |          |                           |           |           |             |        |
| <b>ATA 22 - AUTO FLIGHT</b>      |                                |           |          |          |                           |           |           |             |        |
| 221001                           | AFCS CONTROL PANEL             |           |          |          |                           |           |           | Component   | ATA:22 |
| PN:PN                            | MOS/MSC                        | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                       | HRS                            | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 22.010                      | AFL                            | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF        |                                |           |          |          |                           |           |           |             |        |
| 221007                           | NO. 1 FLIGHT GUIDANCE COMPUTER |           |          |          |                           |           |           | Component   | ATA:22 |
| PN:822-1108-023                  | MOS/MSC                        | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3J1YN                         | HRS                            | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 22.015                      | AFL                            | 0         |          | TSN 0    |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W                                       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition |               |
|---------------------------------------|---------|---|----------|----------|---------------------------|-----------|------------------|-------------|---------------|
| <b>ATA 22 - AUTO FLIGHT</b>           |         |   |          |          |                           |           |                  |             |               |
| <b>221008</b>                         |         | <b>NO. 2 FLIGHT GUIDANCE COMPUTER</b>     |          |          |                           |           | <b>Component</b> |             | <b>ATA:22</b> |
| PN:822-1108-023                       | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:3J1YP                              | HRS     | 0   |          | TSN 0    |                           |           |                  |             |               |
| WC#: 22.015                           | AFL     | 0   |          | TSN 0    |                           |           |                  |             |               |
| <b>221010</b>                         |         | <b>NO. 1 AUTO PILOT MODE SELECT PANEL</b> |          |          |                           |           | <b>Component</b> |             | <b>ATA:22</b> |
| PN:PN                                 | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                            | HRS     | 0   |          | TSN 0    |                           |           |                  |             |               |
| WC#: 22.040                           | AFL     | 0   |          | TSN 0    |                           |           |                  |             |               |
| <b>221011</b>                         |         | <b>NO. 2 AUTO PILOT MODE SELECT PANEL</b> |          |          |                           |           | <b>Component</b> |             | <b>ATA:22</b> |
| PN:PN                                 | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                            | HRS     | 0   |          | TSN 0    |                           |           |                  |             |               |
| WC#: 22.040                           | AFL     | 0   |          | TSN 0    |                           |           |                  |             |               |
| <b>221037</b>                         |         | <b>AUTOPILOT ELEVATOR SERVO</b>           |          |          |                           |           | <b>Component</b> |             | <b>ATA:22</b> |
| PN:822-1168-002                       | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:3LKBV                              | HRS     | 0   |          | TSN 0    |                           |           |                  |             |               |
| WC#: 22.020                           | AFL     | 0   |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 22-10-30, AMM 22-10-30 |         |   |          |          |                           |           |                  |             |               |
| <b>221039</b>                         |         | <b>ELEVATOR SERVO MOUNT</b>               |          |          |                           |           | <b>Component</b> |             | <b>ATA:22</b> |
| PN:622-5735-004                       | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:39D4X                              | HRS     | 0   |          | TSN 0    |                           |           |                  |             |               |
| WC#: 22.050                           | AFL     | 0   |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 22-10-30               |         |   |          |          |                           |           |                  |             |               |
| <b>221043</b>                         |         | <b>AUTOPILOT RUDDER SERVO</b>             |          |          |                           |           | <b>Component</b> |             | <b>ATA:22</b> |
| PN:822-1168-002                       | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:3LKNX                              | HRS     | 0   |          | TSN 0    |                           |           |                  |             |               |
| WC#: 22.020                           | AFL     | 0   |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 22-10-20, AMM 22-10-20 |         |   |          |          |                           |           |                  |             |               |
| <b>221045</b>                         |         | <b>RUDDER SERVO MOUNT</b>                 |          |          |                           |           | <b>Component</b> |             | <b>ATA:22</b> |
| PN:622-5735-004                       | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:39CVK                              | HRS     | 0   |          | TSN 0    |                           |           |                  |             |               |
| WC#: 22.050                           | AFL     | 0   |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 22-10-20               |         |   |          |          |                           |           |                  |             |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition |               |
|---------------------------------------|---------|--|----------|----------|---------------------------|-----------|------------------|-------------|---------------|
| <b>ATA 22 - AUTO FLIGHT</b>           |         |  |          |          |                           |           |                  |             |               |
| <b>221049</b>                         |         | <b>AUTOPILOT AILERON SERVO</b>                 |          |          |                           |           | <b>Component</b> |             | <b>ATA:22</b> |
| PN:822-1168-002                       | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:3LK2V                              | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 22.020                           | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 22-10-10, AMM 22-10-10 |         |  |          |          |                           |           |                  |             |               |
| <b>221052</b>                         |         | <b>AILERON SERVO MOUNT</b>                     |          |          |                           |           | <b>Component</b> |             | <b>ATA:22</b> |
| PN:622-5735-004                       | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:39DPR                              | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 22.050                           | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM NO REF                 |         |  |          |          |                           |           |                  |             |               |
| <b>ATA 23 - COMMUNICATIONS</b>        |         |  |          |          |                           |           |                  |             |               |
| <b>231001</b>                         |         | <b>NO. 1 HF COMMUNICATIONS CONTROLLER</b>      |          |          |                           |           | <b>Component</b> |             | <b>ATA:23</b> |
| PN:PN                                 | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                            | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 23.015                           | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 23-10-22               |         |  |          |          |                           |           |                  |             |               |
| <b>231002</b>                         |         | <b>NO. 2 HF COMMUNICATIONS CONTROLLER</b>      |          |          |                           |           | <b>Component</b> |             | <b>ATA:23</b> |
| PN:PN                                 | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                            | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 23.015                           | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| <b>231004</b>                         |         | <b>NO. 1 HF CONTROLLER ADAPTER</b>             |          |          |                           |           | <b>Component</b> |             | <b>ATA:23</b> |
| PN:PN                                 | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                            | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 23.020                           | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF             |         |  |          |          |                           |           |                  |             |               |
| <b>231006</b>                         |         | <b>NO. 2 HF CONTROLLER ADAPTER</b>             |          |          |                           |           | <b>Component</b> |             | <b>ATA:23</b> |
| PN:PN                                 | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                            | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 23.020                           | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF             |         |  |          |          |                           |           |                  |             |               |
| <b>231011</b>                         |         | <b>NO. 1 HF COMMUNICATIONS POWER AMPLIFIER</b> |          |          |                           |           | <b>Component</b> |             | <b>ATA:23</b> |
| PN:PN                                 | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                            | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 23.025                           | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF             |         |  |          |          |                           |           |                  |             |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                        | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--------------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 23 - COMMUNICATIONS</b> |   |           |          |          |                           |           |           |             |        |
| 231012                         | NO. 2 HF COMMUNICATIONS POWER AMPLIFIER |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:PN                          | MOS/MSC                                 | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                     | HRS                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 23.025                    | AFL                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF      |   |           |          |          |                           |           |           |             |        |
| 231015                         | COLLINS HG 9041 HF ANTENNA              |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:622-8114-002                | MOS/MSC                                 | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:10091                       | HRS                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 23.130                    | AFL                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF      |   |           |          |          |                           |           |           |             |        |
| 231016                         | COLLINS HF 9031A RECEIVER/TRANSMITTER   |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:822-0101-002                | MOS/MSC                                 | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:4672                        | HRS                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 23.135                    | AFL                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF      |   |           |          |          |                           |           |           |             |        |
| 231017 <sup>U</sup>            | NO. 2 HF RECEIVER                       |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:PN                          | MOS/MSC                                 |           | O/C      |          |                           |           |           |             |        |
| SN:UNKNOWN                     | HRS                                     |           |          |          |                           |           |           |             |        |
|                                | AFL                                     |           |          |          |                           |           |           |             |        |
| 231019 <sup>U</sup>            | NO. 2 HF COUPLER                        |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:PN                          | MOS/MSC                                 |           | O/C      |          |                           |           |           |             |        |
| SN:UNKNOWN                     | HRS                                     |           |          |          |                           |           |           |             |        |
|                                | AFL                                     |           |          |          |                           |           |           |             |        |
| 231025                         | NO. 1 HF RECEIVER EXCITER               |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:PN                          | MOS/MSC                                 | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                     | HRS                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 23.030                    | AFL                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 23-10-06        |   |           |          |          |                           |           |           |             |        |
| 231026                         | NO. 2 HF RECEIVER EXCITER               |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:PN                          | MOS/MSC                                 | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                     | HRS                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 23.030                    | AFL                                     | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 23-10-06        |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                        | Unit    | C/W                                  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |  |
|--------------------------------|---------|--------------------------------------|----------|----------|---------------------------|-----------|-----------|-------------|--|
| <b>ATA 23 - COMMUNICATIONS</b> |         |                                      |          |          |                           |           |           |             |  |
| 231027                         |         | NO. 1 HF BRIDGING AMPLIFIER          |          |          |                           |           | Component | ATA:23      |  |
| PN:PN                          | MOS/MSC | 16-Mar-10                            | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN                     | HRS     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| WC#: 23.035                    | AFL     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF      |         |                                      |          |          |                           |           |           |             |  |
| 231028                         |         | NO. 2 HF BRIDGING AMPLIFIER          |          |          |                           |           | Component | ATA:23      |  |
| PN:PN                          | MOS/MSC | 16-Mar-10                            | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN                     | HRS     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| WC#: 23.035                    | AFL     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF      |         |                                      |          |          |                           |           |           |             |  |
| 231029                         |         | DUAL HF CAPACITOR                    |          |          |                           |           | Component | ATA:23      |  |
| PN:PN                          | MOS/MSC | 16-Mar-10                            | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN                     | HRS     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| WC#: 23.040                    | AFL     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF      |         |                                      |          |          |                           |           |           |             |  |
| 231041                         |         | VHF COMMUNICATION (CTL-23D) CONTROL  |          |          |                           |           | Component | ATA:23      |  |
| PN:822-2177-001                | MOS/MSC | 16-Mar-10                            | O/C      | TSN 0    |                           |           |           |             |  |
| SN:3R24H                       | HRS     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| WC#: 23.136                    | AFL     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF      |         |                                      |          |          |                           |           |           |             |  |
| 231043                         |         | NO. 1 VHF COMMUNICATIONS TRANSCEIVER |          |          |                           |           | Component | ATA:23      |  |
| PN:822-1468-102                | MOS/MSC | 13-Apr-12                            | O/C      | TSN 0    |                           |           |           |             |  |
| SN:3PMLD                       | HRS     | 933.58                               |          | TSN 0    |                           |           |           |             |  |
| WC#: 23.045                    | AFL     | 337                                  |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: AMM 23-10-22        |         |                                      |          |          |                           |           |           |             |  |
| 231049                         |         | NO. 2 VHF COMMUNICATIONS TRANSCEIVER |          |          |                           |           | Component | ATA:23      |  |
| PN:822-1468-102                | MOS/MSC | 29-Jul-20                            | O/C      | TSO 0    |                           |           |           |             |  |
| SN:39B6G                       | HRS     | 3359.38                              |          | TSO 0    |                           |           |           |             |  |
| WC#: 23.045                    | AFL     | 1223                                 |          | TSO 0    |                           |           |           |             |  |
| PROC. REF: AMM 23-10-22        |         |                                      |          |          |                           |           |           |             |  |
| 231050                         |         | ATC UPPER ANTENNA                    |          |          |                           |           | Component | ATA:23      |  |
| PN:PN                          | MOS/MSC | 16-Mar-10                            | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN                     | HRS     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| WC#: 23.050                    | AFL     | 0                                    |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF      |         |                                      |          |          |                           |           |           |             |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 23 - COMMUNICATIONS</b>   |         |           |          |          |                           |           |           |             |
| <b>231052<sup>U</sup> COMMUNICATION MANAGEMENT UNIT</b> Component ATA:23 |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC |           | O/C      |          |                           |           |           |             |
| SN:UNKNOWN   | HRS     |           |          |          |                           |           |           |             |
|  | AFL     |           |          |          |                           |           |           |             |
| <b>231053<sup>U</sup> VHF NO.3 TRANSCEIVER</b> Component ATA:23          |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      |          |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          |          |                           |           |           |             |
|  | AFL     | 0         |          |          |                           |           |           |             |
| <b>231055 NO. 1 VHF AERIAL</b> Component ATA:23                          |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 23.055  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| <b>231056 NO. 2 VHF AERIAL</b> Component ATA:23                          |         |           |          |          |                           |           |           |             |
| PN:16-41-1T  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:7339  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 23.055  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 23-10-35  |         |           |          |          |                           |           |           |             |
| <b>231058 AUDIO TONE GENERATOR</b> Component ATA:23                      |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 23.060  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: MMA 23-16-40  |         |           |          |          |                           |           |           |             |
| <b>231061 NO. 1 RADIO MANAGEMENT UNIT</b> Component ATA:23               |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 23.065  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| <b>231062 NO. 2 RADIO MANAGEMENT UNIT</b> Component ATA:23               |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 23.065  | AFL     | 0         |          | TSN 0    |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                        | Unit                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--------------------------------|--------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 23 - COMMUNICATIONS</b> |                                |           |          |          |                           |           |           |             |        |
| 231064                         | CLEARANCE DELIVERY CONTROL     |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:PN                          | MOS/MSC                        | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                     | HRS                            | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 23.070                    | AFL                            | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF      |                                |           |          |          |                           |           |           |             |        |
| 234051 <sup>U</sup>            | AIRCELL TRANSCEIVER            |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:P12023                      | MOS/MSC                        | 05-May-10 | O/C      |          |                           |           |           |             |        |
| SN:1202311724                  | HRS                            | 4.7       |          |          |                           |           |           |             |        |
|                                | AFL                            | 4         |          |          |                           |           |           |             |        |
| 234052 <sup>U</sup>            | AIRCELL ANTENNA                |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:015-11203-001               | MOS/MSC                        | 05-May-10 | O/C      |          |                           |           |           |             |        |
| SN:449-2751                    | HRS                            | 4.7       |          |          |                           |           |           |             |        |
|                                | AFL                            | 4         |          |          |                           |           |           |             |        |
| 234054 <sup>U</sup>            | COCKPIT AIRCELL HANDSET        |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:P12857-002                  | MOS/MSC                        | 05-May-10 | O/C      |          |                           |           |           |             |        |
| SN:1285700852                  | HRS                            | 4.7       |          |          |                           |           |           |             |        |
|                                | AFL                            | 4         |          |          |                           |           |           |             |        |
| 234055 <sup>U</sup>            | COCKPIT AIRCELL HANDSET CRADLE |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:P12861-002                  | MOS/MSC                        | 05-May-10 | O/C      |          |                           |           |           |             |        |
| SN:1286100818                  | HRS                            | 4.7       |          |          |                           |           |           |             |        |
|                                | AFL                            | 4         |          |          |                           |           |           |             |        |
| 234056 <sup>U</sup>            | CABIN AIRCELL HANDSET          |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:P12857-002                  | MOS/MSC                        | 05-May-10 | O/C      |          |                           |           |           |             |        |
| SN:1285700921                  | HRS                            | 4.7       |          |          |                           |           |           |             |        |
|                                | AFL                            | 4         |          |          |                           |           |           |             |        |
| 234057 <sup>U</sup>            | CABIN AIRCELL HANDSET CRADLE   |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:P12861-002                  | MOS/MSC                        | 05-May-10 | O/C      |          |                           |           |           |             |        |
| SN:1286100782                  | HRS                            | 4.7       |          |          |                           |           |           |             |        |
|                                | AFL                            | 4         |          |          |                           |           |           |             |        |
| 235001                         | NO. 1 AUDIO CONTROLLER         |           |          |          |                           |           |           | Component   | ATA:23 |
| PN:MODEL803-006                | MOS/MSC                        | 05-May-10 | O/C      |          |                           |           |           |             |        |
| SN:1599                        | HRS                            | 4.7       |          |          |                           |           |           |             |        |
| WC#: 23.095                    | AFL                            | 4         |          |          |                           |           |           |             |        |
| PROC. REF: MMA 23-50-20        |                                |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit   | C/W       | Interval | TSX/Adj.    | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--|--|-----------|----------|-------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 23 - COMMUNICATIONS</b>                       |  |           |          |             |                           |           |           |             |        |
| 235002   | NO. 2 AUDIO CONTROLLER                           |           |          |             |                           |           |           | Component   | ATA:23 |
| PN:MODEL803-006                                      | MOS/MSC  | 05-May-10 | O/C      |             |                           |           |           |             |        |
| SN:1675  | HRS  | 4.7       |          |             |                           |           |           |             |        |
| WC#: 23.095  | AFL  | 4         |          |             |                           |           |           |             |        |
| PROC. REF: MMA 23-50-20                              |  |           |          |             |                           |           |           |             |        |
| 235017   | NO. 1 HANDHELD AUDIO MICROPHONE                  |           |          |             |                           |           |           | Component   | ATA:23 |
| PN:PN  | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:UNKNOWN   | HRS  | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 23.100  | AFL  | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                            |  |           |          |             |                           |           |           |             |        |
| 235019   | NO. 2 HANDHELD AUDIO MICROPHONE                  |           |          |             |                           |           |           | Component   | ATA:23 |
| PN:PN  | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:UNKNOWN   | HRS  | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 23.100  | AFL  | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                            |  |           |          |             |                           |           |           |             |        |
| 237001   | COCKPIT VOICE RECORDER                           |           |          |             |                           |           |           | Component   | ATA:23 |
| PN:1603-02-12  | MOS/MSC  | 20-Jul-18 | O/C      | TSN 100     |                           |           |           |             |        |
| SN:2479  | HRS  | 3000.32   |          | TSN 3000.32 |                           |           |           |             |        |
| WC#: 23.105  | AFL  | 1088      |          | TSN 1088    |                           |           |           |             |        |
| PROC. REF: AMM 23-70-36, AMM 23-70-37                |  |           |          |             |                           |           |           |             |        |
| 237004   | COCKPIT VOICE RECORDER NO.1 MICROPHONE           |           |          |             |                           |           |           | Component   | ATA:23 |
| PN:16301-01  | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:2981  | HRS  | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 23.110  | AFL  | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                            |  |           |          |             |                           |           |           |             |        |
| 237005   | COCKPIT VOICE RECORDER NO.2 MICROPHONE           |           |          |             |                           |           |           | Component   | ATA:23 |
| PN:16301-01  | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:2982  | HRS  | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 23.110  | AFL  | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                            |  |           |          |             |                           |           |           |             |        |
| 237014   | COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON |           |          |             |                           |           |           | Component   | ATA:23 |
| PN:PN  | MOS/MSC  | 14-May-20 | O/C      |             |                           |           |           |             |        |
| SN:AT116984  | HRS  | 3357.57   |          |             |                           |           |           |             |        |
| WC#: 23.105  | AFL  | 1222      |          |             |                           |           |           |             |        |
| PROC. REF: AMM 23-70-36, AMM 23-70-37, AMM 25-60-110 |  |           |          |             |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 23 - COMMUNICATIONS</b>  |         |           |          |          |                           |           |           |             |
| <b>237015 TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON Service ATA:23</b>            |         |           |          |          |                           |           |           |             |
|   | MOS     | 04-Mar-24 | 24       |          | 04-Mar-26                 |           | 583 d     |             |
|   | HRS     |           |          |          |                           |           |           |             |
| WC#: 23.105   | AFL     |           |          |          |                           |           |           |             |
| PROC. REF: AMM 25-60-110, AMM 23-70-36, AMM 23-70-37  |         |           |          |          |                           |           |           |             |
| <b>237016 CLEAN/TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON Service ATA:23</b>      |         |           |          |          |                           |           |           |             |
|   | MOS     | 11-Jul-24 | 24       |          | 11-Jul-26                 |           | 712 d     |             |
|   | HRS     | 3907.4    |          |          |                           |           |           |             |
| WC#: 23.105   | AFL     | 1491      |          |          |                           |           |           |             |
| PROC. REF: AMM 23-70-36, AMM 23-70-37, AMM 23-70-36, AMM 23-70-37                             |         |           |          |          |                           |           |           |             |
| <b>237017 REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY Service ATA:23</b> |         |           |          |          |                           |           |           |             |
|   | MOS/MSC | 14-May-20 | DUE      |          | 01-Aug-25 (M)             |           | 368 d     |             |
|   | HRS     | 3357.57   |          |          |                           |           |           |             |
| WC#: 23.105   | AFL     | 1222      |          |          |                           |           |           |             |
| <b>237019 LEFT COCKPIT VOICE RECORDER CONTROL Component ATA:23</b>                            |         |           |          |          |                           |           |           |             |
| PN:1634-01  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:1428   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 23.125   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 23-70-36, AMM 23-70-37   |         |           |          |          |                           |           |           |             |
| <b>237020 RIGHT COCKPIT VOICE RECORDER CONTROL Component ATA:23</b>                           |         |           |          |          |                           |           |           |             |
| PN:PN   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 23.125   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| <b>237021 VOICE RECORDER INERTIA SWITCH Component ATA:23</b>                                  |         |           |          |          |                           |           |           |             |
| PN:3LO453/2.0   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:91614  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 23.115   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>237022 COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY Component ATA:23</b>       |         |           |          |          |                           |           |           |             |
| PN:PN   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
|   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit   | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining  | Disposition |        |
|----------------------------------|--|-----------|-----------------|----------|---------------------------|-----------|------------|-------------|--------|
| <b>ATA 23 - COMMUNICATIONS</b>   |  |           |                 |          |                           |           |            |             |        |
| 238015                           | SELCAL DECODER UNIT                          |           |                 |          |                           |           |            | Component   | ATA:23 |
| PN:1200008-002                   | MOS/MSC                                      | 16-Mar-10 | O/C             | TSN 0    |                           |           |            |             |        |
| SN:6263                          | HRS  | 0         |                 | TSN 0    |                           |           |            |             |        |
| WC#: 23.120                      | AFL  | 0         |                 | TSN 0    |                           |           |            |             |        |
| PROC. REF: AMM 23-20-11          |  |           |                 |          |                           |           |            |             |        |
| <b>ATA 24 - ELECTRICAL POWER</b> |  |           |                 |          |                           |           |            |             |        |
| 240001                           | INSPECT/CHECK NO. 1 ENGINE STARTER/GENERATOR |           |                 |          |                           |           |            | Service     | ATA:24 |
| PN:23080-064                     | MOS  | 12-Feb-24 |                 |          |                           |           |            |             |        |
| SN:Y30489                        | HRS  | 3881.4    | 200 (+200)      |          | 4081.4                    | 4281.4    | 173 (+200) |             |        |
| WC#: 24.045                      | AFL  | 1476      |                 |          |                           |           |            |             |        |
| PROC. REF: AMM 24-30-21          |  |           |                 |          |                           |           |            |             |        |
| 240001                           | INSPECT/CHECK NO. 2 ENGINE STARTER/GENERATOR |           |                 |          |                           |           |            | Service     | ATA:24 |
| PN:23080-064                     | MOS  | 12-Feb-24 |                 |          |                           |           |            |             |        |
| SN:P2065                         | HRS  | 3881.4    | 200 (+200)      |          | 4081.4                    | 4281.4    | 173 (+200) |             |        |
| WC#: 24.045                      | AFL  | 1476      |                 |          |                           |           |            |             |        |
| PROC. REF: AMM 24-30-21          |  |           |                 |          |                           |           |            |             |        |
| 240002 <sup>S</sup>              | OPERATE NO.1 AND NO.2 MAIN STATIC INVERTERS  |           |                 |          |                           |           |            | Service     | ATA:24 |
|                                  | MOS  | 03-Aug-21 |                 |          |                           |           |            |             |        |
|                                  | HRS  | 3405      | 800 (+40/-10)   |          |                           |           |            |             |        |
| WC#: 24.010                      | AFL  | 1243      |                 |          |                           |           |            |             |        |
| PKG:7,91                         |  |           |                 |          |                           |           |            |             |        |
| 240003 <sup>S</sup>              | FUNCTION TEST FREQUENCY WILD A.C. SYSTEM     |           |                 |          |                           |           |            | Service     | ATA:24 |
|                                  | MOS  | 13-Mar-24 |                 |          |                           |           |            |             |        |
|                                  | HRS  | 3890.9    | 3200 (+150/-50) |          |                           |           |            |             |        |
| WC#: 24.030                      | AFL  | 1481      |                 |          |                           |           |            |             |        |
| PROC. REF: AMM 24-22-02          |  |           |                 |          |                           |           |            |             |        |
| 240004 <sup>S</sup>              | CHECK BUSBAR CONTACTOR CONTROL               |           |                 |          |                           |           |            | Service     | ATA:24 |
|                                  | MOS  | 06-Jun-18 |                 |          |                           |           |            |             |        |
|                                  | HRS  | 2965.25   | 1600 (+50/-50)  |          |                           |           |            |             |        |
| WC#: 24.145                      | AFL  | 1073      |                 |          |                           |           |            |             |        |
| PKG:19,92                        |  |           |                 |          |                           |           |            |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit  | C/W       | Interval        | TSX/Adj.                 | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------------|---|-----------|-----------------|--------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 24 - ELECTRICAL POWER</b> |   |           |                 |                          |                           |           |           |             |        |
| 240006 <sup>S</sup>              | CHECK D.C. BUSBAR PROTECTION/VOLTAGE SENSING UNIT           |           |                 |                          |                           |           |           | Service     | ATA:24 |
|                                  | MOS   | 06-Jun-18 |                 |                          |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 3200 (+150/-50) |                          |                           |           |           |             |        |
| WC#: 24.070                      | AFL   | 1073      |                 |                          |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 24-30-142 |                           |           |           | PKG:36,93   |        |
| 240007 <sup>S</sup>              | BENCH CHECK GROUND POWER OVERVOLTAGE SENSOR (IF FITTED).    |           |                 |                          |                           |           |           | Service     | ATA:24 |
|                                  | MOS   | 06-Jun-18 |                 |                          |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 3200 (+150/-50) |                          |                           |           |           |             |        |
| WC#: 24.110                      | AFL   | 1073      |                 |                          |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 24-30-146 |                           |           |           | PKG:37,93   |        |
| 240009 <sup>S</sup>              | FUNCTIONAL TEST D.C. GENERATING SYSTEM                      |           |                 |                          |                           |           |           | Service     | ATA:24 |
|                                  | MOS   | 03-Aug-21 |                 |                          |                           |           |           |             |        |
|                                  | HRS   | 3405      | 800 (+40/-10)   |                          |                           |           |           |             |        |
| WC#: 24.065                      | AFL   | 1243      |                 |                          |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 24-30-01  |                           |           |           | PKG:7,91    |        |
| 240010 <sup>S</sup>              | INSPECT PE, PS1 AND PS2 BUSBAR FEEDER CABLES BELOW PANEL DA |           |                 |                          |                           |           |           | Service     | ATA:24 |
|                                  | MOS   | 06-Jun-18 |                 |                          |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 1600 (+50/-50)  |                          |                           |           |           |             |        |
| WC#: 24.160                      | AFL   | 1073      |                 |                          |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 24-01-00  |                           |           |           | PKG:24,92   |        |
| 240011 <sup>S</sup>              | FUNCTIONAL TEST OF THE BUSBAR PE, PS1 AND PS2 FEEDER FUSES  |           |                 |                          |                           |           |           | Service     | ATA:24 |
|                                  | MOS   | 06-Jun-18 |                 |                          |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 1600 (+50/-50)  |                          |                           |           |           |             |        |
| WC#: 24.150                      | AFL   | 1073      |                 |                          |                           |           |           |             |        |
|                                  |   |           |                 | PROC. REF: AMM 24-01-00  |                           |           |           | PKG:25,92   |        |
| 240012 <sup>U S</sup>            | INSPECT BUSBAR PE, PS1 AND PS2 FEEDER SYSTEM CONNECTIONS    |           |                 |                          |                           |           |           | Service     | ATA:24 |
|                                  | MOS   | 06-Jun-18 |                 |                          |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 1600 (+50/-50)  |                          |                           |           |           |             |        |
| WC#: 24.165                      | AFL   | 1073      |                 |                          |                           |           |           |             |        |
|                                  |   |           |                 |                          |                           |           |           | PKG:25,92   |        |
| 240013 <sup>S</sup>              | FUNCTION TEST ALL CIRCUIT BREAKERS                          |           |                 |                          |                           |           |           | Service     | ATA:24 |
|                                  | MOS   | 06-Jun-18 |                 |                          |                           |           |           |             |        |
|                                  | HRS   | 2965.25   | 3200 (+150/-50) |                          |                           |           |           |             |        |
| WC#: 24.005                      | AFL   | 1073      |                 |                          |                           |           |           |             |        |
|                                  |   |           |                 |                          |                           |           |           | PKG:31,93   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit | C/W       | Interval        | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|------|-----------|-----------------|-------------------------|---------------------------|-----------|-----------|-------------|
| <b>ATA 24 - ELECTRICAL POWER</b>  |      |           |                 |                         |                           |           |           |             |
| <b>240014<sup>S</sup> FUNCTION TEST MAIN GENERATOR CONTROL UNIT (GCU) Service ATA:24</b>                            |      |           |                 |                         |                           |           |           |             |
|   | MOS  | 06-Jun-18 |                 |                         |                           |           |           |             |
|   | HRS  | 2965.25   | 3200 (+150/-50) |                         |                           |           |           |             |
| WC#: 24.040   | AFL  | 1073      |                 |                         |                           |           |           |             |
|   |      |           |                 | PROC. REF: AMM 24-30-07 |                           |           |           | PKG:31,93   |
| <b>240015<sup>S</sup> FUNCTION TEST APU GENERATOR CONTROL UNIT (GCU) Service ATA:24</b>                             |      |           |                 |                         |                           |           |           |             |
|   | MOS  | 06-Jun-18 |                 |                         |                           |           |           |             |
|   | HRS  | 2965.25   | 3200 (+150/-50) |                         |                           |           |           |             |
| WC#: 24.040   | AFL  | 1073      |                 |                         |                           |           |           |             |
|   |      |           |                 | PROC. REF: AMM 24-36-03 |                           |           |           | PKG:31,93   |
| <b>240016<sup>S</sup> INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD) Service ATA:24</b> |      |           |                 |                         |                           |           |           |             |
|   | MOS  | 06-Jun-18 |                 |                         |                           |           |           |             |
|   | HRS  | 2965.25   | 3200 (+150/-50) |                         |                           |           |           |             |
| WC#: 24.235   | AFL  | 1073      |                 |                         |                           |           |           |             |
|   |      |           |                 | PROC. REF: AMM 24-01-00 |                           |           |           | PKG:33,93   |
| <b>240017<sup>S</sup> INSPECT/CHECK EARTH STATIONS *16, *17, *18, AND *19 Service ATA:24</b>                        |      |           |                 |                         |                           |           |           |             |
|   | MOS  | 20-Jun-22 | 48 (+2m/-2m)    |                         |                           |           |           |             |
|   | HRS  | 3511.6    |                 |                         |                           |           |           |             |
| WC#: 24.155   | AFL  | 1288      |                 |                         |                           |           |           |             |
|   |      |           |                 | PROC. REF: AMM 24-01-00 |                           |           |           | PKG:96      |
| <b>240018<sup>S</sup> INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE REAR PRESSURE-BULKHEAD) Service ATA:24</b>    |      |           |                 |                         |                           |           |           |             |
|   | MOS  | 06-Jun-18 |                 |                         |                           |           |           |             |
|   | HRS  | 2965.25   | 3200 (+150/-50) |                         |                           |           |           |             |
| WC#: 24.235   | AFL  | 1073      |                 |                         |                           |           |           |             |
|   |      |           |                 | PROC. REF: AMM 24-01-00 |                           |           |           | PKG:37,93   |
| <b>240024 INSPECT/CHECK APU STARTER/GENERATOR Service ATA:24</b>  |      |           |                 |                         |                           |           |           |             |
| PN:23080-064  | MOS  | 13-Mar-24 |                 |                         |                           |           |           |             |
| SN:P1468  | HRS  | 3890.9    |                 |                         |                           |           |           |             |
| WC#: 24.085   | AFL  | 1481      |                 |                         |                           |           |           |             |
|   | APH  | 3741      | 500             |                         | 4241                      |           | 495       |             |
|   |      |           |                 | PROC. REF: AMM 24-30-21 |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition |
|--|---------|-----------|-----------------|----------|---------------------------|-----------|--------------|-------------|
| <b>ATA 24 - ELECTRICAL POWER</b>   |         |           |                 |          |                           |           |              |             |
| <b>240025<sup>S</sup> INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FUSELAGE KEEL AT THE FRONT SPAR) Service ATA:24</b>                              |         |           |                 |          |                           |           |              |             |
|  | MOS     | 06-Jun-18 |                 |          |                           |           |              |             |
|  | HRS     | 2965.25   | 3200 (+150/-50) |          |                           |           |              |             |
| WC#: 24.245  | AFL     | 1073      |                 |          |                           |           |              |             |
| PROC. REF: AMM 24-01-00  |         |           |                 |          |                           |           |              | PKG:35,93   |
| <b>240026<sup>S</sup> INSPECT ELECTRICAL CABLE PRESSURE BUNGS (IN THE FORWARD PRESSURE BULKHEAD) Service ATA:24</b>                                    |         |           |                 |          |                           |           |              |             |
|  | MOS     | 06-Jun-18 |                 |          |                           |           |              |             |
|  | HRS     | 2965.25   | 3200 (+150/-50) |          |                           |           |              |             |
| WC#: 24.240  | AFL     | 1073      |                 |          |                           |           |              |             |
| PROC. REF: AMM 24-01-00  |         |           |                 |          |                           |           |              | PKG:34,93   |
| <b>240027<sup>S</sup> CHECK MAIN BATTERIES Service ATA:24</b>  |         |           |                 |          |                           |           |              |             |
|  | MOS     | 06-Jun-18 |                 |          |                           |           |              |             |
|  | HRS     | 2965.25   | 3200 (+150/-50) |          |                           |           |              |             |
| WC#: 24.250  | AFL     | 1073      |                 |          |                           |           |              |             |
| PROC. REF: AMM NO REF 1  |         |           |                 |          |                           |           |              | PKG:37,93   |
| <b>240028 VISUAL INSPECTION PANEL GG AND TERMINAL BLOCK M Service ATA:24</b>   |         |           |                 |          |                           |           |              |             |
|  | MOS/MSC | 06-Jun-18 | N/A             |          |                           |           |              |             |
|  | HRS     | 2965.25   |                 |          |                           |           |              |             |
| WC#: 24.095  | AFL     | 1073      |                 |          |                           |           |              |             |
| PROC. REF: AMM 24-01-00  |         |           |                 |          |                           |           |              |             |
| <b>240029<sup>S</sup> VISUAL INSPECTION FOR DISCOLORATION AND SIGNS OF DISTRESS, INSPECT DA-PANEL FOR PROPER MOUNTING OF COMPONENTS Service ATA:24</b> |         |           |                 |          |                           |           |              |             |
|  | MOS     | 25-Jul-24 | 12 (+1m/-1m)    |          |                           |           |              |             |
|  | HRS     | 3908.4    |                 |          |                           |           |              |             |
| WC#: 24.260  | AFL     | 1492      |                 |          |                           |           |              |             |
| PROC. REF: AMM 24-01-00  |         |           |                 |          |                           |           |              | PKG:48,94   |
| <b>240030 FUNCTION TEST CABIN INVERTER (115 VAC) SYSTEM (IF INSTALLED) Service ATA:24</b>  |         |           |                 |          |                           |           |              |             |
|  | MOS     | 13-Mar-24 |                 |          |                           |           |              |             |
|  | HRS     | 3890.9    | 200 (+10%/-10%) |          | 4090.9                    | 4110.9    | 182.5 (+20)  |             |
| WC#: 24.255  | AFL     | 1481      |                 |          |                           |           |              |             |
| PROC. REF: MMA 24-20-10, MMA 24-20-15  |         |           |                 |          |                           |           |              |             |
| <b>240031 INSPECT NO. 1 ENGINE AC GENERATOR QAD PAD FOR DEFORMATION, CRACKS OR OTHER DAMAGE Service ATA:24</b>   |         |           |                 |          |                           |           |              |             |
| PN:BA02801-1   | MOS     | 13-Mar-24 |                 |          |                           |           |              |             |
| SN:3389  | HRS     | 3890.9    | 200 (+200)      |          | 4090.9                    | 4290.9    | 182.5 (+200) |             |
|  | AFL     | 1481      |                 |          |                           |           |              |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit  | C/W       | Interval   | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition |        |
|----------------------------------|---|-----------|------------|------------|---------------------------|-----------|--------------|-------------|--------|
| <b>ATA 24 - ELECTRICAL POWER</b> |   |           |            |            |                           |           |              |             |        |
| 240031                           | INSPECT NO. 2 ENGINE AC GENERATOR QAD PAD FOR DEFORMATION, CRACKS OR OTHER DAMAGE |           |            |            |                           |           |              | Service     | ATA:24 |
| PN:BA02801-1                     | MOS   | 13-Mar-24 |            |            |                           |           |              |             |        |
| SN:1502                          | HRS   | 3890.9    | 200 (+200) |            | 4090.9                    | 4290.9    | 182.5 (+200) |             |        |
|                                  | AFL   | 1481      |            |            |                           |           |              |             |        |
| 242001                           | NO. 1 (MAIN) INVERTER   |           |            |            |                           |           |              | Component   | ATA:24 |
| PN:140-380010-3                  | MOS/MSC   | 16-Mar-10 | O/C        | TSN 0      |                           |           |              |             |        |
| SN:0813371E                      | HRS   | 0         |            | TSN 0      |                           |           |              |             |        |
| WC#: 24.015                      | AFL   | 0         |            | TSN 0      |                           |           |              |             |        |
| PROC. REF: AMM 24-21-102         |   |           |            |            |                           |           |              |             |        |
| 242002                           | NO. 2 (MAIN) INVERTER   |           |            |            |                           |           |              | Component   | ATA:24 |
| PN:140-380010-3                  | MOS/MSC   | 16-Mar-10 | O/C        | TSN 0      |                           |           |              |             |        |
| SN:0813375E                      | HRS   | 0         |            | TSN 0      |                           |           |              |             |        |
| WC#: 24.015                      | AFL   | 0         |            | TSN 0      |                           |           |              |             |        |
| PROC. REF: AMM 24-21-102         |   |           |            |            |                           |           |              |             |        |
| 242013                           | NO. 3 (STANDBY) INVERTER  |           |            |            |                           |           |              | Component   | ATA:24 |
| PN:SPS-1607A                     | MOS/MSC   | 16-Oct-17 | O/C        | TSO 4      |                           |           |              |             |        |
| SN:905                           | HRS   | 2853.82   |            | TSO 0      |                           |           |              |             |        |
| WC#: 24.015                      | AFL   | 1031      |            | TSO 0      |                           |           |              |             |        |
| 242031                           | NO. 1 INVERTER CONTACTOR  |           |            |            |                           |           |              | Component   | ATA:24 |
| PN:PN                            | MOS   | 16-Mar-10 |            | TSN 0      |                           |           |              | OVERHAUL    |        |
| SN:UNKNOWN                       | HRS   | 0         | 5000       | TSN 0      | 5000                      |           | 1091.6       |             |        |
| WC#: 24.020                      | AFL   | 0         |            | TSN 0      |                           |           |              |             |        |
| 242032                           | NO. 2 INVERTER CONTACTOR  |           |            |            |                           |           |              | Component   | ATA:24 |
| PN:PN                            | MOS   | 16-Mar-10 |            | TSN 0      |                           |           |              | OVERHAUL    |        |
| SN:UNKNOWN                       | HRS   | 0         | 5000       | TSN 0      | 5000                      |           | 1091.6       |             |        |
| WC#: 24.020                      | AFL   | 0         |            | TSN 0      |                           |           |              |             |        |
| 242073                           | NO. 1 ENGINE AC GENERATOR   |           |            |            |                           |           |              | Component   | ATA:24 |
| PN:BA02801-1                     | MOS   | 13-Mar-24 | 96         | TSO 69     | 13-Jun-26                 |           | 684 d        | OVERHAUL    |        |
| SN:3389                          | HRS   | 3890.9    | 3000       | TSO 925.65 | 5965.25                   |           | 2056.9       |             |        |
| WC#: 24.025                      | AFL   | 1481      |            | TSO 408    |                           |           |              |             |        |
| PROC. REF: AMM 24-22-21          |   |           |            |            |                           |           |              |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit                            | C/W       | Interval | TSX/Adj.    | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------------|---------------------------------|-----------|----------|-------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 24 - ELECTRICAL POWER</b> |                                 |           |          |             |                           |           |           |             |        |
| 242074                           | NO. 2 ENGINE AC GENERATOR       |           |          |             |                           |           |           | Component   | ATA:24 |
| PN:BA02801-1                     | MOS                             | 13-Mar-24 | 96       | TSO 69      | 13-Jun-26                 |           | 684 d     | OVERHAUL    |        |
| SN:1502                          | HRS                             | 3890.9    | 3000     | TSO 925.65  | 5965.25                   |           | 2056.9    |             |        |
| WC#: 24.025                      | AFL                             | 1481      |          | TSO 408     |                           |           |           |             |        |
| PROC. REF: AMM 24-22-21          |                                 |           |          |             |                           |           |           |             |        |
| 242097                           | LEFT AC GENERATOR CONTROL UNIT  |           |          |             |                           |           |           | Component   | ATA:24 |
| PN:CB02701                       | MOS/MSC                         | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:3540                          | HRS                             | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 24.035                      | AFL                             | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: AMM 24-30-07          |                                 |           |          |             |                           |           |           |             |        |
| 242098                           | RIGHT AC GENERATOR CONTROL UNIT |           |          |             |                           |           |           | Component   | ATA:24 |
| PN:CB02701                       | MOS/MSC                         | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:3544                          | HRS                             | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 24.035                      | AFL                             | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: AMM 24-30-07          |                                 |           |          |             |                           |           |           |             |        |
| 243001                           | NO. 1 ENGINE STARTER/GENERATOR  |           |          |             |                           |           |           | Component   | ATA:24 |
| PN:23080-064                     | MOS                             | 12-Feb-24 |          | TSO 0       |                           |           |           | OVERHAUL    |        |
| SN:Y30489                        | HRS                             | 3881.4    | 1000     | TSO 0       | 4881.4                    |           | 973       |             |        |
| WC#: 24.045                      | AFL                             | 1476      |          | TSO 0       |                           |           |           |             |        |
| PROC. REF: AMM 24-30-21          |                                 |           |          |             |                           |           |           |             |        |
| 243002                           | NO. 2 ENGINE STARTER/GENERATOR  |           |          |             |                           |           |           | Component   | ATA:24 |
| PN:23080-064                     | MOS                             | 12-Feb-24 |          | TSO 0       |                           |           |           | OVERHAUL    |        |
| SN:P2065                         | HRS                             | 3881.4    | 1000     | TSO 0       | 4881.4                    |           | 973       |             |        |
| WC#: 24.045                      | AFL                             | 1476      |          | TSO 0       |                           |           |           |             |        |
| PROC. REF: AMM 24-30-21          |                                 |           |          |             |                           |           |           |             |        |
| 243037                           | NO. 1 DC GENERATOR CONTROL UNIT |           |          |             |                           |           |           | Component   | ATA:24 |
| PN:51539-006H                    | MOS/MSC                         | 16-Aug-19 | O/C      | TSN 123     |                           |           |           |             |        |
| SN:P2232                         | HRS                             | 3266.75   |          | TSN 3266.75 |                           |           |           |             |        |
| WC#: 24.050                      | AFL                             | 1189      |          | TSN 1189    |                           |           |           |             |        |
| PROC. REF: AMM 24-30-07          |                                 |           |          |             |                           |           |           |             |        |
| 243038                           | NO. 2 DC GENERATOR CONTROL UNIT |           |          |             |                           |           |           | Component   | ATA:24 |
| PN:51539-006H                    | MOS/MSC                         | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:P2180                         | HRS                             | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 24.050                      | AFL                             | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: AMM 24-30-07          |                                 |           |          |             |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 24 - ELECTRICAL POWER</b>      |                                    |           |          |          |                           |           |           |             |        |
| 243049                                | H (UPPER) CONTACTOR                |           |          |          |                           |           |           | Component   | ATA:24 |
| PN:140-380022-0001                    | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:CR-43777                           | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 24.055                           | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                    |           |          |          |                           |           |           |             |        |
| 243050                                | H (LOWER) CONTACTOR                |           |          |          |                           |           |           | Component   | ATA:24 |
| PN:140-380022-0001                    | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:CR-51669                           | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 24.055                           | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                    |           |          |          |                           |           |           |             |        |
| 243061                                | G (UPPER) CONTACTOR                |           |          |          |                           |           |           | Component   | ATA:24 |
| PN:140-380021-0001                    | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:CR-38286                           | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 24.060                           | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                    |           |          |          |                           |           |           |             |        |
| 243062                                | G (LOWER) CONTACTOR                |           |          |          |                           |           |           | Component   | ATA:24 |
| PN:140-380017-0001                    | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:CR-22392                           | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 24.060                           | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                    |           |          |          |                           |           |           |             |        |
| 243079                                | DC VOLTAGE SENSING UNIT            |           |          |          |                           |           |           | Component   | ATA:24 |
| PN:PN                                 | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 24.070                           | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                    |           |          |          |                           |           |           |             |        |
| 243091                                | GROUND SUPPLY START (E) CONTACTOR  |           |          |          |                           |           |           | Component   | ATA:24 |
| PN:PN                                 | MOS                                | 16-Mar-10 |          | TSN 0    |                           |           |           | OVERHAUL    |        |
| SN:UNKNOWN                            | HRS                                | 0         | 6000     | TSN 0    | 6000                      |           | 2091.6    |             |        |
| WC#: 24.075                           | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| 243103                                | APU STARTER/GENERATOR CONTROL UNIT |           |          |          |                           |           |           | Component   | ATA:24 |
| PN:51539-006H                         | MOS/MSC                            | 13-Mar-24 | O/C      | TSO 3    |                           |           |           |             |        |
| SN:P1244                              | HRS                                | 3890.9    |          | TSO 0    |                           |           |           |             |        |
| WC#: 24.080                           | AFL                                | 1481      |          | TSO 0    |                           |           |           |             |        |
| PROC. REF: AMM 49-11-00, AMM 24-30-21 |                                    |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                 | Unit    | C/W                          | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |                         |
|---|---------|------------------------------|----------|------------|---------------------------|-----------|-----------|-------------|-------------------------|
| <b>ATA 24 - ELECTRICAL POWER</b>        |         |                              |          |            |                           |           |           |             |                         |
| <b>243115</b>                           |         | <b>APU STARTER/GENERATOR</b> |          |            |                           |           |           |             | <b>Component ATA:24</b> |
| PN:23080-064                            | MOS     | 13-Mar-24                    |          | TSO 69     |                           |           |           | OVERHAUL    |                         |
| SN:P1468                                | HRS     | 3890.9                       |          | TSO 925.65 |                           |           |           |             |                         |
| WC#: 24.085                             | AFL     | 1481                         |          | TSO 408    |                           |           |           |             |                         |
|   | APH     | 3741                         | 1000     | TSO 888    | 3853                      |           | 107       |             |                         |
| PROC. REF: AMM 24-30-21, AMM 49-11-00   |         |                              |          |            |                           |           |           |             |                         |
| <b>243137</b>                           |         | <b>NO. 1 BATTERY</b>         |          |            |                           |           |           |             | <b>Component ATA:24</b> |
| PN:9750W0640                            | MOS/MSC | 11-Jul-24                    | O/C      | TSO 30     |                           |           |           |             |                         |
| SN:162670005                            | HRS     | 3907.4                       |          | TSO 425.7  |                           |           |           |             |                         |
| WC#: 24.090                             | AFL     | 1491                         |          | TSO 219    |                           |           |           |             |                         |
| PROC. REF: AMM 24-30-151                |         |                              |          |            |                           |           |           |             |                         |
| <b>243138</b>                           |         | <b>NO. 2 BATTERY</b>         |          |            |                           |           |           |             | <b>Component ATA:24</b> |
| PN:9750W0640                            | MOS/MSC | 11-Jul-24                    | O/C      | TSO 30     |                           |           |           |             |                         |
| SN:162670006                            | HRS     | 3907.4                       |          | TSO 425.7  |                           |           |           |             |                         |
| WC#: 24.090                             | AFL     | 1491                         |          | TSO 219    |                           |           |           |             |                         |
| PROC. REF: AMM 24-30-151                |         |                              |          |            |                           |           |           |             |                         |
| <b>243139</b>                           |         | <b>NO. 3 BATTERY</b>         |          |            |                           |           |           |             | <b>Component ATA:24</b> |
| PN:100-0540-04                          | MOS     | 11-Mar-24                    | 48       | TSO 26     | 11-Jan-26                 |           | 531 d     |             |                         |
| SN:1126493                              | HRS     | 3890.9                       |          | TSO 409.2  |                           |           |           |             |                         |
| WC#: 24.210                             | AFL     | 1481                         |          | TSO 209    |                           |           |           |             |                         |
| PROC. REF: AMM 24-30-151, AMM 24-30-155 |         |                              |          |            |                           |           |           |             |                         |
| <b>243140</b>                           |         | <b>NO. 4 BATTERY</b>         |          |            |                           |           |           |             | <b>Component ATA:24</b> |
| PN:100-0540-04                          | MOS     | 11-Mar-24                    | 48       | TSO 21     | 11-Jun-26                 |           | 682 d     |             |                         |
| SN:0601813                              | HRS     | 3890.9                       |          |            |                           |           |           |             |                         |
| WC#: 24.220                             | AFL     | 1481                         |          |            |                           |           |           |             |                         |
| PROC. REF: AMM 24-30-07, AMM 24-30-155  |         |                              |          |            |                           |           |           |             |                         |
| <b>243141</b>                           |         | <b>NO. 5 BATTERY</b>         |          |            |                           |           |           |             | <b>Component ATA:24</b> |
| PN:100-0540-04                          | MOS     | 13-Mar-24                    | 48       | TSO 5      | 13-Oct-27                 |           | 1171 d    |             |                         |
| SN:2364                                 | HRS     | 3890.9                       |          | TSO 0      |                           |           |           |             |                         |
| WC#: 24.230                             | AFL     | 1481                         |          | TSO 0      |                           |           |           |             |                         |
| PROC. REF: AMS 24-30-155                |         |                              |          |            |                           |           |           |             |                         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit | C/W                             | Interval         | TSX/Adj.       | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|----------------------------------|------|---------------------------------|------------------|----------------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 24 - ELECTRICAL POWER</b> |      |                                 |                  |                |                           |           |             |             |        |
| 243142                           |      | NO. 6 BATTERY                   |                  |                |                           |           |             | Component   | ATA:24 |
| PN:100-0540-04                   | MOS  | 11-Mar-24                       | 48               | TSN 46, TSR 35 | 11-May-24                 |           | OVD         |             |        |
| SN:0915026                       | HRS  | 3890.9                          |                  | TSR 486.62     |                           |           |             |             |        |
|                                  | AFL  | 1481                            |                  | TSR 239        |                           |           |             |             |        |
| PROC. REF: AMS 24-30-155         |      |                                 |                  |                |                           |           |             |             |        |
| 243143                           |      | NO. 7 BATTERY                   |                  |                |                           |           |             | Component   | ATA:24 |
| PN:100-0540-04                   | MOS  | 11-Mar-24                       | 48               | TSN 46, TSR 35 | 11-May-24                 |           | OVD         |             |        |
| SN:0811484                       | HRS  | 3890.9                          |                  | TSR 486.62     |                           |           |             |             |        |
|                                  | AFL  | 1481                            |                  | TSR 239        |                           |           |             |             |        |
| PROC. REF: AMS 24-30-155         |      |                                 |                  |                |                           |           |             |             |        |
| 243154                           |      | CAPACITY CHECK NO. 1 BATTERY    |                  |                |                           |           |             | Service     | ATA:24 |
| PN:9750W0640                     | MOS  | 11-Jul-24                       | 6 (+15d/-15d)    |                | 11-Jan-25                 | 26-Jan-25 | 166 d (+15) | STC ICA     |        |
| SN:162670005                     | HRS  | 3907.4                          | 1500 (+100/-100) |                | 5407.4                    | 5507.4    | 1499 (+100) |             |        |
| WC#: 24.090                      | AFL  | 1491                            |                  |                |                           |           |             |             |        |
| PROC. REF: GENERIC NO REF        |      |                                 |                  |                |                           |           |             |             |        |
| 243155                           |      | CAPACITY CHECK NO. 2 BATTERY    |                  |                |                           |           |             | Service     | ATA:24 |
| PN:9750W0640                     | MOS  | 11-Jul-24                       | 6 (+15d/-15d)    |                | 11-Jan-25                 | 26-Jan-25 | 166 d (+15) | STC ICA     |        |
| SN:162670006                     | HRS  | 3907.4                          | 1500 (+100/-100) |                | 5407.4                    | 5507.4    | 1499 (+100) |             |        |
| WC#: 24.090                      | AFL  | 1491                            |                  |                |                           |           |             |             |        |
| PROC. REF: AMM 24-30-151         |      |                                 |                  |                |                           |           |             |             |        |
| 243156                           |      | ENERGY LEVEL TEST NO. 3 BATTERY |                  |                |                           |           |             | Service     | ATA:24 |
| PN:100-0540-04                   | MOS  | 11-Mar-24                       | 12 (+30d/-30d)   |                | 11-Mar-25                 | 10-Apr-25 | 225 d (+30) |             |        |
| SN:1126493                       | HRS  | 3890.9                          |                  |                |                           |           |             |             |        |
| WC#: 24.210                      | AFL  | 1481                            |                  |                |                           |           |             |             |        |
| PROC. REF: AMM 24-30-155         |      |                                 |                  |                |                           |           |             |             |        |
| 243157                           |      | ENERGY LEVEL TEST NO.4 BATTERY  |                  |                |                           |           |             | Service     | ATA:24 |
| PN:100-0540-04                   | MOS  | 11-Mar-24                       | 12 (+30d/-30d)   |                | 11-Mar-25                 | 10-Apr-25 | 225 d (+30) |             |        |
| SN:0601813                       | HRS  | 3890.9                          |                  |                |                           |           |             |             |        |
| WC#: 24.220                      | AFL  | 1481                            |                  |                |                           |           |             |             |        |
| PROC. REF: AMM 24-30-155         |      |                                 |                  |                |                           |           |             |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |
|--|---------|-----------|----------------|----------|---------------------------|-----------|-------------|-------------|
| <b>ATA 24 - ELECTRICAL POWER</b>                             |         |           |                |          |                           |           |             |             |
| <b>243158 ENERGY LEVEL TEST NO. 5 BATTERY Service ATA:24</b> |         |           |                |          |                           |           |             |             |
| PN:100-0540-04   | MOS     | 13-Mar-24 | 12 (+30d/-30d) |          | 13-Mar-25                 | 12-Apr-25 | 227 d (+30) |             |
| SN:2364  | HRS     | 3890.9    |                |          |                           |           |             |             |
| WC#: 24.230  | AFL     | 1481      |                |          |                           |           |             |             |
| PROC. REF: AMM 24-30-155                                     |         |           |                |          |                           |           |             |             |
| <b>243159 ENERGY LEVEL TEST NO. 6 BATTERY Service ATA:24</b> |         |           |                |          |                           |           |             |             |
| PN:100-0540-04   | MOS/MSC | 11-Mar-24 | O/C            |          |                           |           |             |             |
| SN:0915026   | HRS     | 3890.9    |                |          |                           |           |             |             |
|  | AFL     | 1481      |                |          |                           |           |             |             |
| PROC. REF: AMM 24-30-155                                     |         |           |                |          |                           |           |             |             |
| <b>243160 ENERGY LEVEL TEST NO. 7 BATTERY Service ATA:24</b> |         |           |                |          |                           |           |             |             |
| PN:100-0540-04   | MOS/MSC | 11-Mar-24 | O/C            |          |                           |           |             |             |
| SN:0811484   | HRS     | 3890.9    |                |          |                           |           |             |             |
|  | AFL     | 1481      |                |          |                           |           |             |             |
| PROC. REF: GENERIC NO REF                                    |         |           |                |          |                           |           |             |             |
| <b>243238 OVERVOLTAGE SENSOR Component ATA:24</b>            |         |           |                |          |                           |           |             |             |
| PN:E311TS  | MOS/MSC | 16-Mar-10 | O/C            | TSN 0    |                           |           |             |             |
| SN:CR-26114  | HRS     | 0         |                | TSN 0    |                           |           |             |             |
| WC#: 24.110  | AFL     | 0         |                | TSN 0    |                           |           |             |             |
| PROC. REF: AMM 24-30-146                                     |         |           |                |          |                           |           |             |             |
| <b>243246 THERMAL SWITCH Component ATA:24</b>                |         |           |                |          |                           |           |             |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C            | TSN 0    |                           |           |             |             |
| SN:UNKNOWN   | HRS     | 0         |                | TSN 0    |                           |           |             |             |
| WC#: 24.115  | AFL     | 0         |                | TSN 0    |                           |           |             |             |
| PROC. REF: AMM NO REF 1                                      |         |           |                |          |                           |           |             |             |
| <b>243247 S CONTACTOR Component ATA:24</b>                   |         |           |                |          |                           |           |             |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C            | TSN 0    |                           |           |             |             |
| SN:UNKNOWN   | HRS     | 0         |                | TSN 0    |                           |           |             |             |
| WC#: 24.120  | AFL     | 0         |                | TSN 0    |                           |           |             |             |
| PROC. REF: GENERIC NO REF                                    |         |           |                |          |                           |           |             |             |
| <b>243253 FORWARD U CONTACTOR Component ATA:24</b>           |         |           |                |          |                           |           |             |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C            | TSN 0    |                           |           |             |             |
| SN:UNKNOWN   | HRS     | 0         |                | TSN 0    |                           |           |             |             |
| WC#: 24.120  | AFL     | 0         |                | TSN 0    |                           |           |             |             |
| PROC. REF: GENERIC NO REF                                    |         |           |                |          |                           |           |             |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit    | C/W                   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |  |
|----------------------------------|---------|-----------------------|----------|----------|---------------------------|-----------|-----------|-------------|--|
| <b>ATA 24 - ELECTRICAL POWER</b> |         |                       |          |          |                           |           |           |             |  |
| 243259                           |         | J CONTACTOR           |          |          |                           |           | Component | ATA:24      |  |
| PN:A770RSSA                      | MOS/MSC | 16-Mar-10             | O/C      | TSN 0    |                           |           |           |             |  |
| SN:CR-18593                      | HRS     | 0                     |          | TSN 0    |                           |           |           |             |  |
| WC#: 24.125                      | AFL     | 0                     |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF        |         |                       |          |          |                           |           |           |             |  |
| 243265                           |         | K CONTACTOR           |          |          |                           |           | Component | ATA:24      |  |
| PN:A770RSSA                      | MOS/MSC | 16-Mar-10             | O/C      | TSN 0    |                           |           |           |             |  |
| SN:CR-18606                      | HRS     | 0                     |          | TSN 0    |                           |           |           |             |  |
| WC#: 24.125                      | AFL     | 0                     |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF        |         |                       |          |          |                           |           |           |             |  |
| 243271                           |         | AFT U CONTACTOR       |          |          |                           |           | Component | ATA:24      |  |
| PN:A848MAS                       | MOS/MSC | 16-Mar-10             | O/C      | TSN 0    |                           |           |           |             |  |
| SN:CR-22580                      | HRS     | 0                     |          | TSN 0    |                           |           |           |             |  |
| WC#: 24.130                      | AFL     | 0                     |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF        |         |                       |          |          |                           |           |           |             |  |
| 243277                           |         | L CONTACTOR           |          |          |                           |           | Component | ATA:24      |  |
| PN:PN                            | MOS/MSC | 16-Mar-10             | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN                       | HRS     | 0                     |          | TSN 0    |                           |           |           |             |  |
| WC#: 24.135                      | AFL     | 0                     |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF        |         |                       |          |          |                           |           |           |             |  |
| 243283                           |         | M CONTACTOR           |          |          |                           |           | Component | ATA:24      |  |
| PN:PN                            | MOS/MSC | 16-Mar-10             | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN                       | HRS     | 0                     |          | TSN 0    |                           |           |           |             |  |
| WC#: 24.135                      | AFL     | 0                     |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF        |         |                       |          |          |                           |           |           |             |  |
| 245001                           |         | BUS TIE (T) CONTACTOR |          |          |                           |           | Component | ATA:24      |  |
| PN:PN                            | MOS     | 16-Mar-10             |          | TSN 0    |                           |           |           | OVERHAUL    |  |
| SN:UNKNOWN                       | HRS     | 0                     | 5000     | TSN 0    | 5000                      |           | 1091.6    |             |  |
| WC#: 24.140                      | AFL     | 0                     |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: AMM NO REF 1          |         |                       |          |          |                           |           |           |             |  |
| 245043                           |         | TEMPERATURE SENSOR    |          |          |                           |           | Component | ATA:24      |  |
| PN:548408-1                      | MOS/MSC | 16-Mar-10             | O/C      | TSN 0    |                           |           |           |             |  |
| SN:548408-02610                  | HRS     | 0                     |          | TSN 0    |                           |           |           |             |  |
| WC#: 24.170                      | AFL     | 0                     |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: AMM NO REF 1          |         |                       |          |          |                           |           |           |             |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit                                | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|-------------------------------------|-----------|-----------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |                                     |           |                 |          |                           |           |           |             |        |
| 250003 <sup>S</sup>                   | CHECK 3RD CREW MEMBERS SEAT         |           |                 |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS                                 | 03-Aug-21 |                 |          |                           |           |           |             |        |
|                                       | HRS                                 | 3405      | 800 (+40/-10)   |          |                           |           |           |             |        |
| WC#: 25.115                           | AFL                                 | 1243      |                 |          |                           |           |           | PKG:12,91   |        |
| 250005                                | INSPECT EMERGENCY PACKS (IF FITTED) |           |                 |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS/MSC                             | 13-Apr-12 | N/R             |          |                           |           |           |             |        |
|                                       | HRS                                 |           |                 |          |                           |           |           |             |        |
| WC#: 25.125                           | AFL                                 |           |                 |          |                           |           |           |             |        |
| 250006 <sup>S</sup>                   | CHECK FIRST AID KITS                |           |                 |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS                                 | 25-Jul-24 | 12 (+1m/-1m)    |          |                           |           |           |             |        |
|                                       | HRS                                 | 3908.4    |                 |          |                           |           |           |             |        |
| WC#: 25.130                           | AFL                                 | 1492      |                 |          |                           |           |           | PKG:48,94   |        |
| 250007 <sup>S</sup>                   | OPERATIONAL CHECK CREW SEATS        |           |                 |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS                                 | 03-Aug-21 |                 |          |                           |           |           |             |        |
|                                       | HRS                                 | 3405      | 800 (+40/-10)   |          |                           |           |           |             |        |
| WC#: 25.145                           | AFL                                 | 1243      |                 |          |                           |           |           | PKG:10,91   |        |
| 250008 <sup>S</sup>                   | DETAILED CHECK CREW SEATS           |           |                 |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS                                 | 06-Jun-18 |                 |          |                           |           |           |             |        |
|                                       | HRS                                 | 2965.25   | 3200 (+150/-50) |          |                           |           |           |             |        |
| WC#: 25.150                           | AFL                                 | 1073      |                 |          |                           |           |           | PKG:34,93   |        |
|                                       |                                     |           |                 |          | PROC. REF: AMM 25-10-14   |           |           |             |        |
| 251001                                | NO. 1 CREW SEAT                     |           |                 |          |                           |           |           | Component   | ATA:25 |
| PN:3A026-0013-00-2                    | MOS/MSC                             | 05-May-10 | O/C             |          |                           |           |           |             |        |
| SN:44658                              | HRS                                 | 4.7       |                 |          |                           |           |           |             |        |
| WC#: 25.010                           | AFL                                 | 4         |                 |          |                           |           |           | PKG:34,93   |        |
|                                       |                                     |           |                 |          | PROC. REF: AMM 25-10-14   |           |           |             |        |
| 251002                                | NO. 2 CREW SEAT                     |           |                 |          |                           |           |           | Component   | ATA:25 |
| PN:3A026-0014-00                      | MOS/MSC                             | 16-Mar-10 | O/C             | TSN 0    |                           |           |           |             |        |
| SN:58659                              | HRS                                 | 0         |                 | TSN 0    |                           |           |           |             |        |
| WC#: 25.010                           | AFL                                 | 0         |                 | TSN 0    |                           |           |           | PKG:34,93   |        |
|                                       |                                     |           |                 |          | PROC. REF: AMM 25-10-14   |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W                             | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|---------------------------------------|---------|---------------------------------|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |         |                                 |          |          |                           |           |           |                  |               |
| <b>251020</b>                         |         | <b>THROTTLE BOX</b>             |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:149-340057-6001                    | MOS/MSC | 16-Mar-10                       | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:1308                               | HRS     | 0                               |          |          | TSN 0                     |           |           |                  |               |
| WC#: 25.020                           | AFL     | 0                               |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF             |         |                                 |          |          |                           |           |           |                  |               |
| <b>251031<sup>U</sup></b>             |         | <b>R/H VIDEO MONITOR-</b>       |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:2710-1-1501                        | MOS/MSC | 05-May-10                       | O/C      |          |                           |           |           |                  |               |
| SN:205150155                          | HRS     | 4.7                             |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                               |          |          |                           |           |           |                  |               |
| <b>251033<sup>U</sup></b>             |         | <b>L/H VIDEO MONITOR-</b>       |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:2710-1-1501                        | MOS/MSC | 05-May-10                       | O/C      |          |                           |           |           |                  |               |
| SN:208070109                          | HRS     | 4.7                             |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                               |          |          |                           |           |           |                  |               |
| <b>251034<sup>U</sup></b>             |         | <b>AIRPLAY AUDIO AMP</b>        |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:3600-1-1                           | MOS/MSC | 05-May-10                       | O/C      |          |                           |           |           |                  |               |
| SN:3MK8P                              | HRS     | 4.7                             |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                               |          |          |                           |           |           |                  |               |
| <b>251036<sup>U</sup></b>             |         | <b>RF-IR REMOTE RECEIVER</b>    |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:2033-1-1                           | MOS/MSC | 05-May-10                       | O/C      |          |                           |           |           |                  |               |
| SN:20723006                           | HRS     | 4.7                             |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                               |          |          |                           |           |           |                  |               |
| <b>251038</b>                         |         | <b>FLIGHT DECK CONTROLLER</b>   |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:922000-2                           | MOS/MSC | 05-May-10                       | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:H01007595                          | HRS     | 4.7                             |          |          | TSN 0                     |           |           |                  |               |
| WC#: 25.135                           | AFL     | 4                               |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF             |         |                                 |          |          |                           |           |           |                  |               |
| <b>251040<sup>U</sup></b>             |         | <b>OVERHEAD DISPLAY PANEL</b>   |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:90-1049-30P4                       | MOS/MSC | 05-May-10                       | O/C      |          |                           |           |           |                  |               |
| SN:0015                               | HRS     | 4.7                             |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                               |          |          |                           |           |           |                  |               |
| <b>251051<sup>U</sup></b>             |         | <b>LEFT HAND WOFFER SPEAKER</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:DT-AWSP-4MRH                       | MOS/MSC | 05-May-10                       | O/C      |          |                           |           |           |                  |               |
| SN:095178014                          | HRS     | 4.7                             |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                               |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W                                  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|---------------------------------------|---------|--------------------------------------|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |         |                                      |          |          |                           |           |           |                  |               |
| <b>251053<sup>U</sup></b>             |         | <b>RIGHT HAND WOFFER SPEAKER</b>     |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:DT-AWSP-4MRH                       | MOS/MSC | 05-May-10                            | O/C      |          |                           |           |           |                  |               |
| SN:095178001                          | HRS     | 4.7                                  |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                                    |          |          |                           |           |           |                  |               |
| <b>251057</b>                         |         | <b>NO. 1 DIGITAL AUDIO AMPLIFIER</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:MODEL700-007                       | MOS/MSC | 05-May-10                            | O/C      |          |                           |           |           |                  |               |
| SN:4164                               | HRS     | 4.7                                  |          |          |                           |           |           |                  |               |
| WC#: 25.050                           | AFL     | 4                                    |          |          |                           |           |           |                  |               |
| PROC. REF: AMM 23-50-10               |         |                                      |          |          |                           |           |           |                  |               |
| <b>251058</b>                         |         | <b>NO. 2 DIGITAL AUDIO AMPLIFIER</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:MODEL700-007                       | MOS/MSC | 05-May-10                            | O/C      |          |                           |           |           |                  |               |
| SN:4165                               | HRS     | 4.7                                  |          |          |                           |           |           |                  |               |
| WC#: 25.050                           | AFL     | 4                                    |          |          |                           |           |           |                  |               |
| PROC. REF: AMM 23-50-10               |         |                                      |          |          |                           |           |           |                  |               |
| <b>251061</b>                         |         | <b>MICROWAVE OVEN</b>                |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:400-1744-01                        | MOS/MSC | 16-Oct-17                            | O/C      |          |                           |           |           |                  |               |
| SN:04-11-36123                        | HRS     | 2853.82                              |          |          |                           |           |           |                  |               |
| WC#: 25.055                           | AFL     | 1031                                 |          |          |                           |           |           |                  |               |
| <b>251070<sup>U</sup></b>             |         | <b>NO. 1 LEFT LCD SCREEN</b>         |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:2516-1-1                           | MOS/MSC | 05-May-10                            | O/C      |          |                           |           |           |                  |               |
| SN:3M7BT                              | HRS     | 4.7                                  |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                                    |          |          |                           |           |           |                  |               |
| <b>251071<sup>U</sup></b>             |         | <b>NO. 2 LEFT LCD SCREEN</b>         |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:2516-1-1                           | MOS/MSC | 05-May-10                            | O/C      |          |                           |           |           |                  |               |
| SN:3M7BR                              | HRS     | 4.7                                  |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                                    |          |          |                           |           |           |                  |               |
| <b>251072<sup>U</sup></b>             |         | <b>NO. 3 LEFT LCD SCREEN</b>         |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:2516-1-1                           | MOS/MSC | 05-May-10                            | O/C      |          |                           |           |           |                  |               |
| SN:3M7BV                              | HRS     | 4.7                                  |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                                    |          |          |                           |           |           |                  |               |
| <b>251073<sup>U</sup></b>             |         | <b>NO. 4 LEFT LCD SCREEN</b>         |          |          |                           |           |           | <b>Component</b> | <b>ATA:25</b> |
| PN:2516-1-1                           | MOS/MSC | 05-May-10                            | O/C      |          |                           |           |           |                  |               |
| SN:3M60P                              | HRS     | 4.7                                  |          |          |                           |           |           |                  |               |
|                                       | AFL     | 4                                    |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W                    | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---------|------------------------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |         |                        |          |          |                           |           |           |             |        |
| 251074 <sup>U</sup>                   |         | NO. 1 RIGHT LCD SCREEN |          |          |                           |           |           | Component   | ATA:25 |
| PN:2516-1-1                           | MOS/MSC | 05-May-10              | O/C      |          |                           |           |           |             |        |
| SN:3M7BN                              | HRS     | 4.7                    |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                      |          |          |                           |           |           |             |        |
| 251075 <sup>U</sup>                   |         | NO. 2 RIGHT LCD SCREEN |          |          |                           |           |           | Component   | ATA:25 |
| PN:2516-1-1                           | MOS/MSC | 05-May-10              | O/C      |          |                           |           |           |             |        |
| SN:3M60X                              | HRS     | 4.7                    |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                      |          |          |                           |           |           |             |        |
| 251076 <sup>U</sup>                   |         | NO. 3 RIGHT LCD SCREEN |          |          |                           |           |           | Component   | ATA:25 |
| PN:2516-1-1                           | MOS/MSC | 05-May-10              | O/C      |          |                           |           |           |             |        |
| SN:3M7BP                              | HRS     | 4.7                    |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                      |          |          |                           |           |           |             |        |
| 251080 <sup>U</sup>                   |         | NO. 1 LEFT H/P JACK    |          |          |                           |           |           | Component   | ATA:25 |
| PN:2517-1-1                           | MOS/MSC | 05-May-10              | O/C      |          |                           |           |           |             |        |
| SN:2Y64Y                              | HRS     | 4.7                    |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                      |          |          |                           |           |           |             |        |
| 251081 <sup>U</sup>                   |         | NO. 2 LEFT H/P JACK    |          |          |                           |           |           | Component   | ATA:25 |
| PN:2517-1-1                           | MOS/MSC | 05-May-10              | O/C      |          |                           |           |           |             |        |
| SN:2Y64X                              | HRS     | 4.7                    |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                      |          |          |                           |           |           |             |        |
| 251082 <sup>U</sup>                   |         | NO. 3 LEFT H/P JACK    |          |          |                           |           |           | Component   | ATA:25 |
| PN:2517-1-1                           | MOS/MSC | 05-May-10              | O/C      |          |                           |           |           |             |        |
| SN:2Y66L                              | HRS     | 4.7                    |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                      |          |          |                           |           |           |             |        |
| 251083 <sup>U</sup>                   |         | NO. 4 LEFT H/P JACK    |          |          |                           |           |           | Component   | ATA:25 |
| PN:2517-1-1                           | MOS/MSC | 05-May-10              | O/C      |          |                           |           |           |             |        |
| SN:2Y67H                              | HRS     | 4.7                    |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                      |          |          |                           |           |           |             |        |
| 251084 <sup>U</sup>                   |         | NO. 1 RIGHT H/P JACK   |          |          |                           |           |           | Component   | ATA:25 |
| PN:2517-1-1                           | MOS/MSC | 05-May-10              | O/C      |          |                           |           |           |             |        |
| SN:2Y63Y                              | HRS     | 4.7                    |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                      |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W                       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---------|---------------------------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |         |                           |          |          |                           |           |           |             |        |
| 251085 <sup>U</sup>                   |         | NO. 2 RIGHT H/P JACK      |          |          |                           |           |           | Component   | ATA:25 |
| PN:2517-1-1                           | MOS/MSC | 05-May-10                 | O/C      |          |                           |           |           |             |        |
| SN:2Y65B                              | HRS     | 4.7                       |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                         |          |          |                           |           |           |             |        |
| 251090 <sup>U</sup>                   |         | NO. 1 RIGHT SPEAKER       |          |          |                           |           |           | Component   | ATA:25 |
| PN:DT-A8RH                            | MOS/MSC | 05-May-10                 | O/C      |          |                           |           |           |             |        |
| SN:092192033                          | HRS     | 4.7                       |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                         |          |          |                           |           |           |             |        |
| 251091 <sup>U</sup>                   |         | NO. 2 RIGHT SPEAKER       |          |          |                           |           |           | Component   | ATA:25 |
| PN:DT-A8RH                            | MOS/MSC | 05-May-10                 | O/C      |          |                           |           |           |             |        |
| SN:091756010                          | HRS     | 4.7                       |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                         |          |          |                           |           |           |             |        |
| 251092 <sup>U</sup>                   |         | NO. 3 RIGHT SPEAKER       |          |          |                           |           |           | Component   | ATA:25 |
| PN:DT-A8RH                            | MOS/MSC | 05-May-10                 | O/C      |          |                           |           |           |             |        |
| SN:092192032                          | HRS     | 4.7                       |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                         |          |          |                           |           |           |             |        |
| 251093 <sup>U</sup>                   |         | NO. 1 LEFT SPEAKER        |          |          |                           |           |           | Component   | ATA:25 |
| PN:DT-A8RH                            | MOS/MSC | 05-May-10                 | O/C      |          |                           |           |           |             |        |
| SN:092191031                          | HRS     | 4.7                       |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                         |          |          |                           |           |           |             |        |
| 251094 <sup>U</sup>                   |         | NO. 2 LEFT SPEAKER        |          |          |                           |           |           | Component   | ATA:25 |
| PN:DT-A8RH                            | MOS/MSC | 05-May-10                 | O/C      |          |                           |           |           |             |        |
| SN:092192013                          | HRS     | 4.7                       |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                         |          |          |                           |           |           |             |        |
| 251095 <sup>U</sup>                   |         | NO. 3 LEFT SPEAKER        |          |          |                           |           |           | Component   | ATA:25 |
| PN:DT-A8RH                            | MOS/MSC | 05-May-10                 | O/C      |          |                           |           |           |             |        |
| SN:092191032                          | HRS     | 4.7                       |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                         |          |          |                           |           |           |             |        |
| 251096 <sup>U</sup>                   |         | NO. 1 LEFT PAGING SPEAKER |          |          |                           |           |           | Component   | ATA:25 |
| PN:DT-PA2NRH-8                        | MOS/MSC | 05-May-10                 | O/C      |          |                           |           |           |             |        |
| SN:095176014                          | HRS     | 4.7                       |          |          |                           |           |           |             |        |
|                                       | AFL     | 4                         |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W   | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---------|---|----------|------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |         |   |          |            |                           |           |           |             |        |
| 251097 <sup>U</sup>                   |         | NO. 2 LEFT PAGING SPEAKER                                   |          |            |                           |           |           | Component   | ATA:25 |
| PN:DT-PA2NRH-8                        | MOS/MSC | 05-May-10   | O/C      |            |                           |           |           |             |        |
| SN:095176006                          | HRS     | 4.7   |          |            |                           |           |           |             |        |
|                                       | AFL     | 4   |          |            |                           |           |           |             |        |
| 251098 <sup>U</sup>                   |         | NO. 1 RIGHT PAGING SPEAKER                                  |          |            |                           |           |           | Component   | ATA:25 |
| PN:DT-PA2NRH-8                        | MOS/MSC | 05-May-10   | O/C      |            |                           |           |           |             |        |
| SN:095176021                          | HRS     | 4.7   |          |            |                           |           |           |             |        |
|                                       | AFL     | 4   |          |            |                           |           |           |             |        |
| 251099 <sup>U</sup>                   |         | NO. 2 RIGHT PAGING SPEAKER                                  |          |            |                           |           |           | Component   | ATA:25 |
| PN:DT-PA2NRH-8                        | MOS/MSC | 05-May-10   | O/C      |            |                           |           |           |             |        |
| SN:095176022                          | HRS     | 4.7   |          |            |                           |           |           |             |        |
|                                       | AFL     | 4   |          |            |                           |           |           |             |        |
| 253090 <sup>U</sup>                   |         | INSPECT TIA MICROWAVE OVEN - CHECK WAVEGUIDE MOISTURE COVER |          |            |                           |           |           | Service     | ATA:25 |
|                                       | MOS     | 11-Jul-24   | 6        |            | 11-Jan-25                 |           | 166 d     |             |        |
|                                       | HRS     | 3907.4  | 1500     |            | 5407.4                    |           | 1499      |             |        |
|                                       | AFL     | 1491  |          |            |                           |           |           |             |        |
| PROC. REF: MMA 25-30-31               |         |   |          |            |                           |           |           |             |        |
| 253316 <sup>U</sup>                   |         | R/H AUDIO VIDEO MODULE                                      |          |            |                           |           |           | Component   | ATA:25 |
| PN:2022-1-1                           | MOS/MSC | 05-May-10   | O/C      |            |                           |           |           |             |        |
| SN:3MHYW                              | HRS     | 4.7   |          |            |                           |           |           |             |        |
|                                       | AFL     | 4   |          |            |                           |           |           |             |        |
| 256001                                |         | EMERGENCY LOCATOR TRANSMITTER (ELT)                         |          |            |                           |           |           | Component   | ATA:25 |
| PN:453-5060                           | MOS/MSC | 20-Oct-14   | O/C      | TSN 55     |                           |           |           |             |        |
| SN:08905                              | HRS     | 2016.2  |          | TSN 2016.2 |                           |           |           |             |        |
| WC#: 25.025                           | AFL     | 729   |          | TSN 729    |                           |           |           |             |        |
| PROC. REF: AMM 25-61-20               |         |   |          |            |                           |           |           |             |        |
| 256004                                |         | RENEW ELT REGISTRATION                                      |          |            |                           |           |           | Service     | ATA:25 |
|                                       | MOS     | 12-Feb-24   | 24       |            | 12-Feb-26                 |           | 563 d     |             |        |
|                                       | HRS     | 3881.4  |          |            |                           |           |           |             |        |
|                                       | AFL     | 1476  |          |            |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |         |   |          |            |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |   |           |          |          |                           |           |           |             |        |
| 256005                                | INSPECT EMERGENCY LOCATOR TRANSMITTER (ELT)         |           |          |          |                           |           |           | Service     | ATA:25 |
| PN:453-5060                           | MOS   | 11-Jul-24 | 12       |          | 11-Jul-25                 |           | 347 d     |             |        |
| SN:08905                              | HRS   | 3907.4    |          |          |                           |           |           |             |        |
| WC#: 25.025                           | AFL   | 1491      |          |          |                           |           |           |             |        |
| 256006                                | ELT REMOTE (CONTROL UNIT) SWITCH                    |           |          |          |                           |           |           | Component   | ATA:25 |
| PN:PN                                 | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 25.030                           | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| 256007                                | REPLACE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY |           |          |          |                           |           |           | Service     | ATA:25 |
| PN:452-0133                           | MOS/MSC   | 13-Mar-24 | DUE      |          | 01-Aug-27 (M)             |           | 1098 d    |             |        |
| SN:396028-012                         | HRS   | 3890.9    |          |          |                           |           |           |             |        |
| WC#: 25.025                           | AFL   | 1481      |          |          |                           |           |           |             |        |
| PROC. REF: AMM NO REF 1               |   |           |          |          |                           |           |           |             |        |
| 256009                                | EMERGENCY LOCATOR TRANSMITTER ANTENNA               |           |          |          |                           |           |           | Component   | ATA:25 |
| PN:110-340                            | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:2806663                            | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 25.015                           | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 25-61-20               |   |           |          |          |                           |           |           |             |        |
| 256010                                | FUNCTIONAL TEST EMERGENCY LOCATOR TRANSMITTER (ELT) |           |          |          |                           |           |           | Service     | ATA:25 |
| PN:453-5060                           | MOS   | 11-Jul-24 | 12       |          | 11-Jul-25                 |           | 347 d     |             |        |
| SN:08905                              | HRS   | 3907.4    |          |          |                           |           |           |             |        |
| WC#: 25.025                           | AFL   | 1491      |          |          |                           |           |           |             |        |
| PROC. REF: AMM 25-61-20               |   |           |          |          |                           |           |           |             |        |
| 256011                                | REPLACE ELT REMOTE (CONTROL UNIT) SWITCH BATTERY    |           |          |          |                           |           |           | Service     | ATA:25 |
| PN:PN                                 | MOS/MSC   |           | N/A      |          |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS   |           |          |          |                           |           |           |             |        |
| WC#: 25.030                           | AFL   |           |          |          |                           |           |           |             |        |
| 256013                                | INSPECT LIFE VESTS                                  |           |          |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS/MSC   | 16-Mar-10 | N/R      |          |                           |           |           |             |        |
|                                       | HRS   | 0         |          |          |                           |           |           |             |        |
| WC#: 25.040                           | AFL   | 0         |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W                                  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---------|--------------------------------------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |         |                                      |          |          |                           |           |           |             |        |
| 256080 <sup>U</sup>                   |         | PILOT LIFE VEST                      |          |          |                           |           |           | Component   | ATA:25 |
| PN:63600-505                          | MOS/MSC | 04-Apr-19                            | O/C      | TSN 0    |                           |           |           |             |        |
| SN:L4082962                           | HRS     | 3175.17                              |          | TSN 0    |                           |           |           |             |        |
|                                       | AFL     | 1157                                 |          | TSN 0    |                           |           |           |             |        |
| 256080A <sup>U</sup>                  |         | RECERTIFY PILOT LIFE VEST            |          |          |                           |           |           | Service     | ATA:25 |
| PN:63600-505                          | MOS     | 04-Apr-19                            | 120      |          | 04-Apr-29                 |           | 1710 d    |             |        |
| SN:L4082962                           | HRS     | 3175.17                              |          |          |                           |           |           |             |        |
|                                       | AFL     | 1157                                 |          |          |                           |           |           |             |        |
| 256081 <sup>U</sup>                   |         | COPILOT LIFE VEST                    |          |          |                           |           |           | Component   | ATA:25 |
| PN:63600-505                          | MOS/MSC | 04-Apr-19                            | O/C      | TSN 0    |                           |           |           |             |        |
| SN:L4082963                           | HRS     | 3175.17                              |          | TSN 0    |                           |           |           |             |        |
|                                       | AFL     | 1157                                 |          | TSN 0    |                           |           |           |             |        |
| 256081A <sup>U</sup>                  |         | RECERTIFY COPILOT LIFE VEST          |          |          |                           |           |           | Service     | ATA:25 |
| PN:63600-505                          | MOS     | 04-Apr-19                            | 120      |          | 04-Apr-29                 |           | 1710 d    |             |        |
| SN:L4082963                           | HRS     | 3175.17                              |          |          |                           |           |           |             |        |
|                                       | AFL     | 1157                                 |          |          |                           |           |           |             |        |
| 256082 <sup>U</sup>                   |         | CREW CABINET LIFE VEST               |          |          |                           |           |           | Component   | ATA:25 |
| PN:63600-105                          | MOS/MSC | 04-Apr-19                            | O/C      | TSN 0    |                           |           |           |             |        |
| SN:L4428044                           | HRS     | 3175.17                              |          | TSN 0    |                           |           |           |             |        |
|                                       | AFL     | 1157                                 |          | TSN 0    |                           |           |           |             |        |
| 256082A <sup>U</sup>                  |         | RECERTIFY CREW CABINET LIFE VEST     |          |          |                           |           |           | Service     | ATA:25 |
| PN:63600-105                          | MOS     | 04-Apr-19                            | 120      |          | 04-Apr-29                 |           | 1710 d    |             |        |
| SN:L4428044                           | HRS     | 3175.17                              |          |          |                           |           |           |             |        |
|                                       | AFL     | 1157                                 |          |          |                           |           |           |             |        |
| 256083 <sup>U</sup>                   |         | NO. 1 LEFT CHAIR LIFE VEST           |          |          |                           |           |           | Component   | ATA:25 |
| PN:63600-105                          | MOS/MSC | 04-Apr-19                            | O/C      | TSN 0    |                           |           |           |             |        |
| SN:L4428045                           | HRS     | 3175.17                              |          | TSN 0    |                           |           |           |             |        |
|                                       | AFL     | 1157                                 |          | TSN 0    |                           |           |           |             |        |
| 256083A <sup>U</sup>                  |         | RECERTIFY NO. 1 LEFT CHAIR LIFE VEST |          |          |                           |           |           | Service     | ATA:25 |
| PN:63600-105                          | MOS     | 04-Apr-19                            | 120      |          | 04-Apr-29                 |           | 1710 d    |             |        |
| SN:L4428045                           | HRS     | 3175.17                              |          |          |                           |           |           |             |        |
|                                       | AFL     | 1157                                 |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b>   |         |           |          |          |                           |           |           |             |
| <b>256084<sup>U</sup> NO. 2 LEFT CHAIR LIFE VEST</b> Component ATA:25           |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS/MSC | 04-Apr-19 | O/C      | TSN 0    |                           |           |           |             |
| SN:L4428046   | HRS     | 3175.17   |          | TSN 0    |                           |           |           |             |
|   | AFL     | 1157      |          | TSN 0    |                           |           |           |             |
| <b>256084A<sup>U</sup> RECERTIFY NO. 2 LEFT CHAIR LIFE VEST</b> Service ATA:25  |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS     | 04-Apr-19 | 120      |          | 04-Apr-29                 |           | 1710 d    |             |
| SN:L4428046   | HRS     | 3175.17   |          |          |                           |           |           |             |
|   | AFL     | 1157      |          |          |                           |           |           |             |
| <b>256085<sup>U</sup> NO. 1 RIGHT CHAIR LIFE VEST</b> Component ATA:25          |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS/MSC | 04-Apr-19 | O/C      | TSN 0    |                           |           |           |             |
| SN:L4428043   | HRS     | 3175.17   |          | TSN 0    |                           |           |           |             |
|   | AFL     | 1157      |          | TSN 0    |                           |           |           |             |
| <b>256085A<sup>U</sup> RECERTIFY NO. 1 RIGHT CHAIR LIFE VEST</b> Service ATA:25 |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS     | 04-Apr-19 | 120      |          | 04-Apr-29                 |           | 1710 d    |             |
| SN:L4428043   | HRS     | 3175.17   |          |          |                           |           |           |             |
|   | AFL     | 1157      |          |          |                           |           |           |             |
| <b>256086<sup>U</sup> NO. 2 RIGHT CHAIR LIFE VEST</b> Component ATA:25          |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS/MSC | 04-Apr-19 | O/C      | TSN 0    |                           |           |           |             |
| SN:L4428040   | HRS     | 3175.17   |          | TSN 0    |                           |           |           |             |
|   | AFL     | 1157      |          | TSN 0    |                           |           |           |             |
| <b>256086A<sup>U</sup> RECERTIFY NO. 2 RIGHT CHAIR LIFE VEST</b> Service ATA:25 |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS     | 04-Apr-19 | 120      |          | 04-Apr-29                 |           | 1710 d    |             |
| SN:L4428040   | HRS     | 3175.17   |          |          |                           |           |           |             |
|   | AFL     | 1157      |          |          |                           |           |           |             |
| <b>256087<sup>U</sup> NO. 3 RIGHT CHAIR LIFE VEST</b> Component ATA:25          |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS/MSC | 04-Apr-19 | O/C      | TSN 0    |                           |           |           |             |
| SN:L4428039   | HRS     | 3175.17   |          | TSN 0    |                           |           |           |             |
|   | AFL     | 1157      |          | TSN 0    |                           |           |           |             |
| <b>256087A<sup>U</sup> RECERTIFY NO. 3 RIGHT CHAIR LIFE VEST</b> Service ATA:25 |         |           |          |          |                           |           |           |             |
|   | MOS     | 04-Apr-19 | 120      |          | 04-Apr-29                 |           | 1710 d    |             |
|   | HRS     | 3175.17   |          |          |                           |           |           |             |
|   | AFL     | 1157      |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b>                                     |         |           |          |          |                           |           |           |             |
| <b>256088<sup>U</sup> NO. 1 DIVAN LIFE VEST</b> Component ATA:25          |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS/MSC | 04-Apr-19 | O/C      | TSN 0    |                           |           |           |             |
| SN:L4428042   | HRS     | 3175.17   |          | TSN 0    |                           |           |           |             |
|   | AFL     | 1157      |          | TSN 0    |                           |           |           |             |
| <b>256088A<sup>U</sup> RECERTIFY NO. 1 DIVAN LIFE VEST</b> Service ATA:25 |         |           |          |          |                           |           |           |             |
|   | MOS     | 04-Apr-19 | 120      |          | 04-Apr-29                 |           | 1710 d    |             |
|   | HRS     | 3175.17   |          |          |                           |           |           |             |
|   | AFL     | 1157      |          |          |                           |           |           |             |
| <b>256089<sup>U</sup> NO. 2 DIVAN LIFE VEST</b> Component ATA:25          |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS/MSC | 04-Apr-19 | O/C      | TSN 0    |                           |           |           |             |
| SN:L4428041   | HRS     | 3175.17   |          | TSN 0    |                           |           |           |             |
|   | AFL     | 1157      |          | TSN 0    |                           |           |           |             |
| <b>256089A<sup>U</sup> RECERTIFY NO. 2 DIVAN LIFE VEST</b> Service ATA:25 |         |           |          |          |                           |           |           |             |
|   | MOS     | 04-Apr-19 | 120      |          | 04-Apr-29                 |           | 1710 d    |             |
|   | HRS     | 3175.17   |          |          |                           |           |           |             |
|   | AFL     | 1157      |          |          |                           |           |           |             |
| <b>256090<sup>U</sup> NO. 3 DIVAN LIFE VEST</b> Component ATA:25          |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS/MSC | 04-Apr-19 | O/C      | TSN 0    |                           |           |           |             |
| SN:L4428038   | HRS     | 3175.17   |          | TSN 0    |                           |           |           |             |
|   | AFL     | 1157      |          | TSN 0    |                           |           |           |             |
| <b>256090A<sup>U</sup> RECERTIFY NO. 3 DIVAN LIFE VEST</b> Service ATA:25 |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS     | 04-Apr-19 | 120      |          | 04-Apr-29                 |           | 1710 d    |             |
| SN:L4428038   | HRS     | 3175.17   |          |          |                           |           |           |             |
|   | AFL     | 1157      |          |          |                           |           |           |             |
| <b>256091<sup>U</sup> LAVATORY LIFE VEST</b> Component ATA:25             |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS/MSC | 04-Apr-19 | O/C      | TSN 0    |                           |           |           |             |
| SN:L4428047   | HRS     | 3175.17   |          | TSN 0    |                           |           |           |             |
|   | AFL     | 1157      |          | TSN 0    |                           |           |           |             |
| <b>256091A<sup>U</sup> RECERTIFY LAVATORY LIFE VEST</b> Service ATA:25    |         |           |          |          |                           |           |           |             |
| PN:63600-105  | MOS     | 04-Apr-19 | 120      |          | 04-Apr-29                 |           | 1710 d    |             |
| SN:L4428047   | HRS     | 3175.17   |          |          |                           |           |           |             |
|   | AFL     | 1157      |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |   |           |          |          |                           |           |           |             |        |
| 256097                                | DIGITAL INTERFACE UNIT                      |           |          |          |                           |           |           | Component   | ATA:25 |
| PN:925000-100                         | MOS/MSC                                     | 01-Jul-16 | O/C      |          |                           |           |           |             |        |
| SN:D01002542                          | HRS   | 2454.03   |          |          |                           |           |           |             |        |
| WC#: 25.140                           | AFL   | 889       |          |          |                           |           |           |             |        |
| PROC. REF: MMA 23-33-41               |   |           |          |          |                           |           |           |             |        |
| 256301                                | EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY |           |          |          |                           |           |           | Component   | ATA:25 |
| PN:452-0133                           | MOS/MSC                                     | 13-Mar-24 | O/C      | TSN 21   |                           |           |           |             |        |
| SN:396028-012                         | HRS   | 3890.9    |          | TSN 0    |                           |           |           |             |        |
|                                       | AFL   | 1481      |          | TSN 0    |                           |           |           |             |        |
| 257209 <sup>U</sup>                   | LIFE RAFT                                   |           |          |          |                           |           |           | Component   | ATA:25 |
| PN:RAF1210-305T1                      | MOS/MSC                                     | 14-Jul-22 | O/C      | TSO 0    |                           |           |           |             |        |
| SN:2307BBA/2279BBA                    | HRS   |           |          | TSO 0    |                           |           |           |             |        |
|                                       | AFL   |           |          | TSO 0    |                           |           |           |             |        |
| 257210 <sup>U</sup>                   | INSPECT LIFE RAFT                           |           |          |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS   | 11-Jul-24 | 12       |          | 31-Jul-25                 |           | 367 d     |             |        |
|                                       | HRS   | 3907.4    |          |          |                           |           |           |             |        |
|                                       | AFL   | 1491      |          |          |                           |           |           |             |        |
| 257220 <sup>U</sup>                   | REGISTER LIFE RAFT ELT                      |           |          |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS   | 11-Jul-24 | 24       |          | 31-Jul-26                 |           | 732 d     |             |        |
|                                       | HRS   | 3907.4    |          |          |                           |           |           |             |        |
|                                       | AFL   | 1491      |          |          |                           |           |           |             |        |
| 257230 <sup>U</sup>                   | LIFE RAFT CYLINDER HYDROSTATIC CHECK        |           |          |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS   | 14-Jun-22 | 60       |          | 30-Jun-27                 |           | 1066 d    |             |        |
|                                       | HRS   |           |          |          |                           |           |           |             |        |
|                                       | AFL   |           |          |          |                           |           |           |             |        |
| 257240 <sup>U</sup>                   | LIFE RAFT ELT                               |           |          |          |                           |           |           | Component   | ATA:25 |
| PN:500-12Y                            | MOS/MSC                                     | 14-Jun-22 | -        |          |                           |           |           |             |        |
| SN:15594                              | HRS   |           |          |          |                           |           |           |             |        |
|                                       | AFL   |           |          |          |                           |           |           |             |        |
| 257245 <sup>U</sup>                   | LIFE RAFT ELT BATTERIES - REPLACE           |           |          |          |                           |           |           | Service     | ATA:25 |
|                                       | MOS   | 14-Jun-22 | 60       |          | 30-Apr-27 (M)             |           | 1005 d    |             |        |
|                                       | HRS   |           |          |          |                           |           |           |             |        |
|                                       | AFL   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b>  |         |           |          |          |                           |           |           |             |
| <b>257515<sup>U</sup> (CALL) (WATER) (FLUSH) LAVATORY SWITCH PANEL</b> Component ATA:25      |         |           |          |          |                           |           |           |             |
| PN:2501-1-138  | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:3MBCJ   | HRS     | 4.7       |          |          |                           |           |           |             |
|  | AFL     | 4         |          |          |                           |           |           |             |
| <b>257516<sup>U</sup> (FASTEN SEAT BELT) (LAVATORY LIGHTS) SWITCH PANEL</b> Component ATA:25 |         |           |          |          |                           |           |           |             |
| PN:2501-1-142  | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:3MBCF   | HRS     | 4.7       |          |          |                           |           |           |             |
|  | AFL     | 4         |          |          |                           |           |           |             |
| <b>257521<sup>U</sup> FWD SEAT BAGGAGE FRONT SWITCH PANEL</b> Component ATA:25               |         |           |          |          |                           |           |           |             |
| PN:2501-1-140  | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:3MBVN   | HRS     | 4.7       |          |          |                           |           |           |             |
|  | AFL     | 4         |          |          |                           |           |           |             |
| <b>257522<sup>U</sup> R/H AFT COAT CLOSET SWITCH PANEL</b> Component ATA:25                  |         |           |          |          |                           |           |           |             |
| PN:2501-1-136  | MOS/MSC | 12-Oct-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:3MBCJ   | HRS     | 158.2     |          | TSN 0    |                           |           |           |             |
|  | AFL     | 73        |          | TSN 0    |                           |           |           |             |
| <b>258001<sup>U</sup> NO. 1 LEFT CHAIR</b> Component ATA:25                                  |         |           |          |          |                           |           |           |             |
| PN:303709-1NS2   | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:46743   | HRS     | 4.7       |          |          |                           |           |           |             |
|  | AFL     | 4         |          |          |                           |           |           |             |
| <b>258002<sup>U</sup> NO. 2 LEFT CHAIR</b> Component ATA:25                                  |         |           |          |          |                           |           |           |             |
| PN:303709-2NS2   | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:46745   | HRS     | 4.7       |          |          |                           |           |           |             |
|  | AFL     | 4         |          |          |                           |           |           |             |
| <b>258003<sup>U</sup> NO. 1 RIGHT CHAIR</b> Component ATA:25                                 |         |           |          |          |                           |           |           |             |
| PN:303709-2NS2   | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:46744   | HRS     | 4.7       |          |          |                           |           |           |             |
|  | AFL     | 4         |          |          |                           |           |           |             |
| <b>258004<sup>U</sup> NO. 2 RIGHT CHAIR</b> Component ATA:25                                 |         |           |          |          |                           |           |           |             |
| PN:303709-1BONS2   | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:46746   | HRS     | 4.7       |          |          |                           |           |           |             |
|  | AFL     | 4         |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W                                    | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---------|--|--------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 25 - EQUIPMENT/FURNISHINGS</b> |         |  |              |          |                           |           |           |             |        |
| 258005 <sup>U</sup>                   |         | NO. 3 RIGHT CHAIR                      |              |          |                           |           |           | Component   | ATA:25 |
| PN:303709-1D41N                       | MOS/MSC | 05-May-10                              | O/C          |          |                           |           |           |             |        |
| SN:46747                              | HRS     | 4.7                                    |              |          |                           |           |           |             |        |
|                                       | AFL     | 4                                      |              |          |                           |           |           |             |        |
| 258006 <sup>U</sup>                   |         | 3 SEAT DIVAN                           |              |          |                           |           |           | Component   | ATA:25 |
| PN:160080-15D2L5                      | MOS/MSC | 05-May-10                              | O/C          |          |                           |           |           |             |        |
| SN:46748                              | HRS     | 4.7                                    |              |          |                           |           |           |             |        |
|                                       | AFL     | 4                                      |              |          |                           |           |           |             |        |
| 258007 <sup>U</sup>                   |         | JUMPSEAT                               |              |          |                           |           |           | Component   | ATA:25 |
| PN:7202-981-67                        | MOS/MSC | 05-May-10                              | O/C          |          |                           |           |           |             |        |
| SN:NSN                                | HRS     | 4.7                                    |              |          |                           |           |           |             |        |
|                                       | AFL     | 4                                      |              |          |                           |           |           |             |        |
| 259050 <sup>U</sup>                   |         | DVD PLAYER                             |              |          |                           |           |           | Component   | ATA:25 |
| PN:866-0027-005                       | MOS/MSC | 03-Aug-21                              | O/C          | TSN 1    |                           |           |           |             |        |
| SN:725-1300                           | HRS     | 3405                                   |              | TSN 0    |                           |           |           |             |        |
|                                       | AFL     | 1243                                   |              | TSN 0    |                           |           |           |             |        |
| <b>ATA 26 - FIRE PROTECTION</b>       |         |  |              |          |                           |           |           |             |        |
| 251086 <sup>U</sup>                   |         | NO. 3 RIGHT H/P JACK                   |              |          |                           |           |           | Component   | ATA:26 |
| PN:2517-1-1                           | MOS/MSC | 05-May-10                              | O/C          |          |                           |           |           |             |        |
| SN:2Y65C                              | HRS     | 4.7                                    |              |          |                           |           |           |             |        |
|                                       | AFL     | 4                                      |              |          |                           |           |           |             |        |
| 260001 <sup>S</sup>                   |         | CHECK AFT ENGINE FIRE EXTINGUISHER     |              |          |                           |           |           | Service     | ATA:26 |
|                                       | MOS     | 25-Jul-24                              | 12 (+1m/-1m) |          |                           |           |           |             |        |
|                                       | HRS     | 3908.4                                 |              |          |                           |           |           |             |        |
| WC#: 26.020                           | AFL     | 1492                                   |              |          |                           |           |           |             |        |
|                                       |         |  |              |          |                           |           |           | PKG:43,94   |        |
| 260001 <sup>S</sup>                   |         | CHECK FORWARD ENGINE FIRE EXTINGUISHER |              |          |                           |           |           | Service     | ATA:26 |
|                                       | MOS     | 25-Jul-24                              | 12 (+1m/-1m) |          |                           |           |           |             |        |
|                                       | HRS     | 3908.4                                 |              |          |                           |           |           |             |        |
| WC#: 26.010                           | AFL     | 1492                                   |              |          |                           |           |           |             |        |
|                                       |         |  |              |          |                           |           |           | PKG:43,94   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval      | TSX/Adj.                              | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |
|---|---------|-----------|---------------|---------------------------------------|---------------------------|-----------|-------------|-------------|
| <b>ATA 26 - FIRE PROTECTION</b>   |         |           |               |                                       |                           |           |             |             |
| <b>260002<sup>S</sup> FUNCTIONAL TEST REAR EQUIPMENT BAY OVERHEAT DETECTION SYSTEM Service ATA:26</b> |         |           |               |                                       |                           |           |             |             |
|   | MOS     | 03-Aug-21 |               |                                       |                           |           |             |             |
|   | HRS     | 3405      | 800 (+40/-10) |                                       |                           |           |             |             |
| WC#: 26.035   | AFL     | 1243      |               |                                       |                           |           |             |             |
|   |         |           |               | PROC. REF: AMM 26-10-00               |                           |           |             | PKG:7,91    |
| <b>260003<sup>S</sup> WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER Service ATA:26</b>              |         |           |               |                                       |                           |           |             |             |
| PN:C354TS   | MOS     | 25-Jul-24 | 12 (+1m/-1m)  |                                       |                           |           |             |             |
| SN:F68185751  | HRS     | 3908.4    |               |                                       |                           |           |             |             |
| WC#: 26.080   | AFL     | 1492      |               |                                       |                           |           |             | PKG:46,94   |
| <b>260004<sup>S</sup> WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER Service ATA:26</b>                |         |           |               |                                       |                           |           |             |             |
| PN:C354   | MOS     | 25-Jul-24 | 12 (+1m/-1m)  |                                       |                           |           |             |             |
| SN:UNKNOWN  | HRS     | 3908.4    |               |                                       |                           |           |             |             |
| WC#: 26.075   | AFL     | 1492      |               |                                       |                           |           |             | PKG:48,94   |
| <b>260008 FUNCTIONAL TEST SMOKE DETECTION SYSTEM (IF FITTED) Service ATA:26</b>                       |         |           |               |                                       |                           |           |             |             |
|   | MOS     | 11-Jul-24 | 6 (+10%)      |                                       | 11-Jan-25                 | 29-Jan-25 | 166 d (+18) |             |
|   | HRS     | 3907.4    |               |                                       |                           |           |             |             |
| WC#: 26.115   | AFL     | 1491      |               |                                       |                           |           |             |             |
|   |         |           |               | PROC. REF: MMA 26-11-00               |                           |           |             |             |
| <b>260010<sup>S</sup> CHECK/FUNCTIONAL TEST APU FIRE EXTINGUISHER Service ATA:26</b>                  |         |           |               |                                       |                           |           |             |             |
|   | MOS     | 25-Jul-24 | 12 (+1m/-1m)  |                                       |                           |           |             |             |
|   | HRS     | 3908.4    |               |                                       |                           |           |             |             |
| WC#: 26.085   | AFL     | 1492      |               |                                       |                           |           |             | PKG:49,94   |
|   |         |           |               | PROC. REF: AMM 49-61-20, CMM 26-20-02 |                           |           |             |             |
| <b>261030 APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH Component ATA:26</b>                         |         |           |               |                                       |                           |           |             |             |
| PN:17343-62-600   | MOS/MSC | 31-Dec-19 | O/C           |                                       |                           |           |             |             |
| SN:1235   | HRS     | 3327.28   |               |                                       |                           |           |             |             |
| WC#: 26.120   | AFL     | 1211      |               |                                       |                           |           |             |             |
| <b>261031 APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH Component ATA:26</b>                         |         |           |               |                                       |                           |           |             |             |
| PN:17343-62-450   | MOS/MSC | 31-Dec-19 | O/C           |                                       |                           |           |             |             |
| SN:0906   | HRS     | 3327.28   |               |                                       |                           |           |             |             |
| WC#: 26.125   | AFL     | 1211      |               |                                       |                           |           |             |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit    | C/W   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |                         |
|---------------------------------|---------|---|----------|----------|---------------------------|-----------|-----------|-------------|-------------------------|
| <b>ATA 26 - FIRE PROTECTION</b> |         |   |          |          |                           |           |           |             |                         |
| <b>261032</b>                   |         | <b>APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH</b>           |          |          |                           |           |           |             | <b>Component ATA:26</b> |
| PN:17343-52-600                 | MOS/MSC | 31-Dec-19   | O/C      |          |                           |           |           |             |                         |
| SN:0905                         | HRS     | 3327.28   |          |          |                           |           |           |             |                         |
| WC#: 26.130                     | AFL     | 1211  |          |          |                           |           |           |             |                         |
| <b>261033</b>                   |         | <b>APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH</b>      |          |          |                           |           |           |             | <b>Component ATA:26</b> |
| PN:17343-62-450                 | MOS/MSC | 31-Dec-19   | O/C      |          |                           |           |           |             |                         |
| SN:BM251                        | HRS     | 3327.28   |          |          |                           |           |           |             |                         |
| WC#: 26.135                     | AFL     | 1211  |          |          |                           |           |           |             |                         |
| <b>261034</b>                   |         | <b>TEST APU ENCLOSURE HOT SECTION LOWER THERMAL SWITCH</b>      |          |          |                           |           |           |             | <b>Service ATA:26</b>   |
| PN:17343-62-600                 | MOS     | 31-Dec-19   | 60       |          | 31-Dec-24                 |           | 155 d     |             |                         |
| SN:1235                         | HRS     | 3327.28   |          |          |                           |           |           |             |                         |
| WC#: 26.120                     | AFL     | 1211  |          |          |                           |           |           |             |                         |
| <b>261035</b>                   |         | <b>TEST APU ENCLOSURE FUEL CONTROL AREA THERMAL SWITCH</b>      |          |          |                           |           |           |             | <b>Service ATA:26</b>   |
| PN:17343-62-450                 | MOS     | 31-Dec-19   | 60       |          | 31-Dec-24                 |           | 155 d     |             |                         |
| SN:0906                         | HRS     | 3327.28   |          |          |                           |           |           |             |                         |
| WC#: 26.125                     | AFL     | 1211  |          |          |                           |           |           |             |                         |
| <b>261036</b>                   |         | <b>TEST APU ENCLOSURE HOT SECTION UPPER THERMAL SWITCH</b>      |          |          |                           |           |           |             | <b>Service ATA:26</b>   |
| PN:17343-52-600                 | MOS     | 31-Dec-19   | 60       |          | 31-Dec-24                 |           | 155 d     |             |                         |
| SN:0905                         | HRS     | 3327.28   |          |          |                           |           |           |             |                         |
| WC#: 26.130                     | AFL     | 1211  |          |          |                           |           |           |             |                         |
| <b>261037</b>                   |         | <b>TEST APU ENCLOSURE STARTER/GENERATOR AREA THERMAL SWITCH</b> |          |          |                           |           |           |             | <b>Service ATA:26</b>   |
| PN:17343-62-450                 | MOS     | 31-Dec-19   | 60       |          | 31-Dec-24                 |           | 155 d     |             |                         |
| SN:BM251                        | HRS     | 3327.28   |          |          |                           |           |           |             |                         |
| WC#: 26.135                     | AFL     | 1211  |          |          |                           |           |           |             |                         |
| <b>261074</b>                   |         | <b>OVERHEAT DETECTION SWITCHES TEST</b>                         |          |          |                           |           |           |             | <b>Service ATA:26</b>   |
|                                 | MOS     | 31-Dec-19   | 60       |          | 31-Dec-24                 |           | 155 d     |             |                         |
|                                 | HRS     | 3327.28   |          |          |                           |           |           |             |                         |
| WC#: 26.030                     | AFL     | 1211  |          |          |                           |           |           |             |                         |
| <b>261171</b>                   |         | <b>NO. 1 ENGINE ZONE 1 FIRE DETECTOR</b>                        |          |          |                           |           |           |             | <b>Component ATA:26</b> |
| PN:3001-112-900-400             | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |             |                         |
| SN:92951                        | HRS     | 0   |          | TSN 0    |                           |           |           |             |                         |
| WC#: 26.050                     | AFL     | 0   |          | TSN 0    |                           |           |           |             |                         |
| PROC. REF: AMM 26-10-12         |         |   |          |          |                           |           |           |             |                         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 26 - FIRE PROTECTION</b> |                                    |           |          |          |                           |           |           |             |        |
| 261172                          | NO. 2 ENGINE ZONE 1 FIRE DETECTOR  |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:3001-112-900-400             | MOS/MSC                            | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:93573                        | HRS                                | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 26.055                     | AFL                                | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 26-10-12         |                                    |           |          |          |                           |           |           |             |        |
| 261183                          | NO. 1 ENGINE ZONE 2 FIRE DETECTOR  |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:3001-133-900-500-6           | MOS/MSC                            | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:92260                        | HRS                                | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 26.050                     | AFL                                | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 26-10-12         |                                    |           |          |          |                           |           |           |             |        |
| 261184                          | NO. 2 ENGINE ZONE 2 FIRE DETECTOR  |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:3001-133-900-500-6           | MOS/MSC                            | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:93231                        | HRS                                | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 26.055                     | AFL                                | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 26-10-12         |                                    |           |          |          |                           |           |           |             |        |
| 261187                          | NO. 1 ENGINE FIRE DETECTOR HARNESS |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:715RA0003-1                  | MOS/MSC                            | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:09-150262-24005              | HRS                                | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 26.161                     | AFL                                | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                    |           |          |          |                           |           |           |             |        |
| 261188                          | NO. 2 ENGINE FIRE DETECTOR HARNESS |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:715RA0003-1                  | MOS/MSC                            | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:09-150262-24001              | HRS                                | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 26.162                     | AFL                                | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                    |           |          |          |                           |           |           |             |        |
| 262001                          | ENGINE FORWARD FIRE EXTINGUISHER   |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:33200009-3                   | MOS/MSC                            | 14-May-20 | O/C      |          | TSO 0                     |           |           |             |        |
| SN:27402C1                      | HRS                                | 3357.57   |          |          | TSO 0                     |           |           |             |        |
| WC#: 26.010                     | AFL                                | 1222      |          |          | TSO 0                     |           |           |             |        |
| PROC. REF: AMM 26-20-12         |                                    |           |          |          |                           |           |           |             |        |
| 262002                          | ENGINE AFT FIRE EXTINGUISHER       |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:33200009-3                   | MOS/MSC                            | 06-Jun-18 | O/C      |          | TSO 0                     |           |           |             |        |
| SN:23794C1                      | HRS                                | 2965.25   |          |          | TSO 0                     |           |           |             |        |
| WC#: 26.020                     | AFL                                | 1073      |          |          | TSO 0                     |           |           |             |        |
| PROC. REF: AMM 26-20-12         |                                    |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit    | C/W   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |                  |
|---------------------------------|---------|---|----------|----------|---------------------------|-----------|-----------|-------------|------------------|
| <b>ATA 26 - FIRE PROTECTION</b> |         |   |          |          |                           |           |           |             |                  |
| <b>262025</b>                   |         | <b>HYDROSTATIC TEST ENGINE FORWARD FIRE EXTINGUISHER</b>                        |          |          |                           |           |           |             | Service ATA:26   |
| PN:33200009-3                   | MOS     | 19-Nov-19   | 120      |          | 19-Nov-29                 |           | 1939 d    |             |                  |
| SN:27402C1                      | HRS     |   |          |          |                           |           |           |             |                  |
| WC#: 26.010                     | AFL     |   |          |          |                           |           |           |             |                  |
| <b>262026</b>                   |         | <b>HYDROSTATIC TEST ENGINE AFT FIRE EXTINGUISHER</b>                            |          |          |                           |           |           |             | Service ATA:26   |
| PN:33200009-3                   | MOS     | 18-May-18   | 120      |          | 18-May-28                 |           | 1389 d    |             |                  |
| SN:23794C1                      | HRS     |   |          |          |                           |           |           |             |                  |
| WC#: 26.020                     | AFL     |   |          |          |                           |           |           |             |                  |
| <b>262027</b>                   |         | <b>FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE</b>                        |          |          |                           |           |           |             | Component ATA:26 |
| PN:30900000M                    | MOS/MSC | 31-Dec-19   | O/C      | TSN 0    |                           |           |           |             |                  |
| SN:0305WL                       | HRS     | 3327.28   |          | TSN 0    |                           |           |           |             |                  |
| WC#: 26.015                     | AFL     | 1211  |          | TSN 0    |                           |           |           |             |                  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |             |                  |
| <b>262028</b>                   |         | <b>AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE</b>                            |          |          |                           |           |           |             | Component ATA:26 |
| PN:30900000M                    | MOS/MSC | 31-Dec-19   | O/C      | TSN 0    |                           |           |           |             |                  |
| SN:0307WL                       | HRS     | 3327.28   |          | TSN 0    |                           |           |           |             |                  |
| WC#: 26.025                     | AFL     | 1211  |          | TSN 0    |                           |           |           |             |                  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |             |                  |
| <b>262029</b>                   |         | <b>FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE</b>                        |          |          |                           |           |           |             | Component ATA:26 |
| PN:30900000M                    | MOS/MSC | 31-Dec-19   | O/C      | TSN 0    |                           |           |           |             |                  |
| SN:0306WL                       | HRS     | 3327.28   |          | TSN 0    |                           |           |           |             |                  |
| WC#: 26.015                     | AFL     | 1211  |          | TSN 0    |                           |           |           |             |                  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |             |                  |
| <b>262030</b>                   |         | <b>AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE</b>                            |          |          |                           |           |           |             | Component ATA:26 |
| PN:30900000M                    | MOS/MSC | 31-Dec-19   | O/C      | TSN 0    |                           |           |           |             |                  |
| SN:0308WL                       | HRS     | 3327.28   |          | TSN 0    |                           |           |           |             |                  |
| WC#: 26.025                     | AFL     | 1211  |          | TSN 0    |                           |           |           |             |                  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |             |                  |
| <b>262037</b>                   |         | <b>REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)</b> |          |          |                           |           |           |             | Service ATA:26   |
| PN:30900000M                    | MOS     | 31-Dec-19   | 120      |          | 31-Dec-29                 |           | 1981 d    | LIFE LIMIT  |                  |
| SN:0305WL                       | HRS     |   |          |          |                           |           |           |             |                  |
| WC#: 26.015                     | AFL     |   |          |          |                           |           |           |             |                  |
| PROC. REF: AMM 26-20-22         |         |   |          |          |                           |           |           |             |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 26 - FIRE PROTECTION</b> |  |           |          |          |                           |           |           |             |        |
| 262038                          | REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (SERVICE LIFE)     |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:30900000M                    | MOS  | 31-Dec-19 | 120      |          | 31-Dec-29                 |           | 1981 d    | LIFE LIMIT  |        |
| SN:0307WL                       | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.025                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: AMM 26-20-22         |  |           |          |          |                           |           |           |             |        |
| 262049                          | REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE) |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:30900000M                    | MOS  | 31-Dec-19 | 120      |          | 31-Dec-29                 |           | 1981 d    | LIFE LIMIT  |        |
| SN:0306WL                       | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.015                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: AMM 26-20-22         |  |           |          |          |                           |           |           |             |        |
| 262050                          | REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (SERVICE LIFE)     |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:30900000M                    | MOS  | 31-Dec-19 | 120      |          | 31-Dec-29                 |           | 1981 d    | LIFE LIMIT  |        |
| SN:0308WL                       | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.025                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: AMM 26-20-22         |  |           |          |          |                           |           |           |             |        |
| 262061                          | REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)   |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:30900000M                    | MOS  | 18-Dec-19 | 180      |          | 18-Dec-34                 |           | 3794 d    | LIFE LIMIT  |        |
| SN:0305WL                       | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.015                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: AMM 26-20-22         |  |           |          |          |                           |           |           |             |        |
| 262062                          | REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD A CARTRIDGE (LIFE LIMIT)       |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:30900000M                    | MOS  | 18-Dec-19 | 180      |          | 18-Dec-34                 |           | 3794 d    | LIFE LIMIT  |        |
| SN:0307WL                       | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.025                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: AMM 26-20-22         |  |           |          |          |                           |           |           |             |        |
| 262073                          | REPLACE FORWARD ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT)   |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:30900000M                    | MOS  | 18-Dec-19 | 180      |          | 18-Dec-34                 |           | 3794 d    | LIFE LIMIT  |        |
| SN:0306WL                       | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.015                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: AMM 26-20-22         |  |           |          |          |                           |           |           |             |        |
| 262074                          | REPLACE AFT ENGINE FIRE EXTINGUISHER HEAD B CARTRIDGE (LIFE LIMIT)       |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:30900000M                    | MOS  | 18-Dec-19 | 180      |          | 18-Dec-34                 |           | 3794 d    | LIFE LIMIT  |        |
| SN:0308WL                       | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.025                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: AMM 26-20-22         |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 26 - FIRE PROTECTION</b> |  |           |          |          |                           |           |           |             |        |
| 262091                          | CABIN PORTABLE FIRE EXTINGUISHER                       |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:C354                         | MOS/MSC  | 25-Jul-24 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                      | HRS  | 3908.4    |          | TSN 0    |                           |           |           |             |        |
| WC#: 26.075                     | AFL  | 1492      |          | TSN 0    |                           |           |           |             |        |
| 262101 <sup>U</sup>             | MID-LIFE INSPECTION COCKPIT PORTABLE FIRE EXTINGUISHER |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:C354TS                       | MOS  | 20-Jun-22 | 72       |          | 20-Jun-28                 |           | 1422 d    |             |        |
| SN:F68185751                    | HRS  | 3511.6    |          |          |                           |           |           |             |        |
|                                 | AFL  | 1288      |          |          |                           |           |           |             |        |
| 262102 <sup>U</sup>             | MID-LIFE INSPECTION CABIN PORTABLE FIRE EXTINGUISHER   |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:C354                         | MOS  | 25-Jul-24 | 72       |          | 25-Jul-30                 |           | 2187 d    |             |        |
| SN:UNKNOWN                      | HRS  | 3908.4    |          |          |                           |           |           |             |        |
|                                 | AFL  | 1492      |          |          |                           |           |           |             |        |
| 262103                          | HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER      |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:C354                         | MOS  | 24-Jul-24 | 144      |          | 24-Jul-36                 |           | 4378 d    |             |        |
| SN:UNKNOWN                      | HRS  | 3908.4    |          |          |                           |           |           |             |        |
| WC#: 26.075                     | AFL  | 1492      |          |          |                           |           |           |             |        |
| 262109                          | COCKPIT PORTABLE FIRE EXTINGUISHER                     |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:C354TS                       | MOS/MSC  | 31-Dec-19 | O/C      | TSN 4    |                           |           |           |             |        |
| SN:F68185751                    | HRS  | 3327.28   |          | TSN 0    |                           |           |           |             |        |
| WC#: 26.080                     | AFL  | 1211      |          | TSN 0    |                           |           |           |             |        |
| 262121                          | HYDROSTATIC TEST COCKPIT PORTABLE FIRE EXTINGUISHER    |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:C354TS                       | MOS  | 01-Aug-19 | 144      | Adj -7   | 01-Jan-31                 |           | 2347 d    |             |        |
| SN:F68185751                    | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.080                     | AFL  |           |          |          |                           |           |           |             |        |
| 262127                          | APU FIRE EXTINGUISHER                                  |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:4190-01                      | MOS/MSC  | 20-Jun-22 | O/C      | TSO 0    |                           |           |           |             |        |
| SN:1951                         | HRS  | 3511.6    |          | TSO 0    |                           |           |           |             |        |
| WC#: 26.085                     | AFL  | 1288      |          | TSO 0    |                           |           |           |             |        |
|                                 |  |           |          |          | PROC. REF: AMM 49-61-20   |           |           |             |        |
| 262137                          | LEAK CHECK APU FIRE EXTINGUISHER                       |           |          |          |                           |           |           | Service     | ATA:26 |
|                                 | MOS/MSC  | 23-Dec-18 | O/C      |          |                           |           |           |             |        |
|                                 | HRS  | 3111.03   |          |          |                           |           |           |             |        |
| WC#: 26.085                     | AFL  | 1133      |          |          |                           |           |           |             |        |
|                                 |  |           |          |          | PROC. REF: CMM 26-20-02   |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 26 - FIRE PROTECTION</b> |  |           |          |          |                           |           |           |             |        |
| 262139                          | HYDROSTATIC TEST APU FIRE EXTINGUISHER   |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:4190-01                      | MOS  | 20-Jun-22 | 60       |          | 20-Jun-27                 |           | 1056 d    |             |        |
| SN:1951                         | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.085                     | AFL  |           |          |          |                           |           |           |             |        |
| 262143                          | APU FORWARD CARTRIDGE  |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:PN-UNKNOWN                   | MOS/MSC  | 20-Jun-22 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                      | HRS  | 3511.6    |          | TSN 0    |                           |           |           |             |        |
| WC#: 26.060                     | AFL  | 1288      |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF       |  |           |          |          |                           |           |           |             |        |
| 262145                          | REPLACE APU FORWARD CARTRIDGE (SERVICE LIFE)   |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:PN-UNKNOWN                   | MOS  | 20-Jun-22 | 120      |          | 20-Jun-32                 |           | 2883 d    | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.060                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: CMM 26-20-02         |  |           |          |          |                           |           |           |             |        |
| 262157                          | REPLACE APU FORWARD CARTRIDGE (LIFE LIMIT)   |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:PN-UNKNOWN                   | MOS  | 08-Jan-18 | 180      |          | 08-Jan-33                 |           | 3085 d    | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.060                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: CMM 26-20-02         |  |           |          |          |                           |           |           |             |        |
| 262190                          | FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED                      |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:A1003(1)                     | MOS/MSC  | 07-Apr-23 | O/C      | TSN 2    |                           |           |           |             |        |
| SN:LOT F1172                    | HRS  | 3710.7    |          | TSN 0    |                           |           |           |             |        |
| WC#: 26.100                     | AFL  | 1397      |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF       |  |           |          |          |                           |           |           |             |        |
| 262195                          | AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED                          |           |          |          |                           |           |           | Component   | ATA:26 |
| PN:A1003(1)                     | MOS/MSC  | 07-Apr-23 | O/C      | TSN 2    |                           |           |           |             |        |
| SN:LOT F1172                    | HRS  | 3710.7    |          | TSN 0    |                           |           |           |             |        |
| WC#: 26.105                     | AFL  | 1397      |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF       |  |           |          |          |                           |           |           |             |        |
| 262199                          | REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (LIFE LIMIT) |           |          |          |                           |           |           | Service     | ATA:26 |
| PN:A1003(1)                     | MOS  | 01-Feb-23 | 48       |          | 01-Feb-27                 |           | 917 d     | LIFE LIMIT  |        |
| SN:LOT F1172                    | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 26.100                     | AFL  |           |          |          |                           |           |           |             |        |
| PROC. REF: AMM 26-20-41         |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 26 - FIRE PROTECTION</b>   |         |           |          |          |                           |           |           |             |
| <b>262200 REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (LIFE LIMIT) Service ATA:26</b>       |         |           |          |          |                           |           |           |             |
| PN:A1003(1)   | MOS     | 01-Feb-23 | 48       |          | 01-Feb-27                 |           | 917 d     | LIFE LIMIT  |
| SN:LOT F1172  | HRS     |           |          |          |                           |           |           |             |
| WC#: 26.105   | AFL     |           |          |          |                           |           |           |             |
| PROC. REF: AMM 26-20-41   |         |           |          |          |                           |           |           |             |
| <b>262201 REPLACE FORWARD EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (SERVICE LIFE) Service ATA:26</b> |         |           |          |          |                           |           |           |             |
| PN:A1003(1)   | MOS     | 07-Apr-23 | 36       |          | 07-Apr-26                 |           | 617 d     | LIFE LIMIT  |
| SN:LOT F1172  | HRS     |           |          |          |                           |           |           |             |
| WC#: 26.100   | AFL     |           |          |          |                           |           |           |             |
| PROC. REF: AMM 26-20-41   |         |           |          |          |                           |           |           |             |
| <b>262202 REPLACE AFT EXTINGUISHER GONE INDICATION FUSE CARTRIDGE, ENGINE AND EXTERNAL BAGGAGE UNIT IF FITTED (SERVICE LIFE) Service ATA:26</b>     |         |           |          |          |                           |           |           |             |
| PN:A1003(1)   | MOS     | 07-Apr-23 | 36       |          | 07-Apr-26                 |           | 617 d     | LIFE LIMIT  |
| SN:LOT F1172  | HRS     |           |          |          |                           |           |           |             |
| WC#: 26.105   | AFL     |           |          |          |                           |           |           |             |
| PROC. REF: AMM 26-20-41   |         |           |          |          |                           |           |           |             |
| <b>262301 SMOKE DETECTOR AMPLIFIER Component ATA:26</b>   |         |           |          |          |                           |           |           |             |
| PN:PN   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 26.070   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: MMA 26-11-00, MMA 26-11-00   |         |           |          |          |                           |           |           |             |
| <b>262307 FORWARD BAGGAGE COMPARTMENT SMOKE DETECTOR Component ATA:26</b>   |         |           |          |          |                           |           |           |             |
| PN:473597-14  | MOS/MSC | 05-May-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:1886   | HRS     | 4.7       |          | TSN 0    |                           |           |           |             |
| WC#: 26.110   | AFL     | 4         |          | TSN 0    |                           |           |           |             |
| PROC. REF: MMA 26-11-00, MMA 26-11-00   |         |           |          |          |                           |           |           |             |
| <b>262308 AFT BAGGAGE COMPARTMENT SMOKE DETECTOR Component ATA:26</b>   |         |           |          |          |                           |           |           |             |
| PN:473597-14  | MOS/MSC | 05-May-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:1881   | HRS     | 4.7       |          | TSN 0    |                           |           |           |             |
| WC#: 26.110   | AFL     | 4         |          | TSN 0    |                           |           |           |             |
| PROC. REF: MMA 26-11-00, MMA 26-11-00   |         |           |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit  | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---|-----------|----------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 26 - FIRE PROTECTION</b>       |   |           |                |          |                           |           |           |             |        |
| 262309                                | VANITY SMOKE DETECTOR                                   |           |                |          |                           |           |           | Component   | ATA:26 |
| PN:473597-14                          | MOS/MSC   | 05-May-10 | O/C            | TSN 0    |                           |           |           |             |        |
| SN:1887                               | HRS   | 4.7       |                | TSN 0    |                           |           |           |             |        |
| WC#: 26.110                           | AFL   | 4         |                | TSN 0    |                           |           |           |             |        |
| PROC. REF: MMA 26-11-00, MMA 26-11-00 |   |           |                |          |                           |           |           |             |        |
| <b>ATA 27 - FLIGHT CONTROLS</b>       |   |           |                |          |                           |           |           |             |        |
| 270001                                | OPERATIONAL TEST AIRBRAKE SELECTOR LEVER BAULK          |           |                |          |                           |           |           | Service     | ATA:27 |
|                                       | MOS/MSC   | 05-May-10 | N/R            |          |                           |           |           |             |        |
|                                       | HRS   | 0         |                |          |                           |           |           |             |        |
| WC#: 27.265                           | AFL   | 0         |                |          |                           |           |           |             |        |
| PROC. REF: AMM 27-61-03, AMS 5-20-08  |   |           |                |          |                           |           |           |             |        |
| 270002 <sup>S</sup>                   | INSPECT LEFT WING FLAP VANE INNER                       |           |                |          |                           |           |           | Service     | ATA:27 |
|                                       | MOS   | 06-Jun-18 |                |          |                           |           |           |             |        |
|                                       | HRS   | 2965.25   | 1600 (+50/-50) |          |                           |           |           |             |        |
| WC#: 27.490                           | AFL   | 1073      |                |          |                           |           |           | PKG:27,92   |        |
| 270003 <sup>S</sup>                   | INSPECT LEFT WING FLAP SCREWJACKS SCREW THREADS         |           |                |          |                           |           |           | Service     | ATA:27 |
|                                       | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                       | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.495                           | AFL   | 1243      |                |          |                           |           |           | PKG:15,91   |        |
| 270004 <sup>S</sup>                   | FUNCTIONAL TEST STALL WARNING AND IDENTIFICATION SYSTEM |           |                |          |                           |           |           | Service     | ATA:27 |
|                                       | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                       | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.120                           | AFL   | 1243      |                |          |                           |           |           | PKG:8,91    |        |
| PROC. REF: AMM 27-33-00               |   |           |                |          |                           |           |           |             |        |
| 270008 <sup>S</sup>                   | FUNCTIONAL TEST RUDDER BIAS STRUT HEATER MUFFS          |           |                |          |                           |           |           | Service     | ATA:27 |
|                                       | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                       | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.060                           | AFL   | 1243      |                |          |                           |           |           | PKG:8,91    |        |
| PROC. REF: AMM 27-20-00               |   |           |                |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit   | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|---------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |  |           |               |          |                           |           |           |             |        |
| 270011 <sup>S</sup>             | INSPECT GUST LOCKS/AILERONS AND ELEVATORS            |           |               |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 27.415                     | AFL  | 1243      |               |          |                           |           |           | PKG:10,91   |        |
| 270012 <sup>S</sup>             | CHECK AND INSPECT RUDDER TRIM TAB AND ANTI SERVO TAB |           |               |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 27.450                     | AFL  | 1243      |               |          |                           |           |           | PKG:14,91   |        |
|                                 |  |           |               |          | PROC. REF: AMM 27-20-00   |           |           |             |        |
| 270013 <sup>S</sup>             | CHECK AND INSPECT ELEVATORS AND TRIM TABS            |           |               |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 27.485                     | AFL  | 1243      |               |          |                           |           |           | PKG:14,91   |        |
|                                 |  |           |               |          | PROC. REF: AMM 27-30-00   |           |           |             |        |
| 270014 <sup>S</sup>             | INSPECT RUDDER AND ELEVATORS PRIMARY SURFACES        |           |               |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 27.420                     | AFL  | 1243      |               |          |                           |           |           | PKG:14,91   |        |
| 270015 <sup>S</sup>             | OPERATIONAL CHECK LEFT AILERON PRIMARY SURFACES      |           |               |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 27.425                     | AFL  | 1243      |               |          |                           |           |           | PKG:15,91   |        |
| 270016 <sup>S</sup>             | CHECK AND INSPECT LEFT AILERON TRIM AND SERVO TABS   |           |               |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 27.435                     | AFL  | 1243      |               |          |                           |           |           | PKG:15,91   |        |
|                                 |  |           |               |          | PROC. REF: AMM 27-10-00   |           |           |             |        |
| 270017 <sup>S</sup>             | CHECK LEFT FLAP SCREWJACK AND REDUCTION GEARBOX      |           |               |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 27.500                     | AFL  | 1243      |               |          |                           |           |           | PKG:15,91   |        |
|                                 |  |           |               |          | PROC. REF: AMM 27-50-141  |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit  | C/W       | Interval      | TSX/Adj.                 | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|---|-----------|---------------|--------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |   |           |               |                          |                           |           |           |             |        |
| 270018 <sup>S</sup>             | INSPECT LEFT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES |           |               |                          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 27.550                     | AFL   | 1243      |               |                          |                           |           |           |             |        |
|                                 |   |           |               |                          |                           |           |           | PKG:15,91   |        |
| 270019 <sup>S</sup>             | CHECK FLAP CONTROL UNIT                                 |           |               |                          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 27.525                     | AFL   | 1243      |               |                          |                           |           |           |             |        |
|                                 |   |           |               | PROC. REF: AMM 27-50-121 |                           |           |           | PKG:15,91   |        |
| 270020 <sup>S</sup>             | OPERATE FLAP CONTROL UNIT                               |           |               |                          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 27.520                     | AFL   | 1243      |               |                          |                           |           |           |             |        |
|                                 |   |           |               |                          |                           |           |           | PKG:15,91   |        |
| 270021 <sup>S</sup>             | INSPECT LEFT FLAP DRIVE SHAFTS                          |           |               |                          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 27.510                     | AFL   | 1243      |               |                          |                           |           |           |             |        |
|                                 |   |           |               |                          |                           |           |           | PKG:15,91   |        |
| 270022 <sup>S</sup>             | OPERATIONAL CHECK RIGHT AILERON PRIMARY SURFACES        |           |               |                          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 27.425                     | AFL   | 1243      |               |                          |                           |           |           |             |        |
|                                 |   |           |               |                          |                           |           |           | PKG:16,91   |        |
| 270023 <sup>S</sup>             | CHECK AND INSPECT RIGHT AILERON SERVO TABS              |           |               |                          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 27.435                     | AFL   | 1243      |               |                          |                           |           |           |             |        |
|                                 |   |           |               | PROC. REF: AMM 27-10-00  |                           |           |           | PKG:16,91   |        |
| 270024 <sup>S</sup>             | CHECK RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX        |           |               |                          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 27.500                     | AFL   | 1243      |               |                          |                           |           |           |             |        |
|                                 |   |           |               | PROC. REF: AMM 27-50-141 |                           |           |           | PKG:16,91   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|----------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |  |           |                |          |                           |           |           |             |        |
| 270025 <sup>S</sup>             | INSPECT RIGHT FLAP SYNCHRONIZATION SYSTEM CONTROL CABLES |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.550                     | AFL  | 1243      |                |          |                           |           |           | PKG:16,91   |        |
| 270026 <sup>S</sup>             | INSPECT RIGHT FLAP DRIVE SHAFTS                          |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.510                     | AFL  | 1243      |                |          |                           |           |           | PKG:16,91   |        |
| 270027 <sup>S</sup>             | FUNCTIONAL TEST FLAP CONTROL SYSTEM                      |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.200                     | AFL  | 1243      |                |          |                           |           |           | PKG:18,91   |        |
|                                 |  |           |                |          | PROC. REF: AMM 27-50-02   |           |           |             |        |
| 270028 <sup>S</sup>             | FUNCTIONAL TEST AIRBRAKE AND LIFT DUMP SYSTEM            |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.260                     | AFL  | 1243      |                |          |                           |           |           | PKG:18,91   |        |
|                                 |  |           |                |          | PROC. REF: AMM 27-61-02   |           |           |             |        |
| 270030 <sup>S</sup>             | CHECK ELEVATOR TRIM SERVO                                |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |          |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |           |             |        |
| WC#: 27.095                     | AFL  | 1073      |                |          |                           |           |           | PKG:20,92   |        |
| 270032 <sup>S</sup>             | CHECK AILERON AUTOPILOT SERVO CONTROL CABLES             |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |          |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |           |             |        |
| WC#: 27.440                     | AFL  | 1073      |                |          |                           |           |           | PKG:22,92   |        |
|                                 |  |           |                |          | PROC. REF: AMM 27-00-00   |           |           |             |        |
| 270033 <sup>S</sup>             | INSPECT ELEVATOR CONTROL SYSTEM BALANCE/FEEL SPRING      |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |          |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |           |             |        |
| WC#: 27.100                     | AFL  | 1073      |                |          |                           |           |           | PKG:22,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit  | C/W       | Interval       | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|---|-----------|----------------|-------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |   |           |                |                         |                           |           |           |             |        |
| 270034 <sup>S</sup>             | CHECK ELEVATOR PRIMARY CONTROL CABLES                   |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.460                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM 27-30-00 |                           |           |           | PKG:23,92   |        |
| 270035 <sup>S</sup>             | CHECK FLAP CONTROL CABLES                               |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.540                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM 27-50-02 |                           |           |           | PKG:23,92   |        |
| 270036 <sup>S</sup>             | CHECK ELEVATOR PRIMARY AND ELEVATOR TRIM CONTROL CABLES |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.465                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM 27-30-00 |                           |           |           | PKG:25,92   |        |
| 270037 <sup>S</sup>             | CHECK RUDDER PRIMARY AND RUDDER TRIM CONTROL CABLES     |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.455                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM 27-20-00 |                           |           |           | PKG:25,92   |        |
| 270038 <sup>S</sup>             | CHECK ELEVATOR AUTOPILOT SERVO CONTROL CABLES           |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.475                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM NO REF 1 |                           |           |           | PKG:25,92   |        |
| 270039 <sup>S</sup>             | CHECK RUDDER AUTOPILOT SERVO CONTROL CABLES             |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.445                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM NO REF 1 |                           |           |           | PKG:25,92   |        |
| 270040 <sup>S</sup>             | CHECK ELEVATOR AUTOPILOT TRIM-SERVO CONTROL CABLES      |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.480                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM 27-30-00 |                           |           |           | PKG:25,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit   | C/W       | Interval       | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|----------------|-------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |  |           |                |                         |                           |           |           |             |        |
| 270041 <sup>S</sup>             | INSPECT ELEVATOR TRIM CABLES                       |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.470                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 27-30-00 |                           |           |           | PKG:26,92   |        |
| 270042 <sup>S</sup>             | CHECK LEFT AILERON PRIMARY AND TRIM CONTROL CABLES |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.430                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 27-10-00 |                           |           |           | PKG:27,92   |        |
| 270043 <sup>S</sup>             | INSPECT LEFT FLAP DRIVE SHAFT UNIVERSAL JOINT      |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.565                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                |                         |                           |           |           | PKG:27,92   |        |
| 270044 <sup>S</sup>             | CHECK LEFT FLAP BEVEL DRIVE ASSEMBLY               |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.535                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                |                         |                           |           |           | PKG:27,92   |        |
| 270045 <sup>S</sup>             | CHECK FLAP CONTROL UNIT BAULK RELEASE CABLE        |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.515                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 27-50-02 |                           |           |           | PKG:27,92   |        |
| 270046 <sup>S</sup>             | CHECK FLAP/AIRBRAKE BAULK BOBBIN                   |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.575                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 27-50-02 |                           |           |           | PKG:27,92   |        |
| 270047 <sup>S</sup>             | CHECK FLAP SPRING DRUM PULLEY-LEVER                |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.555                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                |                         |                           |           |           | PKG:27,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit  | C/W       | Interval       | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|---|-----------|----------------|-------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |   |           |                |                         |                           |           |           |             |        |
| 270048 <sup>S</sup>             | CHECK LEFT FLAP SCREWJACK/REDUCTION GEARBOX         |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.505                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM NO REF 1 |                           |           |           | PKG:27,92   |        |
| 270049 <sup>S</sup>             | CHECK LEFT FLAP SYNCHRONIZING SYSTEM                |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.530                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM 27-50-02 |                           |           |           | PKG:27,92   |        |
| 270050 <sup>S</sup>             | CHECK LEFT AIRBRAKE CONTROL CABLES                  |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.570                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM 27-61-02 |                           |           |           | PKG:27,92   |        |
| 270051 <sup>S</sup>             | CHECK RIGHT AILERON PRIMARY AND TRIM CONTROL CABLES |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.430                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM 27-10-00 |                           |           |           | PKG:28,92   |        |
| 270052 <sup>S</sup>             | INSPECT RIGHT FLAP DRIVE SHAFT UNIVERSAL JOINT      |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.565                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                |                         |                           |           |           | PKG:28,92   |        |
| 270053 <sup>S</sup>             | CHECK RIGHT FLAP BEVEL DRIVE ASSEMBLY               |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.535                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                |                         |                           |           |           | PKG:28,92   |        |
| 270054 <sup>S</sup>             | CHECK RIGHT FLAP SCREWJACK/REDUCTION GEARBOX        |           |                |                         |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 27.505                     | AFL   | 1073      |                |                         |                           |           |           |             |        |
|                                 |   |           |                | PROC. REF: AMM NO REF 1 |                           |           |           | PKG:28,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit   | C/W       | Interval        | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|-----------------|---|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |  |           |                 |   |                           |           |           |             |        |
| 270055 <sup>S</sup>             | CHECK RIGHT FLAP SYNCHRONIZING SYSTEM                                      |           |                 |   |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                 |   |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50)  |   |                           |           |           |             |        |
| WC#: 27.530                     | AFL  | 1073      |                 |   |                           |           |           |             |        |
|                                 |  |           |                 | PROC. REF: AMM 27-50-02   |                           |           |           | PKG:28,92   |        |
| 270056 <sup>S</sup>             | CHECK RIGHT AIRBRAKE CONTROL CABLES  |           |                 |   |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                 |   |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50)  |   |                           |           |           |             |        |
| WC#: 27.570                     | AFL  | 1073      |                 |   |                           |           |           |             |        |
|                                 |  |           |                 | PROC. REF: AMM 27-61-02   |                           |           |           | PKG:28,92   |        |
| 270057 <sup>S</sup>             | CHECK FLAP CONTROL FORWARD SPRING STRUT                                    |           |                 |   |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                 |   |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 3200 (+150/-50) |   |                           |           |           |             |        |
| WC#: 27.560                     | AFL  | 1073      |                 |   |                           |           |           |             |        |
|                                 |  |           |                 | PROC. REF: AMM 27-50-02   |                           |           |           | PKG:34,93   |        |
| 270058 <sup>S</sup>             | CHECK FLAP CONTROL INPUT-CIRCUIT   |           |                 |   |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                 |   |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 3200 (+150/-50) |   |                           |           |           |             |        |
| WC#: 27.210                     | AFL  | 1073      |                 |   |                           |           |           |             |        |
|                                 |  |           |                 | PROC. REF: AMM 27-50-02   |                           |           |           | PKG:34,93   |        |
| 270059 <sup>S</sup>             | INSPECT CONTROL CABLE PRESSURE SEALS AT REAR PRESSURE BULKHEAD             |           |                 |   |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 25-Jul-24 | 12 (+1m/-1m)    |   |                           |           |           |             |        |
|                                 | HRS  | 3908.4    |                 |   |                           |           |           |             |        |
| WC#: 27.545                     | AFL  | 1492      |                 |   |                           |           |           |             |        |
|                                 |  |           |                 |   |                           |           |           | PKG:49,94   |        |
| 270060 <sup>S</sup>             | REPLACE FLAP AUXILIARY HYDRAULIC SYSTEM SUPPLY TO FLAP CONTROL UNIT FILTER |           |                 |   |                           |           |           | Service     | ATA:27 |
|                                 | MOS  | 06-Jun-18 |                 |   |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 3200 (+150/-50) |   |                           |           |           |             |        |
| WC#: 27.215                     | AFL  | 1073      |                 |   |                           |           |           |             |        |
|                                 |  |           |                 |   |                           |           |           | PKG:40,93   |        |
| 270061                          | CHECK FLIGHT CONTROL CABLES TENSION  |           |                 |   |                           |           |           | Service     | ATA:27 |
|                                 | MOS/MS   | 15-Mar-11 | O/C             |   |                           |           |           |             |        |
|                                 | HRS  |           |                 |   |                           |           |           |             |        |
| WC#: 27.010                     | AFL  |           |                 |   |                           |           |           |             |        |
|                                 |  |           |                 | PROC. REF: AMM 27-30-00, AMM 27-10-00, AMM 27-20-00, AMM 27-61-02 |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit  | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|---|-----------|----------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |   |           |                |          |                           |           |           |             |        |
| 270063                          | LUBRICATE/CLEAN SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)          |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS/MSC   | 16-Mar-10 | N/R            |          |                           |           |           |             |        |
|                                 | HRS   | 0         |                |          |                           |           |           |             |        |
| WC#: 27.030                     | AFL   | 0         |                |          |                           |           |           |             |        |
| 270064 <sup>S</sup>             | INSPECT RIGHT WING FLAP VANE INNER                                      |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 06-Jun-18 |                |          |                           |           |           |             |        |
|                                 | HRS   | 2965.25   | 1600 (+50/-50) |          |                           |           |           |             |        |
| WC#: 27.490                     | AFL   | 1073      |                |          |                           |           |           |             |        |
|                                 |   |           |                |          |                           |           |           | PKG:28,92   |        |
| 270065 <sup>S</sup>             | INSPECT RIGHT WING FLAP SCREWJACKS SCREW THREADS                        |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.495                     | AFL   | 1243      |                |          |                           |           |           |             |        |
|                                 |   |           |                |          |                           |           |           | PKG:16,91   |        |
| 270066 <sup>S</sup>             | INSPECT LEFT AILERON CONTROL CABLE PRESSURE SEALS                       |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.600                     | AFL   | 1243      |                |          |                           |           |           |             |        |
|                                 |   |           |                |          |                           |           |           | PKG:15,91   |        |
| 270067 <sup>S</sup>             | INSPECT RIGHT AILERON CONTROL CABLE PRESSURE SEALS                      |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 27.605                     | AFL   | 1243      |                |          |                           |           |           |             |        |
|                                 |   |           |                |          |                           |           |           | PKG:16,91   |        |
| 270068                          | LUBRICATE/CLEAN AILERON SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001)  |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS/MSC   | 05-May-10 | N/R            |          |                           |           |           |             |        |
|                                 | HRS   | 0         |                |          |                           |           |           |             |        |
| WC#: 27.610                     | AFL   | 0         |                |          |                           |           |           |             |        |
| 270069                          | LUBRICATE/CLEAN ELEVATOR SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001) |           |                |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS/MSC   | 05-May-10 | N/R            |          |                           |           |           |             |        |
|                                 | HRS   | 0         |                |          |                           |           |           |             |        |
| WC#: 27.615                     | AFL   | 0         |                |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit  | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|---|-----------|--------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |   |           |              |          |                           |           |           |             |        |
| 270070                          | LUBRICATE/CLEAN RUDDER SERVOMOTOR ASSEMBLY SVO-85B (P/N 622-5027-001) |           |              |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS/MSC   | 05-May-10 | N/R          |          |                           |           |           |             |        |
|                                 | HRS   | 0         |              |          |                           |           |           |             |        |
| WC#: 27.620                     | AFL   | 0         |              |          |                           |           |           |             |        |
| 270071 <sup>S</sup>             | INSPECT RUDDER TRIM JACK  |           |              |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 20-Jun-22 | 48 (+2m/-2m) |          |                           |           |           |             |        |
|                                 | HRS   | 3511.6    |              |          |                           |           |           |             |        |
|                                 | AFL   | 1288      |              |          |                           |           |           |             |        |
|                                 |   |           |              |          | PROC. REF: AMM 27-20-111  |           |           | PKG:96      |        |
| 270072 <sup>S</sup>             | INSPECT ELEVATOR TRIM JACK  |           |              |          |                           |           |           | Service     | ATA:27 |
|                                 | MOS   | 20-Jun-22 | 48 (+2m/-2m) |          |                           |           |           |             |        |
|                                 | HRS   | 3511.6    |              |          |                           |           |           |             |        |
|                                 | AFL   | 1288      |              |          |                           |           |           |             |        |
|                                 |   |           |              |          | PROC. REF: AMM 27-30-51   |           |           | PKG:96      |        |
| 270100                          | LEFT CONTROL COLUMN   |           |              |          |                           |           |           | Component   | ATA:27 |
| PN:25-8CF53-217A                | MOS/MSC   | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |        |
| SN:PPLS/DH/2641                 | HRS   | 0         |              | TSN 0    |                           |           |           |             |        |
| WC#: 27.015                     | AFL   | 0         |              | TSN 0    |                           |           |           |             |        |
|                                 |   |           |              |          | PROC. REF: AMM 27-10-11   |           |           |             |        |
| 270102                          | RIGHT CONTROL COLUMN  |           |              |          |                           |           |           | Component   | ATA:27 |
| PN:25-8CF55-215A                | MOS/MSC   | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |        |
| SN:PPLS/DH/2632                 | HRS   | 0         |              | TSN 0    |                           |           |           |             |        |
| WC#: 27.015                     | AFL   | 0         |              | TSN 0    |                           |           |           |             |        |
|                                 |   |           |              |          | PROC. REF: AMM 27-10-11   |           |           |             |        |
| 271001                          | LEFT AILERON  |           |              |          |                           |           |           | Component   | ATA:27 |
| PN:25-8WG2001-3A                | MOS/MSC   | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |        |
| SN:DHB2199                      | HRS   | 0         |              | TSN 0    |                           |           |           |             |        |
| WC#: 27.020                     | AFL   | 0         |              | TSN 0    |                           |           |           |             |        |
|                                 |   |           |              |          | PROC. REF: AMM 27-10-31   |           |           |             |        |
| 271002                          | RIGHT AILERON   |           |              |          |                           |           |           | Component   | ATA:27 |
| PN:25-8WG2001-4A                | MOS/MSC   | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |        |
| SN:DHB2188                      | HRS   | 0         |              | TSN 0    |                           |           |           |             |        |
| WC#: 27.020                     | AFL   | 0         |              | TSN 0    |                           |           |           |             |        |
|                                 |   |           |              |          | PROC. REF: AMM 27-10-31   |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                 | Unit    | C/W                                | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|---|---------|------------------------------------|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 27 - FLIGHT CONTROLS</b>         |         |                                    |          |          |                           |           |           |                  |               |
| <b>271025</b>                           |         | <b>AILERON TRIM SCREWJACK</b>      |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-8CW49-43A                         | MOS/MSC | 16-Mar-10                          | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:BPEB/DHB/28852                       | HRS     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.025                             | AFL     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 27-10-71                 |         |                                    |          |          |                           |           |           |                  |               |
| <b>272001</b>                           |         | <b>RUDDER</b>                      |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-8TR105-11A                        | MOS/MSC | 16-Mar-10                          | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:SD-DH-287                            | HRS     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.045                             | AFL     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 27-20-23                 |         |                                    |          |          |                           |           |           |                  |               |
| <b>272019</b>                           |         | <b>RUDDER TRIM JACK</b>            |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:PN                                   | MOS/MSC | 16-Mar-10                          | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                              | HRS     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.050                             | AFL     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 27-20-111, AMM 27-20-111 |         |                                    |          |          |                           |           |           |                  |               |
| <b>272020</b>                           |         | <b>RUDDER GEARED TAB</b>           |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25TR209AF                            | MOS/MSC | 16-Mar-10                          | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:CAVP09H005                           | HRS     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.125                             | AFL     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |                                    |          |          |                           |           |           |                  |               |
| <b>272021</b>                           |         | <b>RUDDER TRIM TAB</b>             |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25TR221AF                            | MOS/MSC | 16-Mar-10                          | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:CAVP09G011                           | HRS     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.285                             | AFL     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |                                    |          |          |                           |           |           |                  |               |
| <b>272022</b>                           |         | <b>LEFT RUDDER PEDAL ASSEMBLY</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-8CF549-1A                         | MOS/MSC | 16-Mar-10                          | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:BPEB/DHB/28711                       | HRS     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.065                             | AFL     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 27-20-35                 |         |                                    |          |          |                           |           |           |                  |               |
| <b>272023</b>                           |         | <b>RIGHT RUDDER PEDAL ASSEMBLY</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-8CF549-2A                         | MOS/MSC | 16-Mar-10                          | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:BPEB/DHB/28720                       | HRS     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.065                             | AFL     | 0                                  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 27-20-35                 |         |                                    |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |                                     |           |          |          |                           |           |           |             |        |
| 272049                          | LEFT RUDDER BIAS STRUT              |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:259W03486-603                | MOS/MSC                             | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:HHB162                       | HRS                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.055                     | AFL                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 27-20-51         |                                     |           |          |          |                           |           |           |             |        |
| 272050                          | RIGHT RUDDER BIAS STRUT             |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:259W03486-607                | MOS/MSC                             | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:HHB160                       | HRS                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.055                     | AFL                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 27-20-51         |                                     |           |          |          |                           |           |           |             |        |
| 272066                          | LEFT RUDDER BIAS STRUT HEATER MUFF  |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:259W02862-5A                 | MOS/MSC                             | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:2272                         | HRS                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.060                     | AFL                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                     |           |          |          |                           |           |           |             |        |
| 272067                          | RIGHT RUDDER BIAS STRUT HEATER MUFF |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:259W02862-5A                 | MOS/MSC                             | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:2274                         | HRS                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.061                     | AFL                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                     |           |          |          |                           |           |           |             |        |
| 272103                          | LEFT RUDDER BIAS PRESSURE SWITCH    |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:HTE690011                    | MOS/MSC                             | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:Q10090269                    | HRS                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.290                     | AFL                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                     |           |          |          |                           |           |           |             |        |
| 272105                          | RIGHT RUDDER BIAS PRESSURE SWITCH   |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:HTE690011                    | MOS/MSC                             | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:8091648                      | HRS                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.290                     | AFL                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                     |           |          |          |                           |           |           |             |        |
| 273001                          | LEFT ELEVATOR                       |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:25-8TE1-1A                   | MOS/MSC                             | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:SD-DH-1953                   | HRS                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.070                     | AFL                                 | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 27-30-22         |                                     |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|---------------------------------|---------|--|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |         |  |          |          |                           |           |           |                  |               |
| <b>273002</b>                   |         | <b>RIGHT ELEVATOR</b>                          |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-8TE1-2A                   | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:SD-DH-1946                   | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.070                     | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 27-30-22         |         |  |          |          |                           |           |           |                  |               |
| <b>273021</b>                   |         | <b>ELEVATOR TRIM SERVOMOTOR</b>                |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:622-3260-001                 | MOS     | 04-Apr-19                                      |          | TSO 0    |                           |           |           | OVERHAUL         |               |
| SN:347MH                        | HRS     | 3175.17  | 3500     | TSO 0    | 6675.17                   |           | 2766.8    |                  |               |
| WC#: 27.085                     | AFL     | 1157   |          | TSO 0    |                           |           |           |                  |               |
| PROC. REF: AMM 27-30-61         |         |  |          |          |                           |           |           |                  |               |
| <b>273022</b>                   |         | <b>ELEVATOR TRIM SERVOMOTOR MOUNT ASSEMBLY</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-8CT219-139A               | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:BPEB/DHB28863                | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.701                     | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| <b>273025</b>                   |         | <b>LEFT ELEVATOR TRIM JACK</b>                 |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:PN                           | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                      | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.080                     | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 27-30-51         |         |  |          |          |                           |           |           |                  |               |
| <b>273026</b>                   |         | <b>RIGHT ELEVATOR TRIM JACK</b>                |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:PN                           | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                      | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.080                     | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 27-30-51         |         |  |          |          |                           |           |           |                  |               |
| <b>273040</b>                   |         | <b>LEFT ELEVATOR TRIM TAB</b>                  |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-8TE3-1A                   | MOS/MSC | 20-Jun-22                                      | O/C      |          |                           |           |           |                  |               |
| SN:UNKNOWN                      | HRS     | 3511.6   |          |          |                           |           |           |                  |               |
| WC#: 27.090                     | AFL     | 1288   |          |          |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |  |          |          |                           |           |           |                  |               |
| <b>273041</b>                   |         | <b>RIGHT ELEVATOR TRIM TAB</b>                 |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-8TE3-2A                   | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:CAVP09G008                   | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.090                     | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |  |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |                                |           |          |          |                           |           |           |             |        |
| 273104                          | LEFT STICK SHAKER              |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:B1443-2                      | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:9931                         | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.140                     | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 27-33-20         |                                |           |          |          |                           |           |           |             |        |
| 273105                          | RIGHT STICK SHAKER             |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:B1443-2                      | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:9927                         | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.140                     | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 27-33-20         |                                |           |          |          |                           |           |           |             |        |
| 273110                          | FORWARD STALL WARNING DETECTOR |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:C87706-1                     | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:1642                         | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.145                     | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                |           |          |          |                           |           |           |             |        |
| 273111                          | AFT STALL WARNING DETECTOR     |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:C87706-1                     | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:1641                         | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.145                     | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                |           |          |          |                           |           |           |             |        |
| 273115                          | NO. 1 STALL WARNING VANE       |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:1703-12                      | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3167                         | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.150                     | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                |           |          |          |                           |           |           |             |        |
| 273116                          | NO. 2 STALL WARNING VANE       |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:1703-12                      | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3148                         | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.150                     | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                |           |          |          |                           |           |           |             |        |
| 273121                          | THIRD CHANNEL STALL DETECTOR   |           |          |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                      | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 27.305                     | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                                |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit    | C/W   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |                         |
|---------------------------------|---------|---|----------|----------|---------------------------|-----------|-----------|-------------|-------------------------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |         |   |          |          |                           |           |           |             |                         |
| <b>275001</b>                   |         | <b>LEFT FLAP</b>                                  |          |          |                           |           |           |             | <b>Component ATA:27</b> |
| PN:DOIW01432-1A                 | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |             |                         |
| SN:SD-DH-1921                   | HRS     | 0   |          | TSN 0    |                           |           |           |             |                         |
| WC#: 27.155                     | AFL     | 0   |          | TSN 0    |                           |           |           |             |                         |
| PROC. REF: AMM 27-50-151        |         |   |          |          |                           |           |           |             |                         |
| <b>275002</b>                   |         | <b>RIGHT FLAP</b>                                 |          |          |                           |           |           |             | <b>Component ATA:27</b> |
| PN:DOIW01432-2A                 | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |             |                         |
| SN:SD-DH-1932                   | HRS     | 0   |          | TSN 0    |                           |           |           |             |                         |
| WC#: 27.155                     | AFL     | 0   |          | TSN 0    |                           |           |           |             |                         |
| PROC. REF: AMM 27-50-151        |         |   |          |          |                           |           |           |             |                         |
| <b>275025</b>                   |         | <b>LEFT FLAP SCREWJACK AND REDUCTION GEARBOX</b>  |          |          |                           |           |           |             | <b>Component ATA:27</b> |
| PN:25-8CW159AC                  | MOS     | 20-Jun-22   |          | TSO 0    |                           |           |           | OVERHAUL    |                         |
| SN:MEC/DHB/668                  | HRS     | 3511.6  |          | TSO 0    |                           |           |           |             |                         |
| WC#: 27.160                     | AFL     | 1288  | 4000     | TSO 0    | 5288                      |           | 3796      |             |                         |
| PROC. REF: AMM 27-50-141        |         |   |          |          |                           |           |           |             |                         |
| <b>275026</b>                   |         | <b>RIGHT FLAP SCREWJACK AND REDUCTION GEARBOX</b> |          |          |                           |           |           |             | <b>Component ATA:27</b> |
| PN:25-8CW161AC                  | MOS     | 20-Jun-22   |          | TSO 0    |                           |           |           | OVERHAUL    |                         |
| SN:MEC/DHB/718                  | HRS     | 3511.6  |          | TSO 0    |                           |           |           |             |                         |
| WC#: 27.160                     | AFL     | 1288  | 4000     | TSO 0    | 5288                      |           | 3796      |             |                         |
| PROC. REF: AMM 27-50-141        |         |   |          |          |                           |           |           |             |                         |
| <b>275049</b>                   |         | <b>LEFT OUTBOARD FLAP VANE</b>                    |          |          |                           |           |           |             | <b>Component ATA:27</b> |
| PN:25-8WF13-65A                 | MOS/MSC | 13-Dec-11   | O/C      |          |                           |           |           |             |                         |
| SN:SD-DH-1099                   | HRS     | 807   |          | TSO 0    |                           |           |           |             |                         |
| WC#: 27.165                     | AFL     | 307   |          | TSO 0    |                           |           |           |             |                         |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |             |                         |
| <b>275050</b>                   |         | <b>RIGHT OUTBOARD FLAP VANE</b>                   |          |          |                           |           |           |             | <b>Component ATA:27</b> |
| PN:25-8WF13-66A                 | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |             |                         |
| SN:SD-DH-1902                   | HRS     | 0   |          | TSN 0    |                           |           |           |             |                         |
| WC#: 27.170                     | AFL     | 0   |          | TSN 0    |                           |           |           |             |                         |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |             |                         |
| <b>275051</b>                   |         | <b>LEFT INBOARD FLAP VANE</b>                     |          |          |                           |           |           |             | <b>Component ATA:27</b> |
| PN:25-7WF101A                   | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |             |                         |
| SN:SD-DH-1963                   | HRS     | 0   |          | TSN 0    |                           |           |           |             |                         |
| WC#: 27.165                     | AFL     | 0   |          | TSN 0    |                           |           |           |             |                         |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |             |                         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit    | C/W                                       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|---------------------------------|---------|---|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |         |   |          |          |                           |           |           |                  |               |
| <b>275052</b>                   |         | <b>RIGHT INBOARD FLAP VANE</b>            |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-7WF102A                   | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:SD-DH-1988                   | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.170                     | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |                  |               |
| <b>275057</b>                   |         | <b>LEFT FLAP BEVEL SHAFT ASSEMBLY</b>     |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25CF2667AD                   | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:BPEB/DHB/286/2               | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.175                     | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |                  |               |
| <b>275058</b>                   |         | <b>RIGHT FLAP BEVEL SHAFT ASSEMBLY</b>    |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25CF2668AD                   | MOS/MSC | 31-Mar-11                                 | O/C      | TSO 0    |                           |           |           |                  |               |
| SN:ME/DHB1173                   | HRS     | 373.93                                    |          | TSO 0    |                           |           |           |                  |               |
| WC#: 27.175                     | AFL     | 147                                       |          | TSO 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |                  |               |
| <b>275073</b>                   |         | <b>FLAP CONTROL UNIT</b>                  |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:614MK2                       | MOS     | 16-Mar-10                                 |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN:1557                         | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.180                     | AFL     | 0   | 6000     | TSN 0    | 6000                      |           | 4508      |                  |               |
| PROC. REF: AMM 27-50-121        |         |   |          |          |                           |           |           |                  |               |
| <b>275074</b>                   |         | <b>FLAP DESIGN UNIT ASSEMBLY</b>          |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:25-8NW111-601                | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:83695                        | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.590                     | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |                  |               |
| <b>275085</b>                   |         | <b>FLAP SYNCHRONIZING SYSTEM RECEIVER</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:617MK4                       | MOS     | 16-Mar-10                                 |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN:1803                         | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.185                     | AFL     | 0   | 4500     | TSN 0    | 4500                      |           | 3008      |                  |               |
| PROC. REF: AMM 27-50-162        |         |   |          |          |                           |           |           |                  |               |
| <b>275091</b>                   |         | <b>FLAP POSITION INDICATOR</b>            |          |          |                           |           |           | <b>Component</b> | <b>ATA:27</b> |
| PN:PN                           | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                      | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 27.190                     | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM NO REF 1         |         |   |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit    | C/W                                       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|---------|---|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |         |   |          |          |                           |           |           |             |        |
| 275097                          |         | FLAP POSITION TRANSMITTER                 |          |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                      | HRS     | 0   |          | TSN 0    |                           |           |           |             |        |
| WC#: 27.195                     | AFL     | 0   |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 27-50-181        |         |   |          |          |                           |           |           |             |        |
| 275145                          |         | LEFT FLAP INBOARD FORWARD SYNCHRO CABLE   |          |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS     | 16-Mar-10                                 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS     | 0   |          | TSN 0    |                           |           |           |             |        |
| WC#: 27.220                     | AFL     | 0   | 5000     | TSN 0    | 5000                      |           | 3508      |             |        |
| 275146                          |         | RIGHT FLAP INBOARD FORWARD SYNCHRO CABLE  |          |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS     | 16-Mar-10                                 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS     | 0   |          | TSN 0    |                           |           |           |             |        |
| WC#: 27.225                     | AFL     | 0   | 5000     | TSN 0    | 5000                      |           | 3508      |             |        |
| 275147                          |         | LEFT FLAP INBOARD AFT SYNCHRO CABLE       |          |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS     | 16-Mar-10                                 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS     | 0   |          | TSN 0    |                           |           |           |             |        |
| WC#: 27.220                     | AFL     | 0   | 5000     | TSN 0    | 5000                      |           | 3508      |             |        |
| 275148                          |         | RIGHT FLAP INBOARD AFT SYNCHRO CABLE      |          |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS     | 16-Mar-10                                 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS     | 0   |          | TSN 0    |                           |           |           |             |        |
| WC#: 27.225                     | AFL     | 0   | 5000     | TSN 0    | 5000                      |           | 3508      |             |        |
| 275149                          |         | LEFT FLAP OUTBOARD FORWARD SYNCHRO CABLE  |          |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS     | 16-Mar-10                                 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS     | 0   |          | TSN 0    |                           |           |           |             |        |
| WC#: 27.230                     | AFL     | 0   | 5000     | TSN 0    | 5000                      |           | 3508      |             |        |
| 275150                          |         | RIGHT FLAP OUTBOARD FORWARD SYNCHRO CABLE |          |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS     | 16-Mar-10                                 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS     | 0   |          | TSN 0    |                           |           |           |             |        |
| WC#: 27.235                     | AFL     | 0   | 5000     | TSN 0    | 5000                      |           | 3508      |             |        |
| 275151                          |         | LEFT FLAP OUTBOARD AFT SYNCHRO CABLE      |          |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS     | 16-Mar-10                                 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS     | 0   |          | TSN 0    |                           |           |           |             |        |
| WC#: 27.230                     | AFL     | 0   | 5000     | TSN 0    | 5000                      |           | 3508      |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit    | C/W  | Interval | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |                         |
|---------------------------------|---------|--|----------|-----------------|---------------------------|-----------|-----------|-------------|-------------------------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |         |  |          |                 |                           |           |           |             |                         |
| <b>275152</b>                   |         | <b>RIGHT FLAP OUTBOARD AFT SYNCHRO CABLE</b> |          |                 |                           |           |           |             | <b>Component ATA:27</b> |
| PN:PN                           | MOS     | 16-Mar-10                                    |          | TSN 0           |                           |           |           | LIFE LIMIT  |                         |
| SN:UNKNOWN                      | HRS     | 0  |          | TSN 0           |                           |           |           |             |                         |
| WC#: 27.235                     | AFL     | 0  | 5000     | TSN 0           | 5000                      |           | 3508      |             |                         |
| PROC. REF: AMM 27-61-21         |         |  |          |                 |                           |           |           |             |                         |
| <b>276001</b>                   |         | <b>LEFT UPPER AIRBRAKE</b>                   |          |                 |                           |           |           |             | <b>Component ATA:27</b> |
| PN:PN                           | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0           |                           |           |           |             |                         |
| SN:UNKNOWN                      | HRS     | 0  |          | TSN 0           |                           |           |           |             |                         |
| WC#: 27.240                     | AFL     | 0  |          | TSN 0           |                           |           |           |             |                         |
| PROC. REF: AMM 27-61-21         |         |  |          |                 |                           |           |           |             |                         |
| <b>276002</b>                   |         | <b>RIGHT UPPER AIRBRAKE</b>                  |          |                 |                           |           |           |             | <b>Component ATA:27</b> |
| PN:PN                           | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0           |                           |           |           |             |                         |
| SN:UNKNOWN                      | HRS     | 0  |          | TSN 0           |                           |           |           |             |                         |
| WC#: 27.245                     | AFL     | 0  |          | TSN 0           |                           |           |           |             |                         |
| PROC. REF: AMM 27-61-21         |         |  |          |                 |                           |           |           |             |                         |
| <b>276003</b>                   |         | <b>LEFT LOWER AIRBRAKE</b>                   |          |                 |                           |           |           |             | <b>Component ATA:27</b> |
| PN:PN                           | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0           |                           |           |           |             |                         |
| SN:UNKNOWN                      | HRS     | 0  |          | TSN 0           |                           |           |           |             |                         |
| WC#: 27.240                     | AFL     | 0  |          | TSN 0           |                           |           |           |             |                         |
| PROC. REF: AMM 27-61-21         |         |  |          |                 |                           |           |           |             |                         |
| <b>276004</b>                   |         | <b>RIGHT LOWER AIRBRAKE</b>                  |          |                 |                           |           |           |             | <b>Component ATA:27</b> |
| PN:PN                           | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0           |                           |           |           |             |                         |
| SN:UNKNOWN                      | HRS     | 0  |          | TSN 0           |                           |           |           |             |                         |
| WC#: 27.245                     | AFL     | 0  |          | TSN 0           |                           |           |           |             |                         |
| PROC. REF: AMM 27-61-21         |         |  |          |                 |                           |           |           |             |                         |
| <b>276039</b>                   |         | <b>LEFT AIRBRAKE JACK</b>                    |          |                 |                           |           |           |             | <b>Component ATA:27</b> |
| PN:PN                           | MOS     | 06-Jun-18                                    |          | TSO 0           |                           |           |           | OVERHAUL    |                         |
| SN:APB980905                    | HRS     | 2965.25                                      | 3000     | TSO 0           | 5965.25                   |           | 2056.9    |             |                         |
| WC#: 27.250                     | AFL     | 1073   |          | TSN 1688, TSO 0 |                           |           |           |             |                         |
| PROC. REF: AMM 27-61-31         |         |  |          |                 |                           |           |           |             |                         |
| <b>276040</b>                   |         | <b>RIGHT AIRBRAKE JACK</b>                   |          |                 |                           |           |           |             | <b>Component ATA:27</b> |
| PN:PN                           | MOS     | 06-Jun-18                                    |          | TSO 0           |                           |           |           | OVERHAUL    |                         |
| SN:APB091671                    | HRS     | 2965.25                                      | 3000     | TSO 0           | 5965.25                   |           | 2056.9    |             |                         |
| WC#: 27.255                     | AFL     | 1073   |          | TSN 8082, TSO 0 |                           |           |           |             |                         |
| PROC. REF: AMM 27-61-31         |         |  |          |                 |                           |           |           |             |                         |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit  | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|---|-----------|---------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 27 - FLIGHT CONTROLS</b> |   |           |               |          |                           |           |           |             |        |
| 276051                          | LEFT AIRBRAKE JACK BODY                     |           |               |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS   | 16-Mar-10 |               | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS   | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 27.250                     | AFL   | 0         | 25000         | TSN 0    | 25000                     |           | 23508     |             |        |
| PROC. REF: AMM 27-61-31         |   |           |               |          |                           |           |           |             |        |
| 276052                          | RIGHT AIRBRAKE JACK BODY                    |           |               |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS   | 16-Mar-10 |               | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                      | HRS   | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 27.255                     | AFL   | 0         | 25000         | TSN 0    | 25000                     |           | 23508     |             |        |
| PROC. REF: AMM 27-61-31         |   |           |               |          |                           |           |           |             |        |
| 276063                          | LEFT AIRBRAKE JACK EYE END                  |           |               |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS/MSC                                     | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                      | HRS   | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 27.250                     | AFL   | 0         |               | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 27-61-31         |   |           |               |          |                           |           |           |             |        |
| 276064                          | RIGHT AIRBRAKE JACK EYE END                 |           |               |          |                           |           |           | Component   | ATA:27 |
| PN:PN                           | MOS/MSC                                     | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                      | HRS   | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 27.255                     | AFL   | 0         |               | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 27-61-31         |   |           |               |          |                           |           |           |             |        |
| 276110                          | STICK PUSHER                                |           |               |          |                           |           |           | Component   | ATA:27 |
| PN:104829001                    | MOS/MSC                                     | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |             |        |
| SN:CW0900013                    | HRS   | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 27.585                     | AFL   | 0         |               | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF       |   |           |               |          |                           |           |           |             |        |
| <b>ATA 28 - FUEL</b>            |   |           |               |          |                           |           |           |             |        |
| 280001 <sup>S</sup>             | FLOW CHECK FUEL TRANSFER SYSTEM, WING TANKS |           |               |          |                           |           |           | Service     | ATA:28 |
|                                 | MOS   | 03-Aug-21 |               |          |                           |           |           |             |        |
|                                 | HRS   | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 28.075                     | AFL   | 1243      |               |          |                           |           |           |             |        |

PKG:7,91

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN             | Unit  | C/W       | Interval        | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------|---|-----------|-----------------|-------------------------|---------------------------|-----------|-----------|-------------|--------|
| ATA 28 - FUEL       |   |           |                 |                         |                           |           |           |             |        |
| 280002 <sup>S</sup> | CHECK FUEL VALVE CONTROL CABLES                                       |           |                 |                         |                           |           |           | Service     | ATA:28 |
|                     | MOS   | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                     | HRS   | 2965.25   | 1600 (+50/-50)  |                         |                           |           |           |             |        |
| WC#: 28.010         | AFL   | 1073      |                 |                         |                           |           |           |             |        |
|                     |   |           |                 | PROC. REF: AMM 28-20-83 |                           |           |           | PKG:23,92   |        |
| 280003 <sup>S</sup> | FUNCTIONAL TEST LP VALVES   |           |                 |                         |                           |           |           | Service     | ATA:28 |
|                     | MOS   | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                     | HRS   | 2965.25   | 3200 (+150/-50) |                         |                           |           |           |             |        |
| WC#: 28.050         | AFL   | 1073      |                 |                         |                           |           |           |             |        |
|                     |   |           |                 | PROC. REF: AMM 28-20-00 |                           |           |           | PKG:31,93   |        |
| 280004 <sup>S</sup> | INSPECT/CLEAN OR REPLACE APU FUEL INLET FILTER ELEMENT (IF FITTED)    |           |                 |                         |                           |           |           | Service     | ATA:28 |
|                     | MOS   | 12-Feb-24 |                 |                         |                           |           |           |             |        |
|                     | HRS   | 3881.4    | 3200 (+150/-50) |                         |                           |           |           |             |        |
| WC#: 28.085         | AFL   | 1476      |                 |                         |                           |           |           |             |        |
|                     |   |           |                 |                         |                           |           |           | PKG:37,93   |        |
| 280005 <sup>S</sup> | VISUALLY INSPECT LEFT WING SUCTION PIPE STRAINERS                     |           |                 |                         |                           |           |           | Service     | ATA:28 |
|                     | MOS   | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                     | HRS   | 2965.25   | 1600 (+50/-50)  |                         |                           |           |           |             |        |
| WC#: 28.165         | AFL   | 1073      |                 |                         |                           |           |           |             |        |
|                     |   |           |                 |                         |                           |           |           | PKG:27,92   |        |
| 280006 <sup>S</sup> | VISUALLY INSPECT LEFT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS  |           |                 |                         |                           |           |           | Service     | ATA:28 |
|                     | MOS   | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                     | HRS   | 2965.25   | 1600 (+50/-50)  |                         |                           |           |           |             |        |
| WC#: 28.170         | AFL   | 1073      |                 |                         |                           |           |           |             |        |
|                     |   |           |                 |                         |                           |           |           | PKG:27,92   |        |
| 280007 <sup>S</sup> | VISUALLY INSPECT RIGHT WING SUCTION PIPE STRAINERS                    |           |                 |                         |                           |           |           | Service     | ATA:28 |
|                     | MOS   | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                     | HRS   | 2965.25   | 1600 (+50/-50)  |                         |                           |           |           |             |        |
| WC#: 28.165         | AFL   | 1073      |                 |                         |                           |           |           |             |        |
|                     |   |           |                 |                         |                           |           |           | PKG:28,92   |        |
| 280008 <sup>S</sup> | VISUALLY INSPECT RIGHT WING WATER TRANSFER SYSTEM PIPE SUCTION BLOCKS |           |                 |                         |                           |           |           | Service     | ATA:28 |
|                     | MOS   | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                     | HRS   | 2965.25   | 1600 (+50/-50)  |                         |                           |           |           |             |        |
| WC#: 28.170         | AFL   | 1073      |                 |                         |                           |           |           |             |        |
|                     |   |           |                 |                         |                           |           |           | PKG:28,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|-----------|--------------|----------|---------------------------|-----------|-----------|-------------|
| ATA 28 - FUEL  |         |           |              |          |                           |           |           |             |
| 280010 CHECK CABLE TENSION OF FUEL CONTROL VALVES Service ATA:28   |         |           |              |          |                           |           |           |             |
|  | MOS/MSC | 27-Oct-10 | O/C          |          |                           |           |           |             |
|  | HRS     | 167.32    |              |          |                           |           |           |             |
| WC#: 28.020  | AFL     | 77        |              |          |                           |           |           |             |
| PROC. REF: AMM 28-20-83  |         |           |              |          |                           |           |           |             |
| 280014 CHECK LEFT BOOST PUMP BRUSH LENGTH Service ATA:28   |         |           |              |          |                           |           |           |             |
| PN:2C40-2  | MOS/MSC | 05-May-10 | N/R          |          |                           |           |           |             |
| SN:5BE61   | HRS     | 0         |              |          |                           |           |           |             |
| WC#: 28.080  | AFL     | 0         |              |          |                           |           |           |             |
| 280015 CHECK RIGHT BOOST PUMP BRUSH LENGTH Service ATA:28  |         |           |              |          |                           |           |           |             |
| PN:2C40-2  | MOS/MSC | 05-May-10 | N/R          |          |                           |           |           |             |
| SN:2BE21   | HRS     | 0         |              |          |                           |           |           |             |
| WC#: 28.080  | AFL     | 0         |              |          |                           |           |           |             |
| 280016 <sup>S</sup> VISUAL INSPECTION LOW PRESSURE FUEL VALVE SUPPORT STRUT. PART NO. 25 PF361, 25 PF361-5A (MOD. 25G310A) AND 25 PF363 Service ATA:28 |         |           |              |          |                           |           |           |             |
|  | MOS     | 20-Jun-22 | 48 (+2m/-2m) |          |                           |           |           |             |
|  | HRS     | 3511.6    |              |          |                           |           |           |             |
| WC#: 28.195  | AFL     | 1288      |              |          |                           |           |           |             |
| PKG:96   |         |           |              |          |                           |           |           |             |
| 281067 VENTRAL FUEL TANK Component ATA:28  |         |           |              |          |                           |           |           |             |
| PN:DOIW00325-1A  | MOS/MSC | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |
| SN:SD-DH-800SD   | HRS     | 0         |              | TSN 0    |                           |           |           |             |
| WC#: 28.015  | AFL     | 0         |              | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 28-10-15  |         |           |              |          |                           |           |           |             |
| 282001 LEFT WING HIGH LEVEL FLOAT SWITCH Component ATA:28  |         |           |              |          |                           |           |           |             |
| PN:3515000-107   | MOS/MSC | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |
| SN:7091562   | HRS     | 0         |              | TSN 0    |                           |           |           |             |
| WC#: 28.025  | AFL     | 0         |              | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 28-22-143   |         |           |              |          |                           |           |           |             |
| 282002 RIGHT WING HIGH LEVEL FLOAT SWITCH Component ATA:28   |         |           |              |          |                           |           |           |             |
| PN:3515000-107   | MOS/MSC | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |
| SN:5091252   | HRS     | 0         |              | TSN 0    |                           |           |           |             |
| WC#: 28.025  | AFL     | 0         |              | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 28-22-143   |         |           |              |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 28 - FUEL</b>      |                              |           |          |          |                           |           |           |             |        |
| 282004                    | LOW PRESSURE FUEL COCK VALVE |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:PN                     | MOS/MSC                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS                          | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.191               | AFL                          | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-20-52   |                              |           |          |          |                           |           |           |             |        |
| 282005                    | LEFT FUEL COCK               |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:7913003K               | MOS/MSC                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:38082151               | HRS                          | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.180               | AFL                          | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |                              |           |          |          |                           |           |           |             |        |
| 282006                    | RIGHT FUEL COCK              |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:7913003K               | MOS/MSC                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:54080610               | HRS                          | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.180               | AFL                          | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |                              |           |          |          |                           |           |           |             |        |
| 282007                    | LEFT FUEL ACTUATOR           |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:HTE9044-001            | MOS/MSC                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:M118GB0309             | HRS                          | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.185               | AFL                          | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |                              |           |          |          |                           |           |           |             |        |
| 282008                    | RIGHT FUEL ACTUATOR          |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:HTE9044-001            | MOS/MSC                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:M111GB1108             | HRS                          | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.185               | AFL                          | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |                              |           |          |          |                           |           |           |             |        |
| 282009                    | LEFT FUEL NON-RETURN VALVE   |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:9807870                | MOS/MSC                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:55080987               | HRS                          | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.190               | AFL                          | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-20-32   |                              |           |          |          |                           |           |           |             |        |
| 282010                    | RIGHT FUEL NON-RETURN VALVE  |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:9807870                | MOS/MSC                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:55080988               | HRS                          | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.190               | AFL                          | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-20-32   |                              |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition |               |
|-------------------------|---------|--|----------|----------|---------------------------|-----------|------------------|-------------|---------------|
| <b>ATA 28 - FUEL</b>    |         |  |          |          |                           |           |                  |             |               |
| <b>282011</b>           |         | <b>LEFT FUEL NON-RETURN VALVE</b>                  |          |          |                           |           | <b>Component</b> |             | <b>ATA:28</b> |
| PN:HTE4350              | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:M0115VNR0109         | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 28.192             | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 28-20-32 |         |  |          |          |                           |           |                  |             |               |
| <b>282012</b>           |         | <b>RIGHT FUEL NON-RETURN VALVE</b>                 |          |          |                           |           | <b>Component</b> |             | <b>ATA:28</b> |
| PN:HTE4350              | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:M0123VNR0109         | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 28.193             | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 28-20-32 |         |  |          |          |                           |           |                  |             |               |
| <b>282025</b>           |         | <b>APU FUEL PRESSURE SWITCH</b>                    |          |          |                           |           | <b>Component</b> |             | <b>ATA:28</b> |
| PN:PN                   | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN              | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 28.030             | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 28-22-91 |         |  |          |          |                           |           |                  |             |               |
| <b>282053</b>           |         | <b>LEFT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE</b>  |          |          |                           |           | <b>Component</b> |             | <b>ATA:28</b> |
| PN:PN                   | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN              | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 28.035             | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 28-20-32 |         |  |          |          |                           |           |                  |             |               |
| <b>282054</b>           |         | <b>RIGHT FUEL SYSTEM RIB NO.8 NON-RETURN VALVE</b> |          |          |                           |           | <b>Component</b> |             | <b>ATA:28</b> |
| PN:PN                   | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN              | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 28.035             | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 28-20-32 |         |  |          |          |                           |           |                  |             |               |
| <b>282253</b>           |         | <b>LEFT HAND LP FUEL VALVE</b>                     |          |          |                           |           | <b>Component</b> |             | <b>ATA:28</b> |
| PN:HTE1984-1            | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:4090493              | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 28.045             | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 28-20-52 |         |  |          |          |                           |           |                  |             |               |
| <b>282254</b>           |         | <b>RIGHT HAND LP FUEL VALVE</b>                    |          |          |                           |           | <b>Component</b> |             | <b>ATA:28</b> |
| PN:HTE1984-1            | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:14090938             | HRS     | 0  |          | TSN 0    |                           |           |                  |             |               |
| WC#: 28.045             | AFL     | 0  |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: AMM 28-20-52 |         |  |          |          |                           |           |                  |             |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 28 - FUEL</b>                  |                                     |           |          |          |                           |           |           |             |        |
| 282289                                | FUEL 3C VALVE                       |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:HTE1984-1                          | MOS/MSC                             | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:4090503                            | HRS                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.055                           | AFL                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-20-61               |                                     |           |          |          |                           |           |           |             |        |
| 282295                                | FUEL 4S VALVE                       |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:PN                                 | MOS/MSC                             | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.060                           | AFL                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-20-61, AMM 28-20-71 |                                     |           |          |          |                           |           |           |             |        |
| 282301                                | VENTRAL TANK FUEL TRANSFER VALVE    |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:HTE1984-1                          | MOS/MSC                             | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:38082115                           | HRS                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.065                           | AFL                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-20-78               |                                     |           |          |          |                           |           |           |             |        |
| 282343                                | LEFT BOOST PUMP                     |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:2C40-2                             | MOS/MSC                             | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:5BE61                              | HRS                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.080                           | AFL                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-20-12               |                                     |           |          |          |                           |           |           |             |        |
| 282344                                | RIGHT BOOST PUMP                    |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:2C40-2                             | MOS/MSC                             | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:2BE21                              | HRS                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.080                           | AFL                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-20-12               |                                     |           |          |          |                           |           |           |             |        |
| 282384                                | SINGLE-POINT PRESSURE CONTROL VALVE |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:PN                                 | MOS/MSC                             | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.175                           | AFL                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                     |           |          |          |                           |           |           |             |        |
| 284013                                | LEFT NO. 1 FUEL TANK UNIT           |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0207KTU04                          | MOS/MSC                             | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0691309                          | HRS                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.100                           | AFL                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03               |                                     |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit                      | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|---------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 28 - FUEL           |                           |           |          |          |                           |           |           |             |        |
| 284014                  | RIGHT NO.1 FUEL TANK UNIT |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0207KTU04            | MOS/MSC                   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0665207            | HRS                       | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.100             | AFL                       | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |             |        |
| 284015                  | LEFT NO.2 FUEL TANK UNIT  |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU2             | MOS/MSC                   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0720005            | HRS                       | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.105             | AFL                       | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |             |        |
| 284016                  | RIGHT NO.2 FUEL TANK UNIT |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU2             | MOS/MSC                   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0720005            | HRS                       | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.105             | AFL                       | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |             |        |
| 284017                  | LEFT NO.3 FUEL TANK UNIT  |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0207KTU3             | MOS/MSC                   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0714803            | HRS                       | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.110             | AFL                       | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |             |        |
| 284018                  | RIGHT NO.3 FUEL TANK UNIT |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0207KTU3             | MOS/MSC                   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0713710            | HRS                       | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.110             | AFL                       | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |             |        |
| 284019                  | LEFT NO.4 FUEL TANK UNIT  |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU4             | MOS/MSC                   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0691309            | HRS                       | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.115             | AFL                       | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |             |        |
| 284020                  | RIGHT NO.4 FUEL TANK UNIT |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU4             | MOS/MSC                   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0665207            | HRS                       | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.115             | AFL                       | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                           |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 28 - FUEL</b>    |                                    |           |          |          |                           |           |           |             |        |
| 284021                  | LEFT NO.5 FUEL TANK UNIT           |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU-5            | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0358604            | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.120             | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                                    |           |          |          |                           |           |           |             |        |
| 284022                  | RIGHT NO.5 FUEL TANK UNIT          |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU-5            | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0326604            | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.120             | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                                    |           |          |          |                           |           |           |             |        |
| 284023                  | LEFT NO.6 FUEL TANK UNIT           |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU6             | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0585702            | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.125             | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                                    |           |          |          |                           |           |           |             |        |
| 284024                  | RIGHT NO.6 FUEL TANK UNIT          |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU6             | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0585710            | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.125             | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                                    |           |          |          |                           |           |           |             |        |
| 284025                  | LEFT NO.7 FUEL TANK CONTENTS UNIT  |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU7             | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0741801            | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.130             | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                                    |           |          |          |                           |           |           |             |        |
| 284026                  | RIGHT NO.7 FUEL TANK CONTENTS UNIT |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:0204KTU7             | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FR0741802            | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.130             | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                                    |           |          |          |                           |           |           |             |        |
| 284115                  | LEFT FUEL QUANTITY INDICATOR       |           |          |          |                           |           |           | Component   | ATA:28 |
| PN:PN                   | MOS/MSC                            | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN              | HRS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 28.140             | AFL                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03 |                                    |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit                                     | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|---------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 28 - FUEL</b>            |  |           |               |          |                           |           |           |             |        |
| 284116                          | RIGHT FUEL QUANTITY INDICATOR            |           |               |          |                           |           |           | Component   | ATA:28 |
| PN:PN                           | MOS/MSC                                  | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                      | HRS                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 28.140                     | AFL                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-42-03         |  |           |               |          |                           |           |           |             |        |
| 284130                          | FUEL PRESSURE SWITCH                     |           |               |          |                           |           |           | Component   | ATA:28 |
| PN:HTE690009                    | MOS/MSC                                  | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |             |        |
| SN:2409135                      | HRS                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 28.194                     | AFL                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF       |  |           |               |          |                           |           |           |             |        |
| 284139                          | VENTRAL TANK LOW LEVEL FLOAT SWITCH      |           |               |          |                           |           |           | Component   | ATA:28 |
| PN:3515000-149                  | MOS/MSC                                  | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |             |        |
| SN:9091485                      | HRS                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 28.145                     | AFL                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-44-33         |  |           |               |          |                           |           |           |             |        |
| 284145                          | VENTRAL TANK HIGH LEVEL FLOAT SWITCH     |           |               |          |                           |           |           | Component   | ATA:28 |
| PN:PN                           | MOS/MSC                                  | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                      | HRS                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 28.150                     | AFL                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-44-33         |  |           |               |          |                           |           |           |             |        |
| 284151                          | LEFT SURGE TANK FLOAT SWITCH             |           |               |          |                           |           |           | Component   | ATA:28 |
| PN:3515000-106                  | MOS/MSC                                  | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |             |        |
| SN:51081246                     | HRS                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 28.155                     | AFL                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-44-43         |  |           |               |          |                           |           |           |             |        |
| 284152                          | RIGHT SURGE TANK FLOAT SWITCH            |           |               |          |                           |           |           | Component   | ATA:28 |
| PN:3515000-106                  | MOS/MSC                                  | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |             |        |
| SN:14090122                     | HRS                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| WC#: 28.155                     | AFL                                      | 0         |               | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 28-44-43         |  |           |               |          |                           |           |           |             |        |
| <b>ATA 29 - HYDRAULIC POWER</b> |  |           |               |          |                           |           |           |             |        |
| 290003 <sup>S</sup>             | REPLACE HYDRAULIC SUCTION FILTER ELEMENT |           |               |          |                           |           |           | Service     | ATA:29 |
|                                 | MOS                                      | 03-Aug-21 |               |          |                           |           |           |             |        |
|                                 | HRS                                      | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 29.070                     | AFL                                      | 1243      |               |          |                           |           |           |             |        |
| PROC. REF: AMM NO REF 1         |  |           |               |          |                           |           |           |             |        |

PKG:13,91

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit   | C/W       | Interval       | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|----------------|-------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 29 - HYDRAULIC POWER</b> |  |           |                |                         |                           |           |           |             |        |
| 290004 <sup>S</sup>             | FUNCTIONAL TEST MAIN HYDRAULIC SYSTEM  |           |                |                         |                           |           |           | Service     | ATA:29 |
|                                 | MOS  | 03-Aug-21 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10)  |                         |                           |           |           |             |        |
| WC#: 29.075                     | AFL  | 1243      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 29-10-00 |                           |           |           | PKG:18,91   |        |
| 290005 <sup>S</sup>             | OPERATIONAL TEST LANDING GEAR AND FLAPS EMERGENCY LOWERING SYSTEM                |           |                |                         |                           |           |           | Service     | ATA:29 |
|                                 | MOS  | 03-Aug-21 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10)  |                         |                           |           |           |             |        |
| WC#: 29.115                     | AFL  | 1243      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 29-20-00 |                           |           |           | PKG:18,91   |        |
| 290006 <sup>S</sup>             | DRAIN HYDRAULIC TANK PRESSURIZATION SYSTEM                                       |           |                |                         |                           |           |           | Service     | ATA:29 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 29.160                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                |                         |                           |           |           | PKG:25,92   |        |
| 290007 <sup>S</sup>             | TEST FLAPS, AIRBRAKES, LANDING GEAR, NOSEWHEEL STEERING, NOSE LEG SELF-CENTERING |           |                |                         |                           |           |           | Service     | ATA:29 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 29.165                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 29-10-00 |                           |           |           | PKG:30,92   |        |
| 290008 <sup>S</sup>             | CHECK EMERGENCY BRAKE SYSTEM LEAK RATE   |           |                |                         |                           |           |           | Service     | ATA:29 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 29.175                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 29-10-00 |                           |           |           | PKG:30,92   |        |
| 290009 <sup>S</sup>             | FUNCTIONAL TEST AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM                     |           |                |                         |                           |           |           | Service     | ATA:29 |
|                                 | MOS  | 03-Aug-21 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10)  |                         |                           |           |           |             |        |
| WC#: 29.180                     | AFL  | 1243      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 29-30-00 |                           |           |           | PKG:18,91   |        |
| 290010 <sup>S</sup>             | FUNCTIONAL TEST HYDRAULIC RESERVOIR PRESSURIZATION SYSTEM                        |           |                |                         |                           |           |           | Service     | ATA:29 |
|                                 | MOS  | 06-Jun-18 |                |                         |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |        |
| WC#: 29.170                     | AFL  | 1073      |                |                         |                           |           |           |             |        |
|                                 |  |           |                | PROC. REF: AMM 29-10-13 |                           |           |           | PKG:30,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|-----------|-----------------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 29 - HYDRAULIC POWER</b>  |         |           |                 |          |                           |           |           |             |
| <b>290011<sup>S</sup> CLEAN FULL-FLOW RELIEF VALVE Service ATA:29</b>                            |         |           |                 |          |                           |           |           |             |
|  | MOS     | 06-Jun-18 |                 |          |                           |           |           |             |
|  | HRS     | 2965.25   | 3200 (+150/-50) |          |                           |           |           |             |
| WC#: 29.005  | AFL     | 1073      |                 |          |                           |           |           |             |
|  |         |           |                 |          | PROC. REF: AMM 29-10-71   |           |           | PKG:37,93   |
| <b>290012<sup>S</sup> INSPECT HYDRAULIC POWER HIGH TEMPERATURE WARNING SYSTEM Service ATA:29</b> |         |           |                 |          |                           |           |           |             |
|  | MOS     | 06-Jun-18 |                 |          |                           |           |           |             |
|  | HRS     | 2965.25   | 3200 (+150/-50) |          |                           |           |           |             |
| WC#: 29.145  | AFL     | 1073      |                 |          |                           |           |           |             |
|  |         |           |                 |          | PROC. REF: AMM 29-30-00   |           |           | PKG:37,93   |
| <b>291018 PRESSURE REGULATOR VALVE Component ATA:29</b>  |         |           |                 |          |                           |           |           |             |
| PN: PAS129-163   | MOS/MSC | 16-Mar-10 | O/C             | TSN 0    |                           |           |           |             |
| SN: HAY0415  | HRS     | 0         |                 | TSN 0    |                           |           |           |             |
| WC#: 29.010  | AFL     | 0         |                 | TSN 0    |                           |           |           |             |
|  |         |           |                 |          | PROC. REF: GENERIC NO REF |           |           |             |
| <b>291025 NO. 1 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE Component ATA:29</b>            |         |           |                 |          |                           |           |           |             |
| PN: AIR87240-0   | MOS/MSC | 16-Mar-10 | O/C             | TSN 0    |                           |           |           |             |
| SN: APB090483  | HRS     | 0         |                 | TSN 0    |                           |           |           |             |
| WC#: 29.015  | AFL     | 0         |                 | TSN 0    |                           |           |           |             |
|  |         |           |                 |          | PROC. REF: GENERIC NO REF |           |           |             |
| <b>291026 NO. 2 ENGINE HYDRAULIC PUMP CASE DRAIN NONRETURN VALVE Component ATA:29</b>            |         |           |                 |          |                           |           |           |             |
| PN: PN   | MOS/MSC | 16-Mar-10 | O/C             | TSN 0    |                           |           |           |             |
| SN: UNKNOWN  | HRS     | 0         |                 | TSN 0    |                           |           |           |             |
| WC#: 29.015  | AFL     | 0         |                 | TSN 0    |                           |           |           |             |
|  |         |           |                 |          | PROC. REF: GENERIC NO REF |           |           |             |
| <b>291037 LEFT HYDRAULIC SUCTION VALVE Component ATA:29</b>                                      |         |           |                 |          |                           |           |           |             |
| PN: 7907015E   | MOS/MSC | 16-Mar-10 | O/C             | TSN 0    |                           |           |           |             |
| SN: 54080717   | HRS     | 0         |                 | TSN 0    |                           |           |           |             |
| WC#: 29.020  | AFL     | 0         |                 | TSN 0    |                           |           |           |             |
|  |         |           |                 |          | PROC. REF: AMM 29-10-31   |           |           |             |
| <b>291038 RIGHT HYDRAULIC SUCTION VALVE Component ATA:29</b>                                     |         |           |                 |          |                           |           |           |             |
| PN: 7907015E   | MOS/MSC | 05-Jul-12 | O/C             |          |                           |           |           |             |
| SN: FRTR127/F  | HRS     | 1021      |                 |          |                           |           |           |             |
| WC#: 29.020  | AFL     | 368       |                 |          |                           |           |           |             |
|  |         |           |                 |          | PROC. REF: AMM 29-10-31   |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit    | C/W   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|---------------------------------|---------|---|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 29 - HYDRAULIC POWER</b> |         |   |          |          |                           |           |           |                  |               |
| <b>291049</b>                   |         | <b>NO. 1 FULL FLOW HYDRAULIC RELIEF VALVE</b>         |          |          |                           |           |           | <b>Component</b> | <b>ATA:29</b> |
| PN: AIR45394-0                  | MOS     | 16-Mar-10   |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN: APB090245                   | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 29.025                     | AFL     | 0   | 4500     | TSN 0    | 4500                      |           | 3008      |                  |               |
| <b>291050</b>                   |         | <b>NO. 2 FULL FLOW HYDRAULIC RELIEF VALVE</b>         |          |          |                           |           |           | <b>Component</b> | <b>ATA:29</b> |
| PN: AIR45394-0                  | MOS     | 16-Mar-10   |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN: APB090244                   | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 29.025                     | AFL     | 0   | 4500     | TSN 0    | 4500                      |           | 3008      |                  |               |
| <b>291061</b>                   |         | <b>NO. 1 DUNLOP VALVE</b>                             |          |          |                           |           |           | <b>Component</b> | <b>ATA:29</b> |
| PN: AC69536                     | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |                  |               |
| SN: HBB310                      | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 29.106                     | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |                  |               |
| <b>291062</b>                   |         | <b>NO. 2 DUNLOP VALVE</b>                             |          |          |                           |           |           | <b>Component</b> | <b>ATA:29</b> |
| PN: AC69536                     | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |                  |               |
| SN: HBB314                      | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 29.106                     | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |                  |               |
| <b>291063</b>                   |         | <b>NO. 3 DUNLOP VALVE</b>                             |          |          |                           |           |           | <b>Component</b> | <b>ATA:29</b> |
| PN: AC69536                     | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |                  |               |
| SN: FMB171                      | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 29.106                     | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |                  |               |
| <b>291073</b>                   |         | <b>PRESSURE MAINTAINING VALVE</b>                     |          |          |                           |           |           | <b>Component</b> | <b>ATA:29</b> |
| PN: AIR45474-0                  | MOS     | 12-Oct-10   |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN: LK0354                      | HRS     | 158.2   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 29.030                     | AFL     | 73  | 5000     | TSN 0    | 5073                      |           | 3581      |                  |               |
| <b>291079</b>                   |         | <b>GROUND SERVICE HANDPUMP SUPPLY NONRETURN VALVE</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:29</b> |
| PN: AIR48026-0-1                | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |                  |               |
| SN: APB091379                   | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 29.035                     | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|-----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 29 - HYDRAULIC POWER</b> |                             |           |          |          |                           |           |           |             |        |
| 291091                          | MAIN HYDRAULIC RESERVOIR    |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:PN                           | MOS/MSC                     | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                      | HRS                         | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 29.040                     | AFL                         | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 29-10-13         |                             |           |          |          |                           |           |           |             |        |
| 291096                          | HYDRAULIC PRESSURE GAUGE    |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:PN                           | MOS/MSC                     | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                      | HRS                         | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 29.045                     | AFL                         | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                             |           |          |          |                           |           |           |             |        |
| 291103                          | MAIN HYDRAULIC ACCUMULATOR  |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:AIR45574-4                   | MOS/MSC                     | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:APB091424                    | HRS                         | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 29.050                     | AFL                         | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 29-10-81         |                             |           |          |          |                           |           |           |             |        |
| 291109                          | EMERGENCY BRAKE ACCUMULATOR |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:AIR45574-4                   | MOS/MSC                     | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:APB091457                    | HRS                         | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 29.055                     | AFL                         | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                             |           |          |          |                           |           |           |             |        |
| 291131                          | HYDRAULIC FILTER            |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:MFHA15104                    | MOS/MSC                     | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:BF08/0636                    | HRS                         | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 29.060                     | AFL                         | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF       |                             |           |          |          |                           |           |           |             |        |
| 291132                          | PRESSURE FILTER ASSEMBLY    |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:B2125-H4                     | MOS/MSC                     | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:FYH217249                    | HRS                         | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 29.065                     | AFL                         | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 29-10-21         |                             |           |          |          |                           |           |           |             |        |
| 291163                          | NO. 1 ENGINE HYDRAULIC PUMP |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:42022-03                     | MOS/MSC                     | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:CC711                        | HRS                         | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 29.080                     | AFL                         | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 29-10-54         |                             |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit    | C/W   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition   |  |
|---------------------------------|---------|---|----------|----------|---------------------------|-----------|------------------|---------------|--|
| <b>ATA 29 - HYDRAULIC POWER</b> |         |   |          |          |                           |           |                  |               |  |
| <b>291164</b>                   |         | <b>NO. 2 ENGINE HYDRAULIC PUMP</b>                |          |          |                           |           | <b>Component</b> | <b>ATA:29</b> |  |
| PN:42022-03                     | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |                  |               |  |
| SN:CC709                        | HRS     | 0   |          | TSN 0    |                           |           |                  |               |  |
| WC#: 29.080                     | AFL     | 0   |          | TSN 0    |                           |           |                  |               |  |
| PROC. REF: AMM 29-10-54         |         |   |          |          |                           |           |                  |               |  |
| <b>291165</b>                   |         | <b>NO. 1 ENGINE HYDRAULIC OIL PRESSURE SENSOR</b> |          |          |                           |           | <b>Component</b> | <b>ATA:29</b> |  |
| PN:293RA0001-1                  | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |                  |               |  |
| SN:10121433281                  | HRS     | 0   |          | TSN 0    |                           |           |                  |               |  |
| WC#: 29.181                     | AFL     | 0   |          | TSN 0    |                           |           |                  |               |  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |                  |               |  |
| <b>291166</b>                   |         | <b>NO. 2 ENGINE HYDRAULIC OIL PRESSURE SENSOR</b> |          |          |                           |           | <b>Component</b> | <b>ATA:29</b> |  |
| PN:293RA0001-1                  | MOS/MSC | 08-Nov-11   | O/C      | TSN 0    |                           |           |                  |               |  |
| SN:101121433311                 | HRS     | 764.13  |          | TSN 0    |                           |           |                  |               |  |
| WC#: 29.182                     | AFL     | 284   |          | TSN 0    |                           |           |                  |               |  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |                  |               |  |
| <b>291170</b>                   |         | <b>HYDRAULIC RESERVOIR RELIEF VALVE</b>           |          |          |                           |           | <b>Component</b> | <b>ATA:29</b> |  |
| PN:AIR87236-0                   | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |                  |               |  |
| SN:APB083269                    | HRS     | 0   |          | TSN 0    |                           |           |                  |               |  |
|                                 | AFL     | 0   |          | TSN 0    |                           |           |                  |               |  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |                  |               |  |
| <b>291178</b>                   |         | <b>BANJO ASSEMBLY</b>                             |          |          |                           |           | <b>Component</b> | <b>ATA:29</b> |  |
| PN:FRH460001C                   | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |                  |               |  |
| SN:4090656                      | HRS     | 0   |          | TSN 0    |                           |           |                  |               |  |
|                                 | AFL     | 0   |          | TSN 0    |                           |           |                  |               |  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |                  |               |  |
| <b>291182</b>                   |         | <b>GROUND SERVICING HANDPUMP</b>                  |          |          |                           |           | <b>Component</b> | <b>ATA:29</b> |  |
| PN:AIR45424-0                   | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |                  |               |  |
| SN:APB083106                    | HRS     | 0   |          | TSN 0    |                           |           |                  |               |  |
| WC#: 29.085                     | AFL     | 0   |          | TSN 0    |                           |           |                  |               |  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |                  |               |  |
| <b>291186</b>                   |         | <b>NO. 1 NON-RETURN TANK PRESSURE VALVE</b>       |          |          |                           |           | <b>Component</b> | <b>ATA:29</b> |  |
| PN:HTE4853                      | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |                  |               |  |
| SN:37081668                     | HRS     | 0   |          | TSN 0    |                           |           |                  |               |  |
| WC#: 29.090                     | AFL     | 0   |          | TSN 0    |                           |           |                  |               |  |
| PROC. REF: GENERIC NO REF       |         |   |          |          |                           |           |                  |               |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 29 - HYDRAULIC POWER</b> |   |           |          |          |                           |           |           |             |        |
| 291193                          | NO. 2 NON-RETURN TANK PRESSURE VALVE                |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:PN                           | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                      | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 29.090                     | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |   |           |          |          |                           |           |           |             |        |
| 292001                          | EMERGENCY HYDRAULIC TANK                            |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:25-1H15275-3A                | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:WN155037/24                  | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 29.095                     | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |   |           |          |          |                           |           |           |             |        |
| 292003                          | SUCTION FILTER ASSEMBLY                             |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:AIR87366-0                   | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:BF08-0470                    | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 29.100                     | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 29-10-21         |   |           |          |          |                           |           |           |             |        |
| 292007                          | EMERGENCY HYDRAULIC HAND PUMP                       |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:AIR45448-1                   | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:APB090408                    | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 29.105                     | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |   |           |          |          |                           |           |           |             |        |
| 292013                          | AUXILIARY RESERVOIR LOW-LEVEL WARNING SYSTEM SWITCH |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:PN                           | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                      | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 29.110                     | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 29-30-00         |   |           |          |          |                           |           |           |             |        |
| 292031                          | EMERGENCY TANK ON/OFF HAND PUMP VALVE               |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:AIR45446-2                   | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:APB091322                    | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 29.120                     | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |   |           |          |          |                           |           |           |             |        |
| 292037                          | EMERGENCY SYSTEM CHECK VALVE                        |           |          |          |                           |           |           | Component   | ATA:29 |
| PN:PN                           | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                      | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 29.125                     | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF       |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 29 - HYDRAULIC POWER</b>   |         |           |          |          |                           |           |           |             |
| <b>293001 NO. 1 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH</b> <span style="float:right">Component ATA:29</span> |         |           |          |          |                           |           |           |             |
| PN:PN   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 29.130   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>293002 NO. 2 ENGINE HYDRAULIC PUMP LOW PRESSURE SWITCH</b> <span style="float:right">Component ATA:29</span> |         |           |          |          |                           |           |           |             |
| PN:PN   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 29.130   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>293013 EMERGENCY BRAKE LOW PRESSURE WARNING SWITCH</b> <span style="float:right">Component ATA:29</span>     |         |           |          |          |                           |           |           |             |
| PN:TP42001  | MOS     | 12-Oct-10 |          | TSN 0    |                           |           |           | OVERHAUL    |
| SN:575  | HRS     | 158.2     | 5000     | TSN 0    | 5158.2                    |           | 1249.8    |             |
| WC#: 29.135   | AFL     | 73        |          | TSN 0    |                           |           |           |             |
| <b>293019 HYDRAULIC PRESSURE TRANSDUCER</b> <span style="float:right">Component ATA:29</span>                   |         |           |          |          |                           |           |           |             |
| PN:695-4-20   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:75869352   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 29.140   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>293024 HYDRAULIC SYSTEM OVERTEMPERATURE SWITCH</b> <span style="float:right">Component ATA:29</span>         |         |           |          |          |                           |           |           |             |
| PN:PN   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 29.145   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 29-30-00   |         |           |          |          |                           |           |           |             |
| <b>294001 LEFT HYDRAULIC NON-RETURN VALVE</b> <span style="float:right">Component ATA:29</span>                 |         |           |          |          |                           |           |           |             |
| PN:9840078J   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:4090112  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 29.183   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 29-10-68   |         |           |          |          |                           |           |           |             |
| <b>294002 RIGHT HYDRAULIC NON-RETURN VALVE</b> <span style="float:right">Component ATA:29</span>                |         |           |          |          |                           |           |           |             |
| PN:9840078J   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:5090174  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 29.184   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 29-10-68   |         |           |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---|---------|-----------|---------------|----------|---------------------------|-----------|-----------|------------------|
| <b>ATA 29 - HYDRAULIC POWER</b>                               |         |           |               |          |                           |           |           |                  |
| <b>294003 NO. 1 HYDRAULIC NON-RETURN VALVE</b>                |         |           |               |          |                           |           |           | Component ATA:29 |
| PN:9840000J   | MOS/MSC | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |                  |
| SN:5090166  | HRS     | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 29.186   | AFL     | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 29-10-68                                       |         |           |               |          |                           |           |           |                  |
| <b>294004 NO. 2 HYDRAULIC NON-RETURN VALVE</b>                |         |           |               |          |                           |           |           | Component ATA:29 |
| PN:9840000J   | MOS/MSC | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |                  |
| SN:12080288   | HRS     | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 29.187   | AFL     | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 29-10-68                                       |         |           |               |          |                           |           |           |                  |
| <b>294005 HYDRAULIC NON-RETURN VALVE</b>                      |         |           |               |          |                           |           |           | Component ATA:29 |
| PN:AIR45468-0   | MOS/MSC | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |                  |
| SN:APB090200  | HRS     | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 29.188   | AFL     | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 29-10-68                                       |         |           |               |          |                           |           |           |                  |
| <b>294006 HYDRAULIC RELIEF VALVE</b>                          |         |           |               |          |                           |           |           | Component ATA:29 |
| PN:AIR45418-0   | MOS/MSC | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |                  |
| SN:APB083037  | HRS     | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 29.189   | AFL     | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 29-10-68                                       |         |           |               |          |                           |           |           |                  |
| <b>294007 LEFT HYDRAULIC NON-RETURN VALVE</b>                 |         |           |               |          |                           |           |           | Component ATA:29 |
| PN:AIR87246-0   | MOS/MSC | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |                  |
| SN:APB891022  | HRS     | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 29.190   | AFL     | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 29-10-68                                       |         |           |               |          |                           |           |           |                  |
| <b>294008 RIGHT HYDRAULIC NON-RETURN VALVE</b>                |         |           |               |          |                           |           |           | Component ATA:29 |
| PN:AIR87246-0   | MOS/MSC | 16-Mar-10 | O/C           | TSN 0    |                           |           |           |                  |
| SN:APB090029  | HRS     | 0         |               | TSN 0    |                           |           |           |                  |
| WC#: 29.191   | AFL     | 0         |               | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 29-10-68                                       |         |           |               |          |                           |           |           |                  |
| <b>ATA 30 - ICE AND RAIN PROTECTION</b>                       |         |           |               |          |                           |           |           |                  |
| <b>300001<sup>S</sup> FUNCTIONAL TEST ROTARY ICE DETECTOR</b> |         |           |               |          |                           |           |           | Service ATA:30   |
|   | MOS     | 03-Aug-21 |               |          |                           |           |           |                  |
|   | HRS     | 3405      | 800 (+40/-10) |          |                           |           |           |                  |
| WC#: 30.085   | AFL     | 1243      |               |          |                           |           |           |                  |
| PROC. REF: AMM 30-80-00                                       |         |           |               |          |                           |           |           |                  |

PKG:7,91

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval       | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------------|-------------------------|---------------------------|-----------|-----------|-------------|
| <b>ATA 30 - ICE AND RAIN PROTECTION</b>   |         |           |                |                         |                           |           |           |             |
| <b>300002<sup>S</sup> OPERATIONAL TEST WINDSHIELD ELECTRICAL DE-ICE SYSTEM Service ATA:30</b> |         |           |                |                         |                           |           |           |             |
|   | MOS     | 06-Jun-18 |                |                         |                           |           |           |             |
|   | HRS     | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |
| WC#: 30.080   | AFL     | 1073      |                |                         |                           |           |           |             |
|   |         |           |                | PROC. REF: AMM 30-41-00 |                           |           |           | PKG:19,92   |
| <b>300003<sup>S</sup> REPLACE AIRFRAME DE-ICING FILTER ELEMENT Service ATA:30</b>             |         |           |                |                         |                           |           |           |             |
|   | MOS     | 03-Aug-21 |                |                         |                           |           |           |             |
|   | HRS     | 3405      | 800 (+40/-10)  |                         |                           |           |           |             |
| WC#: 30.020   | AFL     | 1243      |                |                         |                           |           |           |             |
|   |         |           |                | PROC. REF: AMM 30-10-52 |                           |           |           | PKG:12,91   |
| <b>300004<sup>S</sup> FUNCTIONAL TEST PITOT HEAD AND STATIC PLATE HEATERS Service ATA:30</b>  |         |           |                |                         |                           |           |           |             |
|   | MOS     | 06-Jun-18 |                |                         |                           |           |           |             |
|   | HRS     | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |
| WC#: 30.065   | AFL     | 1073      |                |                         |                           |           |           |             |
|   |         |           |                | PROC. REF: AMM 30-35-15 |                           |           |           | PKG:19,92   |
| <b>300005<sup>S</sup> REPLACE AIRFRAME DE-ICING PUMP SUCTION FILTER Service ATA:30</b>        |         |           |                |                         |                           |           |           |             |
|   | MOS     | 06-Jun-18 |                |                         |                           |           |           |             |
|   | HRS     | 2965.25   | 1600 (+50/-50) |                         |                           |           |           |             |
| WC#: 30.045   | AFL     | 1073      |                |                         |                           |           |           |             |
|   |         |           |                | PROC. REF: AMM NO REF 1 |                           |           |           | PKG:24,92   |
| <b>300007 PURGE ICE PROTECTION SYSTEM Service ATA:30</b>                                      |         |           |                |                         |                           |           |           |             |
|   | MOS/MSC | 02-Apr-16 | A/R            |                         |                           |           |           |             |
|   | HRS     | 2351.57   |                |                         |                           |           |           |             |
| WC#: 30.090   | AFL     | 852       |                |                         |                           |           |           |             |
| <b>301001 TKS DE-ICER TANK Component ATA:30</b>   |         |           |                |                         |                           |           |           |             |
| PN:08301-01   | MOS/MSC | 16-Mar-10 | O/C            | TSN 0                   |                           |           |           |             |
| SN:VAVI09F561   | HRS     | 0         |                | TSN 0                   |                           |           |           |             |
| WC#: 30.010   | AFL     | 0         |                | TSN 0                   |                           |           |           |             |
|   |         |           |                | PROC. REF: AMM 30-10-35 |                           |           |           |             |
| <b>301007 AIRFRAME DE-ICING PUMP ASSEMBLY Component ATA:30</b>                                |         |           |                |                         |                           |           |           |             |
| PN:XA9511E009   | MOS/MSC | 16-Mar-10 | O/C            | TSN 0                   |                           |           |           |             |
| SN:CAVI09A1153  | HRS     | 0         |                | TSN 0                   |                           |           |           |             |
| WC#: 30.015   | AFL     | 0         |                | TSN 0                   |                           |           |           |             |
|   |         |           |                | PROC. REF: AMM 30-10-43 |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                 | Unit    | C/W                                      | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|---|---------|--|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 30 - ICE AND RAIN PROTECTION</b> |         |  |          |          |                           |           |           |                  |               |
| <b>301013</b>                           |         | <b>AIRFRAME DE-ICING FILTER ASSEMBLY</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:PN                                   | MOS/MSC | 16-Mar-10                                | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:UNKNOWN                              | HRS     | 0  |          |          | TSN 0                     |           |           |                  |               |
| WC#: 30.020                             | AFL     | 0  |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM 30-10-52                 |         |  |          |          |                           |           |           |                  |               |
| <b>301025</b>                           |         | <b>DE-ICING VALVE ASSEMBLY</b>           |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:FV131-1                              | MOS/MSC | 16-Mar-10                                | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:AST08E1438                           | HRS     | 0  |          |          | TSN 0                     |           |           |                  |               |
| WC#: 30.025                             | AFL     | 0  |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM 30-10-43                 |         |  |          |          |                           |           |           |                  |               |
| <b>301037</b>                           |         | <b>DE-ICING SYSTEM CONTENTS GAUGE</b>    |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:S458-3-191T                          | MOS/MSC | 16-Mar-10                                | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:83688                                | HRS     | 0  |          |          | TSN 0                     |           |           |                  |               |
| WC#: 30.030                             | AFL     | 0  |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |  |          |          |                           |           |           |                  |               |
| <b>301043</b>                           |         | <b>DE-ICING SYSTEM CONTENTS FLOAT</b>    |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:FRH070001                            | MOS/MSC | 16-Mar-10                                | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:21090742                             | HRS     | 0  |          |          | TSN 0                     |           |           |                  |               |
| WC#: 30.035                             | AFL     | 0  |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |  |          |          |                           |           |           |                  |               |
| <b>301063</b>                           |         | <b>EMPENNAGE TKS PROPORTION UNIT</b>     |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:PN                                   | MOS/MSC | 16-Mar-10                                | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:UNKNOWN                              | HRS     | 0  |          |          | TSN 0                     |           |           |                  |               |
| WC#: 30.050                             | AFL     | 0  |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM 30-10-25                 |         |  |          |          |                           |           |           |                  |               |
| <b>301067</b>                           |         | <b>TKS VENT VALVE</b>                    |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:FV141                                | MOS/MSC | 16-Mar-10                                | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:CAVI090976                           | HRS     | 0  |          |          | TSN 0                     |           |           |                  |               |
| WC#: 30.055                             | AFL     | 0  |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |  |          |          |                           |           |           |                  |               |
| <b>301069</b>                           |         | <b>TKS PRESSURE SWITCH</b>               |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:P067D075                             | MOS/MSC | 16-Mar-10                                | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:CAVI09J433                           | HRS     | 0  |          |          | TSN 0                     |           |           |                  |               |
| WC#: 30.060                             | AFL     | 0  |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |  |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                 | Unit    | C/W                                       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|---|---------|---|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 30 - ICE AND RAIN PROTECTION</b> |         |   |          |          |                           |           |           |                  |               |
| <b>301070</b>                           |         | <b>LEFT #1 INBOARD PANEL DISTRIBUTOR</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:25-8WS1513-53                        | MOS/MSC | 20-Jun-22                                 | O/C      |          | TSO 0                     |           |           |                  |               |
| SN:AST06G1499                           | HRS     | 3511.6                                    |          |          | TSO 0                     |           |           |                  |               |
|   | AFL     | 1288                                      |          |          | TSO 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |   |          |          |                           |           |           |                  |               |
| <b>301071</b>                           |         | <b>LEFT #2 INBOARD PANEL DISTRIBUTOR</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:D3377-02                             | MOS/MSC | 20-Jun-22                                 | O/C      |          | TSO 0                     |           |           |                  |               |
| SN:AST01D211                            | HRS     | 3511.6                                    |          |          | TSO 0                     |           |           |                  |               |
|   | AFL     | 1288                                      |          |          | TSO 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |   |          |          |                           |           |           |                  |               |
| <b>301072</b>                           |         | <b>LEFT #3 INBOARD PANEL DISTRIBUTOR</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:D3371-02                             | MOS/MSC | 20-Jun-22                                 | O/C      |          | TSO 0                     |           |           |                  |               |
| SN:AST02J189                            | HRS     | 3511.6                                    |          |          | TSO 0                     |           |           |                  |               |
|   | AFL     | 1288                                      |          |          | TSO 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |   |          |          |                           |           |           |                  |               |
| <b>301073</b>                           |         | <b>LEFT #4 CENTER PANEL DISTRIBUTOR</b>   |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:25-8WS1513-59                        | MOS/MSC | 20-Jun-22                                 | O/C      |          | TSO 0                     |           |           |                  |               |
| SN:AST99H142                            | HRS     | 3511.6                                    |          |          | TSO 0                     |           |           |                  |               |
|   | AFL     | 1288                                      |          |          | TSO 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |   |          |          |                           |           |           |                  |               |
| <b>301074</b>                           |         | <b>LEFT #5 CENTER PANEL DISTRIBUTOR</b>   |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:25-8WS1513-69A                       | MOS/MSC | 20-Jun-22                                 | O/C      |          | TSO 0                     |           |           |                  |               |
| SN:AST05H776                            | HRS     | 3511.6                                    |          |          | TSO 0                     |           |           |                  |               |
|   | AFL     | 1288                                      |          |          | TSO 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |   |          |          |                           |           |           |                  |               |
| <b>301075</b>                           |         | <b>LEFT #6 CENTER PANEL DISTRIBUTOR</b>   |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:25-8WS1513-71A                       | MOS/MSC | 20-Jun-22                                 | O/C      |          | TSO 0                     |           |           |                  |               |
| SN:AST96B345                            | HRS     | 3511.6                                    |          |          | TSO 0                     |           |           |                  |               |
|   | AFL     | 1288                                      |          |          | TSO 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |   |          |          |                           |           |           |                  |               |
| <b>301077</b>                           |         | <b>RIGHT #1 INBOARD PANEL DISTRIBUTOR</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:30</b> |
| PN:25-8WS1513-54                        | MOS/MSC | 20-Jun-22                                 | O/C      |          | TSO 0                     |           |           |                  |               |
| SN:AST03M092                            | HRS     | 3511.6                                    |          |          | TSO 0                     |           |           |                  |               |
|   | AFL     | 1288                                      |          |          | TSO 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF               |         |   |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 30 - ICE AND RAIN PROTECTION</b>                              |         |           |          |          |                           |           |           |             |
| <b>301078 RIGHT #2 INBOARD PANEL DISTRIBUTOR Component ATA:30</b>    |         |           |          |          |                           |           |           |             |
| PN:D3378-02  | MOS/MSC | 20-Jun-22 | O/C      |          | TSO 0                     |           |           |             |
| SN:AST02J433   | HRS     | 3511.6    |          |          | TSO 0                     |           |           |             |
|  | AFL     | 1288      |          |          | TSO 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>301079 RIGHT #3 INBOARD PANEL DISTRIBUTOR Component ATA:30</b>    |         |           |          |          |                           |           |           |             |
| PN:D3372-02  | MOS/MSC | 20-Jun-22 | O/C      |          | TSR 0                     |           |           |             |
| SN:AST07C295   | HRS     | 3511.6    |          |          | TSR 0                     |           |           |             |
|  | AFL     | 1288      |          |          | TSR 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>301080 RIGHT #4 CENTER PANEL DISTRIBUTOR Component ATA:30</b>     |         |           |          |          |                           |           |           |             |
| PN:25-8WS1513-60   | MOS/MSC | 20-Jun-22 | O/C      |          | TSR 0                     |           |           |             |
| SN:CAVI09G774  | HRS     | 3511.6    |          |          | TSR 0                     |           |           |             |
|  | AFL     | 1288      |          |          | TSR 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>301081 RIGHT #5 CENTER PANEL DISTRIBUTOR Component ATA:30</b>     |         |           |          |          |                           |           |           |             |
| PN:25-8WS1513-70A  | MOS/MSC | 20-Jun-22 | O/C      |          | TSO 0                     |           |           |             |
| SN:AST96B334   | HRS     | 3511.6    |          |          | TSO 0                     |           |           |             |
|  | AFL     | 1288      |          |          | TSO 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>301082 RIGHT #6 CENTER PANEL DISTRIBUTOR Component ATA:30</b>     |         |           |          |          |                           |           |           |             |
| PN:25-8WS1513-72A  | MOS/MSC | 20-Jun-22 | O/C      |          | TSO 0                     |           |           |             |
| SN:CAVI21D003  | HRS     | 3511.6    |          |          | TSO 0                     |           |           |             |
|  | AFL     | 1288      |          |          | TSO 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>304019 NO. 1 WINDSCREEN (A PANEL) CONTROLLER Component ATA:30</b> |         |           |          |          |                           |           |           |             |
| PN:ND0075-2011   | MOS/MSC | 03-Aug-21 | O/C      |          |                           |           |           |             |
| SN:L530565   | HRS     | 3405      |          |          |                           |           |           |             |
| WC#: 30.070  | AFL     | 1243      |          |          |                           |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>304020 NO. 2 WINDSCREEN (A PANEL) CONTROLLER Component ATA:30</b> |         |           |          |          |                           |           |           |             |
| PN:ND0075-2011   | MOS/MSC | 08-Nov-11 | O/C      |          | TSN 0                     |           |           |             |
| SN:L380304   | HRS     | 764       |          |          | TSN 0                     |           |           |             |
| WC#: 30.070  | AFL     | 284       |          |          | TSN 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                      | Unit                                   | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--|--|-----------|--------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 30 - ICE AND RAIN PROTECTION</b>      |  |           |              |          |                           |           |           |             |        |
| 304022                                       | NO. 1 WINDSCREEN (B PANEL) CONTROLLER  |           |              |          |                           |           |           | Component   | ATA:30 |
| PN:ND0075-2001                               | MOS/MSC                                | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |        |
| SN:L376379                                   | HRS                                    | 0         |              | TSN 0    |                           |           |           |             |        |
| WC#: 30.075                                  | AFL                                    | 0         |              | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                    |  |           |              |          |                           |           |           |             |        |
| 304023                                       | NO. 2 WINDSCREEN (B PANEL) CONTROLLER  |           |              |          |                           |           |           | Component   | ATA:30 |
| PN:ND0075-2001                               | MOS/MSC                                | 03-Aug-21 | O/C          | TSN 1    |                           |           |           |             |        |
| SN:L528747                                   | HRS                                    | 3405      |              | TSN 0    |                           |           |           |             |        |
| WC#: 30.075                                  | AFL                                    | 1243      |              | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                    |  |           |              |          |                           |           |           |             |        |
| 308001                                       | ROTARY ICE DETECTOR                    |           |              |          |                           |           |           | Component   | ATA:30 |
| PN:NF0075-667                                | MOS/MSC                                | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |        |
| SN:L379792                                   | HRS                                    | 0         |              | TSN 0    |                           |           |           |             |        |
| WC#: 30.085                                  | AFL                                    | 0         |              | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 30-80-11                      |  |           |              |          |                           |           |           |             |        |
| <b>ATA 31 - INDICATING/RECORDING SYSTEMS</b> |  |           |              |          |                           |           |           |             |        |
| 310001 <sup>S</sup>                          | CHECK FLIGHT DATA RECORDER (IF FITTED) |           |              |          |                           |           |           | Service     | ATA:31 |
|  | MOS                                    | 25-Jul-24 | 12 (+1m/-1m) |          |                           |           |           |             |        |
|  | HRS                                    | 3908.4    |              |          |                           |           |           |             |        |
| WC#: 31.085                                  | AFL                                    | 1492      |              |          |                           |           |           |             |        |
| PKG:43,94                                    |  |           |              |          |                           |           |           |             |        |
| 310002                                       | LIGHTNING SENSOR ANTENNA               |           |              |          |                           |           |           | Component   | ATA:31 |
| PN:PN  | MOS/MSC                                | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                                   | HRS                                    | 0         |              | TSN 0    |                           |           |           |             |        |
| WC#: 31.015                                  | AFL                                    | 0         |              | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF 1                      |  |           |              |          |                           |           |           |             |        |
| 310100                                       | LIGHTNING PROCESSOR UNIT               |           |              |          |                           |           |           | Component   | ATA:31 |
| PN:PN  | MOS/MSC                                | 16-Mar-10 | O/C          | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                                   | HRS                                    | 0         |              | TSN 0    |                           |           |           |             |        |
| WC#: 31.010                                  | AFL                                    | 0         |              | TSN 0    |                           |           |           |             |        |
| PROC. REF: MMA 34-43-10                      |  |           |              |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                      | Unit    | C/W                           | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition |               |
|--|---------|-------------------------------|----------|----------|---------------------------|-----------|------------------|-------------|---------------|
| <b>ATA 31 - INDICATING/RECORDING SYSTEMS</b> |         |                               |          |          |                           |           |                  |             |               |
| <b>311001</b>                                |         | <b>TKS TIMER</b>              |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:100-1805-02                               | MOS/MSC | 16-Mar-10                     | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:081308                                    | HRS     | 0                             |          | TSN 0    |                           |           |                  |             |               |
| WC#: 31.020                                  | AFL     | 0                             |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                               |          |          |                           |           |                  |             |               |
| <b>312001</b>                                |         | <b>PILOT CLOCK</b>            |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:PN  | MOS/MSC | 16-Mar-10                     | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                                   | HRS     | 0                             |          | TSN 0    |                           |           |                  |             |               |
| WC#: 31.025                                  | AFL     | 0                             |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                               |          |          |                           |           |                  |             |               |
| <b>312002</b>                                |         | <b>COPILOT CLOCK</b>          |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:PN  | MOS/MSC | 16-Mar-10                     | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:UNKNOWN                                   | HRS     | 0                             |          | TSN 0    |                           |           |                  |             |               |
| WC#: 31.025                                  | AFL     | 0                             |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                               |          |          |                           |           |                  |             |               |
| <b>312008</b>                                |         | <b>O.A.T. INDICATOR</b>       |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:2141-1-14                                 | MOS/MSC | 05-Aug-11                     | O/C      | TSO 0    |                           |           |                  |             |               |
| SN:82480                                     | HRS     | 608.55                        |          | TSO 0    |                           |           |                  |             |               |
| WC#: 31.030                                  | AFL     | 231                           |          | TSO 0    |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                               |          |          |                           |           |                  |             |               |
| <b>312009</b>                                |         | <b>PITOT AMMETER</b>          |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:2132-1-62                                 | MOS/MSC | 16-Mar-10                     | O/C      | TSN 0    |                           |           |                  |             |               |
| SN:83047                                     | HRS     | 0                             |          | TSN 0    |                           |           |                  |             |               |
| WC#: 31.035                                  | AFL     | 0                             |          | TSN 0    |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                               |          |          |                           |           |                  |             |               |
| <b>313003</b>                                |         | <b>NO. 1 CURRENT MONITOR-</b> |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:E37040S                                   | MOS/MSC | 16-Mar-10                     | O/C      |          |                           |           |                  |             |               |
| SN:5535                                      | HRS     | 0                             |          |          |                           |           |                  |             |               |
|  | AFL     | 0                             |          |          |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                               |          |          |                           |           |                  |             |               |
| <b>313004</b>                                |         | <b>NO. 2 CURRENT MONITOR-</b> |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:E37040S                                   | MOS/MSC | 16-Mar-10                     | O/C      |          |                           |           |                  |             |               |
| SN:5538                                      | HRS     | 0                             |          |          |                           |           |                  |             |               |
|  | AFL     | 0                             |          |          |                           |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                               |          |          |                           |           |                  |             |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                      | Unit    | C/W                                  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition |               |
|--|---------|--------------------------------------|----------|----------|---------------------------|-----------|------------------|-------------|---------------|
| <b>ATA 31 - INDICATING/RECORDING SYSTEMS</b> |         |                                      |          |          |                           |           |                  |             |               |
| <b>313005</b>                                |         | <b>LEFT CURRENT LEVEL INDICATOR</b>  |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:770-537                                   | MOS/MSC | 16-Mar-10                            | O/C      |          | TSN 0                     |           |                  |             |               |
| SN:2985                                      | HRS     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| WC#: 31.040                                  | AFL     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                                      |          |          |                           |           |                  |             |               |
| <b>313006</b>                                |         | <b>RIGHT CURRENT LEVEL INDICATOR</b> |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:770-537                                   | MOS/MSC | 16-Mar-10                            | O/C      |          | TSN 0                     |           |                  |             |               |
| SN:2988                                      | HRS     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| WC#: 31.040                                  | AFL     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                                      |          |          |                           |           |                  |             |               |
| <b>313007</b>                                |         | <b>CABIN TEMPERATURE INDICATOR</b>   |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:2132-01-0015                              | MOS/MSC | 16-Mar-10                            | O/C      |          | TSN 0                     |           |                  |             |               |
| SN:82865                                     | HRS     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| WC#: 31.045                                  | AFL     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                                      |          |          |                           |           |                  |             |               |
| <b>313008</b>                                |         | <b>DC VOLTMETER</b>                  |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:2132-01-0012                              | MOS/MSC | 16-Mar-10                            | O/C      |          | TSN 0                     |           |                  |             |               |
| SN:82852                                     | HRS     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| WC#: 31.050                                  | AFL     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                                      |          |          |                           |           |                  |             |               |
| <b>313009</b>                                |         | <b>LEFT DC AMMETER</b>               |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:2132-01-0013                              | MOS/MSC | 16-Mar-10                            | O/C      |          | TSN 0                     |           |                  |             |               |
| SN:83475                                     | HRS     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| WC#: 31.055                                  | AFL     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                                      |          |          |                           |           |                  |             |               |
| <b>313010</b>                                |         | <b>AC VOLTMETER</b>                  |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:2132-1-14                                 | MOS/MSC | 03-Aug-21                            | O/C      |          | TSO 26                    |           |                  |             |               |
| SN:82784                                     | HRS     | 3405                                 |          |          | TSO 0                     |           |                  |             |               |
| WC#: 31.060                                  | AFL     | 1243                                 |          |          | TSO 0                     |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                                      |          |          |                           |           |                  |             |               |
| <b>313011</b>                                |         | <b>RIGHT DC AMMETER</b>              |          |          |                           |           | <b>Component</b> |             | <b>ATA:31</b> |
| PN:2132-01-0013                              | MOS/MSC | 16-Mar-10                            | O/C      |          | TSN 0                     |           |                  |             |               |
| SN:83466                                     | HRS     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| WC#: 31.065                                  | AFL     | 0                                    |          |          | TSN 0                     |           |                  |             |               |
| PROC. REF: GENERIC NO REF                    |         |                                      |          |          |                           |           |                  |             |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                      | Unit    | C/W                                   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|--|---------|---------------------------------------|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 31 - INDICATING/RECORDING SYSTEMS</b> |         |                                       |          |          |                           |           |           |                  |               |
| <b>313012</b>                                |         | <b>FLIGHT DATA ACCELEROMETER</b>      |          |          |                           |           |           | <b>Component</b> | <b>ATA:31</b> |
| PN:971-4193-001                              | MOS/MSC | 05-May-10                             | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:13843                                     | HRS     | 4.7                                   |          |          | TSN 0                     |           |           |                  |               |
| WC#: 31.120                                  | AFL     | 4                                     |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: MMA 31-30-20                      |         |                                       |          |          |                           |           |           |                  |               |
| <b>313014</b>                                |         | <b>DUCT AIR TEMPERATURE INDICATOR</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:31</b> |
| PN:2132-01-0018                              | MOS/MSC | 16-Mar-10                             | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:82855                                     | HRS     | 0                                     |          |          | TSN 0                     |           |           |                  |               |
| WC#: 31.070                                  | AFL     | 0                                     |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF                    |         |                                       |          |          |                           |           |           |                  |               |
| <b>313015</b>                                |         | <b>TEMPERATURE SELECTOR</b>           |          |          |                           |           |           | <b>Component</b> | <b>ATA:31</b> |
| PN:25-6MC415                                 | MOS/MSC | 16-Mar-10                             | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:627578-01775                              | HRS     | 0                                     |          |          | TSN 0                     |           |           |                  |               |
| WC#: 31.075                                  | AFL     | 0                                     |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF                    |         |                                       |          |          |                           |           |           |                  |               |
| <b>313020</b>                                |         | <b>FUEL PROCESSOR UNIT</b>            |          |          |                           |           |           | <b>Component</b> | <b>ATA:31</b> |
| PN:0107KPU1                                  | MOS/MSC | 16-Mar-10                             | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:FE005648                                  | HRS     | 0                                     |          |          | TSN 0                     |           |           |                  |               |
| WC#: 31.080                                  | AFL     | 0                                     |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: GENERIC NO REF                    |         |                                       |          |          |                           |           |           |                  |               |
| <b>313023</b>                                |         | <b>FLIGHT DATA RECORDER</b>           |          |          |                           |           |           | <b>Component</b> | <b>ATA:31</b> |
| PN:980-4710-003                              | MOS/MSC | 20-Jul-18                             | O/C      |          | TSN 98                    |           |           |                  |               |
| SN:ARFDR-02353                               | HRS     | 3000.32                               |          |          | TSN 2995.38               |           |           |                  |               |
| WC#: 31.085                                  | AFL     | 1088                                  |          |          | TSN 1084                  |           |           |                  |               |
| PROC. REF: MMA 31-30-20                      |         |                                       |          |          |                           |           |           |                  |               |
| <b>313030</b>                                |         | <b>FILTER UNIT</b>                    |          |          |                           |           |           | <b>Component</b> | <b>ATA:31</b> |
| PN:25-9NF4027-645                            | MOS/MSC | 16-Mar-10                             | O/C      |          |                           |           |           |                  |               |
| SN:L379530                                   | HRS     | 0                                     |          |          |                           |           |           |                  |               |
|  | AFL     | 0                                     |          |          |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF                    |         |                                       |          |          |                           |           |           |                  |               |
| <b>313031</b>                                |         | <b>FILTER UNIT</b>                    |          |          |                           |           |           | <b>Component</b> | <b>ATA:31</b> |
| PN:25-9NF4027-647                            | MOS/MSC | 16-Mar-10                             | O/C      |          |                           |           |           |                  |               |
| SN:L379598                                   | HRS     | 0                                     |          |          |                           |           |           |                  |               |
|  | AFL     | 0                                     |          |          |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF                    |         |                                       |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                      | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 31 - INDICATING/RECORDING SYSTEMS</b> |  |           |          |          |                           |           |           |             |        |
| 313032                                       | FILTER UNIT  |           |          |          |                           |           |           | Component   | ATA:31 |
| PN:25-9NF4027-649                            | MOS/MSC  | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
| SN:L379562                                   | HRS  | 0         |          |          |                           |           |           |             |        |
|  | AFL  | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                    |  |           |          |          |                           |           |           |             |        |
| 313033                                       | FILTER UNIT  |           |          |          |                           |           |           | Component   | ATA:31 |
| PN:25-9NF4027-651                            | MOS/MSC  | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
| SN:L379554                                   | HRS  | 0         |          |          |                           |           |           |             |        |
|  | AFL  | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                    |  |           |          |          |                           |           |           |             |        |
| 313062                                       | FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON                 |           |          |          |                           |           |           | Component   | ATA:31 |
| PN:PN  | MOS/MSC  | 14-May-20 | O/C      |          |                           |           |           |             |        |
| SN:AT116985                                  | HRS  | 3357.57   |          |          |                           |           |           |             |        |
| WC#: 31.085                                  | AFL  | 1222      |          |          |                           |           |           |             |        |
| PROC. REF: MMA 31-30-20                      |  |           |          |          |                           |           |           |             |        |
| 313064                                       | CLEAN/TEST FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON      |           |          |          |                           |           |           | Service     | ATA:31 |
|  | MOS  | 11-Jul-24 | 24       |          | 11-Jul-26                 |           | 712 d     |             |        |
|  | HRS  | 3907.4    |          |          |                           |           |           |             |        |
| WC#: 31.085                                  | AFL  | 1491      |          |          |                           |           |           |             |        |
| 313067                                       | FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY         |           |          |          |                           |           |           | Component   | ATA:31 |
| PN:PN  | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                                   | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|  | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                    |  |           |          |          |                           |           |           |             |        |
| 313068                                       | REPLACE FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY |           |          |          |                           |           |           | Service     | ATA:31 |
|  | MOS/MSC  | 14-May-20 | DUE      |          | 01-Aug-25 (M)             |           | 368 d     |             |        |
|  | HRS  | 3357.57   |          |          |                           |           |           |             |        |
| WC#: 31.085                                  | AFL  | 1222      |          |          |                           |           |           |             |        |
| 313074                                       | TEST FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON            |           |          |          |                           |           |           | Service     | ATA:31 |
|  | MOS/MSC  | 29-Apr-20 | N/R      |          |                           |           |           |             |        |
|  | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 31.085                                  | AFL  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 31 - INDICATING/RECORDING SYSTEMS</b>   |         |           |          |          |                           |           |           |             |
| <b>313101 ANGLE OF ATTACK INDICATOR COMPUTER</b> <span style="float:right">Component ATA:31</span> |         |           |          |          |                           |           |           |             |
| PN:C87705-4  | MOS/MSC | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |
| SN:1024  | HRS     | 0         |          |          | TSN 0                     |           |           |             |
| WC#: 31.095  | AFL     | 0         |          |          | TSN 0                     |           |           |             |
| PROC. REF: AMM 31-20-05  |         |           |          |          |                           |           |           |             |
| <b>313109 NO. 1 ANGLE OF ATTACK INDEXER</b> <span style="float:right">Component ATA:31</span>      |         |           |          |          |                           |           |           |             |
| PN:965-0113-003  | MOS/MSC | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |
| SN:3403  | HRS     | 0         |          |          | TSN 0                     |           |           |             |
| WC#: 31.100  | AFL     | 0         |          |          | TSN 0                     |           |           |             |
| PROC. REF: AMM 31-20-05  |         |           |          |          |                           |           |           |             |
| <b>313110 NO. 2 ANGLE OF ATTACK INDEXER</b> <span style="float:right">Component ATA:31</span>      |         |           |          |          |                           |           |           |             |
| PN:965-0113-003  | MOS/MSC | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |
| SN:3406  | HRS     | 0         |          |          | TSN 0                     |           |           |             |
| WC#: 31.100  | AFL     | 0         |          |          | TSN 0                     |           |           |             |
| PROC. REF: AMM 31-20-05  |         |           |          |          |                           |           |           |             |
| <b>313201 BRAKE PRESSURE INDICATOR</b> <span style="float:right">Component ATA:31</span>           |         |           |          |          |                           |           |           |             |
| PN:696-1-13  | MOS/MSC | 12-Oct-10 | O/C      |          | TSN 0                     |           |           |             |
| SN:82490   | HRS     | 158.2     |          |          | TSN 0                     |           |           |             |
| WC#: 31.105  | AFL     | 73        |          |          | TSN 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>314008 NO. 1 INCLINOMETER</b> <span style="float:right">Component ATA:31</span>                 |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          |          | TSN 0                     |           |           |             |
| WC#: 31.115  | AFL     | 0         |          |          | TSN 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>314009 NO. 2 INCLINOMETER</b> <span style="float:right">Component ATA:31</span>                 |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          |          | TSN 0                     |           |           |             |
| WC#: 31.115  | AFL     | 0         |          |          | TSN 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>314012 NO. 1 IAPS (ICC 3000) CARD CAGE</b> <span style="float:right">Component ATA:31</span>    |         |           |          |          |                           |           |           |             |
| PN:822-1129-001  | MOS/MSC | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |
| SN:3J4BK   | HRS     | 0         |          |          | TSN 0                     |           |           |             |
|  | AFL     | 0         |          |          | TSN 0                     |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 31 - INDICATING/RECORDING SYSTEMS</b>                                |         |           |          |          |                           |           |           |             |
| <b>314014 MAINTENANCE DIAGNOSTIC COMPUTER</b> Component ATA:31              |         |           |          |          |                           |           |           |             |
| PN:822-1987-005   | MOS/MSC | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |
| SN:3J4YR  | HRS     | 0         |          |          | TSN 0                     |           |           |             |
| WC#: 31.130   | AFL     | 0         |          |          | TSN 0                     |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>315001<sup>U</sup> (RUDDER SURFACE) POTENTIOMETER</b> Component ATA:31   |         |           |          |          |                           |           |           |             |
| PN:M2078-4-502  | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:NSN  | HRS     | 4.7       |          |          |                           |           |           |             |
|   | AFL     | 4         |          |          |                           |           |           |             |
| <b>315002<sup>U</sup> (RUDDER CONTROL) POTENTIOMETER</b> Component ATA:31   |         |           |          |          |                           |           |           |             |
| PN:M2078-4-502  | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:NSN  | HRS     | 4.7       |          |          |                           |           |           |             |
|   | AFL     | 4         |          |          |                           |           |           |             |
| <b>315003<sup>U</sup> (ELEVATOR CONTROL) POTENTIOMETER</b> Component ATA:31 |         |           |          |          |                           |           |           |             |
| PN:M2078-4-502  | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:NSN  | HRS     | 4.7       |          |          |                           |           |           |             |
|   | AFL     | 4         |          |          |                           |           |           |             |
| <b>315004<sup>U</sup> (AILERON CONTROL) POTENTIOMETER</b> Component ATA:31  |         |           |          |          |                           |           |           |             |
| PN:M2078-4-502  | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:NSN  | HRS     | 4.7       |          |          |                           |           |           |             |
|   | AFL     | 4         |          |          |                           |           |           |             |
| <b>315005<sup>U</sup> (ELEVATOR SURFACE) POTENTIOMETER</b> Component ATA:31 |         |           |          |          |                           |           |           |             |
| PN:6005-2007-1  | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:2759   | HRS     | 4.7       |          |          |                           |           |           |             |
|   | AFL     | 4         |          |          |                           |           |           |             |
| <b>315006<sup>U</sup> (AILERON SURFACE) POTENTIOMETER</b> Component ATA:31  |         |           |          |          |                           |           |           |             |
| PN:6005-2007-1  | MOS/MSC | 05-May-10 | O/C      |          |                           |           |           |             |
| SN:2806   | HRS     | 4.7       |          |          |                           |           |           |             |
|   | AFL     | 4         |          |          |                           |           |           |             |
| <b>315010<sup>U</sup> FLIGHT DATA ACQUISITION UNIT</b> Component ATA:31     |         |           |          |          |                           |           |           |             |
| PN:967-0320-001   | MOS/MSC | 12-Nov-10 | O/C      |          |                           |           |           |             |
| SN:DFDAU-03009  | HRS     | 176       |          |          |                           |           |           |             |
|   | AFL     | 88        |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit   | C/W       | Interval      | TSX/Adj.                 | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------------|--|-----------|---------------|--------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 32 - LANDING GEAR</b> |  |           |               |                          |                           |           |           |             |        |
| 320001 <sup>S</sup>          | TEST BRAKING SYSTEMS   |           |               |                          |                           |           |           | Service     | ATA:32 |
|                              | MOS  | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                              | HRS  | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 32.305                  | AFL  | 1243      |               |                          |                           |           |           |             |        |
|                              |  |           |               | PROC. REF: AMM 32-40-00  |                           |           |           | PKG:18,91   |        |
| 320002 <sup>S</sup>          | FUNCTIONAL TEST MAXARET UNITS  |           |               |                          |                           |           |           | Service     | ATA:32 |
|                              | MOS  | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                              | HRS  | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 32.370                  | AFL  | 1243      |               |                          |                           |           |           |             |        |
|                              |  |           |               | PROC. REF: AMM 32-40-101 |                           |           |           | PKG:18,91   |        |
| 320003 <sup>S</sup>          | CHECK NOSE GEAR LEG ASSEMBLY   |           |               |                          |                           |           |           | Service     | ATA:32 |
|                              | MOS  | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                              | HRS  | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 32.430                  | AFL  | 1243      |               |                          |                           |           |           |             |        |
|                              |  |           |               |                          |                           |           |           | PKG:18,91   |        |
| 320004 <sup>S</sup>          | CHECK NOSE GEAR LEG LOCK AND CHANGE OVER MICROSWITCHES OPERATING MECHANISM |           |               |                          |                           |           |           | Service     | ATA:32 |
|                              | MOS  | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                              | HRS  | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 32.435                  | AFL  | 1243      |               |                          |                           |           |           |             |        |
|                              |  |           |               |                          |                           |           |           | PKG:18,91   |        |
| 320005 <sup>S</sup>          | INSPECT NOSEWHEEL STEERING JACK  |           |               |                          |                           |           |           | Service     | ATA:32 |
|                              | MOS  | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                              | HRS  | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 32.470                  | AFL  | 1243      |               |                          |                           |           |           |             |        |
|                              |  |           |               | PROC. REF: AMM 32-50-00  |                           |           |           | PKG:18,91   |        |
| 320006 <sup>S</sup>          | INSPECT NOSE GEAR RETRACTION AND STEERING SYSTEM SPRING STRUTS             |           |               |                          |                           |           |           | Service     | ATA:32 |
|                              | MOS  | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                              | HRS  | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 32.450                  | AFL  | 1243      |               |                          |                           |           |           |             |        |
|                              |  |           |               |                          |                           |           |           | PKG:18,91   |        |
| 320007 <sup>S</sup>          | INSPECT NOSEWHEEL STEERING ON/OFF VALVE                                    |           |               |                          |                           |           |           | Service     | ATA:32 |
|                              | MOS  | 03-Aug-21 |               |                          |                           |           |           |             |        |
|                              | HRS  | 3405      | 800 (+40/-10) |                          |                           |           |           |             |        |
| WC#: 32.350                  | AFL  | 1243      |               |                          |                           |           |           |             |        |
|                              |  |           |               |                          |                           |           |           | PKG:18,91   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit  | C/W       | Interval      | TSX/Adj.                              | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------------|---|-----------|---------------|---------------------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 32 - LANDING GEAR</b> |   |           |               |                                       |                           |           |           |             |        |
| 320008 <sup>S</sup>          | CHECK NOSE GEAR DRAG STAY ASSEMBLY                        |           |               |                                       |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 03-Aug-21 |               |                                       |                           |           |           |             |        |
|                              | HRS   | 3405      | 800 (+40/-10) |                                       |                           |           |           |             |        |
| WC#: 32.440                  | AFL   | 1243      |               |                                       |                           |           |           |             |        |
|                              |   |           |               | PROC. REF: AMM 32-20-21               |                           |           |           | PKG:18,91   |        |
| 320009 <sup>S</sup>          | DETAIL INSPECT NOSEWHEEL STEERING JACK SELECTOR VALVE     |           |               |                                       |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 03-Aug-21 |               |                                       |                           |           |           |             |        |
|                              | HRS   | 3405      | 800 (+40/-10) |                                       |                           |           |           |             |        |
| WC#: 32.545                  | AFL   | 1243      |               |                                       |                           |           |           |             |        |
|                              |   |           |               | PROC. REF: AMM 32-50-11               |                           |           |           | PKG:18,91   |        |
| 320010 <sup>S</sup>          | CHECK MAIN GEAR LEG ASSEMBLIES                            |           |               |                                       |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 03-Aug-21 |               |                                       |                           |           |           |             |        |
|                              | HRS   | 3405      | 800 (+40/-10) |                                       |                           |           |           |             |        |
| WC#: 32.420                  | AFL   | 1243      |               |                                       |                           |           |           |             |        |
|                              |   |           |               | PROC. REF: AMM NO REF 1               |                           |           |           | PKG:18,91   |        |
| 320011 <sup>S</sup>          | INSPECT MAIN LANDING GEAR SIDE-STAYS                      |           |               |                                       |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 03-Aug-21 |               |                                       |                           |           |           |             |        |
|                              | HRS   | 3405      | 800 (+40/-10) |                                       |                           |           |           |             |        |
| WC#: 32.010                  | AFL   | 1243      |               |                                       |                           |           |           |             |        |
|                              |   |           |               | PROC. REF: AMM 32-10-25, AMM 32-10-25 |                           |           |           | PKG:18,91   |        |
| 320012 <sup>S</sup>          | CHECK MAIN LANDING GEAR TORQUE LINKS                      |           |               |                                       |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 03-Aug-21 |               |                                       |                           |           |           |             |        |
|                              | HRS   | 3405      | 800 (+40/-10) |                                       |                           |           |           |             |        |
| WC#: 32.015                  | AFL   | 1243      |               |                                       |                           |           |           |             |        |
|                              |   |           |               | PROC. REF: AMM 32-10-12               |                           |           |           | PKG:18,91   |        |
| 320013 <sup>S</sup>          | INSPECT MAIN LANDING GEAR DOORS                           |           |               |                                       |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 03-Aug-21 |               |                                       |                           |           |           |             |        |
|                              | HRS   | 3405      | 800 (+40/-10) |                                       |                           |           |           |             |        |
| WC#: 32.460                  | AFL   | 1243      |               |                                       |                           |           |           |             |        |
|                              |   |           |               |                                       |                           |           |           | PKG:18,91   |        |
| 320014 <sup>S</sup>          | INSPECT/CLEAN MAIN LANDING GEAR DOOR UPLOCK SPRING STRUTS |           |               |                                       |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 03-Aug-21 |               |                                       |                           |           |           |             |        |
|                              | HRS   | 3405      | 800 (+40/-10) |                                       |                           |           |           |             |        |
| WC#: 32.425                  | AFL   | 1243      |               |                                       |                           |           |           |             |        |
|                              |   |           |               |                                       |                           |           |           | PKG:18,91   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit  | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------------|---|-----------|-----------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 32 - LANDING GEAR</b> |   |           |                 |          |                           |           |           |             |        |
| 320015 <sup>S</sup>          | INSPECT REVERSING VALVES AND OPERATING MECHANISMS           |           |                 |          |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 03-Aug-21 |                 |          |                           |           |           |             |        |
|                              | HRS   | 3405      | 800 (+40/-10)   |          |                           |           |           |             |        |
| WC#: 32.445                  | AFL   | 1243      |                 |          |                           |           |           | PKG:18,91   |        |
| 320016 <sup>S</sup>          | CHECK STEERING SYSTEM CABLES AND CHAINS                     |           |                 |          |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 06-Jun-18 |                 |          |                           |           |           |             |        |
|                              | HRS   | 2965.25   | 1600 (+50/-50)  |          |                           |           |           |             |        |
| WC#: 32.475                  | AFL   | 1073      |                 |          |                           |           |           | PKG:22,92   |        |
|                              |   |           |                 |          | PROC. REF: AMM 32-50-00   |           |           |             |        |
| 320017 <sup>S</sup>          | CHECK NOSE LANDING GEAR RETRACTION SPRING STRUT             |           |                 |          |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 06-Jun-18 |                 |          |                           |           |           |             |        |
|                              | HRS   | 2965.25   | 1600 (+50/-50)  |          |                           |           |           |             |        |
| WC#: 32.180                  | AFL   | 1073      |                 |          |                           |           |           | PKG:30,92   |        |
|                              |   |           |                 |          | PROC. REF: AMM 32-20-21   |           |           |             |        |
| 320018 <sup>S</sup>          | CHECK NOSEWHEEL STEERING SYSTEM SPRING STRUT BREAK-OUT LOAD |           |                 |          |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 06-Jun-18 |                 |          |                           |           |           |             |        |
|                              | HRS   | 2965.25   | 1600 (+50/-50)  |          |                           |           |           |             |        |
| WC#: 32.350                  | AFL   | 1073      |                 |          |                           |           |           | PKG:30,92   |        |
| 320019 <sup>S</sup>          | INSPECT/CLEAN STEERING SYSTEM FILTER ELEMENT                |           |                 |          |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 06-Jun-18 |                 |          |                           |           |           |             |        |
|                              | HRS   | 2965.25   | 3200 (+150/-50) |          |                           |           |           |             |        |
| WC#: 32.385                  | AFL   | 1073      |                 |          |                           |           |           | PKG:42,93   |        |
|                              |   |           |                 |          | PROC. REF: AMM 32-30-22   |           |           |             |        |
| 320020 <sup>S</sup>          | CLEAN FILTERS, HYDRAULIC SUPPLY (4 OFF)                     |           |                 |          |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 06-Jun-18 |                 |          |                           |           |           |             |        |
|                              | HRS   | 2965.25   | 3200 (+150/-50) |          |                           |           |           |             |        |
| WC#: 32.185                  | AFL   | 1073      |                 |          |                           |           |           | PKG:42,93   |        |
|                              |   |           |                 |          | PROC. REF: AMM 32-30-22   |           |           |             |        |
| 320021 <sup>S</sup>          | CLEAN RESTRICTOR VALVES                                     |           |                 |          |                           |           |           | Service     | ATA:32 |
|                              | MOS   | 06-Jun-18 |                 |          |                           |           |           |             |        |
|                              | HRS   | 2965.25   | 3200 (+150/-50) |          |                           |           |           |             |        |
| WC#: 32.145                  | AFL   | 1073      |                 |          |                           |           |           | PKG:42,93   |        |
|                              |   |           |                 |          | PROC. REF: AMM 32-30-01   |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit   | C/W       | Interval       | TSX/Adj.                               | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|------------------------------|--|-----------|----------------|--|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 32 - LANDING GEAR</b> |  |           |                |  |                           |           |             |             |        |
| 320022 <sup>S</sup>          | CHECK BRAKE MASTER CYLINDERS                       |           |                |  |                           |           |             | Service     | ATA:32 |
|                              | MOS  | 03-Aug-21 |                |  |                           |           |             |             |        |
|                              | HRS  | 3405      | 800 (+40/-10)  |  |                           |           |             |             |        |
| WC#: 32.465                  | AFL  | 1243      |                |  |                           |           |             |             |        |
|                              |  |           |                | PROC. REF: AMM 32-40-00                |                           |           |             | PKG:10,91   |        |
| 320023 <sup>S</sup>          | CHECK BRAKE HOSES TO MASTER CYLINDERS              |           |                |  |                           |           |             | Service     | ATA:32 |
|                              | MOS  | 06-Jun-18 |                |  |                           |           |             |             |        |
|                              | HRS  | 2965.25   | 1600 (+50/-50) |  |                           |           |             |             |        |
| WC#: 32.455                  | AFL  | 1073      |                |  |                           |           |             | PKG:22,92   |        |
| 320024 <sup>S</sup>          | REMOVE/INSPECT AXLE/MAXARET/MODULATOR/PLUNGER TUBE |           |                |  |                           |           |             | Service     | ATA:32 |
|                              | MOS  | 06-Jun-18 |                |  |                           |           |             |             |        |
|                              | HRS  | 2965.25   | 1600 (+50/-50) |  |                           |           |             |             |        |
| WC#: 32.375                  | AFL  | 1073      |                |  |                           |           |             | PKG:30,92   |        |
|                              |  |           |                | PROC. REF: AMM 32-40-101, AMM 32-40-91 |                           |           |             |             |        |
| 320027 <sup>S</sup>          | VISUALLY INSPECT NOSE-WHEEL STEERING ON/OFF VALVE  |           |                |  |                           |           |             | Service     | ATA:32 |
|                              | MOS  | 20-Jun-22 | 48 (+2m/-2m)   |  |                           |           |             |             |        |
|                              | HRS  | 3511.6    |                |  |                           |           |             |             |        |
| WC#: 32.350                  | AFL  | 1288      |                |  |                           |           |             | PKG:96      |        |
| 320028                       | INSPECT/NDT MAIN LANDING GEAR FAIRING STRUT        |           |                |  |                           |           |             | Service     | ATA:32 |
|                              | MOS  | 20-Jun-22 | 48 (+3m)       |  | 20-Jun-26                 | 20-Sep-26 | 691 d (+92) |             |        |
|                              | HRS  | 3511.6    |                |  |                           |           |             |             |        |
| WC#: 32.035                  | AFL  | 1288      |                |  |                           |           |             |             |        |
|                              |  |           |                | PROC. REF: NTM 32-10-05                |                           |           |             |             |        |
| 320029                       | CHECK NOSE LANDING GEAR DRAG STAY                  |           |                |  |                           |           |             | Service     | ATA:32 |
|                              | MOS/MSC  | 13-Jul-10 | A/R            |  |                           |           |             |             |        |
|                              | HRS  | 48.52     |                |  |                           |           |             |             |        |
| WC#: 32.070                  | AFL  | 29        |                | Adj -4                                 |                           |           |             |             |        |
|                              |  |           |                | PROC. REF: AMM 32-20-21                |                           |           |             |             |        |
| 320033 <sup>S</sup>          | DETAIL INSPECT MAIN GEAR RETRACTION ACTUATOR       |           |                |  |                           |           |             | Service     | ATA:32 |
|                              | MOS  | 03-Aug-21 |                |  |                           |           |             |             |        |
|                              | HRS  | 3405      | 800 (+40/-10)  |  |                           |           |             |             |        |
| WC#: 32.095                  | AFL  | 1243      |                |  |                           |           |             | PKG:18,91   |        |
|                              |  |           |                | PROC. REF: AMM NO REF 1                |                           |           |             |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |                        |
|------------------------------|--|-----------|----------------|----------|---------------------------|-----------|-----------|-------------|------------------------|
| <b>ATA 32 - LANDING GEAR</b> |  |           |                |          |                           |           |           |             |                        |
| 320034 <sup>S</sup>          | INSPECT MAIN LANDING GEAR PLUNGER TUBE/AXLE JOINT                    |           |                |          |                           |           |           | Service     | ATA:32                 |
|                              | MOS  | 03-Aug-21 |                |          |                           |           |           |             |                        |
|                              | HRS  | 3405      | 800 (+40/-10)  |          |                           |           |           |             |                        |
| WC#: 32.510                  | AFL  | 1243      |                |          |                           |           |           | PKG:18,91   |                        |
| 320035 <sup>S</sup>          | INSPECT MAIN LANDING GEAR MAIN LEG ASSEMBLY RETRACTION LEVER         |           |                |          |                           |           |           | Service     | ATA:32                 |
|                              | MOS  | 06-Jun-18 |                |          |                           |           |           |             |                        |
|                              | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |           |             |                        |
| WC#: 32.520                  | AFL  | 1073      |                |          |                           |           |           | PKG:30,92   |                        |
| 320036 <sup>S</sup>          | INSPECT MAIN LANDING GEAR SIDESTAY ASSEMBLY LOCK MECHANISM LINK      |           |                |          |                           |           |           | Service     | ATA:32                 |
|                              | MOS  | 06-Jun-18 |                |          |                           |           |           |             |                        |
|                              | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |           |             |                        |
| WC#: 32.530                  | AFL  | 1073      |                |          |                           |           |           | PKG:30,92   |                        |
|                              |  |           |                |          | PROC. REF: GENERIC NO REF |           |           |             |                        |
| 320037 <sup>S</sup>          | CHECK NOSE LEG ASSEMBLY TORQUE LINKS                                 |           |                |          |                           |           |           | Service     | ATA:32                 |
|                              | MOS  | 03-Aug-21 |                |          |                           |           |           |             |                        |
|                              | HRS  | 3405      | 800 (+40/-10)  |          |                           |           |           |             |                        |
| WC#: 32.540                  | AFL  | 1243      |                |          |                           |           |           | PKG:18,91   |                        |
|                              |  |           |                |          | PROC. REF: AMM 32-20-12   |           |           |             |                        |
| 320038                       | LUBRICATE MAIN LANDING GEAR SIDESTAY SHIMS                           |           |                |          |                           |           |           | Service     | ATA:32                 |
|                              | MOS/MSC  | 12-Feb-24 | A/R            |          |                           |           |           |             |                        |
|                              | HRS  | 3881.4    |                |          |                           |           |           |             |                        |
| WC#: 32.570                  | AFL  | 1476      |                |          |                           |           |           |             |                        |
|                              | Special Properties: TRACKED ITEM                                     |           |                |          |                           |           |           |             | PROC. REF: AMS 5-20-11 |
| 320039 <sup>S</sup>          | INSPECTION OF LEFT SEQUENCING VALVES AND THEIR OPERATING MECHANISMS  |           |                |          |                           |           |           | Service     | ATA:32                 |
|                              | MOS  | 16-Mar-10 |                |          |                           |           |           |             |                        |
|                              | HRS  | 0         | 800 (+40/-10)  |          |                           |           |           |             |                        |
|                              | AFL  | 0         |                |          |                           |           |           | PKG:18,91   |                        |
|                              |  |           |                |          | PROC. REF: GENERIC NO REF |           |           |             |                        |
| 320039 <sup>S</sup>          | INSPECTION OF RIGHT SEQUENCING VALVES AND THEIR OPERATING MECHANISMS |           |                |          |                           |           |           | Service     | ATA:32                 |
|                              | MOS  | 16-Mar-10 |                |          |                           |           |           |             |                        |
|                              | HRS  | 0         | 800 (+40/-10)  |          |                           |           |           |             |                        |
|                              | AFL  | 0         |                |          |                           |           |           | PKG:18,91   |                        |
|                              |  |           |                |          | PROC. REF: GENERIC NO REF |           |           |             |                        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit | C/W   | Interval | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|------------------------------|------|---|----------|-----------------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 32 - LANDING GEAR</b> |      |   |          |                 |                           |           |           |                  |               |
| <b>321001</b>                |      | <b>LEFT MAIN LEG</b>                              |          |                 |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:140-810044-17             | MOS  | 20-Jun-22   | 144      | TSO 3           | 20-Mar-34                 |           | 3521 d    | OVERHAUL         |               |
| SN:DCL0314/09                | HRS  | 3511.6  |          | TSO 0           |                           |           |           |                  |               |
| WC#: 32.020                  | AFL  | 1288  | 5000     | TSN 1218, TSO 0 | 6288                      |           | 4796      |                  |               |
| PROC. REF: AMM 32-10-12      |      |   |          |                 |                           |           |           |                  |               |
| <b>321002</b>                |      | <b>RIGHT MAIN LEG</b>                             |          |                 |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:140-810044-18             | MOS  | 20-Jun-22   | 144      | TSO 6           | 20-Dec-33                 |           | 3431 d    | OVERHAUL         |               |
| SN:DCL0282/08                | HRS  | 3511.6  |          | TSO 0           |                           |           |           |                  |               |
| WC#: 32.020                  | AFL  | 1288  | 5000     | TSN 1218, TSO 0 | 6288                      |           | 4796      |                  |               |
| PROC. REF: AMM 32-10-12      |      |   |          |                 |                           |           |           |                  |               |
| <b>321013</b>                |      | <b>LEFT SIDESTAY</b>                              |          |                 |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:140-810043-11             | MOS  | 20-Jun-22   | 144      | TSO 3           | 20-Mar-34                 |           | 3521 d    | OVERHAUL         |               |
| SN:DCL0082/06                | HRS  | 3511.6  |          | TSO 0           |                           |           |           |                  |               |
| WC#: 32.025                  | AFL  | 1288  | 5000     | TSN 1218, TSO 0 | 6288                      |           | 4796      |                  |               |
| PROC. REF: AMM 32-10-25      |      |   |          |                 |                           |           |           |                  |               |
| <b>321014</b>                |      | <b>RIGHT SIDESTAY</b>                             |          |                 |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:140-810043-12             | MOS  | 20-Jun-22   | 144      | TSO 3           | 20-Mar-34                 |           | 3521 d    | OVERHAUL         |               |
| SN:ASD-0135                  | HRS  | 3511.6  |          | TSO 0           |                           |           |           |                  |               |
| WC#: 32.030                  | AFL  | 1288  | 5000     | TSN 1218, TSO 0 | 6288                      |           | 4796      |                  |               |
| PROC. REF: AMM 32-10-25      |      |   |          |                 |                           |           |           |                  |               |
| <b>321015</b>                |      | <b>LEFT MAIN LANDING GEAR SIDESTAY UPPER ARM</b>  |          |                 |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:140-810125-0001           | MOS  | 20-Jun-22   |          |                 |                           |           |           | LIFE LIMIT       |               |
| SN:WAL50896                  | HRS  | 3511.6  |          |                 |                           |           |           |                  |               |
| WC#: 32.025                  | AFL  | 1288  | 10000    | TSN 1218        | 10070                     |           | 8578      |                  |               |
| PROC. REF: AMM 32-10-25      |      |   |          |                 |                           |           |           |                  |               |
| <b>321016</b>                |      | <b>RIGHT MAIN LANDING GEAR SIDESTAY UPPER ARM</b> |          |                 |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:140-810125-0002           | MOS  | 20-Jun-22   |          |                 |                           |           |           | LIFE LIMIT       |               |
| SN:WO-7179                   | HRS  | 3511.6  |          |                 |                           |           |           |                  |               |
| WC#: 32.030                  | AFL  | 1288  | 10000    | TSN 1218        | 10070                     |           | 8578      |                  |               |
| PROC. REF: AMM 32-10-25      |      |   |          |                 |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining  | Disposition      |               |
|------------------------------|---------|--|----------|----------|---------------------------|-----------|------------|------------------|---------------|
| <b>ATA 32 - LANDING GEAR</b> |         |  |          |          |                           |           |            |                  |               |
| <b>321017</b>                |         | <b>LEFT MAIN LANDING GEAR SIDESTAY LOWER ARM</b>     |          |          |                           |           |            | <b>Component</b> | <b>ATA:32</b> |
| PN:140-810064-0001           | MOS     | 20-Jun-22  |          |          |                           |           | LIFE LIMIT |                  |               |
| SN:WAL52241                  | HRS     | 3511.6   |          |          |                           |           |            |                  |               |
| WC#: 32.025                  | AFL     | 1288   | 12000    | TSN 1218 | 12070                     |           | 10578      |                  |               |
| PROC. REF: AMM 32-10-25      |         |  |          |          |                           |           |            |                  |               |
| <b>321018</b>                |         | <b>RIGHT MAIN LANDING GEAR SIDESTAY LOWER ARM</b>    |          |          |                           |           |            | <b>Component</b> | <b>ATA:32</b> |
| PN:140-810064-0002           | MOS     | 20-Jun-22  |          |          |                           |           | LIFE LIMIT |                  |               |
| SN:ST-0034                   | HRS     | 3511.6   |          |          |                           |           |            |                  |               |
| WC#: 32.030                  | AFL     | 1288   | 12000    | TSN 1218 | 12070                     |           | 10578      |                  |               |
| PROC. REF: AMM 32-10-25      |         |  |          |          |                           |           |            |                  |               |
| <b>321050</b>                |         | <b>LEFT MAIN LANDING GEAR UPPER CASING</b>           |          |          |                           |           |            | <b>Component</b> | <b>ATA:32</b> |
| PN:25-8UM169-31A             | MOS     | 20-Jun-22  |          |          |                           |           | LIFE LIMIT |                  |               |
| SN:08MDZ00030                | HRS     | 3511.6   |          |          |                           |           |            |                  |               |
| WC#: 32.390                  | AFL     | 1288   | 24000    | TSN 1218 | 24070                     |           | 22578      |                  |               |
| <b>321051</b>                |         | <b>RIGHT MAIN LANDING GEAR UPPER CASING</b>          |          |          |                           |           |            | <b>Component</b> | <b>ATA:32</b> |
| PN:25-8UM169-32A             | MOS     | 20-Jun-22  |          |          |                           |           | LIFE LIMIT |                  |               |
| SN:07MDZ03579                | HRS     | 3511.6   |          |          |                           |           |            |                  |               |
| WC#: 32.390                  | AFL     | 1288   | 24000    | TSN 1218 | 24070                     |           | 22578      |                  |               |
| <b>321061</b>                |         | <b>LEFT MAIN LANDING GEAR JACK PIVOT</b>             |          |          |                           |           |            | <b>Component</b> | <b>ATA:32</b> |
| PN:PN                        | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |            |                  |               |
| SN:UNKNOWN                   | HRS     | 0  |          | TSN 0    |                           |           |            |                  |               |
| WC#: 32.040                  | AFL     | 0  |          | TSN 0    |                           |           |            |                  |               |
| <b>321062</b>                |         | <b>RIGHT MAIN LANDING GEAR JACK PIVOT</b>            |          |          |                           |           |            | <b>Component</b> | <b>ATA:32</b> |
| PN:PN                        | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |            |                  |               |
| SN:UNKNOWN                   | HRS     | 0  |          | TSN 0    |                           |           |            |                  |               |
| WC#: 32.040                  | AFL     | 0  |          | TSN 0    |                           |           |            |                  |               |
| <b>321065</b>                |         | <b>LEFT MAIN LANDING GEAR UPPER TORQUE LINK PIN</b>  |          |          |                           |           |            | <b>Component</b> | <b>ATA:32</b> |
| PN:PN                        | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |            |                  |               |
| SN:UNKNOWN                   | HRS     | 0  |          | TSN 0    |                           |           |            |                  |               |
| WC#: 32.400                  | AFL     | 0  |          | TSN 0    |                           |           |            |                  |               |
| <b>321066</b>                |         | <b>RIGHT MAIN LANDING GEAR UPPER TORQUE LINK PIN</b> |          |          |                           |           |            | <b>Component</b> | <b>ATA:32</b> |
| PN:PN                        | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |            |                  |               |
| SN:UNKNOWN                   | HRS     | 0  |          | TSN 0    |                           |           |            |                  |               |
| WC#: 32.400                  | AFL     | 0  |          | TSN 0    |                           |           |            |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 32 - LANDING GEAR</b>   |         |           |          |          |                           |           |           |             |
| <b>321067 LEFT MAIN LANDING GEAR LOWER TORQUE LINK PIN Component ATA:32</b>  |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 32.495  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| <b>321068 RIGHT MAIN LANDING GEAR LOWER TORQUE LINK PIN Component ATA:32</b> |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 32.495  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| <b>321071 LEFT MAIN LANDING GEAR JACK DISTANCE PIN Component ATA:32</b>      |         |           |          |          |                           |           |           |             |
| PN:25UM423   | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:N/A   | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.045  | AFL     | 1288      | 24000    | TSN 1218 | 24070                     |           | 22578     |             |
| <b>321072 RIGHT MAIN LANDING GEAR JACK DISTANCE PIN Component ATA:32</b>     |         |           |          |          |                           |           |           |             |
| PN:25UM423   | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:WO-7255   | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.045  | AFL     | 1288      | 24000    | TSN 1218 | 24070                     |           | 22578     |             |
| <b>321075 LEFT MAIN LANDING GEAR PLUNGER TUBE Component ATA:32</b>           |         |           |          |          |                           |           |           |             |
| PN:140-810016-1  | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:08MDC1928   | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.410  | AFL     | 1288      | 17000    | TSN 1218 | 17070                     |           | 15578     |             |
| <b>321076 RIGHT MAIN LANDING GEAR PLUNGER TUBE Component ATA:32</b>          |         |           |          |          |                           |           |           |             |
| PN:140-810016-2  | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:08MDC01481  | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.410  | AFL     | 1288      | 17000    | TSN 1218 | 17070                     |           | 15578     |             |
| <b>321081 LEFT MAIN LANDING GEAR UPPER TORQUE LINK Component ATA:32</b>      |         |           |          |          |                           |           |           |             |
| PN:25-9UM9-13A   | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:EPI-0742  | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.550  | AFL     | 1288      | 20000    | TSN 1218 | 20070                     |           | 18578     |             |
| <b>321082 RIGHT MAIN LANDING GEAR UPPER TORQUE LINK Component ATA:32</b>     |         |           |          |          |                           |           |           |             |
| PN:25-9UM9-13A   | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:EPI-0645  | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.550  | AFL     | 1288      | 20000    | TSN 1218 | 20070                     |           | 18578     |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W  | Interval  | TSX/Adj.        | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|------|-----------|-----------------|---------------------------|-----------|-----------|-------------|
| <b>ATA 32 - LANDING GEAR</b>   |         |      |           |                 |                           |           |           |             |
| <b>321083 LEFT MAIN LANDING GEAR LOWER TORQUE LINK Component ATA:32</b>  |         |      |           |                 |                           |           |           |             |
| PN:25-9UM11-17A  | MOS     |      | 20-Jun-22 |                 |                           |           |           | LIFE LIMIT  |
| SN:EPI-0673  | HRS     |      | 3511.6    |                 |                           |           |           |             |
| WC#: 32.555  | AFL     | 1288 | 20000     | TSN 1218        | 20070                     |           | 18578     |             |
| <b>321084 RIGHT MAIN LANDING GEAR LOWER TORQUE LINK Component ATA:32</b> |         |      |           |                 |                           |           |           |             |
| PN:25-9UM11-17A  | MOS     |      | 20-Jun-22 |                 |                           |           |           | LIFE LIMIT  |
| SN:EPI-0628  | HRS     |      | 3511.6    |                 |                           |           |           |             |
| WC#: 32.555  | AFL     | 1288 | 20000     | TSN 1218        | 20070                     |           | 18578     |             |
| <b>321087 LEFT MAIN LANDING GEAR AXLE ASSEMBLY Component ATA:32</b>      |         |      |           |                 |                           |           |           |             |
| PN:PN  | MOS/MSC |      | 16-Mar-10 | O/C             | TSN 0                     |           |           |             |
| SN:UNKNOWN   | HRS     |      | 0         |                 | TSN 0                     |           |           |             |
| WC#: 32.571  | AFL     |      | 0         |                 | TSN 0                     |           |           |             |
| <b>321088 RIGHT MAIN LANDING GEAR AXLE ASSEMBLY Component ATA:32</b>     |         |      |           |                 |                           |           |           |             |
| PN:PN  | MOS/MSC |      | 16-Mar-10 | O/C             | TSN 0                     |           |           |             |
| SN:UNKNOWN   | HRS     |      | 0         |                 | TSN 0                     |           |           |             |
| WC#: 32.572  | AFL     |      | 0         |                 | TSN 0                     |           |           |             |
| <b>322001 NOSE LEG ASSEMBLY Component ATA:32</b>                         |         |      |           |                 |                           |           |           |             |
| PN:25-9UN1-407A  | MOS     |      | 20-Jun-22 | 144             | TSO 1                     | 20-May-34 | 3582 d    | OVERHAUL    |
| SN:DCL0334/09  | HRS     |      | 3511.6    |                 | TSO 0                     |           |           |             |
| WC#: 32.050  | AFL     | 1288 | 5000      | TSN 2288, TSO 0 | 6288                      |           | 4796      |             |
| PROC. REF: AMM 32-20-12  |         |      |           |                 |                           |           |           |             |
| <b>322003 NOSE LANDING GEAR PIVOT PIN Component ATA:32</b>               |         |      |           |                 |                           |           |           |             |
| PN:25UN645A  | MOS     |      | 20-Jun-22 |                 |                           |           |           | LIFE LIMIT  |
| SN:WO-81139/12   | HRS     |      | 3511.6    |                 |                           |           |           |             |
| WC#: 32.055  | AFL     | 1288 | 16000     | TSN 2288        | 15000                     |           | 13508     |             |
| <b>322007 NOSE LANDING GEAR DRAG STAY Component ATA:32</b>               |         |      |           |                 |                           |           |           |             |
| PN:25-8UN3-179A  | MOS     |      | 20-Jun-22 | 144             | TSO 8                     | 20-Oct-33 | 3370 d    | OVERHAUL    |
| SN:ASD-0130  | HRS     |      | 3511.6    |                 | TSO 0                     |           |           |             |
| WC#: 32.070  | AFL     | 1288 | 5000      | TSN 1218, TSO 0 | 6288                      |           | 4796      |             |
| PROC. REF: AMM 32-20-21  |         |      |           |                 |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit | C/W  | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--|------|------|-----------|----------|---------------------------|-----------|-----------|------------------|
| <b>ATA 32 - LANDING GEAR</b>                                   |      |      |           |          |                           |           |           |                  |
| <b>322009 NOSE LANDING GEAR JACK LOWER PIVOT PIN</b>           |      |      |           |          |                           |           |           |                  |
| PN:25UN597   | MOS  |      | 20-Jun-22 |          |                           |           |           | Component ATA:32 |
| SN:WO-81146/17   | HRS  |      | 3511.6    |          |                           |           |           | LIFE LIMIT       |
| WC#: 32.075  | AFL  | 1288 | 22000     | TSN 2288 | 21000                     |           | 19508     |                  |
| <b>322011 NOSE LANDING GEAR DRAG STAY BRIDGE CASTING</b>       |      |      |           |          |                           |           |           |                  |
| PN:25-8UN487-1A  | MOS  |      | 20-Jun-22 |          |                           |           |           | Component ATA:32 |
| SN:ST-0018   | HRS  |      | 3511.6    |          |                           |           |           | LIFE LIMIT       |
| WC#: 32.075  | AFL  | 1288 | 33000     | TSN 1218 | 33070                     |           | 31578     |                  |
| <b>322015 NOSE LANDING GEAR UPPER TORQUE LINK</b>              |      |      |           |          |                           |           |           |                  |
| PN:25-8UN267-23A   | MOS  |      | 20-Jun-22 |          |                           |           |           | Component ATA:32 |
| SN:EPI-0375  | HRS  |      | 3511.6    |          |                           |           |           | LIFE LIMIT       |
| WC#: 32.080  | AFL  | 1288 | 32000     | TSN 2288 | 31000                     |           | 29508     |                  |
| <b>322016 NOSE LANDING GEAR LOWER TORQUE LINK</b>              |      |      |           |          |                           |           |           |                  |
| PN:25-8UN269-27A   | MOS  |      | 20-Jun-22 |          |                           |           |           | Component ATA:32 |
| SN:EPI-0356  | HRS  |      | 3511.6    |          |                           |           |           | LIFE LIMIT       |
| WC#: 32.080  | AFL  | 1288 | 32000     | TSN 2288 | 31000                     |           | 29508     |                  |
| <b>322017 NOSE LANDING GEAR DRAG STRUT PICK-UP</b>             |      |      |           |          |                           |           |           |                  |
| PN:25-8UN265-1A  | MOS  |      | 20-Jun-22 |          |                           |           |           | Component ATA:32 |
| SN:EPI-0401  | HRS  |      | 3511.6    |          |                           |           |           | LIFE LIMIT       |
| WC#: 32.560  | AFL  | 1288 | 13900     | TSN 2288 | 12900                     |           | 11408     |                  |
| <b>322025 NOSE GEAR MAIN PICK-UP TRUNNION ATTACHMENT BOLTS</b> |      |      |           |          |                           |           |           |                  |
| PN:PN  | MOS  |      | 16-Mar-10 | TSN 0    |                           |           |           | Component ATA:32 |
| SN:UNKNOWN   | HRS  |      | 0         | TSN 0    |                           |           |           | LIFE LIMIT       |
| WC#: 32.380  | AFL  | 0    | 10000     | TSN 0    | 10000                     |           | 8508      |                  |
| <b>322031 NOSE GEAR RADIUS ROD PICK-UP ATTACHMENT BOLTS</b>    |      |      |           |          |                           |           |           |                  |
| PN:PN  | MOS  |      | 16-Mar-10 | TSN 0    |                           |           |           | Component ATA:32 |
| SN:UNKNOWN   | HRS  |      | 0         | TSN 0    |                           |           |           | LIFE LIMIT       |
| WC#: 32.085  | AFL  | 0    | 10000     | TSN 0    | 10000                     |           | 8508      |                  |
| <b>322045 NOSE LANDING GEAR PLUNGER TUBE</b>                   |      |      |           |          |                           |           |           |                  |
| PN:S25UN649  | MOS  |      | 20-Jun-22 |          |                           |           |           | Component ATA:32 |
| SN:WAL51158  | HRS  |      | 3511.6    |          |                           |           |           | LIFE LIMIT       |
| WC#: 32.075  | AFL  | 1288 | 20000     | TSN 0    | 21288                     |           | 19796     |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition   |  |
|------------------------------|---------|--|----------|----------|---------------------------|-----------|------------------|---------------|--|
| <b>ATA 32 - LANDING GEAR</b> |         |  |          |          |                           |           |                  |               |  |
| <b>323001</b>                |         | <b>NOSE LANDING GEAR RETRACTION JACK</b>       |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AIR4504-1-4              | MOS     | 16-Mar-10                                      |          | TSN 0    |                           |           |                  | OVERHAUL      |  |
| SN: APB090436                | HRS     | 0  |          | TSN 0    |                           |           |                  |               |  |
| WC#: 32.090                  | AFL     | 0  | 5000     | TSN 0    | 5000                      |           | 3508             |               |  |
| PROC. REF: AMM 32-30-28      |         |  |          |          |                           |           |                  |               |  |
| <b>323007</b>                |         | <b>LEFT MAIN LANDING GEAR RETRACTION JACK</b>  |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AIR48502-7               | MOS     | 30-Sep-13                                      |          |          |                           |           |                  | OVERHAUL      |  |
| SN: LK9203917                | HRS     | 1558.87  |          |          |                           |           |                  |               |  |
| WC#: 32.100                  | AFL     | 570  | 5000     | TSN 180  | 5390                      |           | 3898             |               |  |
| PROC. REF: AMM 32-30-27      |         |  |          |          |                           |           |                  |               |  |
| <b>323008</b>                |         | <b>RIGHT MAIN LANDING GEAR RETRACTION JACK</b> |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AIR48503-7               | MOS     | 30-Sep-13                                      |          |          |                           |           |                  | OVERHAUL      |  |
| SN: APB970377                | HRS     | 1558.87  |          |          |                           |           |                  |               |  |
| WC#: 32.100                  | AFL     | 570  | 5000     | TSN 3770 | 1800                      |           | 308              |               |  |
| PROC. REF: AMM 32-30-27      |         |  |          |          |                           |           |                  |               |  |
| <b>323019</b>                |         | <b>LEFT MAIN LANDING GEAR DOOR JACK</b>        |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AIR48485-3               | MOS     | 16-Mar-10                                      |          | TSN 0    |                           |           |                  | OVERHAUL      |  |
| SN: APB091467                | HRS     | 0  |          | TSN 0    |                           |           |                  |               |  |
| WC#: 32.105                  | AFL     | 0  | 5000     | TSN 0    | 5000                      |           | 3508             |               |  |
| <b>323020</b>                |         | <b>RIGHT MAIN LANDING GEAR DOOR JACK</b>       |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AIR48484-3               | MOS     | 16-Mar-10                                      |          | TSN 0    |                           |           |                  | OVERHAUL      |  |
| SN: APB091414                | HRS     | 0  |          | TSN 0    |                           |           |                  |               |  |
| WC#: 32.105                  | AFL     | 0  | 5000     | TSN 0    | 5000                      |           | 3508             |               |  |
| <b>323031</b>                |         | <b>LEFT SEQUENCE VALVE</b>                     |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AIR48540-1               | MOS/MSC | 23-Jun-23                                      | O/C      | TSO 1    |                           |           |                  |               |  |
| SN: APB030656                | HRS     | 3746.1   |          | TSO 0    |                           |           |                  |               |  |
| WC#: 32.110                  | AFL     | 1412   |          | TSO 0    |                           |           |                  |               |  |
| PROC. REF: AMM 32-30-41      |         |  |          |          |                           |           |                  |               |  |
| <b>323032</b>                |         | <b>RIGHT SEQUENCE VALVE</b>                    |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AIR48540-1               | MOS/MSC | 23-Jun-23                                      | O/C      | TSO 1    |                           |           |                  |               |  |
| SN: APB060761                | HRS     | 3746.1   |          | TSO 0    |                           |           |                  |               |  |
| WC#: 32.110                  | AFL     | 1412   |          | TSO 0    |                           |           |                  |               |  |
| PROC. REF: AMM 32-30-41      |         |  |          |          |                           |           |                  |               |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 32 - LANDING GEAR</b> |  |           |          |          |                           |           |           |             |        |
| 323043                       | LEFT REVERSING VALVE                           |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR48542-1               | MOS/MSC  | 06-Mar-23 | O/C      |          | TSO 0                     |           |           |             |        |
| SN: APB082974                | HRS  | 3700.6    |          |          | TSO 0                     |           |           |             |        |
| WC#: 32.115                  | AFL  | 1392      |          |          | TSO 0                     |           |           |             |        |
| PROC. REF: AMM 32-30-31      |  |           |          |          |                           |           |           |             |        |
| 323044                       | RIGHT REVERSING VALVE                          |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR48593-1               | MOS/MSC  | 23-Jun-23 | O/C      |          | TSO 1                     |           |           |             |        |
| SN: APB083427                | HRS  | 3746.1    |          |          | TSO 0                     |           |           |             |        |
| WC#: 32.115                  | AFL  | 1412      |          |          | TSO 0                     |           |           |             |        |
| PROC. REF: AMM 32-30-31      |  |           |          |          |                           |           |           |             |        |
| 323079                       | LEFT MAIN LANDING GEAR EXTEND NONRETURN VALVE  |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR48026-0-1             | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN: APB091398                | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 32.120                  | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF    |  |           |          |          |                           |           |           |             |        |
| 323080                       | RIGHT MAIN LANDING GEAR EXTEND NONRETURN VALVE |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR48026-0-1             | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN: APB091388                | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 32.120                  | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF    |  |           |          |          |                           |           |           |             |        |
| 323090                       | FRAME 15A NON-RETURN VALVE                     |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR45420-0               | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN: APB061006                | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 32.505                  | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF    |  |           |          |          |                           |           |           |             |        |
| 323091                       | MAIN LANDING GEAR CENTER NONRETURN VALVE       |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: PN                       | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN: UNKNOWN                  | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 32.125                  | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF    |  |           |          |          |                           |           |           |             |        |
| 323097                       | FRAME 14 NON-RETURN VALVE                      |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: PN                       | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN: UNKNOWN                  | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 32.130                  | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF    |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 32 - LANDING GEAR</b> |   |           |          |          |                           |           |           |             |        |
| 323098                       | FRAME 14A NONRETURN VALVE                             |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR45420-0               | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN: APB070701                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 32.130                  | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF    |   |           |          |          |                           |           |           |             |        |
| 323099                       | FRAME 15A NONRETURN VALVE                             |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR45420-0               | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN: APB082224                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 32.130                  | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF    |   |           |          |          |                           |           |           |             |        |
| 323103                       | LANDING GEAR SELECTOR/DUMP VALVE                      |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR45406-1               | MOS/MSC   | 13-Apr-12 | O/C      | TSO 15   |                           |           |           |             |        |
| SN: APB950860                | HRS   | 933.58    |          | TSO 0    |                           |           |           |             |        |
| WC#: 32.135                  | AFL   | 337       |          | TSO 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF    |   |           |          |          |                           |           |           |             |        |
| 323115                       | LEFT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE  |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR45444-0               | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN: APB083132                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 32.140                  | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF    |   |           |          |          |                           |           |           |             |        |
| 323116                       | RIGHT MAIN LANDING GEAR RETRACT JACK RESTRICTOR VALVE |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: AIR45444-0               | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN: APB083320                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 32.140                  | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF    |   |           |          |          |                           |           |           |             |        |
| 323139                       | LEFT MAIN LANDING GEAR JACK PIVOT BOLT                |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: 25UM153A                 | MOS   | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN: N/A                      | HRS   | 3511.6    |          |          |                           |           |           |             |        |
| WC#: 32.150                  | AFL   | 1288      | 30000    | TSN 0    | 31288                     |           | 29796     |             |        |
| 323140                       | RIGHT MAIN LANDING GEAR JACK PIVOT BOLT               |           |          |          |                           |           |           | Component   | ATA:32 |
| PN: 25UM153A                 | MOS   | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN: N/A                      | HRS   | 3511.6    |          |          |                           |           |           |             |        |
| WC#: 32.150                  | AFL   | 1288      | 30000    | TSN 0    | 31288                     |           | 29796     |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit                                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 32 - LANDING GEAR</b> |  |           |          |          |                           |           |           |             |        |
| 323151                       | LEFT MAIN LANDING GEAR JACK CYLINDER HEAD  |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:AIR141082                 | MOS  | 30-Sep-13 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:TRP109                    | HRS  | 1558.87   |          |          |                           |           |           |             |        |
| WC#: 32.155                  | AFL  | 570       | 20000    | TSN 180  | 20390                     |           | 18898     |             |        |
| 323152                       | RIGHT MAIN LANDING GEAR JACK CYLINDER HEAD |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:AIR141082                 | MOS  | 30-Sep-13 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:TUR4048                   | HRS  | 1558.87   |          | TSN 0    |                           |           |           |             |        |
| WC#: 32.155                  | AFL  | 570       | 20000    | TSN 0    | 20570                     |           | 19078     |             |        |
| 323163                       | LEFT MAIN LANDING GEAR JACK EYE END        |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:AIR158922                 | MOS  | 30-Sep-13 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:12534/32                  | HRS  | 1558.87   |          |          |                           |           |           |             |        |
| WC#: 32.160                  | AFL  | 570       | 10000    | TSN 180  | 10390                     |           | 8898      |             |        |
| 323164                       | RIGHT MAIN LANDING GEAR JACK EYE END       |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:AIR158922                 | MOS  | 30-Sep-13 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:PIP72                     | HRS  | 1558.87   |          |          |                           |           |           |             |        |
| WC#: 32.160                  | AFL  | 570       | 10000    | TSN 3770 | 6800                      |           | 5308      |             |        |
| 323175                       | LEFT MAIN LANDING GEAR RETRACTION ARM      |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:25-8UM63-1A               | MOS  | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:EPI-0342                  | HRS  | 3511.6    |          |          |                           |           |           |             |        |
| WC#: 32.165                  | AFL  | 1288      | 12000    | TSN 1218 | 12070                     |           | 10578     |             |        |
| 323176                       | RIGHT MAIN LANDING GEAR RETRACTION ARM     |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:25-8UM63-2A               | MOS  | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:EPI-0304                  | HRS  | 3511.6    |          |          |                           |           |           |             |        |
| WC#: 32.165                  | AFL  | 1288      | 12000    | TSN 1218 | 12070                     |           | 10578     |             |        |
| 323181                       | LEFT MAIN LANDING GEAR RETRACTION ARM PIN  |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:25UM787                   | MOS  | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:N/A                       | HRS  | 3511.6    |          |          |                           |           |           |             |        |
| WC#: 32.170                  | AFL  | 1288      | 32000    | TSN 0    | 33288                     |           | 31796     |             |        |
| 323182                       | RIGHT MAIN LANDING GEAR RETRACTION ARM PIN |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:25UM787                   | MOS  | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:N/A                       | HRS  | 3511.6    |          |          |                           |           |           |             |        |
| WC#: 32.170                  | AFL  | 1288      | 32000    | TSN 0    | 33288                     |           | 31796     |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 32 - LANDING GEAR</b>   |         |           |          |          |                           |           |           |             |
| <b>323187 LANDING GEAR LEVER LOCK SOLENOID Component ATA:32</b>                    |         |           |          |          |                           |           |           |             |
| PN:D5327   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:L3299   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 32.175  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 32-30-21  |         |           |          |          |                           |           |           |             |
| <b>324001 NOSE LANDING GEAR AXLE BARREL Component ATA:32</b>                       |         |           |          |          |                           |           |           |             |
| PN:25-8UN257-27A   | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:EPI-0376  | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.195  | AFL     | 1288      | 30000    | TSN 2288 | 29000                     |           | 27508     |             |
| PROC. REF: AMM 32-40-31  |         |           |          |          |                           |           |           |             |
| <b>324002 NOSE LANDING GEAR AXLE ASSEMBLY Component ATA:32</b>                     |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 32.573  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| <b>324003 LEFT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY Component ATA:32</b>  |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 32.574  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>324004 RIGHT NOSE LANDING GEAR DOOR PIVOT BRACKET ASSEMBLY Component ATA:32</b> |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 32.575  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>324006 NOSE LANDING GEAR OUTER CASING Component ATA:32</b>                      |         |           |          |          |                           |           |           |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 32.576  | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF  |         |           |          |          |                           |           |           |             |
| <b>324007 LEFT NOSE WHEEL Component ATA:32</b>                                     |         |           |          |          |                           |           |           |             |
| PN:AH52339   | MOS/MSC | 20-Dec-23 | O/C      | TSR 0    |                           |           |           |             |
| SN:LD030   | HRS     | 3848      |          | TSR 0    |                           |           |           |             |
| WC#: 32.200  | AFL     | 1462      |          | TSR 0    |                           |           |           |             |
| PROC. REF: AMM 32-40-21  |         |           |          |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition   |  |
|------------------------------|---------|--|----------|----------|---------------------------|-----------|------------------|---------------|--|
| <b>ATA 32 - LANDING GEAR</b> |         |  |          |          |                           |           |                  |               |  |
| <b>324008</b>                |         | <b>RIGHT NOSE WHEEL</b>                        |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN:AH52339                   | MOS/MSC | 20-Dec-23                                      | O/C      |          | TSR 0                     |           |                  |               |  |
| SN:JF113                     | HRS     | 3848   |          |          | TSR 0                     |           |                  |               |  |
| WC#: 32.205                  | AFL     | 1462   |          |          | TSR 0                     |           |                  |               |  |
| PROC. REF: AMM 32-40-21      |         |  |          |          |                           |           |                  |               |  |
| <b>324009</b>                |         | <b>NOSE LANDING GEAR TOP LEVER ASSEMBLY</b>    |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN:PN                        | MOS/MSC | 16-Mar-10                                      | O/C      |          | TSN 0                     |           |                  |               |  |
| SN:UNKNOWN                   | HRS     | 0  |          |          | TSN 0                     |           |                  |               |  |
| WC#: 32.577                  | AFL     | 0  |          |          | TSN 0                     |           |                  |               |  |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |                  |               |  |
| <b>324010</b>                |         | <b>NOSE LANDING GEAR BOTTOM LEVER ASSEMBLY</b> |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN:PN                        | MOS/MSC | 16-Mar-10                                      | O/C      |          | TSN 0                     |           |                  |               |  |
| SN:UNKNOWN                   | HRS     | 0  |          |          | TSN 0                     |           |                  |               |  |
| WC#: 32.578                  | AFL     | 0  |          |          | TSN 0                     |           |                  |               |  |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |                  |               |  |
| <b>324019</b>                |         | <b>LEFT NOSE TIRE</b>                          |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN:DR6387T                   | MOS/MSC | 20-Dec-23                                      | T/C      |          | TSN 0                     |           |                  |               |  |
| SN:23094152                  | HRS     | 3848   |          |          | TSN 0                     |           |                  |               |  |
| WC#: 32.200                  | AFL     | 1462   |          |          | TSN 0                     |           |                  |               |  |
| PROC. REF: AMM 32-40-41      |         |  |          |          |                           |           |                  |               |  |
| <b>324020</b>                |         | <b>RIGHT NOSE TIRE</b>                         |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN:DR6387T                   | MOS/MSC | 20-Dec-23                                      | T/C      |          | TSN 0                     |           |                  |               |  |
| SN:23094143                  | HRS     | 3848   |          |          | TSN 0                     |           |                  |               |  |
| WC#: 32.205                  | AFL     | 1462   |          |          | TSN 0                     |           |                  |               |  |
| PROC. REF: AMM 32-40-41      |         |  |          |          |                           |           |                  |               |  |
| <b>324031</b>                |         | <b>LEFT OUTBOARD MAIN WHEEL</b>                |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN:AHA1814                   | MOS/MSC | 20-Dec-23                                      | O/C      |          |                           |           |                  |               |  |
| SN:5203GJ                    | HRS     | 3848   |          |          |                           |           |                  |               |  |
| WC#: 32.210                  | AFL     | 1462   |          |          |                           |           |                  |               |  |
| PROC. REF: AMM 32-40-12      |         |  |          |          |                           |           |                  |               |  |
| <b>324032</b>                |         | <b>RIGHT OUTBOARD MAIN WHEEL</b>               |          |          |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN:AHA1814                   | MOS/MSC | 30-Nov-23                                      | O/C      |          | TSO 10                    |           |                  |               |  |
| SN:5120GP                    | HRS     | 3824.5   |          |          | TSO 78.2                  |           |                  |               |  |
| WC#: 32.215                  | AFL     | 1449   |          |          | TSO 36                    |           |                  |               |  |
| PROC. REF: AMM 32-40-12      |         |  |          |          |                           |           |                  |               |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit    | C/W                             | Interval | TSX/Adj.  | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining        | Disposition   |  |
|----------------------------------|---------|---------------------------------|----------|-----------|---------------------------|-----------|------------------|---------------|--|
| <b>ATA 32 - LANDING GEAR</b>     |         |                                 |          |           |                           |           |                  |               |  |
| <b>324033</b>                    |         | <b>LEFT INBOARD MAIN WHEEL</b>  |          |           |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AHA1814                      | MOS/MSC | 20-Dec-23                       | O/C      |           |                           |           |                  |               |  |
| SN: 5058ET                       | HRS     | 3848                            |          |           |                           |           |                  |               |  |
| WC#: 32.220                      | AFL     | 1462                            |          |           |                           |           |                  |               |  |
| PROC. REF: AMM 32-40-12          |         |                                 |          |           |                           |           |                  |               |  |
| <b>324034</b>                    |         | <b>RIGHT INBOARD MAIN WHEEL</b> |          |           |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AHA1814                      | MOS/MSC | 30-Nov-23                       | O/C      | TSO 17    |                           |           |                  |               |  |
| SN: ZC055                        | HRS     | 3824.5                          |          | TSO 312.9 |                           |           |                  |               |  |
| WC#: 32.225                      | AFL     | 1449                            |          | TSO 161   |                           |           |                  |               |  |
| Special Properties: TRACKED ITEM |         |                                 |          |           |                           |           |                  |               |  |
| PROC. REF: AMM 32-40-12          |         |                                 |          |           |                           |           |                  |               |  |
| <b>324055</b>                    |         | <b>LEFT OUTBOARD MAIN TIRE</b>  |          |           |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: DR14628T                     | MOS/MSC | 20-Dec-23                       | T/C      | TSN 0     |                           |           |                  |               |  |
| SN: 23066196                     | HRS     | 3848                            |          | TSN 0     |                           |           |                  |               |  |
| WC#: 32.210                      | AFL     | 1462                            |          | TSN 0     |                           |           |                  |               |  |
| PROC. REF: AMM 32-40-41          |         |                                 |          |           |                           |           |                  |               |  |
| <b>324056</b>                    |         | <b>RIGHT OUTBOARD MAIN TIRE</b> |          |           |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: 237K23-2                     | MOS/MSC | 20-Jul-23                       | T/C      | TSN 7     |                           |           |                  |               |  |
| SN: 23350560                     | HRS     | 3746.3                          |          | TSN 0     |                           |           |                  |               |  |
| WC#: 32.215                      | AFL     | 1413                            |          | TSN 0     |                           |           |                  |               |  |
| PROC. REF: AMM 32-40-41          |         |                                 |          |           |                           |           |                  |               |  |
| <b>324057</b>                    |         | <b>LEFT INBOARD MAIN TIRE</b>   |          |           |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: DR14628T                     | MOS/MSC | 20-Dec-23                       | T/C      | TSN 0     |                           |           |                  |               |  |
| SN: 23066195                     | HRS     | 3848                            |          | TSN 0     |                           |           |                  |               |  |
| WC#: 32.220                      | AFL     | 1462                            |          | TSN 0     |                           |           |                  |               |  |
| PROC. REF: AMM 32-40-41          |         |                                 |          |           |                           |           |                  |               |  |
| <b>324058</b>                    |         | <b>RIGHT INBOARD MAIN TIRE</b>  |          |           |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: 237K23-2                     | MOS/MSC | 20-Jul-23                       | T/C      | TSN 0     |                           |           |                  |               |  |
| SN: 23270561                     | HRS     | 3746.3                          |          | TSN 0     |                           |           |                  |               |  |
| WC#: 32.225                      | AFL     | 1413                            |          | TSN 0     |                           |           |                  |               |  |
| Special Properties: TRACKED ITEM |         |                                 |          |           |                           |           |                  |               |  |
| PROC. REF: AMM 32-40-41          |         |                                 |          |           |                           |           |                  |               |  |
| <b>324065</b>                    |         | <b>RIGHT WHEEL WELL FILTER</b>  |          |           |                           |           | <b>Component</b> | <b>ATA:32</b> |  |
| PN: AIR48538                     | MOS/MSC | 16-Mar-10                       | O/C      | TSN 0     |                           |           |                  |               |  |
| SN: BF08-0182                    | HRS     | 0                               |          | TSN 0     |                           |           |                  |               |  |
| WC#: 32.230                      | AFL     | 0                               |          | TSN 0     |                           |           |                  |               |  |
| PROC. REF: AMM 32-30-22          |         |                                 |          |           |                           |           |                  |               |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit    | C/W                               | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining               | Disposition |  |
|------------------------------|---------|-----------------------------------|----------|----------|---------------------------|-----------|-------------------------|-------------|--|
| <b>ATA 32 - LANDING GEAR</b> |         |                                   |          |          |                           |           |                         |             |  |
| <b>324066</b>                |         | <b>LEFT FRAME 14A FILTER</b>      |          |          |                           |           | <b>Component ATA:32</b> |             |  |
| PN: AIR48538                 | MOS/MSC | 16-Mar-10                         | O/C      | TSN 0    |                           |           |                         |             |  |
| SN: BF080696                 | HRS     | 0                                 | TSN 0    |          |                           |           |                         |             |  |
| WC#: 32.235                  | AFL     | 0                                 | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM 32-30-22      |         |                                   |          |          |                           |           |                         |             |  |
| <b>324067</b>                |         | <b>RIGHT FRAME 14A FILTER</b>     |          |          |                           |           | <b>Component ATA:32</b> |             |  |
| PN: AIR48538                 | MOS/MSC | 16-Mar-10                         | O/C      | TSN 0    |                           |           |                         |             |  |
| SN: BF080695                 | HRS     | 0                                 | TSN 0    |          |                           |           |                         |             |  |
| WC#: 32.235                  | AFL     | 0                                 | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM 32-30-22      |         |                                   |          |          |                           |           |                         |             |  |
| <b>324068</b>                |         | <b>FRAME 15 FILTER</b>            |          |          |                           |           | <b>Component ATA:32</b> |             |  |
| PN: AIR48538                 | MOS/MSC | 16-Mar-10                         | O/C      | TSN 0    |                           |           |                         |             |  |
| SN: BF0810718                | HRS     | 0                                 | TSN 0    |          |                           |           |                         |             |  |
| WC#: 32.235                  | AFL     | 0                                 | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM 32-30-22      |         |                                   |          |          |                           |           |                         |             |  |
| <b>324069</b>                |         | <b>NOSE WHEEL STEERING FILTER</b> |          |          |                           |           | <b>Component ATA:32</b> |             |  |
| PN: AIR45412-0-1             | MOS/MSC | 16-Mar-10                         | O/C      | TSN 0    |                           |           |                         |             |  |
| SN: BF090034                 | HRS     | 0                                 | TSN 0    |          |                           |           |                         |             |  |
| WC#: 32.240                  | AFL     | 0                                 | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: GENERIC NO REF    |         |                                   |          |          |                           |           |                         |             |  |
| <b>324077</b>                |         | <b>PORT SHUTTLE VALVES</b>        |          |          |                           |           | <b>Component ATA:32</b> |             |  |
| PN: AH081963                 | MOS/MSC | 16-Mar-10                         | O/C      |          |                           |           |                         |             |  |
| SN: 5015HK                   | HRS     | 0                                 |          |          |                           |           |                         |             |  |
|                              | AFL     | 0                                 |          |          |                           |           |                         |             |  |
| PROC. REF: GENERIC NO REF    |         |                                   |          |          |                           |           |                         |             |  |
| <b>324078</b>                |         | <b>STARBOARD SHUTTLE VALVES</b>   |          |          |                           |           | <b>Component ATA:32</b> |             |  |
| PN: AH081963                 | MOS/MSC | 16-Mar-10                         | O/C      |          |                           |           |                         |             |  |
| SN: 5078HR                   | HRS     | 0                                 |          |          |                           |           |                         |             |  |
|                              | AFL     | 0                                 |          |          |                           |           |                         |             |  |
| PROC. REF: GENERIC NO REF    |         |                                   |          |          |                           |           |                         |             |  |
| <b>324079</b>                |         | <b>PORT SHUTTLE VALVES</b>        |          |          |                           |           | <b>Component ATA:32</b> |             |  |
| PN: AHO81964                 | MOS/MSC | 16-Mar-10                         | O/C      |          |                           |           |                         |             |  |
| SN: 50108DW                  | HRS     | 0                                 |          |          |                           |           |                         |             |  |
|                              | AFL     | 0                                 |          |          |                           |           |                         |             |  |
| PROC. REF: GENERIC NO REF    |         |                                   |          |          |                           |           |                         |             |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit    | C/W   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|------------------------------|---------|---|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 32 - LANDING GEAR</b> |         |   |          |          |                           |           |           |                  |               |
| <b>324080</b>                |         | <b>STARBOARD SHUTTLE VALVES</b>                   |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN: AHO81964                 | MOS/MSC | 16-Mar-10   | O/C      |          |                           |           |           |                  |               |
| SN: 5091HT                   | HRS     | 0   |          |          |                           |           |           |                  |               |
|                              | AFL     | 0   |          |          |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |   |          |          |                           |           |           |                  |               |
| <b>324115</b>                |         | <b>BRAKE CONTROL VALVE</b>                        |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN: AC67732                  | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |                  |               |
| SN: 15HB                     | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.245                  | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-40-71      |         |   |          |          |                           |           |           |                  |               |
| <b>324121</b>                |         | <b>BRAKE CONTROL VALVE LEFT OUTER KNIFE EDGE</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN: PN                       | MOS     | 16-Mar-10   |          | TSN 0    |                           |           |           | LIFE LIMIT       |               |
| SN: UNKNOWN                  | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.245                  | AFL     | 0   | 4500     | TSN 0    | 4500                      |           | 3008      |                  |               |
| PROC. REF: AMM 32-40-71      |         |   |          |          |                           |           |           |                  |               |
| <b>324122</b>                |         | <b>BRAKE CONTROL VALVE RIGHT OUTER KNIFE EDGE</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN: PN                       | MOS     | 16-Mar-10   |          | TSN 0    |                           |           |           | LIFE LIMIT       |               |
| SN: UNKNOWN                  | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.245                  | AFL     | 0   | 4500     | TSN 0    | 4500                      |           | 3008      |                  |               |
| PROC. REF: AMM 32-40-71      |         |   |          |          |                           |           |           |                  |               |
| <b>324123</b>                |         | <b>BRAKE CONTROL VALVE INNER KNIFE EDGE</b>       |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN: PN                       | MOS     | 16-Mar-10   |          | TSN 0    |                           |           |           | LIFE LIMIT       |               |
| SN: UNKNOWN                  | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.245                  | AFL     | 0   | 4500     | TSN 0    | 4500                      |           | 3008      |                  |               |
| PROC. REF: AMM 32-40-71      |         |   |          |          |                           |           |           |                  |               |
| <b>324145</b>                |         | <b>MAIN REDUCING VALVE</b>                        |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN: AC61518                  | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |                  |               |
| SN: 139GW                    | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.250                  | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |   |          |          |                           |           |           |                  |               |
| <b>324151</b>                |         | <b>EMERGENCY REDUCING VALVE</b>                   |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN: AC69784                  | MOS/MSC | 16-Mar-10   | O/C      | TSN 0    |                           |           |           |                  |               |
| SN: 168HA                    | HRS     | 0   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.255                  | AFL     | 0   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-40-51      |         |   |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|------------------------------|---------|--|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 32 - LANDING GEAR</b> |         |  |          |          |                           |           |           |                  |               |
| <b>324157</b>                |         | <b>EMERGENCY REDUCING VALVE LEFT KNIFE EDGE</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:PN                        | MOS     | 16-Mar-10  |          | TSN 0    |                           |           |           | LIFE LIMIT       |               |
| SN:UNKNOWN                   | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.255                  | AFL     | 0  | 4500     | TSN 0    | 4500                      |           | 3008      |                  |               |
| <b>324158</b>                |         | <b>EMERGENCY REDUCING VALVE RIGHT KNIFE EDGE</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:PN                        | MOS     | 16-Mar-10  |          | TSN 0    |                           |           |           | LIFE LIMIT       |               |
| SN:UNKNOWN                   | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.255                  | AFL     | 0  | 4500     | TSN 0    | 4500                      |           | 3008      |                  |               |
| <b>324169</b>                |         | <b>EMERGENCY BRAKE PRESSURE NONRETURN VALVE</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:AIR45420-0-1              | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:APB090818                 | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.500                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |           |                  |               |
| <b>324175</b>                |         | <b>LEFT OUTBOARD BRAKE UNIT</b>                  |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:AHA1897                   | MOS/MSC | 07-Apr-23  | O/C      | TSO 0    |                           |           |           |                  |               |
| SN:5028GG                    | HRS     | 3710.7   |          | TSO 0    |                           |           |           |                  |               |
| WC#: 32.265                  | AFL     | 1397   |          | TSO 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-40-114     |         |  |          |          |                           |           |           |                  |               |
| <b>324176</b>                |         | <b>RIGHT OUTBOARD BRAKE UNIT</b>                 |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:AHA1897                   | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:5103FJ                    | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.260                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-40-114     |         |  |          |          |                           |           |           |                  |               |
| <b>324177</b>                |         | <b>LEFT INBOARD BRAKE UNIT</b>                   |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:AHA1897                   | MOS/MSC | 07-Apr-23  | O/C      | TSO 0    |                           |           |           |                  |               |
| SN:5031GG                    | HRS     | 3710.7   |          | TSO 0    |                           |           |           |                  |               |
| WC#: 32.265                  | AFL     | 1397   |          | TSO 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-40-114     |         |  |          |          |                           |           |           |                  |               |
| <b>324178</b>                |         | <b>RIGHT INBOARD BRAKE UNIT</b>                  |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:AHA1897                   | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:5155EV                    | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.260                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-40-114     |         |  |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit    | C/W                                 | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|------------------------------|---------|-------------------------------------|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 32 - LANDING GEAR</b> |         |                                     |          |          |                           |           |           |                  |               |
| <b>324223</b>                |         | <b>LEFT OUTBOARD MAXARET</b>        |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:AC65218                   | MOS     | 16-Mar-10                           |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN:25GS                      | HRS     | 0                                   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.270                  | AFL     | 0                                   | 3000     | TSN 0    | 3000                      |           | 1508      |                  |               |
| PROC. REF: AMM 32-40-101     |         |                                     |          |          |                           |           |           |                  |               |
| <b>324224</b>                |         | <b>RIGHT OUTBOARD MAXARET</b>       |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:AC65216                   | MOS     | 30-Sep-13                           |          | TSO 0    |                           |           |           | OVERHAUL         |               |
| SN:K14352                    | HRS     | 1558.87                             |          | TSO 0    |                           |           |           |                  |               |
| WC#: 32.275                  | AFL     | 570                                 | 3000     | TSO 0    | 3570                      |           | 2078      |                  |               |
| PROC. REF: AMM 32-40-101     |         |                                     |          |          |                           |           |           |                  |               |
| <b>324225</b>                |         | <b>LEFT INBOARD MAXARET</b>         |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:AC65216                   | MOS     | 16-Mar-10                           |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN:69GT                      | HRS     | 0                                   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.270                  | AFL     | 0                                   | 3000     | TSN 0    | 3000                      |           | 1508      |                  |               |
| PROC. REF: AMM 32-40-101     |         |                                     |          |          |                           |           |           |                  |               |
| <b>324226</b>                |         | <b>RIGHT INBOARD MAXARET</b>        |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:AC65218                   | MOS     | 16-Mar-10                           |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN:171GW                     | HRS     | 0                                   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.275                  | AFL     | 0                                   | 3000     | TSN 0    | 3000                      |           | 1508      |                  |               |
| PROC. REF: AMM 32-40-101     |         |                                     |          |          |                           |           |           |                  |               |
| <b>324260</b>                |         | <b>LEFT MAIN LANDING GEAR DOOR</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:25-8UD505-235A            | MOS/MSC | 16-Mar-10                           | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:40460003                  | HRS     | 0                                   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.280                  | AFL     | 0                                   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-10-41      |         |                                     |          |          |                           |           |           |                  |               |
| <b>324261</b>                |         | <b>RIGHT MAIN LANDING GEAR DOOR</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:25-8UD505-236A            | MOS/MSC | 16-Mar-10                           | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:40424209                  | HRS     | 0                                   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.280                  | AFL     | 0                                   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-10-41      |         |                                     |          |          |                           |           |           |                  |               |
| <b>324262</b>                |         | <b>LEFT NOSE GEAR DOOR</b>          |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:25-8UD501-1A              | MOS/MSC | 16-Mar-10                           | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:40481314                  | HRS     | 0                                   |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.285                  | AFL     | 0                                   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-20-42      |         |                                     |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|------------------------------|---------|--|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 32 - LANDING GEAR</b> |         |  |          |          |                           |           |           |                  |               |
| <b>324263</b>                |         | <b>RIGHT NOSE GEAR DOOR</b>                  |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:25-8UD501-2A              | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:40415353                  | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.285                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-20-42      |         |  |          |          |                           |           |           |                  |               |
| <b>324264</b>                |         | <b>NOSE GEAR DOOR (LEG FAIRING) ASSEMBLY</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:25-8UD503-1A              | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:40453466                  | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.290                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-20-42      |         |  |          |          |                           |           |           |                  |               |
| <b>324265</b>                |         | <b>LEFT MAIN LANDING GEAR FAIRING</b>        |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:25-8UD507-1A              | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:40479473                  | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.295                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-10-32      |         |  |          |          |                           |           |           |                  |               |
| <b>324266</b>                |         | <b>RIGHT MAIN LANDING GEAR FAIRING</b>       |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:25-8UD507-2A              | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:40451477                  | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.295                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 32-10-32      |         |  |          |          |                           |           |           |                  |               |
| <b>324267</b>                |         | <b>VENTRAL FAIRING ASSEMBLY</b>              |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:259W03059-1A              | MOS/MSC | 16-Mar-10                                    | O/C      |          |                           |           |           |                  |               |
| SN:CAVPO9J004                | HRS     | 0  |          |          |                           |           |           |                  |               |
|                              | AFL     | 0  |          |          |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |           |                  |               |
| <b>324271</b>                |         | <b>LEFT BRAKE MODULATOR</b>                  |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:ACM22740EX                | MOS/MSC | 20-Jun-22                                    | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:110HA                     | HRS     | 3511.6                                       |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.300                  | AFL     | 1288   |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |           |                  |               |
| <b>324272</b>                |         | <b>RIGHT BRAKE MODULATOR</b>                 |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:PN                        | MOS/MSC | 16-Mar-10                                    | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                   | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.300                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|------------------------------|---------|--|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 32 - LANDING GEAR</b> |         |  |          |          |                           |           |           |                  |               |
| <b>324301</b>                |         | <b>PILOT LEFT BRAKE MASTER CYLINDER</b>              |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:ACM30946                  | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:100GW                     | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.310                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |           |                  |               |
| <b>324302</b>                |         | <b>PILOT RIGHT BRAKE MASTER CYLINDER</b>             |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:ACM30946                  | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:112GW                     | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.310                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |           |                  |               |
| <b>324303</b>                |         | <b>COPILOT LEFT BRAKE MASTER CYLINDER</b>            |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:ACM30946                  | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:85GW                      | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.315                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |           |                  |               |
| <b>324304</b>                |         | <b>COPILOT RIGHT BRAKE MASTER CYLINDER</b>           |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:ACM30946                  | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:107GW                     | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.315                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |           |                  |               |
| <b>324325</b>                |         | <b>LEFT EMERGENCY BRAKE PRESSURE WARNING SWITCH</b>  |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:TP42000                   | MOS     | 16-Mar-10  |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN:3717                      | HRS     | 0  | 5000     | TSN 0    | 5000                      |           | 1091.6    |                  |               |
| WC#: 32.320                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| <b>324326</b>                |         | <b>RIGHT EMERGENCY BRAKE PRESSURE WARNING SWITCH</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:TP42000                   | MOS     | 16-Mar-10  |          | TSN 0    |                           |           |           | OVERHAUL         |               |
| SN:3716                      | HRS     | 0  | 5000     | TSN 0    | 5000                      |           | 1091.6    |                  |               |
| WC#: 32.320                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| <b>324337</b>                |         | <b>FORWARD HIGH PRESSURE TRANSDUCER</b>              |          |          |                           |           |           | <b>Component</b> | <b>ATA:32</b> |
| PN:695-4-21                  | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:7470-2-201                | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 32.325                  | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: GENERIC NO REF    |         |  |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 32 - LANDING GEAR</b> |                                  |           |          |          |                           |           |           |             |        |
| 324338                       | AFT HIGH PRESSURE TRANSDUCER     |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:695-4-21                  | MOS/MSC                          | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:7536-2-266                | HRS                              | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 32.325                  | AFL                              | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF    |                                  |           |          |          |                           |           |           |             |        |
| 325001                       | STEERING JACK                    |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:AIR45396-7EX              | MOS/MSC                          | 25-Jan-23 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:LK1200847                 | HRS                              | 3658.7    |          | TSN 0    |                           |           |           |             |        |
| WC#: 32.330                  | AFL                              | 1373      |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 32-50-11      |                                  |           |          |          |                           |           |           |             |        |
| 325003                       | NOSE LANDING GEAR CONNECTING ROD |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:25-8UN433-1A              | MOS                              | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:EPI-0320                  | HRS                              | 3511.6    |          |          |                           |           |           |             |        |
| WC#: 32.335                  | AFL                              | 1288      | 20000    | TSN 2288 | 19000                     |           | 17508     |             |        |
| 325007                       | STEERING JACK EYE END            |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:PN                        | MOS                              | 16-Mar-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:UNKNOWN                   | HRS                              | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 32.340                  | AFL                              | 0         | 14400    | TSN 0    | 14400                     |           | 12908     |             |        |
| 325008                       | PORT WING TO FUSELAGE FAIRING    |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:25-6FC601A                | MOS/MSC                          | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
| SN:CAVPO9C046                | HRS                              | 0         |          |          |                           |           |           |             |        |
|                              | AFL                              | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF    |                                  |           |          |          |                           |           |           |             |        |
| 325009                       | WING TO FUSELAGE FAIRING         |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:25FC5808A                 | MOS/MSC                          | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
| SN:CAVPO9G022                | HRS                              | 0         |          |          |                           |           |           |             |        |
|                              | AFL                              | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF    |                                  |           |          |          |                           |           |           |             |        |
| 325010                       | UNDERCARRIAGE FAIRING            |           |          |          |                           |           |           | Component   | ATA:32 |
| PN:25-8FC307-155A            | MOS/MSC                          | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
| SN:DHB995                    | HRS                              | 0         |          |          |                           |           |           |             |        |
|                              | AFL                              | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF    |                                  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 32 - LANDING GEAR</b>  |         |           |          |          |                           |           |           |             |
| <b>325011 NOSE LANDING GEAR TORQUE LINK PICK UP SLEEVE</b> Component ATA:32 |         |           |          |          |                           |           |           |             |
| PN:25-8UN455-9  | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:EPI-0391   | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.335   | AFL     | 1288      | 20000    | TSN 2288 | 19000                     |           | 17508     |             |
| <b>325012 FAIRING SUB ASSEMBLY</b> Component ATA:32                         |         |           |          |          |                           |           |           |             |
| PN:25-8FC3603-605A  | MOS/MSC | 16-Mar-10 | O/C      |          |                           |           |           |             |
| SN:11060901   | HRS     | 0         |          |          |                           |           |           |             |
|   | AFL     | 0         |          |          |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>325015 NOSE LANDING GEAR STEERING PIN</b> Component ATA:32               |         |           |          |          |                           |           |           |             |
| PN:25UN605  | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:WO-81086/15  | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.345   | AFL     | 1288      | 25000    | TSN 2288 | 24000                     |           | 22508     |             |
| <b>325021 NOSE LANDING GEAR MAIN CASING BOLT</b> Component ATA:32           |         |           |          |          |                           |           |           |             |
| PN:25UN603  | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:A061760  | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.345   | AFL     | 1288      | 33000    | TSN 0    | 34288                     |           | 32796     |             |
| <b>325025 NOSE WHEEL STEERING ON/OFF VALVE</b> Component ATA:32             |         |           |          |          |                           |           |           |             |
| PN:AIR45408-0   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:APB091293  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 32.350   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>325031 NOSE WHEEL ANTI-SHIMMING VALVE</b> Component ATA:32               |         |           |          |          |                           |           |           |             |
| PN:AIR48284-2   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:APB090961  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 32.355   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>325041 NOSE LANDING GEAR UPPER STEERING MAIN MEMBER</b> Component ATA:32 |         |           |          |          |                           |           |           |             |
| PN:25-8UN431-1A   | MOS     | 20-Jun-22 |          |          |                           |           |           | LIFE LIMIT  |
| SN:WO-81026/12  | HRS     | 3511.6    |          |          |                           |           |           |             |
| WC#: 32.360   | AFL     | 1288      | 35000    | TSN 2288 | 34000                     |           | 32508     |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit   | C/W  | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------------|--|------|-----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 32 - LANDING GEAR</b> |  |      |           |          |                           |           |           |             |        |
| 325042                       | NOSE LANDING GEAR LOWER STEERING MAIN MEMBER   |      |           |          |                           |           |           | Component   | ATA:32 |
| PN:25-8UN431-2A              | MOS  |      | 20-Jun-22 |          |                           |           |           | LIFE LIMIT  |        |
| SN:WO-81060/15               | HRS  |      | 3511.6    |          |                           |           |           |             |        |
| WC#: 32.360                  | AFL  | 1288 | 35000     | TSN 2288 | 34000                     |           | 32508     |             |        |
| 325051                       | NOSE LANDING GEAR STEERING JACK PICK-UP        |      |           |          |                           |           |           | Component   | ATA:32 |
| PN:25-8UN263-1A              | MOS  |      | 20-Jun-22 |          |                           |           |           | LIFE LIMIT  |        |
| SN:EPI-0415                  | HRS  |      | 3511.6    |          |                           |           |           |             |        |
| WC#: 32.365                  | AFL  | 1288 | 18000     | TSN 2288 | 17000                     |           | 15508     |             |        |
| 325058                       | NOSE LANDING GEAR STEERING SLEEVE              |      |           |          |                           |           |           | Component   | ATA:32 |
| PN:25-8UN439-1A              | MOS  |      | 20-Jun-22 |          |                           |           |           | LIFE LIMIT  |        |
| SN:WAL52369                  | HRS  |      | 3511.6    |          |                           |           |           |             |        |
| WC#: 32.365                  | AFL  | 1288 | 20000     | TSN 0    | 21288                     |           | 19796     |             |        |
| <b>ATA 33 - LIGHTS</b>       |  |      |           |          |                           |           |           |             |        |
| 330003 <sup>S</sup>          | CLEAN/TEST/REPLACE ANTI-COLLISION LIGHT SYSTEM |      |           |          |                           |           |           | Service     | ATA:33 |
|                              | MOS  |      | 03-Aug-21 |          |                           |           |           |             |        |
|                              | HRS  |      | 3405      |          | 800 (+40/-10)             |           |           |             |        |
| WC#: 33.080                  | AFL  | 1243 |           |          |                           |           |           |             |        |
| PKG:7,91                     |  |      |           |          |                           |           |           |             |        |
| 330007                       | MAIN CG ILLUMINATED LABEL                      |      |           |          |                           |           |           | Component   | ATA:33 |
| PN:PN                        | MOS/MSC  |      | 16-Mar-10 | O/C      | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                   | HRS  |      | 0         |          | TSN 0                     |           |           |             |        |
| WC#: 33.015                  | AFL  |      | 0         |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF    |  |      |           |          |                           |           |           |             |        |
| 330008                       | FORWARD CG ILLUMINATED LABEL                   |      |           |          |                           |           |           | Component   | ATA:33 |
| PN:PN                        | MOS/MSC  |      | 16-Mar-10 | O/C      | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                   | HRS  |      | 0         |          | TSN 0                     |           |           |             |        |
| WC#: 33.015                  | AFL  |      | 0         |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF    |  |      |           |          |                           |           |           |             |        |
| 334001                       | TOP ANTI COLLISION BEACON                      |      |           |          |                           |           |           | Component   | ATA:33 |
| PN:PN                        | MOS/MSC  |      | 16-Mar-10 | O/C      | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                   | HRS  |      | 0         |          | TSN 0                     |           |           |             |        |
| WC#: 33.020                  | AFL  |      | 0         |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 33-40-42      |  |      |           |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                          | Unit    | C/W   | Interval                  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition      |               |
|----------------------------------|---------|---|---------------------------|----------|---------------------------|-----------|-------------|------------------|---------------|
| <b>ATA 33 - LIGHTS</b>           |         |   |                           |          |                           |           |             |                  |               |
| <b>334002</b>                    |         | <b>BOTTOM ANTI COLLISION BEACON</b>           |                           |          |                           |           |             | <b>Component</b> | <b>ATA:33</b> |
| PN:01-0790044-54                 | MOS/MSC | 19-Sep-23                                     | O/C                       | TSN 0    |                           |           |             |                  |               |
| SN:14114840001                   | HRS     | 3798.8  |                           | TSN 0    |                           |           |             |                  |               |
| WC#: 33.020                      | AFL     | 1434  |                           | TSN 0    |                           |           |             |                  |               |
| Special Properties: TRACKED ITEM |         |   | PROC. REF: AMM 33-40-42   |          |                           |           |             |                  |               |
| <b>334013</b>                    |         | <b>LEFT WING STROBE LIGHT</b>                 |                           |          |                           |           |             | <b>Component</b> | <b>ATA:33</b> |
| PN:PN                            | MOS/MSC | 16-Mar-10                                     | O/C                       | TSN 0    |                           |           |             |                  |               |
| SN:UNKNOWN                       | HRS     | 0   |                           | TSN 0    |                           |           |             |                  |               |
| WC#: 33.025                      | AFL     | 0   |                           | TSN 0    |                           |           |             |                  |               |
|                                  |         |   | PROC. REF: AMM 33-40-12   |          |                           |           |             |                  |               |
| <b>334014</b>                    |         | <b>RIGHT WING STROBE LIGHT</b>                |                           |          |                           |           |             | <b>Component</b> | <b>ATA:33</b> |
| PN:01-0770935-01                 | MOS/MSC | 20-Jun-22                                     | O/C                       | TSN 0    |                           |           |             |                  |               |
| SN:N/A                           | HRS     | 3511.6  |                           | TSN 0    |                           |           |             |                  |               |
| WC#: 33.025                      | AFL     | 1288  |                           | TSN 0    |                           |           |             |                  |               |
|                                  |         |   | PROC. REF: AMM 33-40-12   |          |                           |           |             |                  |               |
| <b>334016</b>                    |         | <b>TEST LEFT WING STROBE LIGHT INTENSITY</b>  |                           |          |                           |           |             | <b>Service</b>   | <b>ATA:33</b> |
| PN:PN                            | MOS     | 13-Mar-24                                     |                           |          |                           |           |             |                  |               |
| SN:UNKNOWN                       | HRS     | 3890.9  | 400 (+50/-50)             | Adj 20.7 | 4311.6                    | 4361.6    | 403.2 (+50) |                  |               |
| WC#: 33.025                      | AFL     | 1481  |                           |          |                           |           |             |                  |               |
| <b>334017</b>                    |         | <b>TEST RIGHT WING STROBE LIGHT INTENSITY</b> |                           |          |                           |           |             | <b>Service</b>   | <b>ATA:33</b> |
| PN:01-0770935-01                 | MOS     | 13-Mar-24                                     |                           |          |                           |           |             |                  |               |
| SN:N/A                           | HRS     | 3890.9  | 400 (+50/-50)             | Adj 20.7 | 4311.6                    | 4361.6    | 403.2 (+50) |                  |               |
| WC#: 33.025                      | AFL     | 1481  |                           |          |                           |           |             |                  |               |
| <b>334021</b>                    |         | <b>NO. 1 POWER CONVERTER</b>                  |                           |          |                           |           |             | <b>Component</b> | <b>ATA:33</b> |
| PN:LT-55                         | MOS/MSC | 16-Mar-10                                     | O/C                       | TSN 0    |                           |           |             |                  |               |
| SN:3061                          | HRS     | 0   |                           | TSN 0    |                           |           |             |                  |               |
| WC#: 33.070                      | AFL     | 0   |                           | TSN 0    |                           |           |             |                  |               |
|                                  |         |   | PROC. REF: GENERIC NO REF |          |                           |           |             |                  |               |
| <b>334022</b>                    |         | <b>NO. 2 POWER CONVERTER</b>                  |                           |          |                           |           |             | <b>Component</b> | <b>ATA:33</b> |
| PN:LT-55                         | MOS/MSC | 16-Mar-10                                     | O/C                       | TSN 0    |                           |           |             |                  |               |
| SN:3054                          | HRS     | 0   |                           | TSN 0    |                           |           |             |                  |               |
| WC#: 33.070                      | AFL     | 0   |                           | TSN 0    |                           |           |             |                  |               |
|                                  |         |   | PROC. REF: GENERIC NO REF |          |                           |           |             |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval                | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |
|--|---------|-----------|-------------------------|----------|---------------------------|-----------|-------------|-------------|
| <b>ATA 33 - LIGHTS</b>   |         |           |                         |          |                           |           |             |             |
| <b>334044 TAIL STROBE LIGHT</b> Component ATA:33                   |         |           |                         |          |                           |           |             |             |
| PN:31-1840-1   | MOS/MSC | 20-Jun-22 | O/C                     | TSN 0    |                           |           |             |             |
| SN:N/A   | HRS     | 3511.6    |                         | TSN 0    |                           |           |             |             |
| WC#: 33.040  | AFL     | 1288      |                         | TSN 0    |                           |           |             |             |
| Special Properties: TRACKED ITEM                                   |         |           | PROC. REF: AMM 33-40-12 |          |                           |           |             |             |
| <b>334047 TEST TAIL STROBE LIGHT INTENSITY</b> Service ATA:33      |         |           |                         |          |                           |           |             |             |
| PN:31-1840-1   | MOS     | 13-Mar-24 |                         |          |                           |           |             |             |
| SN:N/A   | HRS     | 3890.9    | 400 (+50/-50)           | Adj 20.7 | 4311.6                    | 4361.6    | 403.2 (+50) |             |
| WC#: 33.040  | AFL     | 1481      |                         |          |                           |           |             |             |
| <b>334061 STROBE LIGHTS POWER SUPPLY</b> Component ATA:33          |         |           |                         |          |                           |           |             |             |
| PN:701571  | MOS/MSC | 16-Mar-10 | O/C                     | TSN 0    |                           |           |             |             |
| SN:1520402   | HRS     | 0         |                         | TSN 0    |                           |           |             |             |
| WC#: 33.045  | AFL     | 0         |                         | TSN 0    |                           |           |             |             |
| PROC. REF: GENERIC NO REF  |         |           |                         |          |                           |           |             |             |
| <b>334525<sup>U</sup> CREW CABINET EXIT LIGHT</b> Component ATA:33 |         |           |                         |          |                           |           |             |             |
| PN:RAY-ELES-101  | MOS/MSC | 05-May-10 | O/C                     |          |                           |           |             |             |
| SN:NSN   | HRS     | 4.7       |                         |          |                           |           |             |             |
|  | AFL     | 4         |                         |          |                           |           |             |             |
| <b>334526<sup>U</sup> HEADLINER EXIT LIGHT</b> Component ATA:33    |         |           |                         |          |                           |           |             |             |
| PN:RAY-ELES-101  | MOS/MSC | 05-May-10 | O/C                     |          |                           |           |             |             |
| SN:NSN   | HRS     | 4.7       |                         |          |                           |           |             |             |
|  | AFL     | 4         |                         |          |                           |           |             |             |
| <b>334527<sup>U</sup> HATCH EXIT COVER</b> Component ATA:33        |         |           |                         |          |                           |           |             |             |
| PN:138-533049-0005   | MOS/MSC | 05-May-10 | O/C                     |          |                           |           |             |             |
| SN:NSN   | HRS     | 4.7       |                         |          |                           |           |             |             |
|  | AFL     | 4         |                         |          |                           |           |             |             |
| <b>334530<sup>U</sup> LOGO LIGHTS</b> Component ATA:33             |         |           |                         |          |                           |           |             |             |
| PN:140-3030-0001   | MOS/MSC | 05-May-10 | O/C                     |          |                           |           |             |             |
| SN:275   | HRS     | 4.7       |                         |          |                           |           |             |             |
|  | AFL     | 4         |                         |          |                           |           |             |             |
| <b>335001 EMERGENCY LIGHTING INERTIA SWITCH</b> Component ATA:33   |         |           |                         |          |                           |           |             |             |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C                     | TSN 0    |                           |           |             |             |
| SN:UNKNOWN   | HRS     | 0         |                         | TSN 0    |                           |           |             |             |
| WC#: 33.050  | AFL     | 0         |                         | TSN 0    |                           |           |             |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 33 - LIGHTS</b> |   |           |          |          |                           |           |           |             |        |
| 335005                 | EMERGENCY LIGHT DEGRADATION             |           |          |          |                           |           |           | Service     | ATA:33 |
|                        | MOS                                     | 04-Apr-19 |          |          |                           |           |           |             |        |
|                        | HRS                                     | 3175.17   | 3500     |          | 6675.17                   |           | 2766.8    |             |        |
|                        | AFL                                     | 1157      |          |          |                           |           |           |             |        |
| 335009                 | FORWARD EMERGENCY LIGHTING POWER SUPPLY |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:61-0478-9           | MOS/MSC                                 | 16-Jun-23 | O/C      |          |                           |           |           |             |        |
| SN:24404               | HRS                                     | 3746.1    |          |          |                           |           |           |             |        |
| WC#: 33.090            | AFL                                     | 1412      |          |          |                           |           |           |             |        |
| 335011                 | AFT EMERGENCY LIGHTING POWER SUPPLY     |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:61-0478-9           | MOS/MSC                                 | 16-Jun-23 | O/C      |          |                           |           |           |             |        |
| SN:24425               | HRS                                     | 3746.1    |          |          |                           |           |           |             |        |
| WC#: 33.095            | AFL                                     | 1412      |          |          |                           |           |           |             |        |
| 335025                 | NO. 1 (AA PNL) DIMMER                   |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:LT52A               | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:20400               | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 33.055            | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
|                        | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |             |        |
| 335027                 | NO. 2 (AA PNL) DIMMER                   |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:LT52A               | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:20401               | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 33.055            | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
|                        | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |             |        |
| 335029                 | NO. 1 (AB PNL) DIMMER                   |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:LT52A               | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:20199               | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 33.060            | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
|                        | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |             |        |
| 335031                 | NO. 2 (AB PNL) DIMMER                   |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:LT52A               | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:20391               | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 33.060            | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
|                        | PROC. REF: GENERIC NO REF               |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 33 - LIGHTS                       |                                 |           |          |          |                           |           |           |             |        |
| 335200                                | PULSELIGHT CONTROL UNIT         |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:2401                               | MOS/MSC                         | 05-May-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:TR01660                            | HRS                             | 4.7       |          | TSN 0    |                           |           |           |             |        |
| WC#: 33.085                           | AFL                             | 4         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: MMA 33-40-10, MMA 33-40-15 |                                 |           |          |          |                           |           |           |             |        |
| 336015 <sup>U</sup>                   | L/H GALLEY SWITCH PANEL         |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:2501-2-176                         | MOS/MSC                         | 05-May-10 | O/C      |          |                           |           |           |             |        |
| SN:3MBCH                              | HRS                             | 4.7       |          |          |                           |           |           |             |        |
|                                       | AFL                             | 4         |          |          |                           |           |           |             |        |
| 336020 <sup>U</sup>                   | ORDINANCE SIGN                  |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:1202-009                           | MOS/MSC                         | 02-Jun-17 | O/C      |          |                           |           |           |             |        |
| SN:C1701                              | HRS                             | 2731.07   |          |          |                           |           |           |             |        |
|                                       | AFL                             | 986       |          |          |                           |           |           |             |        |
| 336025 <sup>U</sup>                   | R/H AFT BULKHEAD ORDINANCE SIGN |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:1202-009                           | MOS/MSC                         | 05-May-10 | O/C      |          |                           |           |           |             |        |
| SN:150376                             | HRS                             | 4.7       |          |          |                           |           |           |             |        |
|                                       | AFL                             | 4         |          |          |                           |           |           |             |        |
| 336027                                | NO. 5 POWER CONVERTER           |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:LT52A                              | MOS/MSC                         | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
| SN:20472                              | HRS                             | 0         |          |          |                           |           |           |             |        |
|                                       | AFL                             | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                 |           |          |          |                           |           |           |             |        |
| 336028                                | NO. 6 POWER CONVERTER           |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:LT52A                              | MOS/MSC                         | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
| SN:20473                              | HRS                             | 0         |          |          |                           |           |           |             |        |
|                                       | AFL                             | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                 |           |          |          |                           |           |           |             |        |
| 336029                                | NO. 7 POWER CONVERTER           |           |          |          |                           |           |           | Component   | ATA:33 |
| PN:LT52A                              | MOS/MSC                         | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
| SN:20303                              | HRS                             | 0         |          |          |                           |           |           |             |        |
|                                       | AFL                             | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                 |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                      | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition |        |
|------------------------------|--|-----------|----------------|----------|---------------------------|-----------|--------------|-------------|--------|
| <b>ATA 33 - LIGHTS</b>       |  |           |                |          |                           |           |              |             |        |
| 336030                       | NO. 8 POWER CONVERTER                                |           |                |          |                           |           |              | Component   | ATA:33 |
| PN:LT52A                     | MOS/MSC  | 16-Mar-10 | O/C            |          |                           |           |              |             |        |
| SN:20407                     | HRS  | 0         |                |          |                           |           |              |             |        |
|                              | AFL  | 0         |                |          |                           |           |              |             |        |
| PROC. REF: GENERIC NO REF    |  |           |                |          |                           |           |              |             |        |
| 336040                       | ESCAPE HATCH BETALIGHT "EXIT" SIGN                   |           |                |          |                           |           |              | Component   | ATA:33 |
| PN:132848-11                 | MOS  | 14-May-20 | 72 (+24m)      | Adj 110d | 30-Apr-26                 | 30-Apr-28 | 640 d (+731) | REPLACE     |        |
| SN:40655                     | HRS  | 3357.57   |                | TSN 0    |                           |           |              |             |        |
|                              | AFL  | 1222      |                | TSN 0    |                           |           |              |             |        |
| Manufacture Date:: 10-Jan-20 |  |           |                |          |                           |           |              |             |        |
| <b>ATA 34 - NAVIGATION</b>   |  |           |                |          |                           |           |              |             |        |
| 340002                       | DRAIN PITOT/STATIC DRAIN TRAPS                       |           |                |          |                           |           |              | Service     | ATA:34 |
|                              | MOS  | 11-Jul-24 | 24 (+2m)       | Adj -21d | 20-Jun-26                 | 20-Aug-26 | 691 d (+61)  |             |        |
|                              | HRS  | 3907.4    |                |          |                           |           |              |             |        |
| WC#: 34.025                  | AFL  | 1491      |                |          |                           |           |              |             |        |
| PROC. REF: AMM 34-11-19      |  |           |                |          |                           |           |              |             |        |
| 340003 <sup>S</sup>          | INSPECT AUTOPILOT AILERON SERVO UNIT AND MOUNT       |           |                |          |                           |           |              | Service     | ATA:34 |
|                              | MOS  | 06-Jun-18 |                |          |                           |           |              |             |        |
|                              | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |              |             |        |
| WC#: 34.405                  | AFL  | 1073      |                |          |                           |           |              |             |        |
| PKG:22,92                    |  |           |                |          |                           |           |              |             |        |
| 340004 <sup>S</sup>          | INSPECT AUTOPILOT SERVO UNITS, RUDDER AND ELEVATOR   |           |                |          |                           |           |              | Service     | ATA:34 |
|                              | MOS  | 06-Jun-18 |                |          |                           |           |              |             |        |
|                              | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |              |             |        |
| WC#: 34.410                  | AFL  | 1073      |                |          |                           |           |              |             |        |
| PKG:25,92                    |  |           |                |          |                           |           |              |             |        |
| 340005 <sup>S</sup>          | INSPECT AUTOPILOT ELEVATOR TRIM SERVO UNIT AND MOUNT |           |                |          |                           |           |              | Service     | ATA:34 |
|                              | MOS  | 06-Jun-18 |                |          |                           |           |              |             |        |
|                              | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |              |             |        |
| WC#: 34.415                  | AFL  | 1073      |                |          |                           |           |              |             |        |
| PKG:25,92                    |  |           |                |          |                           |           |              |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit   | C/W       | Interval        | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|----------------------------|--|-----------|-----------------|-------------------------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b> |  |           |                 |                         |                           |           |             |             |        |
| 340006                     | PRESSURE/SUCTION TEST PITOT/STATIC AND STALL WARNING SYSTEMS       |           |                 |                         |                           |           |             | Service     | ATA:34 |
|                            | MOS  | 11-Jul-24 | 24 (+2m)        |                         | 11-Jul-26                 | 11-Sep-26 | 712 d (+62) |             |        |
|                            | HRS  | 3907.4    |                 |                         |                           |           |             |             |        |
| WC#: 34.015                | AFL  | 1491      |                 |                         |                           |           |             |             |        |
|                            |  |           |                 | PROC. REF: AMM 34-11-19 |                           |           |             |             |        |
| 340007                     | CHECK PITOT SYSTEM ISOLATION VALVES                                |           |                 |                         |                           |           |             | Service     | ATA:34 |
|                            | MOS/MSC  | 13-Apr-12 | N/A             | Adj -7d                 |                           |           |             |             |        |
|                            | HRS  | 933.58    |                 |                         |                           |           |             |             |        |
| WC#: 34.290                | AFL  | 337       |                 |                         |                           |           |             |             |        |
| 340008 <sup>S</sup>        | TEST MACH TRIM SYSTEM  |           |                 |                         |                           |           |             | Service     | ATA:34 |
|                            | MOS  | 06-Jun-18 |                 |                         |                           |           |             |             |        |
|                            | HRS  | 2965.25   | 3200 (+150/-50) |                         |                           |           |             |             |        |
| WC#: 34.270                | AFL  | 1073      |                 |                         |                           |           |             |             |        |
|                            |  |           |                 | PROC. REF: AMM 22-20-00 |                           |           |             | PKG:31,93   |        |
| 340010 <sup>S</sup>        | TEST AUTOTRIM COMMAND ISOLATION RELAY AND AUTOTRIM SWITCHING RELAY |           |                 |                         |                           |           |             | Service     | ATA:34 |
|                            | MOS  | 06-Jun-18 |                 |                         |                           |           |             |             |        |
|                            | HRS  | 2965.25   | 3200 (+150/-50) |                         |                           |           |             |             |        |
| WC#: 34.425                | AFL  | 1073      |                 |                         |                           |           |             |             |        |
|                            |  |           |                 | PROC. REF: AMM 27-30-00 |                           |           |             | PKG:31,93   |        |
| 340011 <sup>S</sup>        | CHECK MACH TRIM FAIL ANNUNCIATION RELAYS                           |           |                 |                         |                           |           |             | Service     | ATA:34 |
|                            | MOS/MSC  | 06-Jun-18 | N/R             |                         |                           |           |             |             |        |
|                            | HRS  | 2965.25   |                 |                         |                           |           |             |             |        |
| WC#: 34.420                | AFL  | 1073      |                 |                         |                           |           |             |             |        |
|                            |  |           |                 |                         |                           |           |             | PKG:31      |        |
| 340012                     | SWING CHECK NO. 1 COMPASS  |           |                 |                         |                           |           |             | Service     | ATA:34 |
|                            | MOS  | 20-Jun-22 | 36 (+2m)        |                         | 20-Jun-25                 | 20-Aug-25 | 326 d (+61) |             |        |
|                            | HRS  | 3511.6    |                 |                         |                           |           |             |             |        |
| WC#: 34.095                | AFL  | 1288      |                 |                         |                           |           |             |             |        |
|                            |  |           |                 | PROC. REF: AMM 34-20-05 |                           |           |             |             |        |
| 340012                     | SWING CHECK NO. 2 COMPASS  |           |                 |                         |                           |           |             | Service     | ATA:34 |
|                            | MOS  | 20-Jun-22 | 36 (+2m)        |                         | 20-Jun-25                 | 20-Aug-25 | 326 d (+61) |             |        |
|                            | HRS  | 3511.6    |                 |                         |                           |           |             |             |        |
| WC#: 34.095                | AFL  | 1288      |                 |                         |                           |           |             |             |        |
|                            |  |           |                 | PROC. REF: AMM 34-20-05 |                           |           |             |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|----------------------------|--|-----------|----------|----------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b> |  |           |          |          |                           |           |             |             |        |
| 340012                     | SWING CHECK STANDBY COMPASS                                      |           |          |          |                           |           |             | Service     | ATA:34 |
|                            | MOS  | 20-Jun-22 | 36 (+2m) |          | 20-Jun-25                 | 20-Aug-25 | 326 d (+61) |             |        |
|                            | HRS  | 3511.6    |          |          |                           |           |             |             |        |
| WC#: 34.095                | AFL  | 1288      |          |          |                           |           |             |             |        |
| PROC. REF: AMM 34-20-05    |  |           |          |          |                           |           |             |             |        |
| 340013                     | COMPLY WITH RVSM REQUIREMENTS FOR THE STATIC PLATES AND AIRFRAME |           |          |          |                           |           |             | Service     | ATA:34 |
|                            | MOS/MSC  | 29-Apr-10 | A/R      |          |                           |           |             |             |        |
|                            | HRS  |           |          |          |                           |           |             |             |        |
| WC#: 34.020                | AFL  |           |          |          |                           |           |             |             |        |
| 341001                     | LEFT PITOT PRESSURE HEAD   |           |          |          |                           |           |             | Component   | ATA:34 |
| PN:PN                      | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |             |             |        |
| SN:UNKNOWN                 | HRS  | 0         |          | TSN 0    |                           |           |             |             |        |
| WC#: 34.010                | AFL  | 0         |          | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM 34-11-24    |  |           |          |          |                           |           |             |             |        |
| 341002                     | RIGHT PITOT PRESSURE HEAD  |           |          |          |                           |           |             | Component   | ATA:34 |
| PN:PN                      | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |             |             |        |
| SN:UNKNOWN                 | HRS  | 0         |          | TSN 0    |                           |           |             |             |        |
| WC#: 34.010                | AFL  | 0         |          | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM 34-11-24    |  |           |          |          |                           |           |             |             |        |
| 341109                     | LEFT AIRSPEED INDICATOR  |           |          |          |                           |           |             | Component   | ATA:34 |
| PN:PN                      | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |             |             |        |
| SN:UNKNOWN                 | HRS  | 0         |          | TSN 0    |                           |           |             |             |        |
| WC#: 34.050                | AFL  | 0         |          | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |             |             |        |
| 341110                     | RIGHT AIRSPEED INDICATOR   |           |          |          |                           |           |             | Component   | ATA:34 |
| PN:PN                      | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |             |             |        |
| SN:UNKNOWN                 | HRS  | 0         |          | TSN 0    |                           |           |             |             |        |
| WC#: 34.055                | AFL  | 0         |          | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |             |             |        |
| 341111                     | NO. 1 AIRSPEED REFERENCE PANEL                                   |           |          |          |                           |           |             | Component   | ATA:34 |
| PN:PN                      | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |             |             |        |
| SN:UNKNOWN                 | HRS  | 0         |          | TSN 0    |                           |           |             |             |        |
| WC#: 34.315                | AFL  | 0         |          | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |             |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit    | C/W                                   | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining               | Disposition |  |
|----------------------------|---------|---------------------------------------|----------|----------|---------------------------|-----------|-------------------------|-------------|--|
| <b>ATA 34 - NAVIGATION</b> |         |                                       |          |          |                           |           |                         |             |  |
| <b>341112</b>              |         | <b>NO. 2 AIRSPEED REFERENCE PANEL</b> |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:PN                      | MOS/MSC | 16-Mar-10                             | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:UNKNOWN                 | HRS     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| WC#: 34.315                | AFL     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| PROC. REF: AMM NO REF      |         |                                       |          |          |                           |           |                         |             |  |
| <b>341115</b>              |         | <b>STANDBY AIRSPEED INDICATOR</b>     |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:PN                      | MOS/MSC | 16-Mar-10                             | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:UNKNOWN                 | HRS     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| WC#: 34.045                | AFL     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| PROC. REF: AMM NO REF      |         |                                       |          |          |                           |           |                         |             |  |
| <b>341163</b>              |         | <b>LEFT SAT/TAS INDICATOR</b>         |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:PN                      | MOS/MSC | 16-Mar-10                             | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:UNKNOWN                 | HRS     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| WC#: 34.320                | AFL     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| PROC. REF: AMM 34-10-19    |         |                                       |          |          |                           |           |                         |             |  |
| <b>341164</b>              |         | <b>RIGHT SAT/TAS INDICATOR</b>        |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:PN                      | MOS/MSC | 16-Mar-10                             | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:UNKNOWN                 | HRS     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| WC#: 34.320                | AFL     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| PROC. REF: AMM 34-10-19    |         |                                       |          |          |                           |           |                         |             |  |
| <b>341195</b>              |         | <b>VOICE ADVISORY</b>                 |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:PN                      | MOS/MSC | 16-Mar-10                             | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:UNKNOWN                 | HRS     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| WC#: 34.060                | AFL     | 0                                     |          | TSN 0    |                           |           |                         |             |  |
| PROC. REF: AMM NO REF      |         |                                       |          |          |                           |           |                         |             |  |
| <b>341228</b>              |         | <b>NO. 1 AIR DATA COMPUTER</b>        |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:822-1109-015            | MOS/MSC | 06-Jun-18                             | O/C      | TSO 0    |                           |           |                         |             |  |
| SN:39LDH                   | HRS     | 2965.25                               |          | TSO 0    |                           |           |                         |             |  |
| WC#: 34.065                | AFL     | 1073                                  |          | TSO 0    |                           |           |                         |             |  |
| <b>341229</b>              |         | <b>NO. 2 AIR DATA COMPUTER</b>        |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:822-1109-015            | MOS/MSC | 08-Jun-18                             | O/C      | TSO 0    |                           |           |                         |             |  |
| SN:39LBY                   | HRS     | 2966.07                               |          | TSO 0    |                           |           |                         |             |  |
| WC#: 34.066                | AFL     | 1074                                  |          | TSO 0    |                           |           |                         |             |  |
| PROC. REF: GENERIC NO REF  |         |                                       |          |          |                           |           |                         |             |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                  | Unit                                     | C/W       | Interval | TSX/Adj.    | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--|--|-----------|----------|-------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b>               |  |           |          |             |                           |           |           |             |        |
| 341230                                   | NO. 1 AIR DATA MODULE                    |           |          |             |                           |           |           | Component   | ATA:34 |
| PN:PN                                    | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:UNKNOWN                               | HRS                                      | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 34.325                              | AFL                                      | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: AMM NO REF                    |  |           |          |             |                           |           |           |             |        |
| 341231                                   | NO. 2 AIR DATA MODULE                    |           |          |             |                           |           |           | Component   | ATA:34 |
| PN:PN                                    | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:UNKNOWN                               | HRS                                      | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 34.325                              | AFL                                      | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: AMM NO REF                    |  |           |          |             |                           |           |           |             |        |
| 341234                                   | SIGNAL INTERFERENCE ADAPTER              |           |          |             |                           |           |           | Component   | ATA:34 |
| PN:PN                                    | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:UNKNOWN                               | HRS                                      | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 34.330                              | AFL                                      | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: AMM NO REF                    |  |           |          |             |                           |           |           |             |        |
| 341235                                   | (ESIS) MAGNETOMETER                      |           |          |             |                           |           |           | Component   | ATA:34 |
| PN:19004-00-01                           | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0       |                           |           |           |             |        |
| SN:M024592                               | HRS                                      | 0         |          | TSN 0       |                           |           |           |             |        |
| WC#: 34.485                              | AFL                                      | 0         |          | TSN 0       |                           |           |           |             |        |
| PROC. REF: AMM NO REF                    |  |           |          |             |                           |           |           |             |        |
| 341237                                   | AIR DATA ESIS UNIT                       |           |          |             |                           |           |           | Component   | ATA:34 |
| PN:27301-01-01                           | MOS/MSC                                  | 02-Apr-16 | O/C      | TSN 73      |                           |           |           |             |        |
| SN:M024948                               | HRS                                      | 2351.57   |          | TSN 2351.57 |                           |           |           |             |        |
| WC#: 34.435                              | AFL                                      | 852       |          | TSN 852     |                           |           |           |             |        |
| PROC. REF: AMM NO REF                    |  |           |          |             |                           |           |           |             |        |
| 341238                                   | TEST AIR DATA ESIS UNIT (FAA 91.411)     |           |          |             |                           |           |           | Service     | ATA:34 |
| PN:27301-01-01                           | MOS                                      | 19-Jun-23 | 24       |             | 19-Jun-25                 |           | 325 d     | MANDATORY   |        |
| SN:M024948                               | HRS                                      |           |          |             |                           |           |           |             |        |
| WC#: 34.435                              | AFL                                      |           |          |             |                           |           |           |             |        |
| PROC. REF: AMM 31-20-66, FAR FAR PART 91 |  |           |          |             |                           |           |           |             |        |
| 341240                                   | TEST NO.1 AIR DATA COMPUTER (FAA 91.411) |           |          |             |                           |           |           | Service     | ATA:34 |
| PN:822-1109-015                          | MOS                                      | 19-Jun-23 | 24       |             | 19-Jun-25                 |           | 325 d     | MANDATORY   |        |
| SN:39LDH                                 | HRS                                      |           |          |             |                           |           |           |             |        |
| WC#: 34.065                              | AFL                                      |           |          |             |                           |           |           |             |        |
| PROC. REF: AMM 34-10-19, FAR FAR PART 91 |  |           |          |             |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|--|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| <b>ATA 34 - NAVIGATION</b>                             |         |           |          |          |                           |           |           |                  |
| <b>341241 TEST NO.2 AIR DATA COMPUTER (FAA 91.411)</b> |         |           |          |          |                           |           |           | Service ATA:34   |
| PN:822-1109-015  | MOS     | 19-Jun-23 | 24       |          | 19-Jun-25                 |           | 325 d     | MANDATORY        |
| SN:39LBY   | HRS     |           |          |          |                           |           |           |                  |
| WC#: 34.066  | AFL     |           |          |          |                           |           |           |                  |
| PROC. REF: AMM 34-10-19, FAR FAR PART 91               |         |           |          |          |                           |           |           |                  |
| <b>341276 RADIO ALTIMETER UNIT</b>                     |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:822-0615-206  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |                  |
| SN:3LVDK   | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.070  | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-40-05, AMM 34-40-05                  |         |           |          |          |                           |           |           |                  |
| <b>341279 LEFT RADIO ALTIMETER ANTENNA</b>             |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:S67-2002  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |                  |
| SN:54349998  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.075  | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-40-05, AMM 34-40-05                  |         |           |          |          |                           |           |           |                  |
| <b>341281 RIGHT RADIO ALTIMETER ANTENNA</b>            |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:S67-2002  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |                  |
| SN:54349791  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.080  | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-40-05, AMM 34-40-05                  |         |           |          |          |                           |           |           |                  |
| <b>342013 EMERGENCY GYRO HORIZON INDICATOR</b>         |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:PN  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN   | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.090  | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM NO REF                                  |         |           |          |          |                           |           |           |                  |
| <b>342014 SECONDARY FLIGHT DISPLAY</b>                 |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:39213-00-01   | MOS/MSC | 30-May-23 | O/C      | TSO 1    |                           |           |           |                  |
| SN:M011328   | HRS     | 3715.2    |          | TSO 0    |                           |           |           |                  |
| WC#: 34.490  | AFL     | 1400      |          | TSO 0    |                           |           |           |                  |
| PROC. REF: AMM NO REF                                  |         |           |          |          |                           |           |           |                  |
| <b>342097 STANDBY COMPASS (E2B) INDICATOR</b>          |         |           |          |          |                           |           |           | Component ATA:34 |
| PN:KCA0104W  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |                  |
| SN:BB9341008   | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 34.106  | AFL     | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: AMM 34-09-112, AMM 34-09-112                |         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit                             | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------|----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b> |                                  |           |          |          |                           |           |           |             |        |
| 342141                     | NO. 1 VLF/OMEGA SENSOR           |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                          | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                 | HRS                              | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.105                | AFL                              | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |                                  |           |          |          |                           |           |           |             |        |
| 342142                     | NO. 2 VLF/OMEGA SENSOR           |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                          | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                 | HRS                              | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.105                | AFL                              | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |                                  |           |          |          |                           |           |           |             |        |
| 342143                     | H FIELD (TOP) ANTENNA            |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                          | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                 | HRS                              | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.110                | AFL                              | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |                                  |           |          |          |                           |           |           |             |        |
| 342144                     | H FIELD ( BOTTOM) ANTENNA        |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                          | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                 | HRS                              | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.110                | AFL                              | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |                                  |           |          |          |                           |           |           |             |        |
| 342145                     | NO. 1 DATA LOADER                |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                          | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                 | HRS                              | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.115                | AFL                              | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 34-60-20    |                                  |           |          |          |                           |           |           |             |        |
| 342220                     | NO. 1 FLIGHT MANAGEMENT COMPUTER |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-0868-111            | MOS/MSC                          | 11-Jul-24 | O/C      |          |                           |           |           |             |        |
| SN:46VWK                   | HRS                              | 3907.4    |          |          |                           |           |           |             |        |
| WC#: 34.350                | AFL                              | 1491      |          |          |                           |           |           |             |        |
| PROC. REF: AMM 34-60-10    |                                  |           |          |          |                           |           |           |             |        |
| 342221                     | NO. 2 FLIGHT MANAGEMENT COMPUTER |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-0868-111            | MOS/MSC                          | 10-Feb-20 | O/C      | TSO 0    |                           |           |           |             |        |
| SN:33DDP                   | HRS                              | 3334.37   |          | TSO 0    |                           |           |           |             |        |
| WC#: 34.350                | AFL                              | 1214      |          | TSO 0    |                           |           |           |             |        |
| PROC. REF: AMM 34-60-10    |                                  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------|--------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b> |                          |           |          |          |                           |           |           |             |        |
| 342240                     | REMOTE TUNING UNIT       |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.340                | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                          |           |          |          |                           |           |           |             |        |
| 342253                     | NO. 1 COMPASS FLUX VALVE |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.120                | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-20-05    |                          |           |          |          |                           |           |           |             |        |
| 342254                     | NO. 2 COMPASS FLUX VALVE |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.120                | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-20-05    |                          |           |          |          |                           |           |           |             |        |
| 342265                     | NO. 1 AHRS COMPUTER      |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1110-002            | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3PF9M                   | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.125                | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-20-05    |                          |           |          |          |                           |           |           |             |        |
| 342266                     | NO. 2 AHRS COMPUTER      |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1110-002            | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3PFDR                   | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.125                | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-20-05    |                          |           |          |          |                           |           |           |             |        |
| 342289                     | NO. 1 AHRS CONTROLLER    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.140                | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-20-05    |                          |           |          |          |                           |           |           |             |        |
| 342290                     | NO. 2 AHRS CONTROLLER    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.140                | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-20-05    |                          |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit   | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|--|-----------|----------|------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b>            |  |           |          |            |                           |           |           |             |        |
| 342501                                | <b>NO. 1 MULTIFUNCTION DISPLAY</b>           |           |          |            |                           |           |           | Component   | ATA:34 |
| PN:822-1753-310                       | MOS/MSC                                      | 01-Sep-23 | O/C      |            |                           |           |           |             |        |
| SN:3HG2G                              | HRS  | 3779      |          |            |                           |           |           |             |        |
| WC#: 34.130                           | AFL  | 1427      |          |            |                           |           |           |             |        |
| PROC. REF: AMM 34-60-35, AMM 34-60-35 |  |           |          |            |                           |           |           |             |        |
| 342502                                | <b>NO. 2 MULTIFUNCTION DISPLAY</b>           |           |          |            |                           |           |           | Component   | ATA:34 |
| PN:822-1753-310                       | MOS/MSC                                      | 01-Sep-23 | O/C      | TSO 1      |                           |           |           |             |        |
| SN:33T1D                              | HRS  | 3779      |          | TSO 19.2   |                           |           |           |             |        |
| WC#: 34.135                           | AFL  | 1427      |          | TSO 9      |                           |           |           |             |        |
| PROC. REF: AMM 34-60-35, AMM 34-60-35 |  |           |          |            |                           |           |           |             |        |
| 342513                                | <b>NO. 1 PRIMARY FLIGHT DISPLAY</b>          |           |          |            |                           |           |           | Component   | ATA:34 |
| PN:822-1084-310                       | MOS/MSC                                      | 05-Apr-12 | O/C      | TSN 25     |                           |           |           |             |        |
| SN:3HFPX                              | HRS  | 933.58    |          | TSN 933.58 |                           |           |           |             |        |
| WC#: 34.130                           | AFL  | 337       |          | TSN 337    |                           |           |           |             |        |
| PROC. REF: AMM 34-60-35, AMM 34-60-35 |  |           |          |            |                           |           |           |             |        |
| 342514                                | <b>NO. 2 PRIMARY FLIGHT DISPLAY</b>          |           |          |            |                           |           |           | Component   | ATA:34 |
| PN:822-1084-310                       | MOS/MSC                                      | 13-Apr-12 | O/C      | TSN 25     |                           |           |           |             |        |
| SN:3HFXP                              | HRS  | 933.58    |          | TSN 933.35 |                           |           |           |             |        |
| WC#: 34.135                           | AFL  | 337       |          | TSN 337    |                           |           |           |             |        |
| PROC. REF: AMM 34-60-35, AMM 34-60-35 |  |           |          |            |                           |           |           |             |        |
| 342515                                | <b>EFIS MULTIFUNCTION ELECTRONIC DISPLAY</b> |           |          |            |                           |           |           | Component   | ATA:34 |
| PN:PN                                 | MOS/MSC                                      | 16-Mar-10 | O/C      | TSN 0      |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS  | 0         |          | TSN 0      |                           |           |           |             |        |
| WC#: 34.140                           | AFL  | 0         |          | TSN 0      |                           |           |           |             |        |
| 342516                                | <b>NO. 1 REMOTE INSTRUMENT CONTROL</b>       |           |          |            |                           |           |           | Component   | ATA:34 |
| PN:PN                                 | MOS/MSC                                      | 16-Mar-10 | O/C      | TSN 0      |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS  | 0         |          | TSN 0      |                           |           |           |             |        |
| WC#: 34.145                           | AFL  | 0         |          | TSN 0      |                           |           |           |             |        |
| PROC. REF: AMM NO REF                 |  |           |          |            |                           |           |           |             |        |
| 342517                                | <b>NO. 2 REMOTE INSTRUMENT CONTROL</b>       |           |          |            |                           |           |           | Component   | ATA:34 |
| PN:PN                                 | MOS/MSC                                      | 16-Mar-10 | O/C      | TSN 0      |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS  | 0         |          | TSN 0      |                           |           |           |             |        |
| WC#: 34.145                           | AFL  | 0         |          | TSN 0      |                           |           |           |             |        |
| PROC. REF: AMM NO REF                 |  |           |          |            |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN               | Unit                           | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-----------------------|--------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 34 - NAVIGATION   |                                |           |          |          |                           |           |           |             |        |
| 342523                | MULTIFUNCTION PROCESS UNIT     |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                 | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN            | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.335           | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF |                                |           |          |          |                           |           |           |             |        |
| 342525                | NO. 1 EFIS DISPLAY PROCESSOR   |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                 | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN            | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.335           | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF |                                |           |          |          |                           |           |           |             |        |
| 342526                | NO. 2 EFIS DISPLAY PROCESSOR   |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                 | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN            | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.335           | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF |                                |           |          |          |                           |           |           |             |        |
| 342527                | NO. 1 EFIS SYMBOL GENERATOR    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                 | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN            | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.150           | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF |                                |           |          |          |                           |           |           |             |        |
| 342528                | NO. 2 EFIS SYMBOL GENERATOR    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                 | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN            | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.150           | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF |                                |           |          |          |                           |           |           |             |        |
| 342530                | MULTIFUNCTION SYMBOL GENERATOR |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                 | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN            | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.150           | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF |                                |           |          |          |                           |           |           |             |        |
| 342537                | NO. 1 DISPLAY CONTROL PANEL    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-2117-002       | MOS/MSC                        | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3HLYR              | HRS                            | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.155           | AFL                            | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF |                                |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit    | C/W                                       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|----------------------------|---------|---|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 34 - NAVIGATION</b> |         |   |          |          |                           |           |           |                  |               |
| <b>342538</b>              |         | <b>NO. 2 DISPLAY CONTROL PANEL</b>        |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-2117-002            | MOS/MSC | 16-Mar-10                                 | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:3HMOT                   | HRS     | 0   |          |          | TSN 0                     |           |           |                  |               |
| WC#: 34.155                | AFL     | 0   |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM NO REF      |         |   |          |          |                           |           |           |                  |               |
| <b>342539</b>              |         | <b>MULTI FUNCTION EFIS CONTROL</b>        |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:PN                      | MOS/MSC | 16-Mar-10                                 | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:UNKNOWN                 | HRS     | 0   |          |          | TSN 0                     |           |           |                  |               |
| WC#: 34.160                | AFL     | 0   |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM NO REF      |         |   |          |          |                           |           |           |                  |               |
| <b>342540</b>              |         | <b>FLIGHT GUIDANCE PANEL</b>              |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1107-102            | MOS/MSC | 16-Mar-10                                 | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:3HM3L                   | HRS     | 0   |          |          | TSN 0                     |           |           |                  |               |
| WC#: 34.440                | AFL     | 0   |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM NO REF      |         |   |          |          |                           |           |           |                  |               |
| <b>342541</b>              |         | <b>NO. 1 CONSOLE CONTROL DISPLAY UNIT</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1485-070            | MOS/MSC | 16-Mar-10                                 | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:3RJGW                   | HRS     | 0   |          |          | TSN 0                     |           |           |                  |               |
| WC#: 34.445                | AFL     | 0   |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM NO REF      |         |   |          |          |                           |           |           |                  |               |
| <b>342542</b>              |         | <b>NO. 2 CONSOLE CONTROL DISPLAY UNIT</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1485-070            | MOS/MSC | 16-Mar-10                                 | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:3RJGX                   | HRS     | 0   |          |          | TSN 0                     |           |           |                  |               |
| WC#: 34.450                | AFL     | 0   |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM NO REF      |         |   |          |          |                           |           |           |                  |               |
| <b>342543</b>              |         | <b>PILOT OPTIONAL CONTROL MODULE</b>      |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1484-252            | MOS/MSC | 16-Mar-10                                 | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:3J55W                   | HRS     | 0   |          |          | TSN 0                     |           |           |                  |               |
| WC#: 34.495                | AFL     | 0   |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM NO REF      |         |   |          |          |                           |           |           |                  |               |
| <b>342544</b>              |         | <b>COPILOT OPTIONAL CONTROL MODULE</b>    |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1484-252            | MOS/MSC | 16-Mar-10                                 | O/C      |          | TSN 0                     |           |           |                  |               |
| SN:3J55X                   | HRS     | 0   |          |          | TSN 0                     |           |           |                  |               |
| WC#: 34.495                | AFL     | 0   |          |          | TSN 0                     |           |           |                  |               |
| PROC. REF: AMM NO REF      |         |   |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b>            |   |           |          |          |                           |           |           |             |        |
| 342545                                | NO. 1 FLUX DETECTOR                             |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                                 | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.500                           | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF                 |   |           |          |          |                           |           |           |             |        |
| 342547                                | NO. 2 FLUX DETECTOR                             |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                                 | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.500                           | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF                 |   |           |          |          |                           |           |           |             |        |
| 342550                                | IAPS ENVIROMENTAL CONTROLLER                    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1167-001                       | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3J4PB                              | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.505                           | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF                 |   |           |          |          |                           |           |           |             |        |
| 342561                                | TCAS COMPUTER                                   |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1294-032                       | MOS/MSC   | 27-Nov-20 | O/C      | TSO 0    |                           |           |           |             |        |
| SN:149438                             | HRS   | 3365.83   |          | TSO 0    |                           |           |           |             |        |
| WC#: 34.175                           | AFL   | 1227      |          | TSO 0    |                           |           |           |             |        |
| PROC. REF: AMM 34-50-35, AMM 34-50-35 |   |           |          |          |                           |           |           |             |        |
| 342562                                | TCAS (TOP) ANTENNA                              |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:622-8973-001                       | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3DVRN                              | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.180                           | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 34-50-35, AMM 34-50-35 |   |           |          |          |                           |           |           |             |        |
| 342563                                | TCAS (BOTTOM) ANTENNA                           |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:622-8973-001                       | MOS/MSC   | 31-Dec-19 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:4G30R7                             | HRS   | 3327.28   |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.180                           | AFL   | 1211      |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 34-50-35, AMM 34-50-35 |   |           |          |          |                           |           |           |             |        |
| 342601                                | NO. 1 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                                 | MOS/MSC   | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.185                           | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF                 |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b> |   |           |          |          |                           |           |           |             |        |
| 342602                     | NO. 2 INTEGRATED NAVIGATION (RNZ-850/-851) UNIT |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.185                | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |   |           |          |          |                           |           |           |             |        |
| 342624                     | NO. 1 ADF ANTENNA                               |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.190                | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-50-20    |   |           |          |          |                           |           |           |             |        |
| 342625                     | NO. 2 ADF ANTENNA                               |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.190                | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-50-20    |   |           |          |          |                           |           |           |             |        |
| 342640                     | EGPWS COMPUTER                                  |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:9000000-86008           | MOS/MSC   | 20-Jul-23 | O/C      |          | TSO 6                     |           |           |             |        |
| SN:TWE00689                | HRS   | 3746.3    |          |          | TSO 0                     |           |           |             |        |
| WC#: 34.455                | AFL   | 1413      |          |          | TSO 0                     |           |           |             |        |
| PROC. REF: AMM 34-40-35    |   |           |          |          |                           |           |           |             |        |
| 342701                     | NO. 1 DATA CONCENTRATOR UNIT                    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1483-010            | MOS/MSC   | 17-Jul-14 | O/C      |          |                           |           |           |             |        |
| SN:3PL3V                   | HRS   | 1940.5    |          |          | TSN 1940.5                |           |           |             |        |
| WC#: 34.515                | AFL   | 703       |          |          | TSN 730                   |           |           |             |        |
| PROC. REF: AMM NO REF      |   |           |          |          |                           |           |           |             |        |
| 342703                     | NO. 2 DATA CONCENTRATOR UNIT                    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1483-010            | MOS/MSC   | 17-Jul-14 | O/C      |          |                           |           |           |             |        |
| SN:3PL3T                   | HRS   | 1940.5    |          |          | TSN 1940.5                |           |           |             |        |
| WC#: 34.515                | AFL   | 703       |          |          | TSN 730                   |           |           |             |        |
| PROC. REF: AMM NO REF      |   |           |          |          |                           |           |           |             |        |
| 342705                     | NO. 3 DATA CONCENTRATOR UNIT                    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC   | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.520                | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit                                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b> |  |           |          |          |                           |           |           |             |        |
| 342707                     | NO. 4 DATA CONCENTRATOR UNIT             |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                 | HRS                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.520                | AFL                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |           |             |        |
| 342709                     | DA PANEL ASSEMBLY                        |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:140M360051-6203         | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:4043699                 | HRS                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.525                | AFL                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |           |             |        |
| 342801                     | NO. 1 INPUT / OUTPUT CONCENTRATOR MODULE |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1361-106            | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3J2WR                   | HRS                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.530                | AFL                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |           |             |        |
| 342802                     | NO. 2 INPUT / OUTPUT CONCENTRATOR MODULE |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1361-106            | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3J35T                   | HRS                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.530                | AFL                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |           |             |        |
| 342805                     | NO. 1 IAPS POWER SUPPLY                  |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1137-001            | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3J42L                   | HRS                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.535                | AFL                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |           |             |        |
| 342806                     | NO. 2 IAPS POWER SUPPLY                  |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1137-001            | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3J4CP                   | HRS                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.535                | AFL                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |           |             |        |
| 342809                     | AURAL WARNING GENERATOR                  |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:630-003                 | MOS/MSC                                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:1872                    | HRS                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 34.540                | AFL                                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM NO REF      |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit                       | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------|----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b> |                            |           |          |          |                           |           |           |             |        |
| 342810                     | NO. 1 CURSOR CONTROL PANEL |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1746-002            | MOS/MSC                    | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3HM7N                   | HRS                        | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.545                | AFL                        | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                            |           |          |          |                           |           |           |             |        |
| 342811                     | NO. 2 CURSOR CONTROL PANEL |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1746-002            | MOS/MSC                    | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3HM7P                   | HRS                        | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.545                | AFL                        | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                            |           |          |          |                           |           |           |             |        |
| 342812                     | NO. 1 FILE SERVER UNIT     |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1543-101            | MOS/MSC                    | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3LLKX                   | HRS                        | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.550                | AFL                        | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                            |           |          |          |                           |           |           |             |        |
| 342813                     | NO. 2 FILE SERVER UNIT     |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC                    | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                        | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.550                | AFL                        | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                            |           |          |          |                           |           |           |             |        |
| 342815                     | FSU (MMT-5000) MOUNT       |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1811-003            | MOS/MSC                    | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3H3MB                   | HRS                        | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.600                | AFL                        | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF  |                            |           |          |          |                           |           |           |             |        |
| 343001                     | GLIDE SLOPE AERIAL         |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:17-21F6                 | MOS/MSC                    | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:7850                    | HRS                        | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.195                | AFL                        | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                            |           |          |          |                           |           |           |             |        |
| 343013                     | MARKER AERIAL              |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:17-5C                   | MOS/MSC                    | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:7736                    | HRS                        | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.200                | AFL                        | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                            |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b>                          |                                   |           |          |          |                           |           |           |             |        |
| 344001  | NO. 1 WEATHER RADAR CONTROL PANEL |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN   | MOS/MSC                           | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN  | HRS                               | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.205   | AFL                               | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF                               |                                   |           |          |          |                           |           |           |             |        |
| 344002  | NO. 2 WEATHER RADAR CONTROL PANEL |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN   | MOS/MSC                           | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN  | HRS                               | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.205   | AFL                               | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF                               |                                   |           |          |          |                           |           |           |             |        |
| 344005  | WEATHER RADAR TRANSCEIVER         |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:622-8441-004                                     | MOS/MSC                           | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3PR8P  | HRS                               | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.210   | AFL                               | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF 1                             |                                   |           |          |          |                           |           |           |             |        |
| 344016  | RADAR CHECKLIST MODULE            |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN   | MOS/MSC                           | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN  | HRS                               | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.215   | AFL                               | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF                               |                                   |           |          |          |                           |           |           |             |        |
| 344036  | ISOLATION VALVE                   |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:25MC2175   | MOS/MSC                           | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:35080159   | HRS                               | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.220   | AFL                               | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-11-52                             |                                   |           |          |          |                           |           |           |             |        |
| 345001  | NO. 1 VHF NAVIGATION RECEIVER     |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1465-101                                     | MOS/MSC                           | 25-Jan-24 | O/C      |          |                           |           |           |             |        |
| SN:3B2BT  | HRS                               | 3870.2    |          |          |                           |           |           |             |        |
| WC#: 34.300   | AFL                               | 1471      |          |          |                           |           |           |             |        |
| PROC. REF: AMM 34-32-30, AMM 34-32-30, AMM 34-32-30 |                                   |           |          |          |                           |           |           |             |        |
| 345002  | NO. 2 VHF NAVIGATION RECEIVER     |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-1465-101                                     | MOS/MSC                           | 12-Feb-24 | O/C      |          | TSO 0                     |           |           |             |        |
| SN:2KF6N  | HRS                               | 3881.4    |          |          | TSO 0                     |           |           |             |        |
| WC#: 34.300   | AFL                               | 1476      |          |          | TSO 0                     |           |           |             |        |
| PROC. REF: AMM 34-32-30, AMM 34-32-30, AMM 34-32-30 |                                   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------|-----------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b> |                       |           |          |          |                           |           |           |             |        |
| 345003                     | DATA BASE UNIT        |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:822-2215-202            | MOS/MSC               | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3R2NL                   | HRS                   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.503                | AFL                   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                       |           |          |          |                           |           |           |             |        |
| 345008                     | SENSOR UNIT DISPLAY   |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC               | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.295                | AFL                   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                       |           |          |          |                           |           |           |             |        |
| 345009                     | SENSOR DRIVER DISPLAY |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC               | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.295                | AFL                   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                       |           |          |          |                           |           |           |             |        |
| 345015                     | ILS CONVERTER         |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC               | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.300                | AFL                   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF      |                       |           |          |          |                           |           |           |             |        |
| 345019                     | NO. 1 ADF RECEIVER    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC               | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.310                | AFL                   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-50-20    |                       |           |          |          |                           |           |           |             |        |
| 345020                     | NO. 2 ADF RECEIVER    |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:PN                      | MOS/MSC               | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                 | HRS                   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.310                | AFL                   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-50-20    |                       |           |          |          |                           |           |           |             |        |
| 345037                     | LEFT VOR/LOC AERIAL   |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:S65-247-12              | MOS/MSC               | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:9025                    | HRS                   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.230                | AFL                   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-32-35    |                       |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b>            |                              |           |          |          |                           |           |           |             |        |
| 345038                                | RIGHT VOR/LOC AERIAL         |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:S65-247-12                         | MOS/MSC                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:9024                               | HRS                          | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.230                           | AFL                          | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-32-35               |                              |           |          |          |                           |           |           |             |        |
| 345049                                | NO. 1 ADF LOOP ANTENNA       |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:622-7384-001                       | MOS/MSC                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:2RBBN                              | HRS                          | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.235                           | AFL                          | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF                 |                              |           |          |          |                           |           |           |             |        |
| 345097                                | PHASING COUPLER              |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:SSPD-113-10                        | MOS/MSC                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:5986                               | HRS                          | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.240                           | AFL                          | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF                 |                              |           |          |          |                           |           |           |             |        |
| 345098                                | COUPLER ANTENNA              |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:SSPD113-13                         | MOS/MSC                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:1249                               | HRS                          | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.245                           | AFL                          | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM NO REF                 |                              |           |          |          |                           |           |           |             |        |
| 345109                                | NO. 1 DME AERIAL             |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:10A1P3                             | MOS/MSC                      | 13-Apr-17 | O/C      |          |                           |           |           |             |        |
| SN:50040                              | HRS                          | 2678.38   |          |          |                           |           |           |             |        |
| WC#: 34.250                           | AFL                          | 965       |          |          |                           |           |           |             |        |
| PROC. REF: AMM 34-50-05, AMM 34-50-05 |                              |           |          |          |                           |           |           |             |        |
| 345110                                | NO. 2 DME AERIAL             |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:S65-5366-10L                       | MOS/MSC                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:10096                              | HRS                          | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.250                           | AFL                          | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-50-05, AMM 34-50-05 |                              |           |          |          |                           |           |           |             |        |
| 345133                                | NO. 1 ATC TRANSPONDER AERIAL |           |          |          |                           |           |           | Component   | ATA:34 |
| PN:S65-5366-10L                       | MOS/MSC                      | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:9804                               | HRS                          | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 34.255                           | AFL                          | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 34-50-25               |                              |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W                                 | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining               | Disposition |  |
|---------------------------------------|---------|-------------------------------------|----------|----------|---------------------------|-----------|-------------------------|-------------|--|
| <b>ATA 34 - NAVIGATION</b>            |         |                                     |          |          |                           |           |                         |             |  |
| <b>345134</b>                         |         | <b>NO. 2 ATC TRANSPONDER AERIAL</b> |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:S65-5366-10L                       | MOS/MSC | 16-Mar-10                           | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:9822                               | HRS     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| WC#: 34.255                           | AFL     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM 34-50-25               |         |                                     |          |          |                           |           |                         |             |  |
| <b>345135</b>                         |         | <b>FORWARD TRANSPONDER ANTENNA</b>  |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:S65-5366-10L                       | MOS/MSC | 16-Mar-10                           | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:9790                               | HRS     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| WC#: 34.460                           | AFL     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM NO REF                 |         |                                     |          |          |                           |           |                         |             |  |
| <b>345136</b>                         |         | <b>AFT TRANSPONDER ANTENNA</b>      |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:S65-5366-10L                       | MOS/MSC | 16-Mar-10                           | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:9798                               | HRS     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| WC#: 34.465                           | AFL     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM NO REF                 |         |                                     |          |          |                           |           |                         |             |  |
| <b>345205</b>                         |         | <b>NO. 1 DME TRANSCEIVER</b>        |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:822-1466-001                       | MOS/MSC | 16-Mar-10                           | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:3VCJX                              | HRS     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| WC#: 34.305                           | AFL     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM 34-50-05, AMM 34-50-05 |         |                                     |          |          |                           |           |                         |             |  |
| <b>345206</b>                         |         | <b>NO. 2 DME TRANSCEIVER</b>        |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:822-1466-001                       | MOS/MSC | 16-Mar-10                           | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:3VCKH                              | HRS     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| WC#: 34.305                           | AFL     | 0                                   | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM 34-50-05, AMM 34-50-05 |         |                                     |          |          |                           |           |                         |             |  |
| <b>345217</b>                         |         | <b>NO. 1 ATC TRANSPONDER</b>        |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:622-9210-501                       | MOS/MSC | 19-Jun-23                           | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:3LT1W                              | HRS     | 3746.1                              | TSN 0    |          |                           |           |                         |             |  |
| WC#: 34.260                           | AFL     | 1412                                | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM 34-50-25               |         |                                     |          |          |                           |           |                         |             |  |
| <b>345218</b>                         |         | <b>NO. 2 ATC TRANSPONDER</b>        |          |          |                           |           | <b>Component ATA:34</b> |             |  |
| PN:622-9210-501                       | MOS/MSC | 19-Jun-23                           | O/C      | TSN 0    |                           |           |                         |             |  |
| SN:3LT1K                              | HRS     | 3746.1                              | TSN 0    |          |                           |           |                         |             |  |
| WC#: 34.260                           | AFL     | 1412                                | TSN 0    |          |                           |           |                         |             |  |
| PROC. REF: AMM 34-50-25               |         |                                     |          |          |                           |           |                         |             |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                  | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|--|---------|--|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 34 - NAVIGATION</b>               |         |  |          |          |                           |           |           |                  |               |
| <b>345229</b>                            |         | <b>SYSTEM TEST NO.1 ATC TRANSPONDER (FAA 91.413)</b> |          |          |                           |           |           | <b>Service</b>   | <b>ATA:34</b> |
| PN:622-9210-501                          | MOS     | 19-Jun-23  | 24       |          | 19-Jun-25                 |           | 325 d     | MANDATORY        |               |
| SN:3LT1W                                 | HRS     |  |          |          |                           |           |           |                  |               |
| WC#: 34.260                              | AFL     |  |          |          |                           |           |           |                  |               |
| PROC. REF: AMM 34-50-25, FAR FAR PART 91 |         |  |          |          |                           |           |           |                  |               |
| <b>345230</b>                            |         | <b>SYSTEM TEST NO.2 ATC TRANSPONDER (FAA 91.413)</b> |          |          |                           |           |           | <b>Service</b>   | <b>ATA:34</b> |
| PN:622-9210-501                          | MOS     | 19-Jun-23  | 24       |          | 19-Jun-25                 |           | 325 d     | MANDATORY        |               |
| SN:3LT1K                                 | HRS     |  |          |          |                           |           |           |                  |               |
| WC#: 34.260                              | AFL     |  |          |          |                           |           |           |                  |               |
| PROC. REF: AMM 34-50-25, FAR FAR PART 91 |         |  |          |          |                           |           |           |                  |               |
| <b>345305</b>                            |         | <b>MACH TRIM COMPUTER</b>                            |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:PN                                    | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                               | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.270                              | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM NO REF                    |         |  |          |          |                           |           |           |                  |               |
| <b>345309</b>                            |         | <b>AFIS DMU</b>                                      |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:PN                                    | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                               | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.470                              | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM NO REF                    |         |  |          |          |                           |           |           |                  |               |
| <b>345310</b>                            |         | <b>AFIS CONFIGURATION MODULE</b>                     |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:PN                                    | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:UNKNOWN                               | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.475                              | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM NO REF                    |         |  |          |          |                           |           |           |                  |               |
| <b>345404</b>                            |         | <b>NO. 1 GPS SENSOR UNIT</b>                         |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-2189-002                          | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:3LNWD                                 | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.275                              | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 34-50-45, AMM 34-50-45    |         |  |          |          |                           |           |           |                  |               |
| <b>345405</b>                            |         | <b>NO. 2 GPS SENSOR UNIT</b>                         |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-2189-002                          | MOS/MSC | 16-Mar-10  | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:3LNWY                                 | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.275                              | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 34-50-45, AMM 34-50-45    |         |  |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit    | C/W  | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |               |
|---------------------------------------|---------|--|----------|----------|---------------------------|-----------|-----------|------------------|---------------|
| <b>ATA 34 - NAVIGATION</b>            |         |  |          |          |                           |           |           |                  |               |
| <b>345406</b>                         |         | <b>NO. 1 GPS ANTENNA</b>                       |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:C1429-200                          | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:307625                             | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.280                           | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 34-50-45, AMM 34-50-45 |         |  |          |          |                           |           |           |                  |               |
| <b>345407</b>                         |         | <b>NO. 2 GPS ANTENNA</b>                       |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:C1429-410                          | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:307967                             | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.280                           | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM 34-50-45, AMM 34-50-45 |         |  |          |          |                           |           |           |                  |               |
| <b>345413</b>                         |         | <b>NO. 1 CONFIGURATION STRAPPING UNIT</b>      |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1363-002                       | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:3J4LT                              | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.285                           | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM NO REF                 |         |  |          |          |                           |           |           |                  |               |
| <b>345414</b>                         |         | <b>NO. 2 CONFIGURATION STRAPPING UNIT</b>      |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1363-002                       | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:3J4LV                              | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.285                           | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM NO REF                 |         |  |          |          |                           |           |           |                  |               |
| <b>345513</b>                         |         | <b>NO. 1 (AHRS) EXTERNAL COMPENSATION UNIT</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1200-002                       | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:3PFVD                              | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.480                           | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM NO REF                 |         |  |          |          |                           |           |           |                  |               |
| <b>345514</b>                         |         | <b>NO. 2 (AHRS) EXTERNAL COMPENSATION UNIT</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1200-002                       | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:3PFVR                              | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.480                           | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM NO REF                 |         |  |          |          |                           |           |           |                  |               |
| <b>345515</b>                         |         | <b>NO. 1 (IFIS) EXTERNAL COMPENSATION UNIT</b> |          |          |                           |           |           | <b>Component</b> | <b>ATA:34</b> |
| PN:822-1200-998                       | MOS/MSC | 16-Mar-10                                      | O/C      | TSN 0    |                           |           |           |                  |               |
| SN:3PFFB                              | HRS     | 0  |          | TSN 0    |                           |           |           |                  |               |
| WC#: 34.555                           | AFL     | 0  |          | TSN 0    |                           |           |           |                  |               |
| PROC. REF: AMM NO REF                 |         |  |          |          |                           |           |           |                  |               |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                    | Unit   | C/W       | Interval | TSX/Adj.      | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|----------------------------|--|-----------|----------|---------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 34 - NAVIGATION</b> |  |           |          |               |                           |           |           |             |        |
| 346810                     | OBSERVERS AMPLIFIER  |           |          |               |                           |           |           | Component   | ATA:34 |
| PN:DB204                   | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0         |                           |           |           |             |        |
| SN:58076                   | HRS  | 0         |          | TSN 0         |                           |           |           |             |        |
| WC#: 34.601                | AFL  | 0         |          | TSN 0         |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF  |  |           |          |               |                           |           |           |             |        |
| 348001                     | ACSS TAWS COMPUTER   |           |          |               |                           |           |           | Component   | ATA:34 |
| PN:9000000-86008           | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0         |                           |           |           |             |        |
| SN:TWE00465                | HRS  | 0         |          | TSN 0         |                           |           |           |             |        |
| WC#: 34.604                | AFL  | 0         |          | TSN 0         |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF  |  |           |          |               |                           |           |           |             |        |
| 348002                     | AP-950 CONFIGURATION MODULE  |           |          |               |                           |           |           | Component   | ATA:34 |
| PN:9000001-10001           | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0         |                           |           |           |             |        |
| SN:APE01166                | HRS  | 0         |          | TSN 0         |                           |           |           |             |        |
| WC#: 34.605                | AFL  | 0         |          | TSN 0         |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF  |  |           |          |               |                           |           |           |             |        |
| 349001 <sup>U</sup>        | NAVIGATION DATA BASE UPDATE  |           |          |               |                           |           |           | Service     | ATA:34 |
|                            | DAYS/MSC   | 11-Jul-24 | DUE      | 07-Aug-24 (M) |                           |           | 9 d       |             |        |
|                            | HRS  | 3907.4    |          |               |                           |           |           |             |        |
|                            | AFL  | 1491      |          |               |                           |           |           |             |        |
| 349101                     | PASSENGER SPEAKER AMPLIFIER  |           |          |               |                           |           |           | Component   | ATA:34 |
| PN:MODEL 240               | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0         |                           |           |           |             |        |
| SN:56070                   | HRS  | 0         |          | TSN 0         |                           |           |           |             |        |
| WC#: 34.606                | AFL  | 0         |          | TSN 0         |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF  |  |           |          |               |                           |           |           |             |        |
| 349998                     | ADJUSTMENT/TEST COLLINS AIR DATA SYSTEM (FOR RVSM CAPABLE AIRPLANES )          |           |          |               |                           |           |           | Service     | ATA:34 |
|                            | MOS/MSC  | 06-Apr-10 | O/C      |               |                           |           |           |             |        |
|                            | HRS  |           |          |               |                           |           |           |             |        |
| WC#: 34.T04                | AFL  |           |          |               |                           |           |           |             |        |
| PROC. REF: AMM 34-10-19    |  |           |          |               |                           |           |           |             |        |
| 349999                     | ADJUSTMENT/TEST HONEYWELL ADZ-810 AIR DATA SYSTEM (FOR RVSM CAPABLE AIRPLANES) |           |          |               |                           |           |           | Service     | ATA:34 |
|                            | MOS/MSC  | 16-Mar-10 | O/C      |               |                           |           |           |             |        |
|                            | HRS  | 0         |          |               |                           |           |           |             |        |
| WC#: 34.T05                | AFL  | 0         |          |               |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                | Unit   | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C                           | Max Limit | Remaining | Disposition |        |
|------------------------|--|-----------|-----------------|----------|---|-----------|-----------|-------------|--------|
| <b>ATA 35 - OXYGEN</b> |  |           |                 |          |   |           |           |             |        |
| 350001 <sup>S</sup>    | CHECK OXYGEN SYSTEM MASTER SUPPLY VALVE                  |           |                 |          |   |           |           | Service     | ATA:35 |
|                        | MOS  | 03-Aug-21 |                 |          |   |           |           |             |        |
|                        | HRS  | 3405      | 800 (+40/-10)   |          |   |           |           |             |        |
| WC#: 35.110            | AFL  | 1243      |                 |          |   |           |           | PKG:10,91   |        |
| 350002 <sup>S</sup>    | FUNCTIONAL TEST AUTOMATIC SHUT-OFF VALVE                 |           |                 |          |   |           |           | Service     | ATA:35 |
|                        | MOS  | 06-Jun-18 |                 |          |   |           |           |             |        |
|                        | HRS  | 2965.25   | 3200 (+150/-50) |          |   |           |           |             |        |
| WC#: 35.035            | AFL  | 1073      |                 |          |   |           |           | PKG:32,93   |        |
|                        |  |           |                 |          | PROC. REF: AMM 35-10-141                            |           |           |             |        |
| 350004 <sup>S</sup>    | TEST/INSPECT PASSENGER OXYGEN SYSTEM                     |           |                 |          |   |           |           | Service     | ATA:35 |
|                        | MOS  | 25-Jul-24 | 12 (+1m/-1m)    |          |   |           |           |             |        |
|                        | HRS  | 3908.4    |                 |          |   |           |           |             |        |
| WC#: 35.075            | AFL  | 1492      |                 |          |   |           |           | PKG:44,94   |        |
|                        |  |           |                 |          | PROC. REF: MMA 35-06-00, MMA 35-20-05, AMM 35-06-00 |           |           |             |        |
| 350005 <sup>S</sup>    | CHECK BAROMATIC CONTROL VALVE                            |           |                 |          |   |           |           | Service     | ATA:35 |
|                        | MOS  | 25-Jul-24 | 12 (+1m/-1m)    |          |   |           |           |             |        |
|                        | HRS  | 3908.4    |                 |          |   |           |           |             |        |
| WC#: 35.100            | AFL  | 1492      |                 |          |   |           |           | PKG:44,94   |        |
| 350006 <sup>S</sup>    | INSPECT CREW MASKS, SMOKE SET MASK (IF FITTED) AND HOSES |           |                 |          |   |           |           | Service     | ATA:35 |
|                        | MOS  | 25-Jul-24 | 12 (+1m/-1m)    |          |   |           |           |             |        |
|                        | HRS  | 3908.4    |                 |          |   |           |           |             |        |
| WC#: 35.115            | AFL  | 1492      |                 |          |   |           |           | PKG:46,94   |        |
| 350007 <sup>S</sup>    | INSPECT PORTABLE BREATHING EQUIPMENT                     |           |                 |          |   |           |           | Service     | ATA:35 |
|                        | MOS  | 25-Jul-24 | 12 (+1m/-1m)    |          |   |           |           |             |        |
|                        | HRS  | 3908.4    |                 |          |   |           |           |             |        |
| WC#: 35.120            | AFL  | 1492      |                 |          |   |           |           | PKG:46,94   |        |
| 350008 <sup>S</sup>    | INSPECT OXYGEN CYLINDERS                                 |           |                 |          |   |           |           | Service     | ATA:35 |
|                        | MOS  | 06-Jun-18 |                 |          |   |           |           |             |        |
|                        | HRS  | 2965.25   | 1600 (+50/-50)  |          |   |           |           |             |        |
| WC#: 35.105            | AFL  | 1073      |                 |          |   |           |           | PKG:25,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit                              | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|-----------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 35 - OXYGEN</b>    |                                   |           |          |          |                           |           |           |             |        |
| 351001                    | MASTER OXYGEN SUPPLY VALVE        |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                     | MOS/MSC                           | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.030               | AFL                               | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 35-10-62   |                                   |           |          |          |                           |           |           |             |        |
| 351013                    | OXYGEN PRESSURE GAUGE             |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                     | MOS/MSC                           | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS                               | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.040               | AFL                               | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 35-10-32   |                                   |           |          |          |                           |           |           |             |        |
| 351014                    | ALTERNATIVE OXYGEN PRESSURE GAUGE |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:18430901-1             | MOS/MSC                           | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:58122                  | HRS                               | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.040               | AFL                               | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 35-10-33   |                                   |           |          |          |                           |           |           |             |        |
| 351015                    | OXYGEN CHARGING FILTER ASSEMBLY   |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:WKA27942-2             | MOS/MSC                           | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:2028                   | HRS                               | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.215               | AFL                               | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |                                   |           |          |          |                           |           |           |             |        |
| 351025                    | OXYGEN REDUCING VALVE             |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:WKA29720/2             | MOS/MSC                           | 29-Dec-22 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:2176                   | HRS                               | 3646.3    |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.045               | AFL                               | 1366      |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |                                   |           |          |          |                           |           |           |             |        |
| 351031                    | PILOT OXYGEN MASK                 |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:MF10-03-02             | MOS                               | 22-Feb-21 | 72       | TSO 7    | 22-Jul-26                 |           | 723 d     | OVERHAUL    |        |
| SN:116657                 | HRS                               | 3396.83   |          | TSO 0    |                           |           |           |             |        |
| WC#: 35.050               | AFL                               | 1239      |          | TSO 0    |                           |           |           |             |        |
| 351032                    | COPILOT OXYGEN MASK               |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:MF10-03-02             | MOS                               | 22-Feb-21 | 72       | TSO 7    | 22-Jul-26                 |           | 723 d     | OVERHAUL    |        |
| SN:110383                 | HRS                               | 3396.83   |          | TSO 0    |                           |           |           |             |        |
| WC#: 35.050               | AFL                               | 1239      |          | TSO 0    |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit                        | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---|-----------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 35 - OXYGEN</b>                              |                             |           |          |          |                           |           |           |             |        |
| 351043  | LEFT OXYGEN OUTLET VALVE    |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN   | MOS/MSC                     | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                         | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.055   | AFL                         | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                           |                             |           |          |          |                           |           |           |             |        |
| 351044  | RIGHT OXYGEN OUTLET VALVE   |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN   | MOS/MSC                     | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                         | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.055   | AFL                         | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                           |                             |           |          |          |                           |           |           |             |        |
| 351050  | CREW CABINET OXYGEN MASK    |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:174290-21  | MOS                         | 12-Feb-24 | 96       |          | 08-Feb-32                 |           | 2750 d    |             |        |
| SN:N/A  | HRS                         | 3881.4    |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.145   | AFL                         | 1476      |          | TSN 0    |                           |           |           |             |        |
| Manufacture Date:: 08-Feb-24 PROC. REF: GENERIC CMM |                             |           |          |          |                           |           |           |             |        |
| 351051  | NO. 1 PASSENGER OXYGEN MASK |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN   | MOS/MSC                     | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                         | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.150   | AFL                         | 1157      |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM                              |                             |           |          |          |                           |           |           |             |        |
| 351052  | NO. 2 PASSENGER OXYGEN MASK |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN   | MOS/MSC                     | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                         | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.150   | AFL                         | 1157      |          |          |                           |           |           |             |        |
| 351053  | NO. 3 PASSENGER OXYGEN MASK |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN   | MOS/MSC                     | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                         | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.155   | AFL                         | 1157      |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM                              |                             |           |          |          |                           |           |           |             |        |
| 351054  | NO. 4 PASSENGER OXYGEN MASK |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN   | MOS/MSC                     | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                         | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.155   | AFL                         | 1157      |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                | Unit                         | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|------------------------|------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 35 - OXYGEN</b> |                              |           |          |          |                           |           |           |             |        |
| 351055                 | NO. 5 PASSENGER OXYGEN MASK  |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                  | MOS/MSC                      | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN             | HRS                          | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.160            | AFL                          | 1157      |          |          |                           |           |           |             |        |
| 351056                 | NO. 6 PASSENGER OXYGEN MASK  |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                  | MOS/MSC                      | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN             | HRS                          | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.160            | AFL                          | 1157      |          |          |                           |           |           |             |        |
| 351057                 | NO. 7 PASSENGER OXYGEN MASK  |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                  | MOS/MSC                      | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN             | HRS                          | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.170            | AFL                          | 1157      |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM |                              |           |          |          |                           |           |           |             |        |
| 351058                 | NO. 8 PASSENGER OXYGEN MASK  |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                  | MOS/MSC                      | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN             | HRS                          | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.170            | AFL                          | 1157      |          |          |                           |           |           |             |        |
| 351059                 | NO. 9 PASSENGER OXYGEN MASK  |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                  | MOS/MSC                      | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN             | HRS                          | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.180            | AFL                          | 1157      |          |          |                           |           |           |             |        |
| 351060                 | NO. 10 PASSENGER OXYGEN MASK |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                  | MOS/MSC                      | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN             | HRS                          | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.180            | AFL                          | 1157      |          |          |                           |           |           |             |        |
| 351061                 | NO. 11 PASSENGER OXYGEN MASK |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                  | MOS/MSC                      | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN             | HRS                          | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.190            | AFL                          | 1157      |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM |                              |           |          |          |                           |           |           |             |        |
| 351062                 | NO. 12 PASSENGER OXYGEN MASK |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:PN                  | MOS/MSC                      | 04-Apr-19 | A/R      |          |                           |           |           |             |        |
| SN:UNKNOWN             | HRS                          | 3175.17   |          |          |                           |           |           |             |        |
| WC#: 35.190            | AFL                          | 1157      |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit  | C/W       | Interval | TSX/Adj.   | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|---|-----------|----------|------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 35 - OXYGEN</b>    |   |           |          |            |                           |           |           |             |        |
| 351074 <sup>U</sup>       | INSPECT THERAPEUTIC OXYGEN MASK THERAPEUTIC OXYGEN MASK |           |          |            |                           |           |           | Service     | ATA:35 |
| PN:174290-41              | MOS   | 23-Jun-23 | 12       |            | 23-Jun-24                 |           | OVD       |             |        |
| SN:LOT 1729               | HRS   | 3746.1    |          |            |                           |           |           |             |        |
|                           | AFL   | 1412      |          |            |                           |           |           |             |        |
| 351075 <sup>U</sup>       | THERAPEUTIC OXYGEN MASK                                 |           |          |            |                           |           |           | Component   | ATA:35 |
| PN:174290-41              | MOS   | 23-Jun-23 | 96       | TSN 70     | 23-Aug-25                 |           | 390 d     |             |        |
| SN:LOT 1729               | HRS   | 3746.1    |          | TSN 892.28 |                           |           |           |             |        |
|                           | AFL   | 1412      |          | TSN 381    |                           |           |           |             |        |
| 351080                    | NO. 1 MASK DEPLOYMENT CONTAINER                         |           |          |            |                           |           |           | Component   | ATA:35 |
| PN:833-649-01             | MOS/MSC   | 05-May-10 | O/C      | TSN 0      |                           |           |           |             |        |
| SN:D09010272              | HRS   | 4.7       |          | TSN 0      |                           |           |           |             |        |
| WC#: 35.195               | AFL   | 4         |          | TSN 0      |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |            |                           |           |           |             |        |
| 351081                    | NO. 2 MASK DEPLOYMENT CONTAINER                         |           |          |            |                           |           |           | Component   | ATA:35 |
| PN:833-648-01             | MOS/MSC   | 05-May-10 | O/C      | TSN 0      |                           |           |           |             |        |
| SN:D09010285              | HRS   | 4.7       |          | TSN 0      |                           |           |           |             |        |
| WC#: 35.195               | AFL   | 4         |          | TSN 0      |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |            |                           |           |           |             |        |
| 351082                    | NO. 3 MASK DEPLOYMENT CONTAINER                         |           |          |            |                           |           |           | Component   | ATA:35 |
| PN:833-648-01             | MOS/MSC   | 05-May-10 | O/C      | TSN 0      |                           |           |           |             |        |
| SN:D09010293              | HRS   | 4.7       |          | TSN 0      |                           |           |           |             |        |
| WC#: 35.200               | AFL   | 4         |          | TSN 0      |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |            |                           |           |           |             |        |
| 351083                    | NO. 4 MASK DEPLOYMENT CONTAINER                         |           |          |            |                           |           |           | Component   | ATA:35 |
| PN:833-648-01             | MOS/MSC   | 05-May-10 | O/C      | TSN 0      |                           |           |           |             |        |
| SN:D09010295              | HRS   | 4.7       |          | TSN 0      |                           |           |           |             |        |
| WC#: 35.200               | AFL   | 4         |          | TSN 0      |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |            |                           |           |           |             |        |
| 351084                    | NO. 5 MASK DEPLOYMENT CONTAINER                         |           |          |            |                           |           |           | Component   | ATA:35 |
| PN:833-648-01             | MOS/MSC   | 05-May-10 | O/C      | TSN 0      |                           |           |           |             |        |
| SN:D09010299              | HRS   | 4.7       |          | TSN 0      |                           |           |           |             |        |
| WC#: 35.205               | AFL   | 4         |          | TSN 0      |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |            |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit                            | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 35 - OXYGEN</b>                |                                 |           |          |          |                           |           |           |             |        |
| 351085                                | NO. 6 MASK DEPLOYMENT CONTAINER |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:833-648-01                         | MOS/MSC                         | 05-May-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:D09010300                          | HRS                             | 4.7       |          |          | TSN 0                     |           |           |             |        |
| WC#: 35.205                           | AFL                             | 4         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                 |           |          |          |                           |           |           |             |        |
| 351086                                | NO. 7 MASK DEPLOYMENT CONTAINER |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:833-648-01                         | MOS/MSC                         | 05-May-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:D09010346                          | HRS                             | 4.7       |          |          | TSN 0                     |           |           |             |        |
| WC#: 35.210                           | AFL                             | 4         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                 |           |          |          |                           |           |           |             |        |
| 351093                                | OXYGEN PRESSURE SWITCH          |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:1106P76-1                          | MOS/MSC                         | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:1376                               | HRS                             | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 35.125                           | AFL                             | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF             |                                 |           |          |          |                           |           |           |             |        |
| 351101                                | NO. 1 OXYGEN CYLINDER           |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:WKA37447                           | MOS/MSC                         | 02-Mar-23 | O/C      |          | TSO 0                     |           |           |             |        |
| SN:735957/1151                        | HRS                             | 3695.3    |          |          | TSO 0                     |           |           |             |        |
| WC#: 35.010                           | AFL                             | 1390      |          |          | TSO 0                     |           |           |             |        |
| PROC. REF: AMM 35-10-14               |                                 |           |          |          |                           |           |           |             |        |
| 351102                                | NO. 2 OXYGEN CYLINDER           |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:WKA37447                           | MOS/MSC                         | 02-Mar-23 | O/C      |          | TSO 0                     |           |           |             |        |
| SN:721392/1268                        | HRS                             | 3695.3    |          |          | TSO 0                     |           |           |             |        |
| WC#: 35.015                           | AFL                             | 1390      |          |          | TSO 0                     |           |           |             |        |
| PROC. REF: AMM 35-10-14               |                                 |           |          |          |                           |           |           |             |        |
| 351103                                | NO. 3 OXYGEN CYLINDER           |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:WKA37447                           | MOS/MSC                         | 18-Mar-23 | O/C      |          |                           |           |           |             |        |
| SN:075723                             | HRS                             | 3710.7    |          |          |                           |           |           |             |        |
| WC#: 35.020                           | AFL                             | 1397      |          |          |                           |           |           |             |        |
| PROC. REF: MMA 35-06-01, AMM 35-10-14 |                                 |           |          |          |                           |           |           |             |        |
| 351104                                | NO. 4 OXYGEN CYLINDER           |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:WKA37447                           | MOS/MSC                         | 18-Mar-23 | O/C      |          |                           |           |           |             |        |
| SN:14534X                             | HRS                             | 3710.7    |          |          |                           |           |           |             |        |
| WC#: 35.025                           | AFL                             | 1397      |          |          |                           |           |           |             |        |
| PROC. REF: MMA 35-06-01               |                                 |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit                                   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 35 - OXYGEN</b>    |  |           |          |          |                           |           |           |             |        |
| 351110                    | HYDROSTATIC TEST NO. 1 OXYGEN CYLINDER |           |          |          |                           |           |           | Service     | ATA:35 |
| PN:WKA37447               | MOS                                    | 24-Jan-23 | 60       |          | 24-Jan-28                 |           | 1274 d    |             |        |
| SN:735957/1151            | HRS                                    |           |          |          |                           |           |           |             |        |
| WC#: 35.010               | AFL                                    |           |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM    |  |           |          |          |                           |           |           |             |        |
| 351110                    | HYDROSTATIC TEST NO. 2 OXYGEN CYLINDER |           |          |          |                           |           |           | Service     | ATA:35 |
| PN:WKA37447               | MOS                                    | 24-Jan-23 | 60       |          | 24-Jan-28                 |           | 1274 d    |             |        |
| SN:721392/1268            | HRS                                    |           |          |          |                           |           |           |             |        |
| WC#: 35.015               | AFL                                    |           |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM    |  |           |          |          |                           |           |           |             |        |
| 351110                    | HYDROSTATIC TEST NO. 3 OXYGEN CYLINDER |           |          |          |                           |           |           | Service     | ATA:35 |
| PN:WKA37447               | MOS                                    | 14-Mar-23 | 60       |          | 14-Mar-28                 |           | 1324 d    |             |        |
| SN:075723                 | HRS                                    |           |          |          |                           |           |           |             |        |
| WC#: 35.020               | AFL                                    |           |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM    |  |           |          |          |                           |           |           |             |        |
| 351110                    | HYDROSTATIC TEST NO. 4 OXYGEN CYLINDER |           |          |          |                           |           |           | Service     | ATA:35 |
| PN:WKA37447               | MOS                                    | 14-Mar-23 | 60       |          | 31-Mar-28 (M)             |           | 1341 d    |             |        |
| SN:14534X                 | HRS                                    |           |          |          |                           |           |           |             |        |
| WC#: 35.025               | AFL                                    |           |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM    |  |           |          |          |                           |           |           |             |        |
| 352001                    | ON/OFF OXYGEN VALVE                    |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:SDV1012                | MOS/MSC                                | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:16466                  | HRS                                    | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.065               | AFL                                    | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 352007                    | BAROMATIC VALVE                        |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:K39117/3               | MOS/MSC                                | 20-Jun-22 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:245                    | HRS                                    | 3511.6    |          | TSN 0    |                           |           |           |             |        |
| WC#: 35.070               | AFL                                    | 1288      |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 35-20-42   |  |           |          |          |                           |           |           |             |        |
| 353001                    | PORTABLE OXYGEN BOTTLE                 |           |          |          |                           |           |           | Component   | ATA:35 |
| PN:176960-14              | MOS/MSC                                | 31-Dec-19 | O/C      | TSO 0    |                           |           |           |             |        |
| SN:560353704              | HRS                                    | 3327.28   |          | TSO 0    |                           |           |           |             |        |
| WC#: 35.080               | AFL                                    | 1211      |          | TSO 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit                                    | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|--|---|-----------|---------------|----------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 35 - OXYGEN</b>                                   |   |           |               |          |                           |           |             |             |        |
| 353007   | HYDROSTATIC TEST PORTABLE OXYGEN BOTTLE |           |               |          |                           |           |             | Service     | ATA:35 |
| PN:176960-14   | MOS                                     | 27-Nov-19 | 60            |          | 27-Nov-24                 |           | 121 d       | MANDATORY   |        |
| SN:560353704   | HRS                                     |           |               |          |                           |           |             |             |        |
| WC#: 35.080  | AFL                                     |           |               |          |                           |           |             |             |        |
| PROC. REF: GENERIC NO REF                                |   |           |               |          |                           |           |             |             |        |
| 353031   | (PBE) PROTECTIVE BREATHING EQUIPMENT    |           |               |          |                           |           |             | Component   | ATA:35 |
| PN:802300-14   | MOS                                     | 04-Apr-19 | 120           | TSN 3    | 14-Jan-29                 |           | 1630 d      | LIFE LIMIT  |        |
| SN:E18090369   | HRS                                     | 3175.17   |               | TSN 0    |                           |           |             |             |        |
| WC#: 35.085  | AFL                                     | 1157      |               | TSN 0    |                           |           |             |             |        |
| Manufacture Date:: 14-Jan-19 PROC. REF: GENERIC NO REF   |   |           |               |          |                           |           |             |             |        |
| 354000   | AUTOMATIC SHUT OFF VALVE                |           |               |          |                           |           |             | Component   | ATA:35 |
| PN:WKA35964-1  | MOS/MSC                                 | 09-Jan-23 | O/C           | TSO 0    |                           |           |             |             |        |
| SN:1935  | HRS                                     | 3646.3    |               | TSO 0    |                           |           |             |             |        |
| WC#: 35.130  | AFL                                     | 1366      |               | TSO 0    |                           |           |             |             |        |
| PROC. REF: AMM 35-10-141                                 |   |           |               |          |                           |           |             |             |        |
| <b>ATA 38 - WATER/WASTE</b>                              |   |           |               |          |                           |           |             |             |        |
| 380001 <sup>S</sup>                                      | INSPECT TOILET AND GALLEY WATER SYSTEMS |           |               |          |                           |           |             | Service     | ATA:38 |
|  | MOS                                     | 03-Aug-21 |               |          |                           |           |             |             |        |
|  | HRS                                     | 3405      | 800 (+40/-10) |          |                           |           |             |             |        |
| WC#: 38.010  | AFL                                     | 1243      |               |          |                           |           |             |             |        |
| PROC. REF: AMM 12-20-25                                  |   |           |               |          |                           |           |             |             |        |
| 381090   | CLEAN GALLEY WATER SYSTEM               |           |               |          |                           |           |             | Service     | ATA:38 |
|  | MOS/MSC                                 | 20-Jun-22 | A/R           |          |                           |           |             |             |        |
|  | HRS                                     | 3511.6    |               |          |                           |           |             |             |        |
| WC#: 38.020  | AFL                                     | 1288      |               |          |                           |           |             |             |        |
| Special Properties: TRACKED ITEM PROC. REF: MMA 38-10-00 |   |           |               |          |                           |           |             |             |        |
| 381091   | CLEAN LAVATORY WATER SYSTEM             |           |               |          |                           |           |             | Service     | ATA:38 |
|  | MOS/MSC                                 | 20-Jun-22 | A/R           |          |                           |           |             |             |        |
|  | HRS                                     | 3511.6    |               |          |                           |           |             |             |        |
| WC#: 38.030  | AFL                                     | 1288      |               |          |                           |           |             |             |        |
| PROC. REF: MMA 38-20-05                                  |   |           |               |          |                           |           |             |             |        |
| <b>ATA 49 - AIRBORNE AUXILIARY POWER</b>                 |   |           |               |          |                           |           |             |             |        |
| 490001   | INSPECT PATS APU GTCP36-150W            |           |               |          |                           |           |             | Service     | ATA:49 |
|  | MOS                                     | 13-Mar-24 | 12 (+1m)      |          | 13-Mar-25                 | 13-Apr-25 | 227 d (+31) |             |        |
|  | HRS                                     | 3890.9    |               |          |                           |           |             |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                           | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |                |
|-----------------------------------|--|-----------|----------|----------|---------------------------|-----------|-------------|-------------|----------------|
| ATA 49 - AIRBORNE AUXILIARY POWER |  |           |          |          |                           |           |             |             |                |
| WC#: 49.205                       | AFL  | 1481      |          |          |                           |           |             |             |                |
|                                   | APH  | 3741      | 750      |          | 4491                      |           | 745         |             |                |
| 490002                            | REMOVE/CLEAN/INSPECT APU IGNITER PLUG  |           |          |          |                           |           |             |             | Service ATA:49 |
|                                   | MOS  | 12-Feb-24 |          |          |                           |           |             |             |                |
|                                   | HRS  | 3881.4    |          |          |                           |           |             |             |                |
| WC#: 49.210                       | AFL  | 1476      |          |          |                           |           |             |             |                |
|                                   | APH  | 3719      | 750      |          | 4469                      |           | 723         |             |                |
| 490003                            | ACCOMPLISH APU (OPTION 1) OIL AND FILTER CHANGE AND MAGNETIC DRAIN PLUG INSPECTION |           |          |          |                           |           |             |             | Service ATA:49 |
|                                   | MOS/MS   | 19-Mar-13 | N/R      |          |                           |           |             |             |                |
|                                   | HRS  | 1320.78   |          |          |                           |           |             |             |                |
| WC#: 49.220                       | AFL  | 481       |          |          |                           |           |             |             |                |
| 490003                            | ACCOMPLISH APU (OPTION 2) S.O.A.P CHECK  |           |          |          |                           |           |             |             | Service ATA:49 |
|                                   | MOS  | 13-Mar-24 | 12 (+1m) |          | 13-Mar-25                 | 13-Apr-25 | 227 d (+31) |             |                |
|                                   | HRS  | 3890.9    |          |          |                           |           |             |             |                |
| WC#: 49.221                       | AFL  | 1481      |          |          |                           |           |             |             |                |
|                                   | APH  | 3741      | 750      |          | 4491                      |           | 745         |             |                |
| 490004                            | REMOVE AND REPLACE APU FUEL FILTER ELEMENT   |           |          |          |                           |           |             |             | Service ATA:49 |
|                                   | MOS  | 12-Feb-24 |          |          |                           |           |             |             |                |
|                                   | HRS  | 3881.4    |          |          |                           |           |             |             |                |
| WC#: 49.230                       | AFL  | 1476      |          |          |                           |           |             |             |                |
|                                   | APH  | 3719      | 1000     |          | 4719                      |           | 973         |             |                |
| 490005                            | FLOW CHECK APU FUEL NOZZLE ASSEMBLIES  |           |          |          |                           |           |             |             | Service ATA:49 |
|                                   | MOS  | 05-May-10 |          |          |                           |           |             |             |                |
|                                   | HRS  | 0         |          |          |                           |           |             |             |                |
| WC#: 49.240                       | AFL  | 0         |          |          |                           |           |             |             |                |
|                                   | APH  | 0         | 4500     |          | 4500                      |           | 754         |             |                |
| 490006                            | ACCOMPLISH APU DETAILED HOT SECTION INSPECTION                                     |           |          |          |                           |           |             |             | Service ATA:49 |
|                                   | MOS  | 05-May-10 |          |          |                           |           |             |             |                |
|                                   | HRS  | 0         |          |          |                           |           |             |             |                |
| WC#: 49.250                       | AFL  | 0         |          |          |                           |           |             |             |                |
|                                   | APH  | 0         | 4500     |          | 4500                      |           | 754         |             |                |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                           | Unit                                | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-----------------------------------|-------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 49 - AIRBORNE AUXILIARY POWER |                                     |           |          |          |                           |           |           |             |        |
| 490007                            | VISUALLY CHECK APU COMPRESSOR ROTOR |           |          |          |                           |           |           | Service     | ATA:49 |
|                                   | MOS                                 | 05-May-10 |          |          |                           |           |           |             |        |
|                                   | HRS                                 | 0         |          |          |                           |           |           |             |        |
| WC#: 49.260                       | AFL                                 | 0         |          |          |                           |           |           |             |        |
|                                   | APH                                 | 0         | 4500     |          | 4500                      |           | 754       |             |        |
| 491010                            | APU - TURBINE ROTOR                 |           |          |          |                           |           |           | Component   | ATA:49 |
| PN:3615880-1                      | MOS                                 | 26-May-09 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:09-156101-01026                | HRS                                 | 0         | 10000    | TSN 0    | 10000                     |           | 6236      |             |        |
| WC#: 49.010                       | APUS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF         |                                     |           |          |          |                           |           |           |             |        |
| 491020                            | APU - COMPRESSOR ROTOR              |           |          |          |                           |           |           | Component   | ATA:49 |
| PN:3822101-1                      | MOS                                 | 26-May-09 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:08-13651-04471                 | HRS                                 | 0         | 100000   | TSN 0    | 100000                    |           | 96236     |             |        |
| WC#: 49.015                       | APUS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF         |                                     |           |          |          |                           |           |           |             |        |
| 491025 <sup>S</sup>               | APU - INSPECT COMPRESSOR ROTOR      |           |          |          |                           |           |           | Service     | ATA:49 |
| PN:3822101-1                      | MOS                                 | 26-May-09 |          |          |                           |           |           |             |        |
| SN:08-13651-04471                 | HRS                                 | 0         | 4500     |          |                           |           |           |             |        |
| WC#: 49.020                       | APUS                                | 0         |          |          |                           |           |           |             |        |
| PROC. REF: MM 49-20-00            |                                     |           |          |          |                           |           |           |             |        |
| 491030 <sup>S</sup>               | APU - INSPECT HOT SECTION           |           |          |          |                           |           |           | Service     | ATA:49 |
|                                   | MOS                                 | 26-May-09 |          |          |                           |           |           |             |        |
|                                   | HRS                                 | 0         | 4500     |          |                           |           |           |             |        |
| WC#: 49.025                       | APUS                                | 0         |          |          |                           |           |           |             |        |
| PROC. REF: MM 49-20-00            |                                     |           |          |          |                           |           |           |             |        |
| 491035                            | APU - FLOW CONTROL VALVE            |           |          |          |                           |           |           | Component   | ATA:49 |
| PN:PN                             | MOS/MSC                             | 26-May-09 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                        | HRS                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 49.135                       | APUS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF         |                                     |           |          |          |                           |           |           |             |        |
| 491038                            | APU - FIRE LOOP DETECTOR            |           |          |          |                           |           |           | Component   | ATA:49 |
| PN:PN                             | MOS/MSC                             | 26-May-09 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                        | HRS                                 | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 49.140                       | APUS                                | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF         |                                     |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                  | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|--|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 49 - AIRBORNE AUXILIARY POWER</b> |  |           |          |          |                           |           |           |             |        |
| 491042                                   | APU - VOLTAGE REGULATOR                      |           |          |          |                           |           |           | Component   | ATA:49 |
| PN:PN                                    | MOS/MSC                                      | 26-May-09 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                               | HRS  | 0         | TSN 0    |          |                           |           |           |             |        |
| WC#: 49.145                              | APUS   | 0         | TSN 0    |          |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                |  |           |          |          |                           |           |           |             |        |
| 493010                                   | APU - FUEL CONTROL                           |           |          |          |                           |           |           | Component   | ATA:49 |
| PN:3882730-9                             | MOS/MSC                                      | 26-May-09 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:34294                                 | HRS  | 0         | TSN 0    |          |                           |           |           |             |        |
| WC#: 49.030                              | APUS   | 0         | TSN 0    |          |                           |           |           |             |        |
| PROC. REF: MM 49-30-52                   |  |           |          |          |                           |           |           |             |        |
| 493020 <sup>S</sup>                      | APU - REMOVE AND REPLACE FUEL FILTER ELEMENT |           |          |          |                           |           |           | Service     | ATA:49 |
|  | MOS  | 12-Feb-24 |          |          |                           |           |           |             |        |
|  | HRS  | 3738      | 1000     |          |                           |           |           |             |        |
| WC#: 49.035                              | APUS   |           |          |          |                           |           |           |             |        |
| PROC. REF: MM 49-30-52                   |  |           |          |          |                           |           |           |             |        |
| 493030                                   | APU - ORIFICE FITTING                        |           |          |          |                           |           |           | Component   | ATA:49 |
| PN:PN                                    | MOS/MSC                                      | 26-May-09 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                               | HRS  | 0         | TSN 0    |          |                           |           |           |             |        |
| WC#: 49.040                              | APUS   | 0         | TSN 0    |          |                           |           |           |             |        |
| PROC. REF: MM 49-30-56                   |  |           |          |          |                           |           |           |             |        |
| 493040                                   | APU - FUEL SHUTOFF VALVE                     |           |          |          |                           |           |           | Component   | ATA:49 |
| PN:692545-18                             | MOS/MSC                                      | 03-Apr-24 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:T#10344                               | HRS  | 3759      | TSN 0    |          |                           |           |           |             |        |
| WC#: 49.045                              | APUS   | 0         | TSN 0    |          |                           |           |           |             |        |
| PROC. REF: MM 49-30-54                   |  |           |          |          |                           |           |           |             |        |
| 493050 <sup>S</sup>                      | APU - CHECK FUEL NOZZLE FLOW RATE            |           |          |          |                           |           |           | Service     | ATA:49 |
|  | MOS  | 26-May-09 |          |          |                           |           |           |             |        |
|  | HRS  | 0         | 4500     |          |                           |           |           |             |        |
| WC#: 49.050                              | APUS   | 0         |          |          |                           |           |           |             |        |
| PROC. REF: MM 49-20-00                   |  |           |          |          |                           |           |           |             |        |
| 493060                                   | APU - CONTROLLER                             |           |          |          |                           |           |           | Component   | ATA:49 |
| PN:2118330-2                             | MOS/MSC                                      | 11-Jul-24 | O/C      |          |                           |           |           |             |        |
| SN:74-B0617                              | HRS  |           |          |          |                           |           |           |             |        |
| WC#: 49.055                              | APUS   | 0         |          |          |                           |           |           |             |        |
| PROC. REF: MM 49-60-46                   |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition      |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|------------------|
| <b>ATA 49 - AIRBORNE AUXILIARY POWER</b>                        |         |           |          |          |                           |           |           |                  |
| <b>493070 APU - LOAD CONTROL VALVE</b>                          |         |           |          |          |                           |           |           | Component ATA:49 |
| PN:109812-9   | MOS/MSC | 26-May-09 | O/C      | TSN 0    |                           |           |           |                  |
| SN:4921   | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 49.060   | APUS    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-50-33  |         |           |          |          |                           |           |           |                  |
| <b>494010 APU - IGNITION UNIT</b>                               |         |           |          |          |                           |           |           | Component ATA:49 |
| PN:3888000-2  | MOS/MSC | 26-May-09 | O/C      | TSN 0    |                           |           |           |                  |
| SN:090218094338   | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 49.065   | APUS    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-40-32  |         |           |          |          |                           |           |           |                  |
| <b>494020 APU - IGNITER PLUG</b>                                |         |           |          |          |                           |           |           | Component ATA:49 |
| PN:3888002-2  | MOS/MSC | 12-Feb-24 | O/C      | TSN 0    |                           |           |           |                  |
| SN:N/A  | HRS     | 3738      |          | TSN 0    |                           |           |           |                  |
| WC#: 49.070   | APUS    |           |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-40-33  |         |           |          |          |                           |           |           |                  |
| <b>494025 APU - IGNITER PLUG LEAD</b>                           |         |           |          |          |                           |           |           | Component ATA:49 |
| PN:PN   | MOS/MSC | 26-May-09 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 49.150   | APUS    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-40-33  |         |           |          |          |                           |           |           |                  |
| <b>494030<sup>S</sup> APU - REMOVE AND INSPECT IGNITER PLUG</b> |         |           |          |          |                           |           |           | Service ATA:49   |
| PN:3888002-2  | MOS     | 12-Feb-24 |          |          |                           |           |           |                  |
| SN:N/A  | HRS     | 3738      | 750      |          |                           |           |           |                  |
| WC#: 49.075   | APUS    |           |          |          |                           |           |           |                  |
| PROC. REF: MM 49-40-33  |         |           |          |          |                           |           |           |                  |
| <b>497010 APU - MOTION PICK UP TRANSDUCER</b>                   |         |           |          |          |                           |           |           | Component ATA:49 |
| PN:PN   | MOS/MSC | 26-May-09 | O/C      | TSN 0    |                           |           |           |                  |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 49.080   | APUS    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-60-43  |         |           |          |          |                           |           |           |                  |
| <b>497020 APU - IMMERSION THERMOCOUPLE</b>                      |         |           |          |          |                           |           |           | Component ATA:49 |
| PN:3876003-3  | MOS/MSC | 26-May-09 | O/C      | TSN 0    |                           |           |           |                  |
| SN:09-20219-02602   | HRS     | 0         |          | TSN 0    |                           |           |           |                  |
| WC#: 49.085   | APUS    | 0         |          | TSN 0    |                           |           |           |                  |
| PROC. REF: MM 49-60-45  |         |           |          |          |                           |           |           |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                  | Unit  | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit  | Remaining | Disposition |        |
|--|---|-----------|-----------------|----------|---------------------------|------------|-----------|-------------|--------|
| <b>ATA 49 - AIRBORNE AUXILIARY POWER</b> |   |           |                 |          |                           |            |           |             |        |
| 497030                                   | APU - HOURMETER                             |           |                 |          |                           |            |           | Component   | ATA:49 |
| PN:PN                                    | MOS/MSC                                     | 26-May-09 | O/C             | TSN 0    |                           |            |           |             |        |
| SN:UNKNOWN                               | HRS   | 0         |                 | TSN 0    |                           |            |           |             |        |
| WC#: 49.090                              | APUS  | 0         |                 | TSN 0    |                           |            |           |             |        |
| PROC. REF: MM 49-70-41                   |   |           |                 |          |                           |            |           |             |        |
| 499010                                   | APU - ROTARY OIL PUMP                       |           |                 |          |                           |            |           | Component   | ATA:49 |
| PN:PN                                    | MOS/MSC                                     | 26-May-09 | O/C             | TSN 0    |                           |            |           |             |        |
| SN:UNKNOWN                               | HRS   | 0         |                 | TSN 0    |                           |            |           |             |        |
| WC#: 49.095                              | APUS  | 0         |                 | TSN 0    |                           |            |           |             |        |
| PROC. REF: MM 49-90-51                   |   |           |                 |          |                           |            |           |             |        |
| 499020 <sup>S</sup>                      | APU - INSPECT MAGNETIC DRAIN PLUG           |           |                 |          |                           |            |           | Service     | ATA:49 |
|  | MOS   | 13-Mar-24 | 12              |          |                           |            |           |             |        |
|  | HRS   | 3741      | 750             |          |                           |            |           |             |        |
| WC#: 49.100                              | APUS  |           |                 |          |                           |            |           |             |        |
| PROC. REF: MM 49-90-46                   |   |           |                 |          |                           |            |           |             |        |
| 499030 <sup>S</sup>                      | APU - CHANGE OIL                            |           |                 |          |                           |            |           | Service     | ATA:49 |
|  | MOS/MSC                                     | 19-Mar-13 | O/C             |          |                           |            |           |             |        |
|  | HRS   | 1343      |                 |          |                           |            |           |             |        |
| WC#: 49.105                              | APUS  |           |                 |          |                           |            |           |             |        |
| PROC. REF: MM 49-20-00                   |   |           |                 |          |                           |            |           |             |        |
| 499040                                   | APU - REMOVE AND REPLACE OIL FILTER ELEMENT |           |                 |          |                           |            |           | Service     | ATA:49 |
|  | MOS   | 07-Apr-23 |                 |          |                           |            |           |             |        |
|  | HRS   | 3580      | 500 (+20%/-20%) | 4080     | 4180                      | 316 (+100) |           |             |        |
| WC#: 49.110                              | APUS  |           |                 |          |                           |            |           |             |        |
| PROC. REF: MM 49-90-47                   |   |           |                 |          |                           |            |           |             |        |
| 499050                                   | APU - PRESSURE REGULATOR VALVE              |           |                 |          |                           |            |           | Component   | ATA:49 |
| PN:PN                                    | MOS/MSC                                     | 26-May-09 | O/C             | TSN 0    |                           |            |           |             |        |
| SN:UNKNOWN                               | HRS   | 0         |                 | TSN 0    |                           |            |           |             |        |
| WC#: 49.115                              | APUS  | 0         |                 | TSN 0    |                           |            |           |             |        |
| PROC. REF: MM 49-90-52                   |   |           |                 |          |                           |            |           |             |        |
| 499060                                   | APU - HIGH OIL TEMPERATURE SWITCH           |           |                 |          |                           |            |           | Component   | ATA:49 |
| PN:PN                                    | MOS/MSC                                     | 26-May-09 | O/C             | TSN 0    |                           |            |           |             |        |
| SN:UNKNOWN                               | HRS   | 0         |                 | TSN 0    |                           |            |           |             |        |
| WC#: 49.120                              | APUS  | 0         |                 | TSN 0    |                           |            |           |             |        |
| PROC. REF: MM 49-60-46                   |   |           |                 |          |                           |            |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit   | C/W       | Interval        | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition |        |
|--|--|-----------|-----------------|----------|---------------------------|-----------|--------------|-------------|--------|
| <b>ATA 49 - AIRBORNE AUXILIARY POWER</b>       |  |           |                 |          |                           |           |              |             |        |
| 499070   | APU - LOW OIL PRESSURE SWITCH  |           |                 |          |                           |           |              | Component   | ATA:49 |
| PN:3876001-8                                   | MOS/MSC  | 12-Feb-24 | O/C             | TSN 0    |                           |           |              |             |        |
| SN:N/A   | HRS  | 3738      |                 | TSN 0    |                           |           |              |             |        |
| WC#: 49.125                                    | APUS   |           |                 | TSN 0    |                           |           |              |             |        |
| PROC. REF: MM 49-60-43                         |  |           |                 |          |                           |           |              |             |        |
| 499110   | APU - SOAP CHECK OIL   |           |                 |          |                           |           |              | Service     | ATA:49 |
|  | MOS  | 13-Mar-24 |                 |          |                           |           |              |             |        |
|  | HRS  | 3741      | 500 (+20%/-20%) |          | 4241                      | 4341      | 477 (+100)   |             |        |
| WC#: 49.130                                    | APUS   |           |                 |          |                           |           |              |             |        |
| 49APU1   | APU  |           |                 |          |                           |           |              | Component   | ATA:49 |
| PN:3800304-1                                   | MOS/MSC  | 05-May-10 | E/C             | TSN 0    |                           |           |              |             |        |
| SN:P-1179                                      | HRS  | 0         |                 | TSN 0    |                           |           |              |             |        |
| WC#: 49.APU1                                   | AFL  | 0         |                 | TSN 0    |                           |           |              |             |        |
| PROC. REF: AMM 49-11-00                        |  |           |                 |          |                           |           |              |             |        |
| <b>ATA 51 - STD PRACTICES AND STRUCT-GENRL</b> |  |           |                 |          |                           |           |              |             |        |
| 510001   | INSPECT/NDT NOSE LANDING GEAR BAY SIDEWALLS                                |           |                 |          |                           |           |              | Service     | ATA:51 |
|  | MOS  | 20-Jun-22 | 144 (+3m)       |          | 20-Jun-34                 | 20-Sep-34 | 3613 d (+92) |             |        |
|  | HRS  | 3511.6    |                 |          |                           |           |              |             |        |
| WC#: 51.100                                    | AFL  | 1288      | 5000 (+10%)     |          | 6288                      | 6788      | 4796 (+500)  |             |        |
| PROC. REF: NTM 53-10-10                        |  |           |                 |          |                           |           |              |             |        |
| 510002   | DETAIL INSPECT FRONT PRESSURE BULKHEAD                                     |           |                 |          |                           |           |              | Service     | ATA:51 |
|  | MOS  | 05-May-10 |                 |          |                           |           |              |             |        |
|  | HRS  | 0         |                 |          |                           |           |              |             |        |
| WC#: 51.010                                    | AFL  | 0         | T:5000 (+10%)   |          | 5000                      | 5500      | 3508 (+500)  |             |        |
| 510003   | INSPECT/NDT FLIGHT COMPARTMENT SKIN AND WINDOW STRUCTURE ABOVE WINDSHIELDS |           |                 |          |                           |           |              | Service     | ATA:51 |
|  | MOS  | 20-Jun-22 | 48 (+3m)        |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)  |             |        |
|  | HRS  | 3511.6    |                 |          |                           |           |              |             |        |
| WC#: 51.020                                    | AFL  | 1288      |                 |          |                           |           |              |             |        |
| PROC. REF: NTM 53-10-30, NTM 53-10-35          |  |           |                 |          |                           |           |              |             |        |
| 510004   | DETAIL INSPECT UPPER CANOPY RAIL AT INTERSECTION WITH THE CANOPY POSTS     |           |                 |          |                           |           |              | Service     | ATA:51 |
|  | MOS  | 05-May-10 |                 |          |                           |           |              |             |        |
|  | HRS  | 0         |                 |          |                           |           |              |             |        |
| WC#: 51.030                                    | AFL  | 0         | 20000 (+500)    |          | 20000                     | 20500     | 18508 (+500) |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|--|--|-----------|----------------|----------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 51 - STD PRACTICES AND STRUCT-GENRL</b> |  |           |                |          |                           |           |             |             |        |
| 510005   | INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, NOSE LANDING GEAR BAY TO FRAME 13 AND FRAMES 16 TO 19 |           |                |          |                           |           |             | Service     | ATA:51 |
|  | MOS  | 05-May-10 | T:180 (+3m)    |          | 05-May-25                 | 05-Aug-25 | 280 d (+92) |             |        |
|  | HRS  | 0         |                |          |                           |           |             |             |        |
| WC#: 51.040                                    | AFL  | 0         |                |          |                           |           |             |             |        |
| PROC. REF: NTM 53-10-45                        |  |           |                |          |                           |           |             |             |        |
| 510006   | DETAIL INSPECT STRUCTURE BELOW ESCAPE HATCH, FRAMES 13 TO 14   |           |                |          |                           |           |             | Service     | ATA:51 |
|  | MOS  | 05-May-10 | T:180 (+3m)    |          | 05-May-25                 | 05-Aug-25 | 280 d (+92) |             |        |
|  | HRS  | 0         |                |          |                           |           |             |             |        |
| WC#: 51.050                                    | AFL  | 0         |                |          |                           |           |             |             |        |
| 510007   | INSPECT/NDT CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 8 TO 17  |           |                |          |                           |           |             | Service     | ATA:51 |
|  | MOS  | 05-May-10 | T:180 (+3m)    |          | 05-May-25                 | 05-Aug-25 | 280 d (+92) |             |        |
|  | HRS  | 0         |                |          |                           |           |             |             |        |
| WC#: 51.060                                    | AFL  | 0         |                |          |                           |           |             |             |        |
| PROC. REF: NTM 53-10-45                        |  |           |                |          |                           |           |             |             |        |
| 510008   | X-RAY CENTER FUSELAGE STRUCTURE BELOW THE FLOOR, FRAMES 13 TO 16   |           |                |          |                           |           |             | Service     | ATA:51 |
|  | MOS  | 05-May-10 | T:180 (+3m)    |          | 05-May-25                 | 05-Aug-25 | 280 d (+92) |             |        |
|  | HRS  | 0         |                |          |                           |           |             |             |        |
| WC#: 51.070                                    | AFL  | 0         |                |          |                           |           |             |             |        |
| PROC. REF: NTM 53-10-45                        |  |           |                |          |                           |           |             |             |        |
| 510009   | DETAIL INSPECT ENTRY DOOR SURROUND   |           |                |          |                           |           |             | Service     | ATA:51 |
|  | MOS  | 20-Jun-22 | 48 (+3m)       |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92) |             |        |
|  | HRS  | 3511.6    |                |          |                           |           |             |             |        |
| WC#: 51.080                                    | AFL  | 1288      |                |          |                           |           |             |             |        |
| 510010   | INSPECT/NDT CENTER FUSELAGE STRUCTURE, ABOVE THE FLOOR   |           |                |          |                           |           |             | Service     | ATA:51 |
|  | MOS  | 05-May-10 | T:180 (+3m)    |          | 05-May-25                 | 05-Aug-25 | 280 d (+92) |             |        |
|  | HRS  | 0         |                |          |                           |           |             |             |        |
| WC#: 51.090                                    | AFL  | 0         |                |          |                           |           |             |             |        |
| PROC. REF: NTM 53-10-40                        |  |           |                |          |                           |           |             |             |        |
| <b>ATA 52 - DOORS</b>                          |  |           |                |          |                           |           |             |             |        |
| 520004 <sup>S</sup>                            | CHECK MAIN ENTRY DOOR "NOT LOCKED" WARNING MICROSWITCHES   |           |                |          |                           |           |             | Service     | ATA:52 |
|  | MOS  | 06-Jun-18 |                |          |                           |           |             |             |        |
|  | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |             |             |        |
| WC#: 52.025                                    | AFL  | 1073      |                |          |                           |           |             |             |        |
| PROC. REF: AMM 12-24-00                        |  |           |                |          |                           |           |             |             |        |
| PKG:24,92                                      |  |           |                |          |                           |           |             |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN             | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition |           |
|---------------------|--|-----------|----------------|----------|---------------------------|-----------|--------------|-------------|-----------|
| ATA 52 - DOORS      |  |           |                |          |                           |           |              |             |           |
| 520005 <sup>S</sup> | CHECK ESCAPE HATCH RELEASE MECHANISM                   |           |                |          |                           |           |              | Service     | ATA:52    |
|                     | MOS  | 03-Aug-21 |                |          |                           |           |              |             |           |
|                     | HRS  | 3405      | 800 (+40/-10)  |          |                           |           |              |             |           |
| WC#: 52.015         | AFL  | 1243      |                |          |                           |           |              |             |           |
|                     | PROC. REF: AMM NO REF 1                                |           |                |          |                           |           |              |             | PKG:12,91 |
| 520006 <sup>S</sup> | INSPECT ESCAPE HATCH SEALS                             |           |                |          |                           |           |              | Service     | ATA:52    |
|                     | MOS  | 03-Aug-21 |                |          |                           |           |              |             |           |
|                     | HRS  | 3405      | 800 (+40/-10)  |          |                           |           |              |             |           |
| WC#: 52.035         | AFL  | 1243      |                |          |                           |           |              |             |           |
|                     | PROC. REF: AMM NO REF 1                                |           |                |          |                           |           |              |             | PKG:12,91 |
| 520007 <sup>S</sup> | INSPECT/CHECK ENTRY DOOR                               |           |                |          |                           |           |              | Service     | ATA:52    |
|                     | MOS  | 06-Jun-18 |                |          |                           |           |              |             |           |
|                     | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |              |             |           |
| WC#: 52.010         | AFL  | 1073      |                |          |                           |           |              |             |           |
|                     | PROC. REF: AMM 52-11-00                                |           |                |          |                           |           |              |             | PKG:24,92 |
| 520008              | INSPECT/NDT MAIN ENTRY DOOR                            |           |                |          |                           |           |              | Service     | ATA:52    |
|                     | MOS  | 20-Jun-22 | 96 (+3m)       |          | 20-Jun-30                 | 20-Sep-30 | 2152 d (+92) |             |           |
|                     | HRS  | 3511.6    |                |          |                           |           |              |             |           |
| WC#: 52.010         | AFL  | 1288      |                |          |                           |           |              |             |           |
|                     | PROC. REF: NTM 52-80-10                                |           |                |          |                           |           |              |             |           |
| 520009              | DETAIL INSPECT ESCAPE HATCH                            |           |                |          |                           |           |              | Service     | ATA:52    |
|                     | MOS  | 05-May-10 | T:180 (+3m)    |          | 05-May-25                 | 05-Aug-25 | 280 d (+92)  |             |           |
|                     | HRS  | 0         |                |          |                           |           |              |             |           |
| WC#: 52.015         | AFL  | 0         |                |          |                           |           |              |             |           |
| 520010 <sup>S</sup> | INSPECT MAIN ENTRY DOOR - FOLDING HANDRAIL (IF FITTED) |           |                |          |                           |           |              | Service     | ATA:52    |
|                     | MOS  | 06-Jun-18 |                |          |                           |           |              |             |           |
|                     | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |              |             |           |
| WC#: 52.050         | AFL  | 1073      |                |          |                           |           |              |             |           |
|                     | PROC. REF: MMA 52-15-00                                |           |                |          |                           |           |              |             | PKG:24,92 |
| 521001              | MAIN ENTRY DOOR ASSEMBLY                               |           |                |          |                           |           |              | Component   | ATA:52    |
| PN:259W03838-1A     | MOS/MSC  | 16-Mar-10 | O/C            | TSN 0    |                           |           |              |             |           |
| SN:SD-DH-947        | HRS  | 0         |                | TSN 0    |                           |           |              |             |           |
| WC#: 52.010         | AFL  | 0         |                | TSN 0    |                           |           |              |             |           |
|                     | PROC. REF: AMM 52-11-00                                |           |                |          |                           |           |              |             |           |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit   | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition |        |
|---------------------------|--|-----------|-------------|----------|---------------------------|-----------|--------------|-------------|--------|
| <b>ATA 52 - DOORS</b>     |  |           |             |          |                           |           |              |             |        |
| 521016                    | LONG RANGE TANK DOOR   |           |             |          |                           |           |              | Component   | ATA:52 |
| PN:25-8PT111-87A          | MOS/MSC  | 16-Mar-10 | O/C         | TSN 0    |                           |           |              |             |        |
| SN:PLL-DH-893             | HRS  | 0         |             | TSN 0    |                           |           |              |             |        |
| WC#: 52.055               | AFL  | 0         |             | TSN 0    |                           |           |              |             |        |
| PROC. REF: GENERIC NO REF |  |           |             |          |                           |           |              |             |        |
| 522001                    | ESCAPE HATCH   |           |             |          |                           |           |              | Component   | ATA:52 |
| PN:25-8FC3601-151A        | MOS/MSC  | 16-Mar-10 | O/C         | TSN 0    |                           |           |              |             |        |
| SN:11110902SAL            | HRS  | 0         |             | TSN 0    |                           |           |              |             |        |
| WC#: 52.015               | AFL  | 0         |             | TSN 0    |                           |           |              |             |        |
| PROC. REF: AMM 52-20-00   |  |           |             |          |                           |           |              |             |        |
| <b>ATA 53 - FUSELAGE</b>  |  |           |             |          |                           |           |              |             |        |
| 530001                    | DETAIL INSPECT SKIN EXTERIOR UNDER THE DORSAL INTAKE, FORWARD OF FRAME 19  |           |             |          |                           |           |              | Service     | ATA:53 |
|                           | MOS  | 20-Jun-22 | 48 (+3m)    |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)  |             |        |
|                           | HRS  | 3511.6    |             |          |                           |           |              |             |        |
| WC#: 53.115               | AFL  | 1288      |             |          |                           |           |              |             |        |
| 530002                    | INSPECT FUSELAGE SKIN UNDER WING-TO-FUSELAGE FAIRINGS                      |           |             |          |                           |           |              | Service     | ATA:53 |
|                           | MOS  | 20-Jun-22 | 48 (+3m)    |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)  |             |        |
|                           | HRS  | 3511.6    |             |          |                           |           |              |             |        |
| WC#: 53.040               | AFL  | 1288      |             |          |                           |           |              |             |        |
| 530003                    | DETAIL INSPECT FUSELAGE SKIN COVERED BY THE VENTRAL FUEL TANK (IF FITTED). |           |             |          |                           |           |              | Service     | ATA:53 |
|                           | MOS  | 05-May-10 | T:180 (+3m) |          | 05-May-25                 | 05-Aug-25 | 280 d (+92)  |             |        |
|                           | HRS  | 0         |             |          |                           |           |              |             |        |
| WC#: 53.110               | AFL  | 0         |             |          |                           |           |              |             |        |
| 530004                    | DETAIL INSPECT VENTRAL FUEL TANK AND ATTACHMENTS, (IF FITTED)              |           |             |          |                           |           |              | Service     | ATA:53 |
|                           | MOS  | 05-May-10 | T:180 (+3m) |          | 05-May-25                 | 05-Aug-25 | 280 d (+92)  |             |        |
|                           | HRS  | 0         |             |          |                           |           |              |             |        |
| WC#: 28.015               | AFL  | 0         |             |          |                           |           |              |             |        |
| PROC. REF: AMM NO REF 1   |  |           |             |          |                           |           |              |             |        |
| 530007                    | DETAIL INSPECT WING TO FUSELAGE ATTACHMENT LINKS, BRACKETS AND BOLTS       |           |             |          |                           |           |              | Service     | ATA:53 |
|                           | MOS  | 20-Jun-22 | 96 (+3m)    |          | 20-Jun-30                 | 20-Sep-30 | 2152 d (+92) |             |        |
|                           | HRS  | 3511.6    |             |          |                           |           |              |             |        |
| WC#: 53.105               | AFL  | 1288      |             |          |                           |           |              |             |        |
| PROC. REF: AMM 53-40-01   |  |           |             |          |                           |           |              |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                  | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition |        |
|--------------------------|--|-----------|----------------|----------|---------------------------|-----------|----------------|-------------|--------|
| <b>ATA 53 - FUSELAGE</b> |  |           |                |          |                           |           |                |             |        |
| 530009                   | INSPECT/NDT FUSELAGE LAP JOINTS  |           |                |          |                           |           |                | Service     | ATA:53 |
|                          | MOS  | 05-May-10 |                |          |                           |           |                |             |        |
|                          | HRS  | 0         |                |          |                           |           |                |             |        |
| WC#: 53.125              | AFL  | 0         | T:27000 (+500) |          | 27000                     | 27500     | 25508 (+500)   |             |        |
| PROC. REF: NTM 53-10-25  |  |           |                |          |                           |           |                |             |        |
| 530010                   | DETAIL INSPECT SKIN OF THE FUSELAGE, WING ATTACHMENT BRACKETS, DRAG SPIGOT BEARING AND DRAG SPIGOT HOUSING |           |                |          |                           |           |                | Service     | ATA:53 |
|                          | MOS/MSC  | 05-May-10 | A/R            |          |                           |           |                |             |        |
|                          | HRS  | 0         |                |          |                           |           |                |             |        |
| WC#: 53.020              | AFL  | 0         |                |          |                           |           |                |             |        |
| 530011                   | INSPECT LEFT-HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)                                     |           |                |          |                           |           |                | Service     | ATA:53 |
|                          | MOS  | 20-Jun-22 | 48 (+3m)       |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)    |             |        |
|                          | HRS  | 3511.6    |                |          |                           |           |                |             |        |
| WC#: 53.175              | AFL  | 1288      |                |          |                           |           |                |             |        |
| 530012                   | INSPECT RIGHT- HAND SIDE FRONT FACE OF REAR PRESSURE BULKHEAD (FRAME 19)                                   |           |                |          |                           |           |                | Service     | ATA:53 |
|                          | MOS  | 06-Jun-18 | 96 (+3m)       | Adj -32d | 05-May-26                 | 05-Aug-26 | 645 d (+92)    |             |        |
|                          | HRS  | 2965.25   |                |          |                           |           |                |             |        |
| WC#: 53.070              | AFL  | 1073      |                |          |                           |           |                |             |        |
| 530013                   | INSPECT/NDT NO. 1 ENGINE MOUNTING PYLON ENGINE MAIN MOUNTING ATTACHMENT FITTINGS                           |           |                |          |                           |           |                | Service     | ATA:53 |
|                          | MOS  | 05-May-10 |                |          |                           |           |                |             |        |
|                          | HRS  | 0         | 10000 (+500)   |          | 10000                     | 10500     | 6091.6 (+500)  |             |        |
| WC#: 53.030              | AFL  | 0         |                |          |                           |           |                |             |        |
| PROC. REF: NTM 53-10-05  |  |           |                |          |                           |           |                |             |        |
| 530014                   | INSPECT/NDT REAR ENGINE MOUNT FITTINGS   |           |                |          |                           |           |                | Service     | ATA:53 |
|                          | MOS  | 05-May-10 |                |          |                           |           |                |             |        |
|                          | HRS  | 0         | 20000 (+500)   |          | 20000                     | 20500     | 16091.6 (+500) |             |        |
| WC#: 53.035              | AFL  | 0         |                |          |                           |           |                |             |        |
| PROC. REF: NTM 53-10-05  |  |           |                |          |                           |           |                |             |        |
| 530015                   | INSPECT/NDT VERTICAL STABILIZER ROOT ATTACHMENT TO FUSELAGE  |           |                |          |                           |           |                | Service     | ATA:53 |
|                          | MOS  | 05-May-10 |                |          |                           |           |                |             |        |
|                          | HRS  | 0         | 30000 (+500)   |          | 30000                     | 30500     | 26091.6 (+500) |             |        |
| WC#: 53.015              | AFL  | 0         |                |          |                           |           |                |             |        |
| PROC. REF: NTM 55-30-20  |  |           |                |          |                           |           |                |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit  | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition |        |
|-------------------------|---|-----------|---------------|----------|---------------------------|-----------|---------------|-------------|--------|
| ATA 53 - FUSELAGE       |   |           |               |          |                           |           |               |             |        |
| 530016                  | DETAIL INSPECT NO. 1 ENGINE MOUNTING ENGINE BEAM                    |           |               |          |                           |           |               | Service     | ATA:53 |
|                         | MOS   | 05-May-10 |               |          |                           |           |               |             |        |
|                         | HRS   | 0         | 10000 (+500)  |          | 10000                     | 10500     | 6091.6 (+500) |             |        |
| WC#: 53.080             | AFL   | 0         |               |          |                           |           |               |             |        |
| PROC. REF: AMM NO REF 1 |   |           |               |          |                           |           |               |             |        |
| 530017                  | INSPECT NO. 1 ENGINE MOUNTING BRACKETS                              |           |               |          |                           |           |               | Service     | ATA:53 |
|                         | MOS/MSC   | 19-Dec-17 | E/C           |          |                           |           |               | PART OF MPI |        |
|                         | HRS   | 2886.88   |               |          |                           |           |               |             |        |
| WC#: 53.200             | AFL   | 1043      |               |          |                           |           |               |             |        |
| 530017                  | INSPECT NO. 2 ENGINE MOUNTING BRACKETS                              |           |               |          |                           |           |               | Service     | ATA:53 |
|                         | MOS/MSC   | 19-Dec-17 | E/C           |          |                           |           |               | PART OF MPI |        |
|                         | HRS   | 2886.88   |               |          |                           |           |               |             |        |
| WC#: 53.200             | AFL   | 1043      |               |          |                           |           |               |             |        |
| 530018                  | DETAIL INSPECT FUSELAGE SKIN ADJACENT TO CABIN WINDOW CUTOUTS       |           |               |          |                           |           |               | Service     | ATA:53 |
|                         | MOS   | 05-May-10 |               |          |                           |           |               |             |        |
|                         | HRS   | 0         | T:4800 (+10%) |          | 4800                      | 5280      | 891.6 (+480)  |             |        |
| WC#: 53.205             | AFL   | 0         |               |          |                           |           |               |             |        |
| 530019                  | DETAIL INSPECT APU SUPPORT STRUCTURE EXTERNAL TO THE FIRE ENCLOSURE |           |               |          |                           |           |               | Service     | ATA:53 |
|                         | MOS   | 11-Jul-24 | 12 (+1m)      |          | 11-Jul-25                 | 11-Aug-25 | 347 d (+31)   |             |        |
|                         | HRS   | 3907.4    |               |          |                           |           |               |             |        |
| WC#: 53.210             | AFL   | 1491      |               |          |                           |           |               |             |        |
| 530021                  | DETAIL INSPECT APU SUPPORT STRUCTURE                                |           |               |          |                           |           |               | Service     | ATA:53 |
|                         | MOS   | 06-Jun-18 |               |          |                           |           |               |             |        |
|                         | HRS   | 2965.25   |               |          |                           |           |               |             |        |
| WC#: 53.010             | AFL   | 1073      |               |          |                           |           |               |             |        |
|                         | APH   | 2853      | 3000          |          | 5853                      |           | 2107          |             |        |
| 530022                  | DETAIL INSPECT APU MOUNTING HARDWARE                                |           |               |          |                           |           |               | Service     | ATA:53 |
|                         | MOS   | 05-May-10 |               |          |                           |           |               |             |        |
|                         | HRS   | 0         |               |          |                           |           |               |             |        |
| WC#: 53.215             | AFL   | 0         |               |          |                           |           |               |             |        |
|                         | APH   | 0         | 4500          |          | 4500                      |           | 754           |             |        |
| PROC. REF: AMS 5-20-09  |   |           |               |          |                           |           |               |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit  | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|---------------------------|---|-----------|--------------|----------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 53 - FUSELAGE</b>  |   |           |              |          |                           |           |             |             |        |
| 530023                    | DETAIL INSPECT FUSELAGE STRUCTURE FOR CRACKS                      |           |              |          |                           |           |             | Service     | ATA:53 |
|                           | MOS   | 05-May-10 |              |          |                           |           |             |             |        |
|                           | HRS   | 0         |              |          |                           |           |             |             |        |
| WC#: 53.220               | AFL   | 0         |              |          |                           |           |             |             |        |
|                           | APH   | 0         | 4500         |          | 4500                      |           | 754         |             |        |
| 530024                    | FLUORESCENT PENETRANT INSPECT APU SUPPORT HARDWARE                |           |              |          |                           |           |             | Service     | ATA:53 |
|                           | MOS   | 05-May-10 |              |          |                           |           |             |             |        |
|                           | HRS   | 0         |              |          |                           |           |             |             |        |
| WC#: 53.225               | AFL   | 0         |              |          |                           |           |             |             |        |
|                           | APH   | 0         | 22500        |          | 22500                     |           | 18754       |             |        |
| PROC. REF: AMS 5-20-09    |   |           |              |          |                           |           |             |             |        |
| 530025                    | DETAIL INSPECT APU EXHAUST AND INLET DOUBLER FRAMES AND STRINGERS |           |              |          |                           |           |             | Service     | ATA:53 |
|                           | MOS   | 05-May-10 |              |          |                           |           |             |             |        |
|                           | HRS   | 0         |              |          |                           |           |             |             |        |
| WC#: 53.170               | AFL   | 0         | 10000 (+500) |          | 10000                     | 10500     | 8508 (+500) |             |        |
| 530027 <sup>S</sup>       | VISUAL INSPECTION FUSELAGE SKIN                                   |           |              |          |                           |           |             | Service     | ATA:53 |
|                           | MOS   | 20-Jun-22 | 48 (+2m/-2m) |          |                           |           |             |             |        |
|                           | HRS   | 3511.6    |              |          |                           |           |             |             |        |
| WC#: 53.235               | AFL   | 1288      |              |          |                           |           |             |             |        |
| PKG:96                    |   |           |              |          |                           |           |             |             |        |
| 531146                    | RADOME  |           |              |          |                           |           |             | Component   | ATA:53 |
| PN:DOIW00019-1A           | MOS/MSC   | 16-Mar-10 | O/C          | TSN 0    |                           |           |             |             |        |
| SN:DOIWCML205             | HRS   | 0         |              | TSN 0    |                           |           |             |             |        |
| WC#: 53.135               | AFL   | 0         |              | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM 53-50-14   |   |           |              |          |                           |           |             |             |        |
| 531152                    | TAIL CONE FAIRING   |           |              |          |                           |           |             | Component   | ATA:53 |
| PN:251W00120-3A           | MOS/MSC   | 16-Mar-10 | O/C          | TSN 0    |                           |           |             |             |        |
| SN:CAVPO91033             | HRS   | 0         |              | TSN 0    |                           |           |             |             |        |
| WC#: 53.140               | AFL   | 0         |              | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM 53-50-16   |   |           |              |          |                           |           |             |             |        |
| 531154                    | FUSELAGE  |           |              |          |                           |           |             | Component   | ATA:53 |
| PN:25-8FA1-6047           | MOS/MSC   | 16-Mar-10 | O/C          | TSN 0    |                           |           |             |             |        |
| SN:259156                 | HRS   | 0         |              | TSN 0    |                           |           |             |             |        |
| WC#: 53.145               | AFL   | 0         |              | TSN 0    |                           |           |             |             |        |
| PROC. REF: GENERIC NO REF |   |           |              |          |                           |           |             |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|---------------------------------------|--|-----------|----------|----------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 55 - STABILIZERS</b>           |  |           |          |          |                           |           |             |             |        |
| 550001                                | DETAIL INSPECT ELEVATORS AND TABS                                  |           |          |          |                           |           |             | Service     | ATA:55 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m) |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92) |             |        |
|                                       | HRS  | 3511.6    |          |          |                           |           |             |             |        |
| WC#: 27.070                           | AFL  | 1288      |          |          |                           |           |             |             |        |
| PROC. REF: AMM NO REF 1               |  |           |          |          |                           |           |             |             |        |
| 550002                                | LUBRICATE/REPLACE ELEVATOR TRIM TABS, CONNECTING RODS              |           |          |          |                           |           |             | Service     | ATA:55 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m) |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92) |             |        |
|                                       | HRS  | 3511.6    |          |          |                           |           |             |             |        |
| WC#: 55.075                           | AFL  | 1288      |          |          |                           |           |             |             |        |
| PROC. REF: AMM 27-30-00, AMM 27-30-00 |  |           |          |          |                           |           |             |             |        |
| 550003                                | XRAY ELEVATORS   |           |          |          |                           |           |             | Service     | ATA:55 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m) |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92) |             |        |
|                                       | HRS  | 3511.6    |          |          |                           |           |             |             |        |
| WC#: 55.055                           | AFL  | 1288      |          |          |                           |           |             |             |        |
| PROC. REF: NTM 55-20-10               |  |           |          |          |                           |           |             |             |        |
| 550004                                | DETAIL INSPECT RUDDER AND TAB                                      |           |          |          |                           |           |             | Service     | ATA:55 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m) |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92) |             |        |
|                                       | HRS  | 3511.6    |          |          |                           |           |             |             |        |
| WC#: 27.045                           | AFL  | 1288      |          |          |                           |           |             |             |        |
| PROC. REF: AMM NO REF 1               |  |           |          |          |                           |           |             |             |        |
| 550005                                | INSPECT RUDDER CONNECTING RODS, RUDDER TRIM TAB AND ANTI-SERVO TAB |           |          |          |                           |           |             | Service     | ATA:55 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m) |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92) |             |        |
|                                       | HRS  | 3511.6    |          |          |                           |           |             |             |        |
| WC#: 55.065                           | AFL  | 1288      |          |          |                           |           |             |             |        |
| 550006                                | X-RAY RUDDER (IN-SITU)   |           |          |          |                           |           |             | Service     | ATA:55 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m) |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92) |             |        |
|                                       | HRS  | 3511.6    |          |          |                           |           |             |             |        |
| WC#: 27.045                           | AFL  | 1288      |          |          |                           |           |             |             |        |
| PROC. REF: NTM 55-40-05               |  |           |          |          |                           |           |             |             |        |
| 550007                                | DETAIL INSPECT RUDDER HINGE BRACKETS AND ATTACHMENTS               |           |          |          |                           |           |             | Service     | ATA:55 |
|                                       | MOS  | 06-Jun-18 | 96 (+3m) | Adj -32d | 05-May-26                 | 05-Aug-26 | 645 d (+92) |             |        |
|                                       | HRS  | 2965.25   |          |          |                           |           |             |             |        |
| WC#: 27.045                           | AFL  | 1073      |          |          |                           |           |             |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                     | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining    | Disposition   |        |
|-----------------------------|--|-----------|----------------|----------|---------------------------|-----------|--------------|---|--------|
| <b>ATA 55 - STABILIZERS</b> |  |           |                |          |                           |           |              |   |        |
| 550008 <sup>S</sup>         | INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER REAR ATTACHMENT FITTING                                   |           |                |          |                           |           |              | Service   | ATA:55 |
|                             | MOS  | 25-Jul-24 | 24 (+2m/-2m)   |          |                           |           |              |   |        |
|                             | HRS  | 3908.4    |                |          |                           |           |              |   |        |
| WC#: 55.010                 | AFL  | 1492      |                |          |                           |           |              |   |        |
|                             |  |           |                |          |                           |           |              | PKG:62,95   |        |
| 550009                      | DETAIL INSPECT HORIZONTAL STABILIZER   |           |                |          |                           |           |              | Service   | ATA:55 |
|                             | MOS  | 06-Jun-18 | 96 (+3m)       | Adj -32d | 05-May-26                 | 05-Aug-26 | 645 d (+92)  |   |        |
|                             | HRS  | 2965.25   |                |          |                           |           |              |   |        |
| WC#: 55.040                 | AFL  | 1073      |                |          |                           |           |              |   |        |
| 550010                      | INSPECT/NDT VERTICAL STABILIZER  |           |                |          |                           |           |              | Service   | ATA:55 |
|                             | MOS  | 05-May-10 | T:180 (+3m)    |          | 05-May-25                 | 05-Aug-25 | 280 d (+92)  |   |        |
|                             | HRS  | 0         |                |          |                           |           |              |   |        |
| WC#: 55.050                 | AFL  | 0         |                |          |                           |           |              |   |        |
|                             |  |           |                |          |                           |           |              | PROC. REF: NTM 55-30-05, NTM 55-30-10, NTM 55-30-15               |        |
| 550011                      | INSPECT HORIZONTAL STABILIZER TO VERTICAL STABILIZER ATTACHMENTS   |           |                |          |                           |           |              | Service   | ATA:55 |
|                             | MOS  | 05-May-10 | T:192 (+3m)    |          | 05-May-26                 | 05-Aug-26 | 645 d (+92)  |   |        |
|                             | HRS  | 0         |                |          |                           |           |              |   |        |
| WC#: 55.025                 | AFL  | 0         |                |          |                           |           |              |   |        |
| 550012                      | INSPECT/NDT HORIZONTAL STABILIZER  |           |                |          |                           |           |              | Service   | ATA:55 |
|                             | MOS  | 05-May-10 | T:288 (+3m)    |          | 05-May-34                 | 05-Aug-34 | 3567 d (+92) |   |        |
|                             | HRS  | 0         |                |          |                           |           |              |   |        |
| WC#: 55.045                 | AFL  | 0         |                |          |                           |           |              |   |        |
|                             |  |           |                |          |                           |           |              | PROC. REF: NTM 55-10-05, NTM 55-10-10, NTM 55-10-15               |        |
| 550013                      | X-RAY HORIZONTAL STABILIZER  |           |                |          |                           |           |              | Service   | ATA:55 |
|                             | MOS  | 05-May-10 | T:180 (+3m)    |          | 05-May-25                 | 05-Aug-25 | 280 d (+92)  |   |        |
|                             | HRS  | 0         |                |          |                           |           |              |   |        |
| WC#: 55.035                 | AFL  | 0         |                |          |                           |           |              |   |        |
|                             |  |           |                |          |                           |           |              | PROC. REF: NTM 55-10-05, NTM 55-10-10, NTM 55-10-15, NTM 55-10-20 |        |
| 550014                      | DETAIL INSPECT HORIZONTAL STABILIZER TOP SKIN 'T' FITTING AND JOINT STRAP AT THE CENTER LINE OF THE STABILIZER |           |                |          |                           |           |              | Service   | ATA:55 |
|                             | MOS  | 05-May-10 |                |          |                           |           |              |   |        |
|                             | HRS  | 0         |                |          |                           |           |              |   |        |
| WC#: 55.060                 | AFL  | 0         | T:15000 (+500) |          | 15000                     | 15500     | 13508 (+500) |   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                     | Unit  | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition |        |
|-----------------------------|---|-----------|----------------|----------|---------------------------|-----------|-------------|-------------|--------|
| <b>ATA 55 - STABILIZERS</b> |   |           |                |          |                           |           |             |             |        |
| 550015                      | INSPECT ELEVATOR MASS BALANCE WEIGHTS AND SPIGOTS         |           |                |          |                           |           |             | Service     | ATA:55 |
|                             | MOS   | 25-Jul-24 | 24 (+2m)       | Adj -35d | 20-Jun-26                 | 20-Aug-26 | 691 d (+61) |             |        |
|                             | HRS   | 3908.4    |                |          |                           |           |             |             |        |
| WC#: 55.070                 | AFL   | 1492      |                |          |                           |           |             |             |        |
| PROC. REF: AMM 27-30-91     |   |           |                |          |                           |           |             |             |        |
| 551004                      | UPPER VERTICAL STABILIZER                                 |           |                |          |                           |           |             | Component   | ATA:55 |
| PN:25-8TF513-1A             | MOS/MSC   | 16-Mar-10 | O/C            | TSN 0    |                           |           |             |             |        |
| SN:CAVP096016               | HRS   | 0         |                | TSN 0    |                           |           |             |             |        |
| WC#: 55.015                 | AFL   | 0         |                | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM 55-32-00     |   |           |                |          |                           |           |             |             |        |
| 551006                      | TAILPLANE   |           |                |          |                           |           |             | Component   | ATA:55 |
| PN:25-8TP509-1A             | MOS/MSC   | 16-Mar-10 | O/C            | TSN 0    |                           |           |             |             |        |
| SN:SD-DH-141                | HRS   | 0         |                | TSN 0    |                           |           |             |             |        |
| WC#: 55.020                 | AFL   | 0         |                | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM 55-13-00     |   |           |                |          |                           |           |             |             |        |
| 551010                      | BULLET FAIRING  |           |                |          |                           |           |             | Component   | ATA:55 |
| PN:25-8GF501-6175A          | MOS/MSC   | 16-Mar-10 | O/C            | TSN 0    |                           |           |             |             |        |
| SN:40368454                 | HRS   | 0         |                | TSN 0    |                           |           |             |             |        |
| WC#: 55.030                 | AFL   | 0         |                | TSN 0    |                           |           |             |             |        |
| PROC. REF: AMM 53-50-18     |   |           |                |          |                           |           |             |             |        |
| 553005                      | FIN LEADING EDGE  |           |                |          |                           |           |             | Component   | ATA:55 |
| PN:25-8TF133-3A             | MOS/MSC   | 16-Mar-10 | O/C            |          |                           |           |             |             |        |
| SN:CAVP08B06G               | HRS   | 0         |                |          |                           |           |             |             |        |
|                             | AFL   | 0         |                |          |                           |           |             |             |        |
| PROC. REF: GENERIC NO REF   |   |           |                |          |                           |           |             |             |        |
| <b>ATA 56 - WINDOWS</b>     |   |           |                |          |                           |           |             |             |        |
| 560004 <sup>S</sup>         | INSPECT WINDOWS DRY-AIR SYSTEM FILTER ELEMENT (IF FITTED) |           |                |          |                           |           |             | Service     | ATA:56 |
|                             | MOS   | 06-Jun-18 |                |          |                           |           |             |             |        |
|                             | HRS   | 2965.25   | 1600 (+50/-50) |          |                           |           |             |             |        |
| WC#: 56.065                 | AFL   | 1073      |                |          |                           |           |             |             |        |
| PROC. REF: AMM 56-00-00     |   |           |                |          |                           |           |             |             |        |
|                             |   |           |                |          |                           |           |             | PKG:24,92   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit   | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|--|-----------|---------------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 56 - WINDOWS        |  |           |               |          |                           |           |           |             |        |
| 560005                  | CHECK PASSENGER CABIN WINDOWS  |           |               |          |                           |           |           | Service     | ATA:56 |
|                         | MOS/MSC  | 03-Aug-21 | N/R           |          |                           |           |           |             |        |
|                         | HRS  | 3405      |               |          |                           |           |           |             |        |
| WC#: 56.090             | AFL  | 1243      |               |          |                           |           |           |             |        |
| PROC. REF: AMM 56-00-00 |  |           |               |          |                           |           |           |             |        |
| 560006 <sup>S</sup>     | INSPECT WINDSHIELD PANEL 'C' SILICA GEL CONTAINER  |           |               |          |                           |           |           | Service     | ATA:56 |
|                         | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 56.070             | AFL  | 1243      |               |          |                           |           |           |             |        |
| PKG:10,91               |  |           |               |          |                           |           |           |             |        |
| 560007 <sup>S</sup>     | SCREEN HEAT CIRCUIT BREAKERS - DO A VISUAL INSPECTION FOR HEAT DISTRESS, DISCOLORATION AND DEFORMATION |           |               |          |                           |           |           | Service     | ATA:56 |
|                         | MOS  | 25-Jul-24 | 24 (+2m/-2m)  |          |                           |           |           |             |        |
|                         | HRS  | 3908.4    |               |          |                           |           |           |             |        |
|                         | AFL  | 1492      |               |          |                           |           |           |             |        |
| PKG:60,95               |  |           |               |          |                           |           |           |             |        |
| 561001                  | LEFT (PANEL A) HEATED WINDSCREEN   |           |               |          |                           |           |           | Component   | ATA:56 |
| PN:NF24016-415          | MOS/MSC  | 04-Apr-19 | O/C           |          | TSR 0                     |           |           |             |        |
| SN:L383349              | HRS  | 3175.17   |               |          | TSR 0                     |           |           |             |        |
| WC#: 56.010             | AFL  | 1157      |               |          | TSR 0                     |           |           |             |        |
| PROC. REF: AMM 56-10-11 |  |           |               |          |                           |           |           |             |        |
| 561002                  | RIGHT (PANEL A) HEATED WINDSCREEN  |           |               |          |                           |           |           | Component   | ATA:56 |
| PN:NF24016-416          | MOS/MSC  | 20-Jun-22 | O/C           |          | TSN 0                     |           |           |             |        |
| SN:L562443              | HRS  | 3511.6    |               |          | TSN 0                     |           |           |             |        |
| WC#: 56.010             | AFL  | 1288      |               |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-10-11 |  |           |               |          |                           |           |           |             |        |
| 561003                  | LEFT DIRECT VIEW B WINDOW  |           |               |          |                           |           |           | Component   | ATA:56 |
| PN:NH24016-91           | MOS/MSC  | 05-Jul-19 | O/C           |          | TSN 0                     |           |           |             |        |
| SN:L492425              | HRS  | 3231.9    |               |          | TSN 0                     |           |           |             |        |
| WC#: 56.015             | AFL  | 1175      |               |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-10-22 |  |           |               |          |                           |           |           |             |        |
| 561004                  | RIGHT DIRECT VIEW B WINDOW   |           |               |          |                           |           |           | Component   | ATA:56 |
| PN:NH24016-92           | MOS/MSC  | 03-Aug-21 | O/C           |          | TSN 3                     |           |           |             |        |
| SN:L545937              | HRS  | 3405      |               |          | TSN 0                     |           |           |             |        |
| WC#: 56.015             | AFL  | 1243      |               |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-10-22 |  |           |               |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|--------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 56 - WINDOWS</b> |                          |           |          |          |                           |           |           |             |        |
| 561005                  | LEFT C WINDOW            |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:259W03925-1A         | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:CW20452              | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 56.020             | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-10-31 |                          |           |          |          |                           |           |           |             |        |
| 561006                  | RIGHT C WINDOW           |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:259W03925-2A         | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:CW20544              | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 56.020             | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-10-31 |                          |           |          |          |                           |           |           |             |        |
| 562001                  | NO. 1 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:5556                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 56.025             | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562002                  | NO. 1 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:5565                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 56.025             | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562003                  | NO. 2 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:5516                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 56.030             | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562004                  | NO. 2 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:5409                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 56.030             | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562005                  | NO. 3 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:5562                 | HRS                      | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 56.035             | AFL                      | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit                     | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|--------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 56 - WINDOWS</b> |                          |           |          |          |                           |           |           |             |        |
| 562006                  | NO. 3 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:5548                 | HRS                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 56.035             | AFL                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562007                  | NO. 4 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:5514                 | HRS                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 56.040             | AFL                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562008                  | NO. 4 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:5323                 | HRS                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 56.040             | AFL                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562009                  | NO. 5 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:5442                 | HRS                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 56.045             | AFL                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562010                  | NO. 5 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:5539                 | HRS                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 56.045             | AFL                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562011                  | NO. 6 LEFT CABIN WINDOW  |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:5493                 | HRS                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 56.050             | AFL                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |
| 562012                  | NO. 6 RIGHT CABIN WINDOW |           |          |          |                           |           |           | Component   | ATA:56 |
| PN:LA25FC7881-53        | MOS/MSC                  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:5540                 | HRS                      | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 56.050             | AFL                      | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 56-20-11 |                          |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN               | Unit   | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining   | Disposition                           |        |
|-----------------------|--|-----------|---------------|----------|---------------------------|-----------|-------------|---------------------------------------|--------|
| <b>ATA 57 - WINGS</b> |  |           |               |          |                           |           |             |                                       |        |
| 570001 <sup>S</sup>   | INSPECT LEFT FLAP HINGE FITTINGS   |           |               |          |                           |           |             | Service                               | ATA:57 |
|                       | MOS  | 03-Aug-21 |               |          |                           |           |             |                                       |        |
|                       | HRS  | 3405      | 800 (+40/-10) |          |                           |           |             |                                       |        |
| WC#: 57.095           | AFL  | 1243      |               |          |                           |           |             |                                       |        |
|                       |  |           |               |          |                           |           |             | PKG:15,91                             |        |
| 570002 <sup>S</sup>   | INSPECT RIGHT FLAP HINGE FITTINGS  |           |               |          |                           |           |             | Service                               | ATA:57 |
|                       | MOS  | 03-Aug-21 |               |          |                           |           |             |                                       |        |
|                       | HRS  | 3405      | 800 (+40/-10) |          |                           |           |             |                                       |        |
| WC#: 57.095           | AFL  | 1243      |               |          |                           |           |             |                                       |        |
|                       |  |           |               |          |                           |           |             | PKG:16,91                             |        |
| 570003 <sup>S</sup>   | DETAIL INSPECT LEFT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4   |           |               |          |                           |           |             | Service                               | ATA:57 |
|                       | MOS  | 25-Jul-24 | 24 (+2m/-2m)  |          |                           |           |             |                                       |        |
|                       | HRS  | 3908.4    |               |          |                           |           |             |                                       |        |
| WC#: 57.090           | AFL  | 1492      |               |          |                           |           |             |                                       |        |
|                       |  |           |               |          |                           |           |             | PROC. REF: AMM 28-10-00, AMM 28-10-00 |        |
|                       |  |           |               |          |                           |           |             | PKG:63,95                             |        |
| 570004                | INSPECT LEFT FLAP SKIN PROTECTION PANELS (IF FITTED)   |           |               |          |                           |           |             | Service                               | ATA:57 |
|                       | MOS/MSC  | 05-May-10 | N/R           |          |                           |           |             |                                       |        |
|                       | HRS  | 0         |               |          |                           |           |             |                                       |        |
| WC#: 57.140           | AFL  | 0         |               |          |                           |           |             |                                       |        |
| 570005 <sup>S</sup>   | DETAIL INSPECT RIGHT WING INTERNAL STRUCTURE OF THE WING IN THE AREA OF RIBS 0 TO 4  |           |               |          |                           |           |             | Service                               | ATA:57 |
|                       | MOS  | 25-Jul-24 | 24 (+2m/-2m)  |          |                           |           |             |                                       |        |
|                       | HRS  | 3908.4    |               |          |                           |           |             |                                       |        |
| WC#: 57.090           | AFL  | 1492      |               |          |                           |           |             |                                       |        |
|                       |  |           |               |          |                           |           |             | PROC. REF: AMM 28-10-00               |        |
|                       |  |           |               |          |                           |           |             | PKG:64,95                             |        |
| 570006                | INSPECT RIGHT FLAP SKIN PROTECTION PANELS (IF FITTED)  |           |               |          |                           |           |             | Service                               | ATA:57 |
|                       | MOS/MSC  | 05-May-10 | N/R           |          |                           |           |             |                                       |        |
|                       | HRS  | 0         |               |          |                           |           |             |                                       |        |
| WC#: 57.140           | AFL  | 0         |               |          |                           |           |             |                                       |        |
| 570007                | X-RAY WING BOTTOM SKINS AND STRINGERS BETWEEN THE FRONT AND REAR SPARS, RIB 0 TO RIB 1 AND BETWEEN THE CENTER SPAR AND REAR SPAR FROM RIB 1 TO RIB 4 |           |               |          |                           |           |             | Service                               | ATA:57 |
|                       | MOS  | 20-Jun-22 | 48 (+3m)      |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92) |                                       |        |
|                       | HRS  | 3511.6    |               |          |                           |           |             |                                       |        |
| WC#: 57.040           | AFL  | 1288      |               |          |                           |           |             |                                       |        |
|                       |  |           |               |          |                           |           |             | PROC. REF: NTM 57-30-05               |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit   | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition |        |
|---------------------------------------|--|-----------|---------------|----------|---------------------------|-----------|---------------|-------------|--------|
| ATA 57 - WINGS                        |  |           |               |          |                           |           |               |             |        |
| 570008                                | DETAIL INSPECT MAIN LANDING GEAR AND SIDESTAY ATTACHMENT FITTINGS                    |           |               |          |                           |           |               | Service     | ATA:57 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m)      |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)   |             |        |
|                                       | HRS  | 3511.6    |               |          |                           |           |               |             |        |
| WC#: 57.035                           | AFL  | 1288      |               |          |                           |           |               |             |        |
| 570009                                | DETAIL INSPECT WING BOTTOM SKIN (LH AND RH) ADJACENT TO FLAP OUTBOARD HINGE AT RIB 8 |           |               |          |                           |           |               | Service     | ATA:57 |
|                                       | MOS  | 05-May-10 |               |          |                           |           |               |             |        |
|                                       | HRS  | 0         | T:4800 (+10%) |          | 4800                      | 5280      | 891.6 (+480)  |             |        |
| WC#: 57.070                           | AFL  | 0         |               |          |                           |           |               |             |        |
| 570010                                | DETAIL INSPECT WING FRONT SPAR, FORWARD FACE   |           |               |          |                           |           |               | Service     | ATA:57 |
|                                       | MOS  | 06-Jun-18 | 96 (+3m)      | Adj -32d | 05-May-26                 | 05-Aug-26 | 645 d (+92)   |             |        |
|                                       | HRS  | 2965.25   | 4800 (+10%)   |          | 7765.25                   | 8245.25   | 3856.9 (+480) |             |        |
| WC#: 57.020                           | AFL  | 1073      |               |          |                           |           |               |             |        |
| PROC. REF: MMS 57-00-00, MMS 57-00-00 |  |           |               |          |                           |           |               |             |        |
| 570011                                | INSPECT WING REAR SPAR, REAR FACE  |           |               |          |                           |           |               | Service     | ATA:57 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m)      |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)   |             |        |
|                                       | HRS  | 3511.6    | 2400 (+10%)   |          | 5911.6                    | 6151.6    | 2003.2 (+240) |             |        |
| WC#: 57.030                           | AFL  | 1288      |               |          |                           |           |               |             |        |
| 570012                                | DETAIL INSPECT LEFT LOWER AIRBRAKE   |           |               |          |                           |           |               | Service     | ATA:57 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m)      |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)   |             |        |
|                                       | HRS  | 3511.6    | 2400 (+10%)   |          | 5911.6                    | 6151.6    | 2003.2 (+240) |             |        |
| WC#: 27.240                           | AFL  | 1288      |               |          |                           |           |               |             |        |
| 570012                                | DETAIL INSPECT LEFT UPPER AIRBRAKE   |           |               |          |                           |           |               | Service     | ATA:57 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m)      |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)   |             |        |
|                                       | HRS  | 3511.6    | 2400 (+10%)   |          | 5911.6                    | 6151.6    | 2003.2 (+240) |             |        |
| WC#: 27.240                           | AFL  | 1288      |               |          |                           |           |               |             |        |
| 570012                                | DETAIL INSPECT RIGHT LOWER AIRBRAKE  |           |               |          |                           |           |               | Service     | ATA:57 |
|                                       | MOS  | 20-Jun-22 | 48 (+3m)      |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)   |             |        |
|                                       | HRS  | 3511.6    | 2400 (+10%)   |          | 5911.6                    | 6151.6    | 2003.2 (+240) |             |        |
| WC#: 27.245                           | AFL  | 1288      |               |          |                           |           |               |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit  | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition |        |
|---------------------------------------|---|-----------|----------------|----------|---------------------------|-----------|----------------|-------------|--------|
| ATA 57 - WINGS                        |   |           |                |          |                           |           |                |             |        |
| 570012                                | DETAIL INSPECT RIGHT UPPER AIRBRAKE   |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS   | 20-Jun-22 | 48 (+3m)       |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)    |             |        |
|                                       | HRS   | 3511.6    | 2400 (+10%)    |          | 5911.6                    | 6151.6    | 2003.2 (+240)  |             |        |
| WC#: 27.245                           | AFL   | 1288      |                |          |                           |           |                |             |        |
| 570013                                | DETAIL INSPECT AILERONS   |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS   | 20-Jun-22 | 48 (+3m)       |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)    |             |        |
|                                       | HRS   | 3511.6    | 2400 (+10%)    |          | 5911.6                    | 6151.6    | 2003.2 (+240)  |             |        |
| WC#: 27.020                           | AFL   | 1288      |                |          |                           |           |                |             |        |
| PROC. REF: AMM NO REF 1               |   |           |                |          |                           |           |                |             |        |
| 570014                                | LUBRICATE CONNECTING RODS, AILERON TRIM AND SERVO TABS                            |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS   | 20-Jun-22 | 48 (+3m)       |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)    |             |        |
|                                       | HRS   | 3511.6    | 2400 (+10%)    |          | 5911.6                    | 6151.6    | 2003.2 (+240)  |             |        |
| WC#: 57.145                           | AFL   | 1288      |                |          |                           |           |                |             |        |
| PROC. REF: AMM 27-10-00               |   |           |                |          |                           |           |                |             |        |
| 570015                                | INSPECT/X RAY AILERONS  |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS   | 20-Jun-22 | 48 (+3m)       |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)    |             |        |
|                                       | HRS   | 3511.6    | 2400 (+10%)    |          | 5911.6                    | 6151.6    | 2003.2 (+240)  |             |        |
| WC#: 57.100                           | AFL   | 1288      |                |          |                           |           |                |             |        |
| PROC. REF: NTM 57-50-25               |   |           |                |          |                           |           |                |             |        |
| 570016                                | INSPECT/X RAY FLAPS AND FLAP VANES  |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS   | 20-Jun-22 | 48 (+3m)       |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)    |             |        |
|                                       | HRS   | 3511.6    | 2400 (+10%)    |          | 5911.6                    | 6151.6    | 2003.2 (+240)  |             |        |
| WC#: 57.130                           | AFL   | 1288      |                |          |                           |           |                |             |        |
| PROC. REF: NTM 57-50-15, NTM 57-50-20 |   |           |                |          |                           |           |                |             |        |
| 570017                                | DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO FRONT SPAR, BETWEEN RIBS 1 AND 7 |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS   | 05-May-10 |                |          |                           |           |                |             |        |
|                                       | HRS   | 0         | T:24000 (+500) |          | 24000                     | 24500     | 20091.6 (+500) |             |        |
| WC#: 57.055                           | AFL   | 0         |                |          |                           |           |                |             |        |
| PROC. REF: MMS 57-00-00               |   |           |                |          |                           |           |                |             |        |
| 570018                                | DETAIL INSPECT WING BOTTOM SKIN CENTERLINE JOINT STRAP                            |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS   | 05-May-10 |                |          |                           |           |                |             |        |
|                                       | HRS   | 0         | T:24000 (+500) |          | 24000                     | 24500     | 20091.6 (+500) |             |        |
| WC#: 57.080                           | AFL   | 0         |                |          |                           |           |                |             |        |
| PROC. REF: MMS 57-00-00               |   |           |                |          |                           |           |                |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining      | Disposition |        |
|---------------------------------------|--|-----------|----------------|----------|---------------------------|-----------|----------------|-------------|--------|
| ATA 57 - WINGS                        |  |           |                |          |                           |           |                |             |        |
| 570019                                | INSPECT/NDT UPPER SURFACE OF THE WING BOTTOM SKIN AT THE ATTACHMENT TO THE CENTERLINE JOINT ADJACENT TO RIB 0    |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS  | 05-May-10 |                |          |                           |           |                |             |        |
|                                       | HRS  | 0         | T:24000 (+500) |          | 24000                     | 24500     | 20091.6 (+500) |             |        |
| WC#: 57.060                           | AFL  | 0         |                |          |                           |           |                |             |        |
| PROC. REF: NTM 57-30-15, MMS 57-00-00 |  |           |                |          |                           |           |                |             |        |
| 570020                                | INSPECT/NDT WING BOTTOM SKIN CENTERLINE BUTT STRAP AND CENTER SECTION BEAMS (24 POSITIONS)                       |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS  | 05-May-10 |                |          |                           |           |                |             |        |
|                                       | HRS  | 0         | T:24000 (+500) |          | 24000                     | 24500     | 20091.6 (+500) |             |        |
| WC#: 57.075                           | AFL  | 0         |                |          |                           |           |                |             |        |
| PROC. REF: NTM 57-00-10               |  |           |                |          |                           |           |                |             |        |
| 570021                                | DETAIL INSPECT WING TOP SKIN IN THE AREA THAT IS COVERED BY THE FUSELAGE STRUCTURE AND MAIN ATTACHMENT BRACKETS. |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS/MSC  | 05-May-10 | A/R            |          |                           |           |                |             |        |
|                                       | HRS  | 0         |                |          |                           |           |                |             |        |
| WC#: 57.010                           | AFL  | 0         |                |          |                           |           |                |             |        |
| 570022                                | DETAIL INSPECT REAR SPAR, REAR FACE BETWEEN RIB 1 LH AND RIB 1 RH  |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS  | 05-May-10 |                |          |                           |           |                |             |        |
|                                       | HRS  | 0         | 4800 (+10%)    |          | 4800                      | 5280      | 891.6 (+480)   |             |        |
| WC#: 57.050                           | AFL  | 0         |                |          |                           |           |                |             |        |
| PROC. REF: MMS 57-00-00               |  |           |                |          |                           |           |                |             |        |
| 570023                                | INSPECT/NDT AILERON HORN BALANCE WEIGHT  |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS/MSC  | 05-May-10 | N/R            |          |                           |           |                |             |        |
|                                       | HRS  | 0         |                |          |                           |           |                |             |        |
| WC#: 57.135                           | AFL  | 0         |                |          |                           |           |                |             |        |
| PROC. REF: NTM 57-50-25, MMS 57-00-00 |  |           |                |          |                           |           |                |             |        |
| 570024                                | DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO RIB 1 LH AND RH   |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS  | 05-May-10 |                |          |                           |           |                |             |        |
|                                       | HRS  | 0         | T:12000 (+500) |          | 12000                     | 12500     | 8091.6 (+500)  |             |        |
| WC#: 57.065                           | AFL  | 0         |                |          |                           |           |                |             |        |
| PROC. REF: MMS 57-00-00               |  |           |                |          |                           |           |                |             |        |
| 570025                                | DETAIL INSPECT WING BOTTOM SKIN AT ATTACHMENT TO THE REAR SPAR, BETWEEN RIB 1 LH AND RIB 1 RH                    |           |                |          |                           |           |                | Service     | ATA:57 |
|                                       | MOS  | 05-May-10 |                |          |                           |           |                |             |        |
|                                       | HRS  | 0         | 4800 (+10%)    |          | 4800                      | 5280      | 891.6 (+480)   |             |        |
| WC#: 57.050                           | AFL  | 0         |                |          |                           |           |                |             |        |
| PROC. REF: MMS 57-00-00               |  |           |                |          |                           |           |                |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit   | C/W       | Interval     | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition |        |
|---------------------------|--|-----------|--------------|----------|---------------------------|-----------|---------------|-------------|--------|
| ATA 57 - WINGS            |  |           |              |          |                           |           |               |             |        |
| 570026                    | INSPECT WING LEADING EDGES   |           |              |          |                           |           |               | Service     | ATA:57 |
|                           | MOS  | 20-Jun-22 | 48 (+3m)     |          | 20-Jun-26                 | 20-Sep-26 | 691 d (+92)   |             |        |
|                           | HRS  | 3511.6    |              |          |                           |           |               |             |        |
| WC#: 57.025               | AFL  | 1288      |              |          |                           |           |               |             |        |
| 570027                    | DETAIL INSPECT WING INTERNAL STRUCTURE FORWARD OF THE CENTER SPAR INCLUDING THE FRONT AND CENTER SPARS FROM RIBS 0 TO 4, AND BETWEEN AND INCLUDING THE FRONT AND REAR SPARS FROM RIB 4 TO THE WING TIP |           |              |          |                           |           |               | Service     | ATA:57 |
|                           | MOS  | 06-Jun-18 | 96 (+3m)     | Adj -32d | 05-May-26                 | 05-Aug-26 | 645 d (+92)   |             |        |
|                           | HRS  | 2965.25   | 4800 (+10%)  |          | 7765.25                   | 8245.25   | 3856.9 (+480) |             |        |
| WC#: 57.045               | AFL  | 1073      |              |          |                           |           |               |             |        |
| PROC. REF: AMM 28-10-00   |  |           |              |          |                           |           |               |             |        |
| 570028                    | INSPECT AILERON AT OUTBOARD HINGE CASTING  |           |              |          |                           |           |               | Service     | ATA:57 |
|                           | MOS/MSC  | 05-May-10 | N/R          |          |                           |           |               |             |        |
|                           | HRS  | 0         |              |          |                           |           |               |             |        |
| WC#: 57.125               | AFL  | 0         |              |          |                           |           |               |             |        |
| 570029                    | VISUALLY INSPECT WING OUTER, UPPER AND LOWER SKINS   |           |              |          |                           |           |               | Service     | ATA:57 |
|                           | MOS  | 10-Oct-23 |              |          |                           |           |               |             |        |
|                           | HRS  | 3810.8    | 300 (+10%)   |          | 4110.8                    | 4140.8    | 202.4 (+30)   |             |        |
| WC#: 57.155               | AFL  | 1442      |              |          |                           |           |               |             |        |
| 570030 <sup>S</sup>       | INSPECT LEFT WING RIB 16 AND SPAR FITTING WHERE THE WINGLET IS ATTACHED TO THE WING  |           |              |          |                           |           |               | Service     | ATA:57 |
|                           | MOS  | 25-Jul-24 | 24 (+2m/-2m) |          |                           |           |               |             |        |
|                           | HRS  | 3908.4    |              |          |                           |           |               |             |        |
|                           | AFL  | 1492      |              |          |                           |           |               |             |        |
| PKG:63,95                 |  |           |              |          |                           |           |               |             |        |
| 570031 <sup>S</sup>       | INSPECT RIGHT WING RIB 16 AND SPAR FITTING WHERE THE WINGLET IS ATTACHED TO THE WING   |           |              |          |                           |           |               | Service     | ATA:57 |
|                           | MOS  | 25-Jul-24 | 24 (+2m/-2m) |          |                           |           |               |             |        |
|                           | HRS  | 3908.4    |              |          |                           |           |               |             |        |
|                           | AFL  | 1492      |              |          |                           |           |               |             |        |
| PKG:64,95                 |  |           |              |          |                           |           |               |             |        |
| 571010                    | WING   |           |              |          |                           |           |               | Component   | ATA:57 |
| PN:25-8WA7-6001           | MOS/MSC  | 16-Mar-10 | O/C          | TSN 0    |                           |           |               |             |        |
| SN:259159                 | HRS  | 0         |              | TSN 0    |                           |           |               |             |        |
| WC#: 57.010               | AFL  | 0         |              | TSN 0    |                           |           |               |             |        |
| PROC. REF: GENERIC NO REF |  |           |              |          |                           |           |               |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                     | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-----------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 57 - WINGS</b>       |  |           |          |          |                           |           |           |             |        |
| 571109                      | REPLACE LEFT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS  |           |          |          |                           |           |           | Service     | ATA:57 |
|                             | MOS  | 16-Mar-10 |          |          |                           |           |           | LIFE LIMIT  |        |
|                             | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 57.150                 | AFL  | 0         | 14600    |          | 14600                     |           | 13108     |             |        |
| 571110                      | REPLACE RIGHT FLAP HINGE ATTACHMENT ANGLES TO MAIN LANDING GEAR MOUNTING FITTING BOLTS |           |          |          |                           |           |           | Service     | ATA:57 |
|                             | MOS  | 16-Mar-10 |          |          |                           |           |           | LIFE LIMIT  |        |
|                             | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 57.150                 | AFL  | 0         | 14600    |          | 14600                     |           | 13108     |             |        |
| 574001                      | LEFT LEADING EDGE ASSEMBLY   |           |          |          |                           |           |           | Component   | ATA:57 |
| PN:25-8WS3299-3A            | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:CAV09K048                | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 57.085                 | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF   |  |           |          |          |                           |           |           |             |        |
| 574002                      | RIGHT LEADING EDGE ASSEMBLY  |           |          |          |                           |           |           | Component   | ATA:57 |
| PN:25-8WS3299-4A            | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:CAV09K043                | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 57.085                 | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF   |  |           |          |          |                           |           |           |             |        |
| <b>ATA 71 - POWER PLANT</b> |  |           |          |          |                           |           |           |             |        |
| 710049                      | COMPRESSOR WASH NO. 1 ENGINE   |           |          |          |                           |           |           | Service     | ATA:71 |
|                             | MOS/MSC  | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
|                             | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 71.025                 | AFL  | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM      |  |           |          |          |                           |           |           |             |        |
| 710050                      | COMPRESSOR WASH NO. 2 ENGINE   |           |          |          |                           |           |           | Service     | ATA:71 |
|                             | MOS/MSC  | 16-Mar-10 | O/C      |          |                           |           |           |             |        |
|                             | HRS  | 0         |          |          |                           |           |           |             |        |
| WC#: 71.025                 | AFL  | 0         |          |          |                           |           |           |             |        |
| PROC. REF: GENERIC CMM      |  |           |          |          |                           |           |           |             |        |
| 710081                      | NO. 1 ENGINE INLET COWL  |           |          |          |                           |           |           | Component   | ATA:71 |
| PN:716RA0001-3              | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:102995700005             | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 71.055                 | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 71-10-00     |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                     | Unit   | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition |        |
|-----------------------------|--|-----------|-------------|----------|---------------------------|-----------|---------------|-------------|--------|
| <b>ATA 71 - POWER PLANT</b> |  |           |             |          |                           |           |               |             |        |
| 710082                      | NO. 2 ENGINE INLET COWL                        |           |             |          |                           |           |               | Component   | ATA:71 |
| PN:716RA0001-3              | MOS/MSC  | 16-Mar-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:102995700006             | HRS  | 0         |             | TSN 0    |                           |           |               |             |        |
| WC#: 71.055                 | AFL  | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: AMM 71-10-00     |  |           |             |          |                           |           |               |             |        |
| 710083                      | NO. 1 ENGINE UPPER FAN COWL DOOR               |           |             |          |                           |           |               | Component   | ATA:71 |
| PN:711RA0005-2              | MOS/MSC  | 16-Mar-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:080APN600024             | HRS  | 0         |             | TSN 0    |                           |           |               |             |        |
| WC#: 71.060                 | AFL  | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: AMM 71-10-00     |  |           |             |          |                           |           |               |             |        |
| 710084                      | NO. 2 ENGINE UPPER FAN COWL DOOR               |           |             |          |                           |           |               | Component   | ATA:71 |
| PN:711RA0006-2              | MOS/MSC  | 16-Mar-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:070APN600019             | HRS  | 0         |             | TSN 0    |                           |           |               |             |        |
| WC#: 71.060                 | AFL  | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: AMM 71-10-00     |  |           |             |          |                           |           |               |             |        |
| 710089                      | NO. 1 ENGINE LOWER FAN COWL DOOR               |           |             |          |                           |           |               | Component   | ATA:71 |
| PN:711RA0003-2              | MOS/MSC  | 16-Mar-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:080APN600024             | HRS  | 0         |             | TSN 0    |                           |           |               |             |        |
| WC#: 71.070                 | AFL  | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: AMM 71-10-00     |  |           |             |          |                           |           |               |             |        |
| 710090                      | NO. 2 ENGINE LOWER FAN COWL DOOR               |           |             |          |                           |           |               | Component   | ATA:71 |
| PN:711RA0004-2              | MOS/MSC  | 16-Mar-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:080APN600023             | HRS  | 0         |             | TSN 0    |                           |           |               |             |        |
| WC#: 71.070                 | AFL  | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: AMM 71-10-00     |  |           |             |          |                           |           |               |             |        |
| 710120                      | NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI) |           |             |          |                           |           |               | Service     | ATA:71 |
|                             | MOS  | 04-Dec-17 |             |          |                           |           |               |             |        |
|                             | HRS  | 2853.82   | 3000 (+100) |          | (5853.82)<br>5866.92      | 5953.82   | 1958.5 (+100) |             |        |
|                             | ENC  | 1031      |             |          |                           |           |               |             |        |
| PROC. REF: LMM 72-00-00     |  |           |             |          |                           |           |               |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                     | Unit   | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition |        |
|-----------------------------|--|-----------|-------------|----------|---------------------------|-----------|---------------|-------------|--------|
| <b>ATA 71 - POWER PLANT</b> |  |           |             |          |                           |           |               |             |        |
| 710120                      | NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)       |           |             |          |                           |           |               | Service     | ATA:71 |
|                             | MOS  | 28-Nov-17 |             |          |                           |           |               |             |        |
|                             | HRS  | 2853.82   | 3000 (+100) |          | (5853.82)<br>5866.92      | 5953.82   | 1958.5 (+100) |             |        |
|                             | ENC  | 1031      |             |          |                           |           |               |             |        |
|                             |  |           |             |          | PROC. REF: LMM 72-00-00   |           |               |             |        |
| 710130 <sup>S</sup>         | NO. 1 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY |           |             |          |                           |           |               | Service     | ATA:71 |
|                             | MOS  | 20-Jun-22 |             |          |                           |           |               |             |        |
|                             | HRS  | 3498.5    | 850         |          |                           |           |               |             |        |
|                             | ENC  | 1274      |             |          |                           |           |               |             |        |
|                             |  |           |             |          | PROC. REF: LMM 72-50-04   |           |               | PKG:3       |        |
| 710130 <sup>S</sup>         | NO. 2 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY |           |             |          |                           |           |               | Service     | ATA:71 |
|                             | MOS  | 20-Jun-22 |             |          |                           |           |               |             |        |
|                             | HRS  | 3498.5    | 850         |          |                           |           |               |             |        |
|                             | ENC  | 1274      |             |          |                           |           |               |             |        |
|                             |  |           |             |          | PROC. REF: LMM 72-50-04   |           |               | PKG:3       |        |
| 710140 <sup>S</sup>         | NO. 1 ENGINE - INSPECT INLET/FAN AREA                |           |             |          |                           |           |               | Service     | ATA:71 |
|                             | MOS  | 20-Jun-22 |             |          |                           |           |               |             |        |
|                             | HRS  | 3498.5    | 850         |          |                           |           |               |             |        |
|                             | ENC  | 1274      |             |          |                           |           |               |             |        |
|                             |  |           |             |          | PROC. REF: LMM 72-00-00   |           |               | PKG:3       |        |
| 710140 <sup>S</sup>         | NO. 2 ENGINE - INSPECT INLET/FAN AREA                |           |             |          |                           |           |               | Service     | ATA:71 |
|                             | MOS  | 20-Jun-22 |             |          |                           |           |               |             |        |
|                             | HRS  | 3498.5    | 850         |          |                           |           |               |             |        |
|                             | ENC  | 1274      |             |          |                           |           |               |             |        |
|                             |  |           |             |          | PROC. REF: LMM 72-00-00   |           |               | PKG:3       |        |
| 712001                      | NO. 1 ENGINE MOUNTING                                |           |             |          |                           |           |               | Component   | ATA:71 |
| PN:PN                       | MOS/MSC  | 16-Mar-10 | O/C         |          | TSN 0                     |           |               |             |        |
| SN:UNKNOWN                  | HRS  | 0         |             |          | TSN 0                     |           |               |             |        |
| WC#: 71.075                 | AFL  | 0         |             |          | TSN 0                     |           |               |             |        |
|                             |  |           |             |          | PROC. REF: AMM 71-20-00   |           |               |             |        |
| 712002                      | NO. 2 ENGINE MOUNTING                                |           |             |          |                           |           |               | Component   | ATA:71 |
| PN:PN                       | MOS/MSC  | 16-Mar-10 | O/C         |          | TSN 0                     |           |               |             |        |
| SN:UNKNOWN                  | HRS  | 0         |             |          | TSN 0                     |           |               |             |        |
| WC#: 71.080                 | AFL  | 0         |             |          | TSN 0                     |           |               |             |        |
|                             |  |           |             |          | PROC. REF: AMM 71-20-00   |           |               |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                     | Unit   | C/W       | Interval                                 | TSX/Adj.    | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition      |
|-----------------------------|--|-----------|--|-------------|---------------------------|-----------|---------------|------------------|
| <b>ATA 71 - POWER PLANT</b> |  |           |  |             |                           |           |               |                  |
| 714010 <sup>S</sup>         | NO. 1 ENGINE - VISUALLY  |           | INSPECT ELECTRICAL WIRES AND CONNECTIONS |             |                           |           |               | Service ATA:71   |
|                             | MOS  | 20-Jun-22 |  |             |                           |           |               |                  |
|                             | HRS  | 3498.5    | 850                                      |             |                           |           |               |                  |
|                             | ENC  | 1274      |  |             |                           |           |               |                  |
|                             |  |           |  |             | PROC. REF: LMM 70-00-00   |           |               | PKG:3            |
| 714010 <sup>S</sup>         | NO. 2 ENGINE - VISUALLY  |           | INSPECT ELECTRICAL WIRES AND CONNECTIONS |             |                           |           |               | Service ATA:71   |
|                             | MOS  | 20-Jun-22 |  |             |                           |           |               |                  |
|                             | HRS  | 3498.5    | 850                                      |             |                           |           |               |                  |
|                             | ENC  | 1274      |  |             |                           |           |               |                  |
|                             |  |           |  |             | PROC. REF: LMM 70-00-00   |           |               | PKG:3            |
| 715010 <sup>S</sup>         | NO. 1 ENGINE - VISUALLY  |           | INSPECT PLUMBING LINES AND CONNECTIONS   |             |                           |           |               | Service ATA:71   |
|                             | MOS  | 20-Jun-22 |  |             |                           |           |               |                  |
|                             | HRS  | 3498.5    | 850                                      |             |                           |           |               |                  |
|                             | ENC  | 1274      |  |             |                           |           |               |                  |
|                             |  |           |  |             | PROC. REF: LMM 70-00-00   |           |               | PKG:3            |
| 715010 <sup>S</sup>         | NO. 2 ENGINE - VISUALLY  |           | INSPECT PLUMBING LINES AND CONNECTIONS   |             |                           |           |               | Service ATA:71   |
|                             | MOS  | 20-Jun-22 |  |             |                           |           |               |                  |
|                             | HRS  | 3498.5    | 850                                      |             |                           |           |               |                  |
|                             | ENC  | 1274      |  |             |                           |           |               |                  |
|                             |  |           |  |             | PROC. REF: LMM 70-00-00   |           |               | PKG:3            |
| 71EN1                       | NO. 1 ENGINE   |           |  |             |                           |           |               | Component ATA:71 |
| PN:3060090-1                | MOS/MSC  | 19-Dec-17 | E/C                                      |             |                           |           |               |                  |
| SN:P122372                  | HRS  | 2886.88   |  | TSN 2853.82 |                           |           |               |                  |
| WC#: 71.EN1                 | AFL  | 1043      |  |             |                           |           |               |                  |
|                             |  |           |  |             | PROC. REF: AMM 71-00-01   |           |               |                  |
| 71EN2                       | NO. 2 ENGINE   |           |  |             |                           |           |               | Component ATA:71 |
| PN:3060090-1                | MOS/MSC  | 19-Dec-17 | E/C                                      |             |                           |           |               |                  |
| SN:P122371                  | HRS  | 2886.88   |  | TSN 2853.82 |                           |           |               |                  |
| WC#: 71.EN2                 | AFL  | 1043      |  |             |                           |           |               |                  |
|                             |  |           |  |             | PROC. REF: AMM 71-00-01   |           |               |                  |
| <b>ATA 72 - ENGINE</b>      |  |           |  |             |                           |           |               |                  |
| 720002                      | INSPECT NO. 1 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT |           |  |             |                           |           |               | Service ATA:72   |
|                             | MOS  | 16-Oct-17 |  |             |                           |           |               | PART OF MPI      |
|                             | HRS  | 2853.82   | 3000 (+10%)                              |             | 5853.82                   | 6153.82   | 1945.4 (+300) |                  |
| WC#: 72.030                 | AFL  | 1031      |  |             |                           |           |               |                  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                | Unit   | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition |        |
|------------------------|--|-----------|-------------|----------|---------------------------|-----------|---------------|-------------|--------|
| <b>ATA 72 - ENGINE</b> |  |           |             |          |                           |           |               |             |        |
| 720002                 | INSPECT NO. 2 ENGINE AFT COWLING/INNER FAN DUCT AND EXHAUST DUCT |           |             |          |                           |           |               | Service     | ATA:72 |
|                        | MOS  | 19-Dec-17 |             |          |                           |           |               | PART OF MPI |        |
|                        | HRS  | 2886.88   | 3000 (+10%) |          | 5886.88                   | 6186.88   | 1978.5 (+300) |             |        |
| WC#: 72.030            | AFL  | 1043      |             |          |                           |           |               |             |        |
| 720003                 | DETAIL INSPECT NO. 1 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP  |           |             |          |                           |           |               | Service     | ATA:72 |
|                        | MOS  | 16-Oct-17 |             |          |                           |           |               | PART OF MPI |        |
|                        | HRS  | 2853.82   | 3000 (+10%) |          | 5853.82                   | 6153.82   | 1945.4 (+300) |             |        |
| WC#: 72.040            | AFL  | 1031      |             |          |                           |           |               |             |        |
| 720003                 | DETAIL INSPECT NO. 2 ENGINE EXHAUST NOZZLE/EXHAUST PIPE V CLAMP  |           |             |          |                           |           |               | Service     | ATA:72 |
|                        | MOS  | 16-Oct-17 |             |          |                           |           |               | PART OF MPI |        |
|                        | HRS  | 2853.82   | 3000 (+10%) |          | 5853.82                   | 6153.82   | 1945.4 (+300) |             |        |
| WC#: 72.040            | AFL  | 1031      |             |          |                           |           |               |             |        |
| 720110                 | NO. 1 ENGINE - ACCESSORY GEARBOX                                 |           |             |          |                           |           |               | Component   | ATA:72 |
| PN:3060827-2           | MOS/MSC  | 18-Feb-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:S-3474              | HRS  | 0         |             | TSN 0    |                           |           |               |             |        |
|                        | ENC  | 0         |             | TSN 0    |                           |           |               |             |        |
|                        | PROC. REF: LMM 05-10-01, LMM 72-60-02                            |           |             |          |                           |           |               |             |        |
| 720110                 | NO. 2 ENGINE - ACCESSORY GEARBOX                                 |           |             |          |                           |           |               | Component   | ATA:72 |
| PN:3060827-2           | MOS/MSC  | 18-Feb-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:S-3437              | HRS  | 0         |             | TSN 0    |                           |           |               |             |        |
|                        | ENC  | 0         |             | TSN 0    |                           |           |               |             |        |
|                        | PROC. REF: LMM 05-10-01, LMM 72-60-02                            |           |             |          |                           |           |               |             |        |
| 720210                 | NO. 1 ENGINE - CHECK AUTO-IGNITION                               |           |             |          |                           |           |               | Service     | ATA:72 |
|                        | DAYS/MSC   | 16-Oct-17 | N/A         |          |                           |           |               |             |        |
|                        | HRS  | 2820.75   |             |          |                           |           |               |             |        |
|                        | ENC  | 1019      |             |          |                           |           |               |             |        |
|                        | PROC. REF: LMM 72-00-00  |           |             |          |                           |           |               |             |        |
| 720210                 | NO. 2 ENGINE - CHECK AUTO-IGNITION                               |           |             |          |                           |           |               | Service     | ATA:72 |
|                        | DAYS/MSC   | 16-Oct-17 | N/A         |          |                           |           |               |             |        |
|                        | HRS  | 2820.75   |             |          |                           |           |               |             |        |
|                        | ENC  | 1019      |             |          |                           |           |               |             |        |
|                        | PROC. REF: LMM 72-00-00  |           |             |          |                           |           |               |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN             | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 72 - ENGINE     |  |           |          |          |                           |           |           |             |        |
| 721001              | NO. 1 ENGINE - PRESERVATION OF ENGINE            |           |          |          |                           |           |           | Service     | ATA:72 |
|                     | MOS/MSC  | 18-Feb-10 | O/C      |          |                           |           |           |             |        |
|                     | HRS  | 0         |          |          |                           |           |           |             |        |
|                     | ENC  | 0         |          |          |                           |           |           |             |        |
|                     |  |           |          |          | PROC. REF: LMM 72-00-00   |           |           |             |        |
| 721001              | NO. 2 ENGINE - PRESERVATION OF ENGINE            |           |          |          |                           |           |           | Service     | ATA:72 |
|                     | MOS/MSC  | 18-Feb-10 | O/C      |          |                           |           |           |             |        |
|                     | HRS  | 0         |          |          |                           |           |           |             |        |
|                     | ENC  | 0         |          |          |                           |           |           |             |        |
|                     |  |           |          |          | PROC. REF: LMM 72-00-00   |           |           |             |        |
| 721002              | NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK |           |          |          |                           |           |           | Service     | ATA:72 |
|                     | MOS/MSC  | 18-Feb-10 | O/C      |          |                           |           |           |             |        |
|                     | HRS  | 0         |          |          |                           |           |           |             |        |
|                     | ENC  | 0         |          |          |                           |           |           |             |        |
|                     |  |           |          |          | PROC. REF: LMM 72-00-00   |           |           |             |        |
| 721002              | NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK |           |          |          |                           |           |           | Service     | ATA:72 |
|                     | MOS/MSC  | 18-Feb-10 | O/C      |          |                           |           |           |             |        |
|                     | HRS  | 0         |          |          |                           |           |           |             |        |
|                     | ENC  | 0         |          |          |                           |           |           |             |        |
|                     |  |           |          |          | PROC. REF: LMM 72-00-00   |           |           |             |        |
| 721003              | NO. 1 ENGINE - DE-PRESERVATION OF ENGINE         |           |          |          |                           |           |           | Service     | ATA:72 |
|                     | MOS/MSC  | 18-Feb-10 | O/C      |          |                           |           |           |             |        |
|                     | HRS  | 0         |          |          |                           |           |           |             |        |
|                     | ENC  | 0         |          |          |                           |           |           |             |        |
|                     |  |           |          |          | PROC. REF: LMM 72-00-00   |           |           |             |        |
| 721003              | NO. 2 ENGINE - DE-PRESERVATION OF ENGINE         |           |          |          |                           |           |           | Service     | ATA:72 |
|                     | MOS/MSC  | 18-Feb-10 | O/C      |          |                           |           |           |             |        |
|                     | HRS  | 0         |          |          |                           |           |           |             |        |
|                     | ENC  | 0         |          |          |                           |           |           |             |        |
|                     |  |           |          |          | PROC. REF: LMM 72-00-00   |           |           |             |        |
| 723010 <sup>S</sup> | NO. 1 ENGINE - CHECK CARBON SEAL HEALTH          |           |          |          |                           |           |           | Service     | ATA:72 |
|                     | MOS  | 04-Dec-17 |          |          |                           |           |           |             |        |
|                     | HRS  | 2853.82   | 1650     |          |                           |           |           |             |        |
|                     | ENC  | 1031      |          |          |                           |           |           |             |        |
|                     |  |           |          |          | PROC. REF: LMM 72-00-00   |           |           | PKG:5       |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit   | C/W       | Interval | TSX/Adj.           | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|--|-----------|----------|--------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 72 - ENGINE</b>    |  |           |          |                    |                           |           |           |             |        |
| 723010 <sup>S</sup>       | NO. 2 ENGINE - CHECK CARBON SEAL HEALTH          |           |          |                    |                           |           |           | Service     | ATA:72 |
|                           | MOS  | 28-Nov-17 |          |                    |                           |           |           |             |        |
|                           | HRS  | 2853.82   | 1650     |                    |                           |           |           |             |        |
|                           | ENC  | 1031      |          |                    |                           |           |           |             |        |
| PROC. REF: LMM 72-00-00   |  |           |          |                    |                           |           |           | PKG:5       |        |
| 725010                    | NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC |           |          |                    |                           |           |           | Component   | ATA:72 |
| PN:3060625-1              | MOS  | 18-Feb-10 |          | TSN 0              |                           |           |           | LIFE LIMIT  |        |
| SN:08-03229-04509         | HRS  | 0         |          | TSN 0              |                           |           |           |             |        |
|                           | ENC  | 0         | 12000    | TSN 0              | (12000)<br>12014          |           | 10522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |                    |                           |           |           |             |        |
| 725010                    | NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC |           |          |                    |                           |           |           | Component   | ATA:72 |
| PN:3060625-1              | MOS  | 18-Feb-10 |          | TSN 0              |                           |           |           | LIFE LIMIT  |        |
| SN:08-03229-04568         | HRS  | 0         |          | TSN 0              |                           |           |           |             |        |
|                           | ENC  | 0         | 12000    | TSN 0              | (12000)<br>12014          |           | 10522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |                    |                           |           |           |             |        |
| 725020                    | NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC |           |          |                    |                           |           |           | Component   | ATA:72 |
| PN:3060611-1              | MOS  | 04-Dec-17 |          | TSR 0              |                           |           |           | LIFE LIMIT  |        |
| SN:08-03229-02954         | HRS  | 2853.82   |          | TSN 2853.82, TSR 0 |                           |           |           |             |        |
|                           | ENC  | 1031      | 12000    | TSN 1031, TSR 0    | (12000)<br>12014          |           | 10522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |                    |                           |           |           |             |        |
| 725020                    | NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC |           |          |                    |                           |           |           | Component   | ATA:72 |
| PN:3060611-1              | MOS  | 28-Nov-17 |          | TSO 0              |                           |           |           | LIFE LIMIT  |        |
| SN:08-03229-02927         | HRS  | 2853.82   |          | TSN 2853.82        |                           |           |           |             |        |
|                           | ENC  | 1031      | 12000    | TSN 1031           | (12000)<br>12014          |           | 10522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |                    |                           |           |           |             |        |
| 725030                    | NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC |           |          |                    |                           |           |           | Component   | ATA:72 |
| PN:3060671-2              | MOS  | 18-Feb-10 |          | TSN 0              |                           |           |           | LIFE LIMIT  |        |
| SN:08-03229-01920         | HRS  | 0         |          | TSN 0              |                           |           |           |             |        |
|                           | ENC  | 0         | 12000    | TSN 0              | (12000)<br>12014          |           | 10522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |                    |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 72 - ENGINE</b>    |  |           |          |          |                           |           |           |             |        |
| 725030                    | NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC                   |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060671-2              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:08-03229-01943         | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 12000    | TSN 0    | (12000)<br>12014          |           | 10522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725040                    | NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC                          |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060841-1              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:09-156111-00182        | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 10000    | TSN 0    | (10000)<br>10014          |           | 8522      |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725040                    | NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC                          |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060841-1              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:08-12172-00219         | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 10000    | TSN 0    | (10000)<br>10014          |           | 8522      |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725050                    | NO. 1 ENGINE - FAN DISC  |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060241-1              | MOS  | 05-May-10 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:08-13651-02952         | HRS  | 4.7       |          | TSN 11.9 |                           |           |           |             |        |
|                           | ENC  | 4         | 20000    | TSN 11   | (19993)<br>20007          |           | 18515     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725050                    | NO. 2 ENGINE - FAN DISC  |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060241-1              | MOS  | 05-May-10 |          |          |                           |           |           | LIFE LIMIT  |        |
| SN:08-13651-02953         | HRS  | 4.7       |          | TSN 11.9 |                           |           |           |             |        |
|                           | ENC  | 4         | 20000    | TSN 11   | (19993)<br>20007          |           | 18515     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725060                    | NO. 1 ENGINE - CHANGE 1ST STAGE LOW PRESSURE AXIAL COMPRESSOR DISC |           |          |          |                           |           |           | Service     | ATA:72 |
|                           | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
|                           | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 10000    | TSN 0    | (10000)<br>10014          |           | 8522      |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 72 - ENGINE</b>    |  |           |          |          |                           |           |           |             |        |
| 725060                    | NO. 2 ENGINE - CHANGE 1ST STAGE LOW PRESSURE AXIAL COMPRESSOR DISC |           |          |          |                           |           |           | Service     | ATA:72 |
|                           | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
|                           | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 10000    | TSN 0    | (10000)<br>10014          |           | 8522      |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725070                    | NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC                |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3075839-1              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:080316001581           | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 20000    | TSN 0    | (20000)<br>20014          |           | 18522     |             |        |
|                           | (AFL)  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725070                    | NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC                |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3075839-1              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:080316001539           | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 20000    | TSN 0    | (20000)<br>20014          |           | 18522     |             |        |
|                           | (AFL)  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725080                    | NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC                |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060374-1              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:080316000372           | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 20000    | TSN 0    | (20000)<br>20014          |           | 18522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725080                    | NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC                |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060374-1              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:080316000368           | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 20000    | TSN 0    | (20000)<br>20014          |           | 18522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 72 - ENGINE</b>                                |   |           |          |          |                           |           |           |             |        |
| 725090  | NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3075326-5  | MOS   | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:08-03501-20190                                     | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         | 20000    | TSN 0    | (20000)<br>20014          |           | 18522     |             |        |
| PROC. REF: GENERIC NO REF                             |   |           |          |          |                           |           |           |             |        |
| 725090  | NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3075326-5  | MOS   | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:08-03501-20376                                     | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         | 20000    | TSN 0    | (20000)<br>20014          |           | 18522     |             |        |
| PROC. REF: GENERIC NO REF                             |   |           |          |          |                           |           |           |             |        |
| 725110  | NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD      |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3074744-1  | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:09P17731   | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF, LMM 72-30-10, LMM 72-30-10 |   |           |          |          |                           |           |           |             |        |
| 725110  | NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD      |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3074744-1  | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:09P17732   | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF, LMM 72-30-10, LMM 72-30-10 |   |           |          |          |                           |           |           |             |        |
| 725120  | NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER    |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060371-1  | MOS   | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:09-162246-02226                                    | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         | 8000     | TSN 0    | (8000)<br>8014            |           | 6522      |             |        |
| PROC. REF: GENERIC NO REF                             |   |           |          |          |                           |           |           |             |        |
| 725120  | NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER    |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060371-1  | MOS   | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:09-162246-02225                                    | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         | 8000     | TSN 0    | (8000)<br>8014            |           | 6522      |             |        |
| PROC. REF: GENERIC NO REF                             |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 72 - ENGINE</b>    |  |           |          |          |                           |           |           |             |        |
| 725130                    | NO. 1 ENGINE - FAN SPINNER                                 |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060242-2              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:09-5060-00133          | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 20000    | TSN 0    | (20000)<br>20014          |           | 18522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725130                    | NO. 2 ENGINE - FAN SPINNER                                 |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060242-2              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:09-5060-00130          | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 20000    | TSN 0    | (20000)<br>20014          |           | 18522     |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725140                    | NO. 1 ENGINE - FAN DRIVE SHAFT                             |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060291-2              | MOS/MSC  | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:08-13663-06778         | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725140                    | NO. 2 ENGINE - FAN DRIVE SHAFT                             |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060291-2              | MOS/MSC  | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:08-13663-06810         | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725160                    | NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060698-1              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:08-03501-19838         | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 7000     | TSN 0    | (7000)<br>7014            |           | 5522      |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 725160                    | NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060698-1              | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:08-03501-19594         | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC  | 0         | 7000     | TSN 0    | (7000)<br>7014            |           | 5522      |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                 | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 72 - ENGINE</b>                  |  |           |          |          |                           |           |           |             |        |
| 725170                                  | NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060366-3                            | MOS/MSC  | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:10P18025                             | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF               |  |           |          |          |                           |           |           |             |        |
| 725170                                  | NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060366-3                            | MOS/MSC  | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:10P18026                             | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF               |  |           |          |          |                           |           |           |             |        |
| 725180                                  | NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE            |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060534-4                            | MOS/MSC  | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:09P06915                             | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF, LMM 72-40-04 |  |           |          |          |                           |           |           |             |        |
| 725180                                  | NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE            |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060534-4                            | MOS/MSC  | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:09P06916                             | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF, LMM 72-40-04 |  |           |          |          |                           |           |           |             |        |
| 725210                                  | NO. 1 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE  |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060514-1                            | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:08-03229-04890                       | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC  | 0         | 10000    | TSN 0    | (10000)<br>10014          |           | 8522      |             |        |
| PROC. REF: GENERIC NO REF               |  |           |          |          |                           |           |           |             |        |
| 725210                                  | NO. 2 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE  |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060514-1                            | MOS  | 18-Feb-10 |          | TSN 0    |                           |           |           | LIFE LIMIT  |        |
| SN:08-03229-04851                       | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC  | 0         | 10000    | TSN 0    | (10000)<br>10014          |           | 8522      |             |        |
| PROC. REF: GENERIC NO REF               |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 72 - ENGINE</b>    |   |           |          |          |                           |           |           |             |        |
| 725220                    | NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT           |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060694-7              | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:09P07465               | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 725220                    | NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT           |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060694-7              | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:09P05725               | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 725230                    | NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT   |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060693-1              | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:093300-00394           | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 725230                    | NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT   |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060693-1              | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:09-3300-00395          | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 725240                    | NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY       |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3061819-4              | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:09P11414               | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 05-10-01   |   |           |          |          |                           |           |           |             |        |
| 725240                    | NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY       |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3061819-4              | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:09P12496               | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 05-10-01   |   |           |          |          |                           |           |           |             |        |
| 725250                    | NO. 1 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING |           |          |          |                           |           |           | Component   | ATA:72 |
| PN:3060502-2              | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:10P18131               | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|                           | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit  | C/W       | Interval    | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition |        |
|---------------------------------------|---|-----------|-------------|----------|---------------------------|-----------|---------------|-------------|--------|
| <b>ATA 72 - ENGINE</b>                |   |           |             |          |                           |           |               |             |        |
| 725250                                | NO. 2 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING |           |             |          |                           |           |               | Component   | ATA:72 |
| PN:3060502-2                          | MOS/MSC   | 18-Feb-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:10P18132                           | HRS   | 0         |             | TSN 0    |                           |           |               |             |        |
|                                       | ENC   | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: GENERIC NO REF             |   |           |             |          |                           |           |               |             |        |
| 725260                                | NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING     |           |             |          |                           |           |               | Component   | ATA:72 |
| PN:3060599-3                          | MOS/MSC   | 18-Feb-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:10P18334                           | HRS   | 0         |             | TSN 0    |                           |           |               |             |        |
|                                       | ENC   | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: GENERIC NO REF             |   |           |             |          |                           |           |               |             |        |
| 725260                                | NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING     |           |             |          |                           |           |               | Component   | ATA:72 |
| PN:3060599-3                          | MOS/MSC   | 18-Feb-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:09P15825                           | HRS   | 0         |             | TSN 0    |                           |           |               |             |        |
|                                       | ENC   | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: GENERIC NO REF             |   |           |             |          |                           |           |               |             |        |
| 725270                                | NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL      |           |             |          |                           |           |               | Component   | ATA:72 |
| PN:3073765-13                         | MOS/MSC   | 18-Feb-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:10-3300-00063                      | HRS   | 0         |             | TSN 0    |                           |           |               |             |        |
|                                       | ENC   | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: GENERIC NO REF             |   |           |             |          |                           |           |               |             |        |
| 725270                                | NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL      |           |             |          |                           |           |               | Component   | ATA:72 |
| PN:3073765-13                         | MOS/MSC   | 18-Feb-10 | O/C         | TSN 0    |                           |           |               |             |        |
| SN:10-3300-00062                      | HRS   | 0         |             | TSN 0    |                           |           |               |             |        |
|                                       | ENC   | 0         |             | TSN 0    |                           |           |               |             |        |
| PROC. REF: GENERIC NO REF             |   |           |             |          |                           |           |               |             |        |
| 726010                                | NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)             |           |             |          |                           |           |               | Service     | ATA:72 |
|                                       | MOS   | 18-Feb-10 |             |          |                           |           |               |             |        |
|                                       | HRS   | 0         | 6000 (+200) |          | (6000)<br>6013.1          | 6200      | 2104.7 (+200) |             |        |
|                                       | ENC   | 0         |             |          |                           |           |               |             |        |
| PROC. REF: LMM 72-00-00, LMM 72-00-00 |   |           |             |          |                           |           |               |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit   | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining     | Disposition |        |
|---|--|-----------|---------------|----------|---------------------------|-----------|---------------|-------------|--------|
| <b>ATA 72 - ENGINE</b>  |  |           |               |          |                           |           |               |             |        |
| 726010  | NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)    |           |               |          |                           |           |               | Service     | ATA:72 |
|   | MOS  | 18-Feb-10 |               |          |                           |           |               |             |        |
|   | HRS  | 0         | 6000 (+200)   |          | (6000)<br>6013.1          | 6200      | 2104.7 (+200) |             |        |
|   | ENC  | 0         |               |          |                           |           |               |             |        |
| PROC. REF: LMM 72-00-00, LMM 72-00-00                             |  |           |               |          |                           |           |               |             |        |
| 726020  | NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY           |           |               |          |                           |           |               | Component   | ATA:72 |
| PN:PN   | MOS/MSC  | 18-Feb-10 | O/C           | TSN 0    |                           |           |               |             |        |
| SN:UNKNOWN  | HRS  | 0         |               | TSN 0    |                           |           |               |             |        |
|   | ENC  | 0         |               | TSN 0    |                           |           |               |             |        |
| PROC. REF: LMM 72-60-03, LMM 72-60-03                             |  |           |               |          |                           |           |               |             |        |
| 726020  | NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY           |           |               |          |                           |           |               | Component   | ATA:72 |
| PN:3070093-16   | MOS/MSC  | 18-Feb-10 | O/C           | TSN 0    |                           |           |               |             |        |
| SN:10P18120   | HRS  | 0         |               | TSN 0    |                           |           |               |             |        |
|   | ENC  | 0         |               | TSN 0    |                           |           |               |             |        |
| PROC. REF: LMM 72-60-03, LMM 72-60-03                             |  |           |               |          |                           |           |               |             |        |
| 727010 <sup>S</sup>   | NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY |           |               |          |                           |           |               | Service     | ATA:72 |
|   | MOS  | 18-Feb-10 |               |          |                           |           |               |             |        |
|   | HRS  | 0         | 1300          |          |                           |           |               |             |        |
|   | ENC  | 0         |               |          |                           |           |               |             |        |
| PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04, LMM 72-70-04 |  |           |               |          |                           |           |               |             |        |
| 727010 <sup>S</sup>   | NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY |           |               |          |                           |           |               | Service     | ATA:72 |
|   | MOS  | 18-Feb-10 |               |          |                           |           |               |             |        |
|   | HRS  | 0         | 1300          |          |                           |           |               |             |        |
|   | ENC  | 0         |               |          |                           |           |               |             |        |
| PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04, LMM 72-70-04 |  |           |               |          |                           |           |               |             |        |
| <b>ATA 73 - ENGINE FUEL AND CONTROL</b>                           |  |           |               |          |                           |           |               |             |        |
| 730001 <sup>S</sup>   | DRAIN PT2 PIPELINES TO FUEL COMPUTERS              |           |               |          |                           |           |               | Service     | ATA:73 |
|   | MOS  | 03-Aug-21 |               |          |                           |           |               |             |        |
|   | HRS  | 3405      | 800 (+40/-10) |          |                           |           |               |             |        |
| WC#: 73.050   | AFL  | 1243      |               |          |                           |           |               |             |        |
| PKG:13,91   |  |           |               |          |                           |           |               |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                 | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 73 - ENGINE FUEL AND CONTROL</b> |   |           |          |          |                           |           |           |             |        |
| 730110                                  | NO. 1 ENGINE - FUEL CONTROL UNIT                      |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:3070800-39                           | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:19837                                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 05-10-01, LMM 73-20-01   |   |           |          |          |                           |           |           |             |        |
| 730110                                  | NO. 2 ENGINE - FUEL CONTROL UNIT                      |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:3070800-39                           | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:19836                                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 05-10-01, LMM 73-20-01   |   |           |          |          |                           |           |           |             |        |
| 730120 <sup>S</sup>                     | NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT |           |          |          |                           |           |           | Service     | ATA:73 |
|   | MOS   | 14-May-20 |          |          |                           |           |           |             |        |
|   | HRS   | 3324.5    | 650      |          |                           |           |           |             |        |
|   | ENC   | 1210      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 73-21-02, LMM 73-21-02   |   |           |          |          |                           |           |           |             |        |
| 730120 <sup>S</sup>                     | NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT |           |          |          |                           |           |           | Service     | ATA:73 |
|   | MOS   | 14-May-20 |          |          |                           |           |           |             |        |
|   | HRS   | 3324.5    | 650      |          |                           |           |           |             |        |
|   | ENC   | 1210      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 73-21-02, LMM 73-21-02   |   |           |          |          |                           |           |           |             |        |
| 730130 <sup>U</sup>                     | NO. 1 ENGINE - ENGINE FUEL PUMP                       |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:3060760-4                            | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3072                                 | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| 730130 <sup>U</sup>                     | NO. 2 ENGINE - ENGINE FUEL PUMP                       |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:3060760-4                            | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3068                                 | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| 731110                                  | NO. 1 ENGINE - PRESSURE LIMITER VALVE                 |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:3070685-12                           | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:18425                                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
|   | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF               |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|---|---------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 73 - ENGINE FUEL AND CONTROL</b>                                     |         |           |          |          |                           |           |           |             |
| <b>731110 NO. 2 ENGINE - PRESSURE LIMITER VALVE Component ATA:73</b>        |         |           |          |          |                           |           |           |             |
| PN:3070685-12   | MOS/MSC | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:18422  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
|   | ENC     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>731120 NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE Component ATA:73</b> |         |           |          |          |                           |           |           |             |
| PN:394476-2   | MOS/MSC | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:3261   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
|   | ENC     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>731120 NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE Component ATA:73</b> |         |           |          |          |                           |           |           |             |
| PN:394476-2   | MOS/MSC | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:3267   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
|   | ENC     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: GENERIC NO REF   |         |           |          |          |                           |           |           |             |
| <b>732025 NO. 1 ENGINE LOW FUEL PRESSURE SWITCH Component ATA:73</b>        |         |           |          |          |                           |           |           |             |
| PN:HTE690014-2  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:43090244   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 73.020   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 73-32-11   |         |           |          |          |                           |           |           |             |
| <b>732026 NO. 2 ENGINE LOW FUEL PRESSURE SWITCH Component ATA:73</b>        |         |           |          |          |                           |           |           |             |
| PN:HTE690014-2  | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:43090247   | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 73.020   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| PROC. REF: AMM 73-32-11   |         |           |          |          |                           |           |           |             |
| <b>732037 NO. 1 ENGINE FUEL FILTER TEMPERATURE SWITCH Component ATA:73</b>  |         |           |          |          |                           |           |           |             |
| PN:PN   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 73.025   | AFL     | 0         |          | TSN 0    |                           |           |           |             |
| <b>732038 NO. 2 ENGINE FUEL FILTER TEMPERATURE SWITCH Component ATA:73</b>  |         |           |          |          |                           |           |           |             |
| PN:PN   | MOS/MSC | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |
| SN:UNKNOWN  | HRS     | 0         |          | TSN 0    |                           |           |           |             |
| WC#: 73.025   | AFL     | 0         |          | TSN 0    |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                                 | Unit                               | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---|------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 73 - ENGINE FUEL AND CONTROL</b> |                                    |           |          |          |                           |           |           |             |        |
| 732109                                  | ENGINE FUEL SYNCHRONIZER           |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:PN                                   | MOS/MSC                            | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                              | HRS                                | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 73.035                             | AFL                                | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF               |                                    |           |          |          |                           |           |           |             |        |
| 733001                                  | NO. 1 ENGINE FUEL FLOW TRANSMITTER |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:3051203-2                            | MOS/MSC                            | 17-Jul-14 | O/C      |          |                           |           |           |             |        |
| SN:239453-271                           | HRS                                | 1940.5    |          |          | TSN 1940.5                |           |           |             |        |
| WC#: 73.040                             | AFL                                | 703       |          |          | TSN 703                   |           |           |             |        |
| PROC. REF: AMM 73-31-11                 |                                    |           |          |          |                           |           |           |             |        |
| 733002                                  | NO. 2 ENGINE FUEL FLOW TRANSMITTER |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:3051203-2                            | MOS/MSC                            | 17-Jul-14 | O/C      |          |                           |           |           |             |        |
| SN:239453-065                           | HRS                                | 1940.5    |          |          |                           |           |           |             |        |
| WC#: 73.040                             | AFL                                | 703       |          |          |                           |           |           |             |        |
| PROC. REF: AMM 73-31-11                 |                                    |           |          |          |                           |           |           |             |        |
| 733013                                  | NO. 1 ENGINE FUEL FLOW INDICATOR   |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:PN                                   | MOS/MSC                            | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                              | HRS                                | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 73.045                             | AFL                                | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF               |                                    |           |          |          |                           |           |           |             |        |
| 733014                                  | NO. 2 ENGINE FUEL FLOW INDICATOR   |           |          |          |                           |           |           | Component   | ATA:73 |
| PN:PN                                   | MOS/MSC                            | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                              | HRS                                | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 73.045                             | AFL                                | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF               |                                    |           |          |          |                           |           |           |             |        |
| <b>ATA 74 - IGNITION</b>                |                                    |           |          |          |                           |           |           |             |        |
| 740110                                  | NO. 1 ENGINE - IGNITION UNIT       |           |          |          |                           |           |           | Component   | ATA:74 |
| PN:3061186-1                            | MOS/MSC                            | 18-Feb-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:J10020136                            | HRS                                | 0         |          |          | TSN 0                     |           |           |             |        |
|   | ENC                                | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 74-00-01                 |                                    |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 74 - IGNITION</b>              |   |           |          |          |                           |           |           |             |        |
| 740110                                | NO. 2 ENGINE - IGNITION UNIT                                      |           |          |          |                           |           |           | Component   | ATA:74 |
| PN:3061186-1                          | MOS/MSC   | 18-Feb-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:J10020102                          | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
|                                       | ENC   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 74-00-01               |   |           |          |          |                           |           |           |             |        |
| 740130                                | NO. 1 ENGINE - 5 O'CLOCK IGNITER PLUG                             |           |          |          |                           |           |           | Component   | ATA:74 |
| PN:3074541-4                          | MOS/MSC   | 04-Dec-17 | O/C      |          |                           |           |           |             |        |
| SN:NSN                                | HRS   | 2853.82   |          |          |                           |           |           |             |        |
|                                       | ENC   | 1031      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 74-00-01               |   |           |          |          |                           |           |           |             |        |
| 740130                                | NO. 2 ENGINE - 5 O'CLOCK IGNITER PLUG                             |           |          |          |                           |           |           | Component   | ATA:74 |
| PN:3074541-4                          | MOS/MSC   | 28-Nov-17 | O/C      |          | TSN 5                     |           |           |             |        |
| SN:UNKNOWN                            | HRS   | 2853.82   |          |          | TSN 0                     |           |           |             |        |
|                                       | ENC   | 1031      |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 74-00-01               |   |           |          |          |                           |           |           |             |        |
| 740140 <sup>S</sup>                   | NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD |           |          |          |                           |           |           | Service     | ATA:74 |
|                                       | MOS   | 04-Dec-17 |          |          |                           |           |           |             |        |
|                                       | HRS   | 2853.82   | 1650     |          |                           |           |           |             |        |
|                                       | ENC   | 1031      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01 |   |           |          |          |                           |           |           |             |        |
| 740140 <sup>S</sup>                   | NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD |           |          |          |                           |           |           | Service     | ATA:74 |
|                                       | MOS   | 28-Nov-17 |          |          |                           |           |           |             |        |
|                                       | HRS   | 2853.82   | 1650     |          |                           |           |           |             |        |
|                                       | ENC   | 1031      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 74-00-01, LMM 74-00-01 |   |           |          |          |                           |           |           |             |        |
| 740150                                | NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG                             |           |          |          |                           |           |           | Component   | ATA:74 |
| PN:3074541-4                          | MOS/MSC   | 04-Dec-17 | O/C      |          |                           |           |           |             |        |
| SN:NSN                                | HRS   | 2853.82   |          |          |                           |           |           |             |        |
|                                       | ENC   | 1031      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 74-00-01               |   |           |          |          |                           |           |           |             |        |
| 740150                                | NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG                             |           |          |          |                           |           |           | Component   | ATA:74 |
| PN:3074541-4                          | MOS/MSC   | 28-Nov-17 | O/C      |          | TSN 5                     |           |           |             |        |
| SN:UNKNOWN                            | HRS   | 2853.82   |          |          | TSN 0                     |           |           |             |        |
|                                       | ENC   | 1031      |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 74-00-01               |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN             | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 74 - IGNITION   |   |           |          |          |                           |           |           |             |        |
| 740160 <sup>S</sup> | NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD |           |          |          |                           |           |           | Service     | ATA:74 |
|                     | MOS   | 04-Dec-17 |          |          |                           |           |           |             |        |
|                     | HRS   | 2853.82   | 1650     |          |                           |           |           |             |        |
|                     | ENC   | 1031      |          |          |                           |           |           |             |        |
|                     |   |           |          |          | PROC. REF: LMM 74-00-01   |           |           | PKG:5       |        |
| 740160 <sup>S</sup> | NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD |           |          |          |                           |           |           | Service     | ATA:74 |
|                     | MOS   | 28-Nov-17 |          |          |                           |           |           |             |        |
|                     | HRS   | 2853.82   | 1650     |          |                           |           |           |             |        |
|                     | ENC   | 1031      |          |          |                           |           |           |             |        |
|                     |   |           |          |          | PROC. REF: LMM 74-00-01   |           |           | PKG:5       |        |
| 740210 <sup>S</sup> | NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM                  |           |          |          |                           |           |           | Service     | ATA:74 |
|                     | MOS   | 14-May-20 |          |          |                           |           |           |             |        |
|                     | HRS   | 3324.5    | 650      |          |                           |           |           |             |        |
|                     | ENC   | 1210      |          |          |                           |           |           |             |        |
|                     |   |           |          |          | PROC. REF: LMM 74-00-01   |           |           | PKG:2       |        |
| 740210 <sup>S</sup> | NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM                  |           |          |          |                           |           |           | Service     | ATA:74 |
|                     | MOS   | 14-May-20 |          |          |                           |           |           |             |        |
|                     | HRS   | 3324.5    | 650      |          |                           |           |           |             |        |
|                     | ENC   | 1210      |          |          |                           |           |           |             |        |
|                     |   |           |          |          | PROC. REF: LMM 74-00-01   |           |           | PKG:2       |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit  | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---|---|-----------|---------------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 75 - AIR  |   |           |               |          |                           |           |           |             |        |
| 750001 <sup>S</sup>                                 | INSPECT THE BLEED AIR PORT LOW PRESSURE (LP) VENTURI GASKET FOR SIGNS OF DETERIORATION, DEEP DISCOLORATION, CRACKS OR MISSING PIECES OF GASKET AND REPLACE AS NECESSARY |           |               |          |                           |           |           | Service     | ATA:75 |
|   | MOS   | 03-Aug-21 |               |          |                           |           |           |             |        |
|   | HRS   | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
|   | AFL   | 1243      |               |          |                           |           |           |             |        |
| PKG:17,91   |   |           |               |          |                           |           |           |             |        |
| 751013  | NO. 1 ENGINE THERMAL ANTI-ICE VALVE   |           |               |          |                           |           |           | Component   | ATA:75 |
| PN:27441482   | MOS/MSC   | 16-Mar-10 | O/C           |          | TSN 0                     |           |           |             |        |
| SN:1BF6   | HRS   | 0         |               |          | TSN 0                     |           |           |             |        |
| WC#: 75.020   | AFL   | 0         |               |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 75-10-11                             |   |           |               |          |                           |           |           |             |        |
| 751014  | NO. 2 ENGINE THERMAL ANTI-ICE VALVE   |           |               |          |                           |           |           | Component   | ATA:75 |
| PN:27441482   | MOS/MSC   | 16-Mar-10 | O/C           |          | TSN 0                     |           |           |             |        |
| SN:1BF3   | HRS   | 0         |               |          | TSN 0                     |           |           |             |        |
| WC#: 75.021   | AFL   | 0         |               |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 75-10-11                             |   |           |               |          |                           |           |           |             |        |
| 754010  | NO. 1 ENGINE ANTI-ICE PRESSURE SWITCH   |           |               |          |                           |           |           | Component   | ATA:75 |
| PN:HTE690013  | MOS/MSC   | 16-Mar-10 | O/C           |          | TSN 0                     |           |           |             |        |
| SN:49091167   | HRS   | 0         |               |          | TSN 0                     |           |           |             |        |
| WC#: 75.015   | AFL   | 0         |               |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 75-40-11                             |   |           |               |          |                           |           |           |             |        |
| 754011  | NO. 2 ENGINE ANTI-ICE PRESSURE SWITCH   |           |               |          |                           |           |           | Component   | ATA:75 |
| PN:HTE690013  | MOS/MSC   | 16-Mar-10 | O/C           |          | TSN 0                     |           |           |             |        |
| SN:49091157   | HRS   | 0         |               |          | TSN 0                     |           |           |             |        |
| WC#: 75.015   | AFL   | 0         |               |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 75-40-11                             |   |           |               |          |                           |           |           |             |        |
| 754210  | NO. 1 ENGINE - INLET TEMPERATURE SENSOR   |           |               |          |                           |           |           | Component   | ATA:75 |
| PN:3070816-14                                       | MOS/MSC   | 21-Dec-13 | O/C           |          | TSN 0                     |           |           |             |        |
| SN:1316901724233                                    | HRS   | 1664.55   |               |          | TSN 0                     |           |           |             |        |
| WC#: 75.010   | ENC   | 612       |               |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01 |   |           |               |          |                           |           |           |             |        |
| 754210  | NO. 2 ENGINE - INLET TEMPERATURE SENSOR   |           |               |          |                           |           |           | Component   | ATA:75 |
| PN:3070816-14                                       | MOS/MSC   | 18-Feb-10 | O/C           |          | TSN 0                     |           |           |             |        |
| SN:091789323544                                     | HRS   | 0         |               |          | TSN 0                     |           |           |             |        |
| WC#: 75.010   | ENC   | 0         |               |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 75-40-01, LMM 75-40-01, LMM 75-40-01 |   |           |               |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                         | Unit   | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------|--|-----------|----------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 76 - ENGINE CONTROLS</b> |  |           |                |          |                           |           |           |             |        |
| 760001 <sup>S</sup>             | CHECK THROTTLE LEVER CONTROLS  |           |                |          |                           |           |           | Service     | ATA:76 |
|                                 | MOS  | 03-Aug-21 |                |          |                           |           |           |             |        |
|                                 | HRS  | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 76.030                     | AFL  | 1243      |                |          |                           |           |           |             |        |
|                                 | PROC. REF: AMM 27-72-00  |           |                |          |                           |           |           | PKG:10,91   |        |
| 760002 <sup>S</sup>             | CHECK ENGINE POWER CONTROL CABLES  |           |                |          |                           |           |           | Service     | ATA:76 |
|                                 | MOS  | 06-Jun-18 |                |          |                           |           |           |             |        |
|                                 | HRS  | 2965.25   | 1600 (+50/-50) |          |                           |           |           |             |        |
| WC#: 76.010                     | AFL  | 1073      |                |          |                           |           |           |             |        |
|                                 | PROC. REF: AMM 76-10-00  |           |                |          |                           |           |           | PKG:23,92   |        |
| 760003                          | CHECK POWER CONTROL CABLES   |           |                |          |                           |           |           | Service     | ATA:76 |
|                                 | MOS/MSC  | 27-Oct-10 | O/C            |          |                           |           |           |             |        |
|                                 | HRS  | 167.32    |                |          |                           |           |           |             |        |
| WC#: 76.020                     | AFL  | 77        |                |          |                           |           |           |             |        |
|                                 | PROC. REF: AMM 76-10-00  |           |                |          |                           |           |           |             |        |
| 760004                          | LUBRICATE NO. 1 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING |           |                |          |                           |           |           | Service     | ATA:76 |
|                                 | MOS  | 19-Dec-17 |                |          |                           |           |           |             |        |
|                                 | HRS  | 2886.88   | 1200           |          | 4086.88                   |           | 178.5     |             |        |
| WC#: 76.040                     | AFL  | 1043      |                |          |                           |           |           |             |        |
|                                 | PROC. REF: AMS 5-20-11   |           |                |          |                           |           |           |             |        |
| 760004                          | LUBRICATE NO. 2 ENGINE THRUST CONTROL TELEFLEX CABLE AND DISCONNECT COUPLING |           |                |          |                           |           |           | Service     | ATA:76 |
|                                 | MOS  | 19-Dec-17 |                |          |                           |           |           |             |        |
|                                 | HRS  | 2886.88   | 1200           |          | 4086.88                   |           | 178.5     |             |        |
| WC#: 76.040                     | AFL  | 1043      |                |          |                           |           |           |             |        |
|                                 | PROC. REF: AMS 5-20-11   |           |                |          |                           |           |           |             |        |
| 761210                          | NO. 1 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM        |           |                |          |                           |           |           | Service     | ATA:76 |
| PN:2118882-5001                 | MOS  | 11-Jul-24 |                |          |                           |           |           |             |        |
| SN:89-BH0011                    | HRS  | 3894.3    | 50             |          | (3944.3)<br>3957.4        |           | 49        |             |        |
| WC#: 76.010                     | ENC  | 1477      |                |          |                           |           |           |             |        |
|                                 | PROC. REF: MSC CAMP EHM ADENDUM, LMM 72-00-00, LMM 76-10-02                  |           |                |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN  | Unit    | C/W | Interval  | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |
|--|---------|-----|-----------|----------|---------------------------|-----------|-----------|-------------|
| <b>ATA 76 - ENGINE CONTROLS</b>  |         |     |           |          |                           |           |           |             |
| <b>761210 NO. 2 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM</b> Service ATA:76 |         |     |           |          |                           |           |           |             |
| PN:2118882-5001  | MOS     |     | 11-Jul-24 |          |                           |           |           |             |
| SN:109-BH0024  | HRS     |     | 3894.3    |          | (3944.3)<br>3957.4        |           | 49        |             |
| WC#: 76.010  | ENC     |     | 1477      |          |                           |           |           |             |
| PROC. REF: MSC CAMP EHM ADENDUM, LMM 72-00-00, LMM 76-10-02  |         |     |           |          |                           |           |           |             |
| <b>761310 NO. 1 ENGINE - SURGE BLEED VALVE</b> Component ATA:76                                    |         |     |           |          |                           |           |           |             |
| PN:978812-7-1  | MOS/MSC |     | 18-Feb-10 | O/C      | TSN 0                     |           |           |             |
| SN:14241   | HRS     |     | 0         |          | TSN 0                     |           |           |             |
| WC#: 76.020  | ENC     |     | 0         |          | TSN 0                     |           |           |             |
| PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01  |         |     |           |          |                           |           |           |             |
| <b>761310 NO. 2 ENGINE - SURGE BLEED VALVE</b> Component ATA:76                                    |         |     |           |          |                           |           |           |             |
| PN:978812-7-1  | MOS/MSC |     | 18-Feb-10 | O/C      | TSN 0                     |           |           |             |
| SN:14236   | HRS     |     | 0         |          | TSN 0                     |           |           |             |
| WC#: 76.020  | ENC     |     | 0         |          | TSN 0                     |           |           |             |
| PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01  |         |     |           |          |                           |           |           |             |
| <b>761320 NO. 1 ENGINE - SOLENOID CONTROL VALVE</b> Component ATA:76                               |         |     |           |          |                           |           |           |             |
| PN:109696-6-1  | MOS/MSC |     | 18-Feb-10 | O/C      | TSN 0                     |           |           |             |
| SN:13416   | HRS     |     | 0         |          | TSN 0                     |           |           |             |
| WC#: 76.030  | ENC     |     | 0         |          | TSN 0                     |           |           |             |
| PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01  |         |     |           |          |                           |           |           |             |
| <b>761320 NO. 2 ENGINE - SOLENOID CONTROL VALVE</b> Component ATA:76                               |         |     |           |          |                           |           |           |             |
| PN:109696-6-1  | MOS/MSC |     | 18-Feb-10 | O/C      | TSN 0                     |           |           |             |
| SN:13703   | HRS     |     | 0         |          | TSN 0                     |           |           |             |
| WC#: 76.030  | ENC     |     | 0         |          | TSN 0                     |           |           |             |
| PROC. REF: LMM 76-10-01, LMM 76-10-01, LMM 76-10-01  |         |     |           |          |                           |           |           |             |
| <b>761330 NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL</b> Component ATA:76             |         |     |           |          |                           |           |           |             |
| PN:2118882-5001  | MOS/MSC |     | 18-Feb-10 | O/C      | TSN 0                     |           |           |             |
| SN:89-BH0011   | HRS     |     | 0         |          | TSN 0                     |           |           |             |
| WC#: 76.040  | ENC     |     | 0         |          | TSN 0                     |           |           |             |
| PROC. REF: LMM 05-10-01, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02                                  |         |     |           |          |                           |           |           |             |
| <b>761330 NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL</b> Component ATA:76             |         |     |           |          |                           |           |           |             |
| PN:2118882-5001  | MOS/MSC |     | 18-Feb-10 | O/C      | TSN 0                     |           |           |             |
| SN:109-BH0024  | HRS     |     | 0         |          | TSN 0                     |           |           |             |
| WC#: 76.040  | ENC     |     | 0         |          | TSN 0                     |           |           |             |
| PROC. REF: LMM 05-10-01, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02                                  |         |     |           |          |                           |           |           |             |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit    | C/W                                       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |  |
|---|---------|---|----------|----------|---------------------------|-----------|-----------|-------------|--|
| <b>ATA 77 - ENGINE INDICATING</b>                   |         |   |          |          |                           |           |           |             |  |
| 771025  |         | NO. 1 ENGINE LOW-PRESSURE (N1) INDICATOR  |          |          |                           |           | Component | ATA:77      |  |
| PN:PN   | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN  | HRS     | 0   |          | TSN 0    |                           |           |           |             |  |
| WC#: 77.010   | AFL     | 0   |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF                           |         |   |          |          |                           |           |           |             |  |
| 771026  |         | NO. 2 ENGINE LOW-PRESSURE (N1) INDICATOR  |          |          |                           |           | Component | ATA:77      |  |
| PN:PN   | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN  | HRS     | 0   |          | TSN 0    |                           |           |           |             |  |
| WC#: 77.010   | AFL     | 0   |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF                           |         |   |          |          |                           |           |           |             |  |
| 771037  |         | NO. 1 ENGINE HIGH-PRESSURE (N2) INDICATOR |          |          |                           |           | Component | ATA:77      |  |
| PN:PN   | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN  | HRS     | 0   |          | TSN 0    |                           |           |           |             |  |
| WC#: 77.015   | AFL     | 0   |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF                           |         |   |          |          |                           |           |           |             |  |
| 771038  |         | NO. 2 ENGINE HIGH-PRESSURE (N2) INDICATOR |          |          |                           |           | Component | ATA:77      |  |
| PN:PN   | MOS/MSC | 16-Mar-10                                 | O/C      | TSN 0    |                           |           |           |             |  |
| SN:UNKNOWN  | HRS     | 0   |          | TSN 0    |                           |           |           |             |  |
| WC#: 77.015   | AFL     | 0   |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: GENERIC NO REF                           |         |   |          |          |                           |           |           |             |  |
| 771210  |         | NO. 1 ENGINE - N1 COMPENSATOR             |          |          |                           |           | Component | ATA:77      |  |
| PN:3060735-7  | MOS/MSC | 18-Feb-10                                 | O/C      | TSN 0    |                           |           |           |             |  |
| SN:091309700221                                     | HRS     | 0   |          | TSN 0    |                           |           |           |             |  |
| WC#: 77.010   | ENC     | 0   |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03 |         |   |          |          |                           |           |           |             |  |
| 771210  |         | NO. 2 ENGINE - N1 COMPENSATOR             |          |          |                           |           | Component | ATA:77      |  |
| PN:3060735-6  | MOS/MSC | 18-Feb-10                                 | O/C      | TSN 0    |                           |           |           |             |  |
| SN:081309700556                                     | HRS     | 0   |          | TSN 0    |                           |           |           |             |  |
| WC#: 77.010   | ENC     | 0   |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: LMM 77-10-03, LMM 77-10-03, LMM 77-10-03 |         |   |          |          |                           |           |           |             |  |
| 771220  |         | NO. 1 ENGINE - N2 TRANSDUCER              |          |          |                           |           | Component | ATA:77      |  |
| PN:3070722-8  | MOS/MSC | 18-Feb-10                                 | O/C      | TSN 0    |                           |           |           |             |  |
| SN:071936055710                                     | HRS     | 0   |          | TSN 0    |                           |           |           |             |  |
| WC#: 77.020   | ENC     | 0   |          | TSN 0    |                           |           |           |             |  |
| PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05 |         |   |          |          |                           |           |           |             |  |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN   | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 77 - ENGINE INDICATING</b>                   |   |           |          |          |                           |           |           |             |        |
| 771220  | NO. 2 ENGINE - N2 TRANSDUCER            |           |          |          |                           |           |           | Component   | ATA:77 |
| PN:3070722-8  | MOS/MSC                                 | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:071936055779                                     | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 77.020   | ENC                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 77-10-05, LMM 77-10-05, LMM 77-10-05 |   |           |          |          |                           |           |           |             |        |
| 772210  | NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS |           |          |          |                           |           |           | Component   | ATA:77 |
| PN:3060763-6  | MOS/MSC                                 | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:091789355098                                     | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 77.030   | ENC                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 77-20-01                             |   |           |          |          |                           |           |           |             |        |
| 772210  | NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS |           |          |          |                           |           |           | Component   | ATA:77 |
| PN:3060763-6  | MOS/MSC                                 | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:091789355097                                     | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 77.030   | ENC                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 77-20-01                             |   |           |          |          |                           |           |           |             |        |
| 773005  | LEFT TIME DELAY SWITCH                  |           |          |          |                           |           |           | Component   | ATA:77 |
| PN:PN   | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 77.025   | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                           |   |           |          |          |                           |           |           |             |        |
| 773006  | RIGHT TIME DELAY SWITCH                 |           |          |          |                           |           |           | Component   | ATA:77 |
| PN:PN   | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 77.025   | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                           |   |           |          |          |                           |           |           |             |        |
| 774013  | NO. 1 ENGINE ITT INDICATOR              |           |          |          |                           |           |           | Component   | ATA:77 |
| PN:PN   | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 77.030   | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                           |   |           |          |          |                           |           |           |             |        |
| 774014  | NO. 2 ENGINE ITT INDICATOR              |           |          |          |                           |           |           | Component   | ATA:77 |
| PN:PN   | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN  | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 77.030   | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF                           |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit   | C/W       | Interval        | TSX/Adj.                | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|--|-----------|-----------------|-------------------------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 78 - EXHAUST</b> |  |           |                 |                         |                           |           |           |             |        |
| 780001 <sup>S</sup>     | INSPECT THRUST REVERSER LINK ARM ASSEMBLIES            |           |                 |                         |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |                 |                         |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10)   |                         |                           |           |           |             |        |
| WC#: 78.110             | AFL  | 1243      |                 |                         |                           |           |           |             |        |
|                         |  |           |                 | PROC. REF: AMM 78-31-10 |                           |           |           | PKG:17,91   |        |
| 780002 <sup>S</sup>     | INSPECT REVERSER DOOR SEALS                            |           |                 |                         |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |                 |                         |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10)   |                         |                           |           |           |             |        |
| WC#: 78.120             | AFL  | 1243      |                 |                         |                           |           |           |             |        |
|                         |  |           |                 | PROC. REF: AMM 78-31-20 |                           |           |           | PKG:17,91   |        |
| 780003 <sup>S</sup>     | TEST THRUST REVERSER STOW/DEPLOY MICROSWITCHES         |           |                 |                         |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                         | HRS  | 2965.25   | 1600 (+50/-50)  |                         |                           |           |           |             |        |
| WC#: 78.130             | AFL  | 1073      |                 |                         |                           |           |           |             |        |
|                         |  |           |                 | PROC. REF: AMM 78-34-20 |                           |           |           | PKG:22,92   |        |
| 780004 <sup>S</sup>     | INSPECT PYLON SKIN PANELS                              |           |                 |                         |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                         | HRS  | 2965.25   | 1600 (+50/-50)  |                         |                           |           |           |             |        |
| WC#: 78.135             | AFL  | 1073      |                 |                         |                           |           |           |             |        |
|                         |  |           |                 |                         |                           |           |           | PKG:29,92   |        |
| 780005 <sup>S</sup>     | DETAIL INSPECT DOOR LINK RODS AND PIVOT BRACKETS       |           |                 |                         |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                         | HRS  | 2965.25   | 1600 (+50/-50)  |                         |                           |           |           |             |        |
| WC#: 78.140             | AFL  | 1073      |                 |                         |                           |           |           |             |        |
|                         |  |           |                 | PROC. REF: AMM 78-31-10 |                           |           |           | PKG:29,92   |        |
| 780006 <sup>S</sup>     | CHECK THRUST REVERSER LEVER BAULK MECHANISM            |           |                 |                         |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 06-Jun-18 |                 |                         |                           |           |           |             |        |
|                         | HRS  | 2965.25   | 3200 (+150/-50) |                         |                           |           |           |             |        |
| WC#: 78.125             | AFL  | 1073      |                 |                         |                           |           |           |             |        |
|                         |  |           |                 |                         |                           |           |           | PKG:34,93   |        |
| 780009 <sup>S</sup>     | INSPECT THRUST REVERSER AFTERBODY, DOORS AND FAN FLAPS |           |                 |                         |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |                 |                         |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10)   |                         |                           |           |           |             |        |
| WC#: 78.155             | AFL  | 1243      |                 |                         |                           |           |           |             |        |
|                         |  |           |                 |                         |                           |           |           | PKG:17,91   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit   | C/W       | Interval      | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|--|-----------|---------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 78 - EXHAUST</b> |  |           |               |          |                           |           |           |             |        |
| 780010 <sup>S</sup>     | INSPECT THRUST REVERSER HYDRAULIC LINES AND WIRING HARNESS |           |               |          |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 78.160             | AFL  | 1243      |               |          |                           |           |           | PKG:13,91   |        |
| 780011 <sup>S</sup>     | DETAIL INSPECT THRUST REVERSER EXHAUST NOZZLES             |           |               |          |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 78.165             | AFL  | 1243      |               |          |                           |           |           | PKG:17,91   |        |
| 780012 <sup>S</sup>     | INSPECT THRUST REVERSER HYDRAULIC LINES                    |           |               |          |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 78.170             | AFL  | 1243      |               |          |                           |           |           | PKG:17,91   |        |
| 780013 <sup>S</sup>     | INSPECT THRUST REVERSER WIRE HARNESSES                     |           |               |          |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 78.175             | AFL  | 1243      |               |          |                           |           |           | PKG:17,91   |        |
| 780014 <sup>S</sup>     | INSPECT THRUST REVERSER FAN DUCTS                          |           |               |          |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 78.180             | AFL  | 1243      |               |          |                           |           |           | PKG:17,91   |        |
| 780015 <sup>S</sup>     | INSPECT THRUST REVERSER LATCH BOX SPRINGS                  |           |               |          |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 78.185             | AFL  | 1243      |               |          |                           |           |           | PKG:17,91   |        |
| 780016 <sup>S</sup>     | OPERATIONAL TEST THRUST REVERSER LATCH MONITORING SWITCHES |           |               |          |                           |           |           | Service     | ATA:78 |
|                         | MOS  | 03-Aug-21 |               |          |                           |           |           |             |        |
|                         | HRS  | 3405      | 800 (+40/-10) |          |                           |           |           |             |        |
| WC#: 78.190             | AFL  | 1243      |               |          |                           |           |           | PKG:17,91   |        |
|                         |  |           |               |          | PROC. REF: AMM 78-33-50   |           |           | PKG:17,91   |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit  | C/W       | Interval       | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|---|-----------|----------------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 78 - EXHAUST</b> |   |           |                |          |                           |           |           |             |        |
| 780017 <sup>S</sup>     | INSPECT THRUST REVERSER LATCHES AND LATCH RECEPTACLES         |           |                |          |                           |           |           | Service     | ATA:78 |
|                         | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                         | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 78.195             | AFL   | 1243      |                |          |                           |           |           |             |        |
|                         |   |           |                |          | PROC. REF: AMM 78-31-35   |           |           | PKG:17,91   |        |
| 780018 <sup>S</sup>     | INSPECT THRUST REVERSER PRIMARY AND LATCH HYDRAULIC ACTUATORS |           |                |          |                           |           |           | Service     | ATA:78 |
|                         | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                         | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 78.200             | AFL   | 1243      |                |          |                           |           |           |             |        |
|                         |   |           |                |          | PROC. REF: AMM NO REF 1   |           |           | PKG:17,91   |        |
| 780019 <sup>S</sup>     | INSPECT THRUST REVERSER THROTTLE RETARD HYDRAULIC ACTUATORS   |           |                |          |                           |           |           | Service     | ATA:78 |
|                         | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                         | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 78.205             | AFL   | 1243      |                |          |                           |           |           |             |        |
|                         |   |           |                |          | PROC. REF: AMM 78-32-30   |           |           | PKG:17,91   |        |
| 780020 <sup>S</sup>     | INSPECT THRUST REVERSER FAN FLAP HYDRAULIC ACTUATORS          |           |                |          |                           |           |           | Service     | ATA:78 |
|                         | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                         | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 78.210             | AFL   | 1243      |                |          |                           |           |           |             |        |
|                         |   |           |                |          | PROC. REF: AMM NO REF 1   |           |           | PKG:17,91   |        |
| 780021 <sup>S</sup>     | INSPECT THRUST REVERSER PYLON PLUGS                           |           |                |          |                           |           |           | Service     | ATA:78 |
|                         | MOS   | 03-Aug-21 |                |          |                           |           |           |             |        |
|                         | HRS   | 3405      | 800 (+40/-10)  |          |                           |           |           |             |        |
| WC#: 78.215             | AFL   | 1243      |                |          |                           |           |           |             |        |
|                         |   |           |                |          |                           |           |           | PKG:17,91   |        |
| 780023 <sup>S</sup>     | CHECK BONDING STRAPS - 900XP AIRPLANES                        |           |                |          |                           |           |           | Service     | ATA:78 |
|                         | MOS   | 06-Jun-18 |                |          |                           |           |           |             |        |
|                         | HRS   | 2965.25   | 1600 (+50/-50) |          |                           |           |           |             |        |
| WC#: 78.225             | AFL   | 1073      |                |          |                           |           |           |             |        |
|                         |   |           |                |          |                           |           |           | PKG:29,92   |        |
| 781001                  | NO. 1 ENGINE THRUST REVERSER AFTERBODY                        |           |                |          |                           |           |           | Component   | ATA:78 |
| PN:PN                   | MOS/MSC   | 16-Mar-10 | O/C            |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN              | HRS   | 0         |                |          | TSN 0                     |           |           |             |        |
| WC#: 78.015             | AFL   | 0         |                |          | TSN 0                     |           |           |             |        |
|                         |   |           |                |          | PROC. REF: AMM 78-33-40   |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 78 - EXHAUST</b>   |  |           |          |          |                           |           |           |             |        |
| 781002                    | NO. 2 ENGINE THRUST REVERSER AFTERBODY         |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                     | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.015               | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 78-33-40   |  |           |          |          |                           |           |           |             |        |
| 781013                    | NO. 1 ENGINE THRUST REVERSER ASSEMBLY          |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:11ND78100-1            | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:HX9135-3               | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.010               | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| 781014                    | NO. 2 ENGINE THRUST REVERSER ASSEMBLY          |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:11ND78100-3            | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:HX9139-4               | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.011               | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| 781026                    | NO. 1 ENGINE THRUST REVERSER INBOARD ACTUATOR  |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                     | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.020               | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 78-32-40   |  |           |          |          |                           |           |           |             |        |
| 781027                    | NO. 1 ENGINE THRUST REVERSER OUTBOARD ACTUATOR |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                     | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.020               | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 78-32-40   |  |           |          |          |                           |           |           |             |        |
| 781028                    | NO. 2 ENGINE THRUST REVERSER INBOARD ACTUATOR  |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                     | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.025               | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 781029                    | NO. 2 ENGINE THRUST REVERSER OUTBOARD ACTUATOR |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                     | MOS/MSC  | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS  | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.025               | AFL  | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 78 - EXHAUST</b> |   |           |          |          |                           |           |           |             |        |
| 781053                  | NO. 1 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY  |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                   | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN              | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.030             | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-32-50 |   |           |          |          |                           |           |           |             |        |
| 781054                  | NO. 1 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                   | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN              | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.030             | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-32-50 |   |           |          |          |                           |           |           |             |        |
| 781055                  | NO. 2 ENGINE INBOARD LATCH ACTUATOR ASSEMBLY  |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                   | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN              | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.035             | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-32-50 |   |           |          |          |                           |           |           |             |        |
| 781056                  | NO. 2 ENGINE OUTBOARD LATCH ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                   | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN              | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.035             | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-32-50 |   |           |          |          |                           |           |           |             |        |
| 781090                  | NO. 1 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:5453511-15           | MOS/MSC                                       | 03-Aug-21 | O/C      | TSO 34   |                           |           |           |             |        |
| SN:943424-02A           | HRS   | 3405      |          | TSO 0    |                           |           |           |             |        |
| WC#: 78.040             | AFL   | 1243      |          | TSO 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-32-60 |   |           |          |          |                           |           |           |             |        |
| 781091                  | NO. 1 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                   | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN              | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.040             | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-32-60 |   |           |          |          |                           |           |           |             |        |
| 781092                  | NO. 2 ENGINE UPPER FAN FLAP ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                   | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN              | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.045             | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-32-60 |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 78 - EXHAUST</b>   |   |           |          |          |                           |           |           |             |        |
| 781093                    | NO. 2 ENGINE LOWER FAN FLAP ACTUATOR ASSEMBLY |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:5453511-15             | MOS/MSC                                       | 18-Nov-19 | O/C      |          | TSO 0                     |           |           |             |        |
| SN:909A                   | HRS   | 3302.9    |          |          | TSO 0                     |           |           |             |        |
| WC#: 78.045               | AFL   | 1203      |          |          | TSO 0                     |           |           |             |        |
| PROC. REF: AMM 78-32-60   |   |           |          |          |                           |           |           |             |        |
| 781117                    | NO. 1 ENGINE RETARD THROTTLE ASSEMBLY         |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                     | MOS/MSC                                       | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.050               | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 78-32-30   |   |           |          |          |                           |           |           |             |        |
| 781118                    | NO. 2 ENGINE RETARD THROTTLE ASSEMBLY         |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                     | MOS/MSC                                       | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.050               | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 78-32-30   |   |           |          |          |                           |           |           |             |        |
| 781129                    | THRUST REVERSER TIME DELAY RELAY              |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:5400619-1              | MOS/MSC                                       | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:HX410-110              | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.055               | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 781130                    | CONTROL RELAY BOX                             |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:5400612-1              | MOS/MSC                                       | 20-Jul-23 | O/C      |          |                           |           |           |             |        |
| SN:109                    | HRS   | 3746.3    |          |          | TSN 9203.9                |           |           |             |        |
| WC#: 78.060               | AFL   | 1413      |          |          |                           |           |           |             |        |
| PROC. REF: AMM 78-33-20   |   |           |          |          |                           |           |           |             |        |
| 781136                    | AUXILIARY RELAY BOX                           |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:5400605-1              | MOS/MSC                                       | 16-Mar-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:HX5494                 | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 78.065               | AFL   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 78-33-30   |   |           |          |          |                           |           |           |             |        |
| 781142                    | NO. 1 ENGINE THRUST REVERSER CONTROL VALVE    |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:064135141-11           | MOS/MSC                                       | 20-Jul-23 | O/C      |          |                           |           |           |             |        |
| SN:A30041741              | HRS   | 3746.3    |          |          |                           |           |           |             |        |
| WC#: 78.070               | AFL   | 1413      |          |          |                           |           |           |             |        |
| PROC. REF: AMM 78-32-20   |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task





# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 78 - EXHAUST</b>   |  |           |          |          |                           |           |           |             |        |
| 781143                    | NO. 2 ENGINE THRUST REVERSER CONTROL VALVE   |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:064135141-11           | MOS/MSC                                      | 20-Jul-23 | O/C      |          |                           |           |           |             |        |
| SN:A3004144               | HRS  | 3746.3    |          |          |                           |           |           |             |        |
| WC#: 78.070               | AFL  | 1413      |          |          |                           |           |           |             |        |
| PROC. REF: AMM 78-32-20   |  |           |          |          |                           |           |           |             |        |
| 781155                    | THRUST REVERSER ACCUMULATOR                  |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:DS259-3                | MOS/MSC                                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:60209-1287             | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.075               | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-32-10   |  |           |          |          |                           |           |           |             |        |
| 781156                    | HYDRAULIC RELIEF VALVE                       |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:MS28893-D6             | MOS/MSC                                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:74982                  | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.080               | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 781161                    | THRUST REVERSER CONTROL PANEL                |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:5412600-3              | MOS/MSC                                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:HX564-103              | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.085               | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-33-10   |  |           |          |          |                           |           |           |             |        |
| 781167                    | NO. 1 ENGINE THRUST REVERSER PRESSURE SWITCH |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:2365-15                | MOS/MSC                                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:4407                   | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.090               | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 781169                    | NO. 2 ENGINE THRUST REVERSER PRESSURE SWITCH |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:2365-15                | MOS/MSC                                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:4405                   | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.090               | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |
| 781173                    | THRUST REVERSER PRESSURE GAUGE               |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:MS28061T7              | MOS/MSC                                      | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:2415                   | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.090               | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit                                    | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 78 - EXHAUST</b>               |   |           |          |          |                           |           |           |             |        |
| 783008                                | NO. 1 ENGINE LOWER THRUST REVERSER DOOR |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                                 | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.095                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-31-10               |   |           |          |          |                           |           |           |             |        |
| 783009                                | NO. 2 ENGINE LOWER THRUST REVERSER DOOR |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                                 | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.095                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-31-10               |   |           |          |          |                           |           |           |             |        |
| 783010                                | NO. 1 ENGINE UPPER THRUST REVERSER DOOR |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                                 | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.100                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-31-10               |   |           |          |          |                           |           |           |             |        |
| 783011                                | NO. 2 ENGINE UPPER THRUST REVERSER DOOR |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:PN                                 | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.100                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 78-31-10               |   |           |          |          |                           |           |           |             |        |
| 783013                                | NO. 1 ENGINE INNER FAN DUCT ASSEMBLY    |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:11ND78310-1                        | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:A30040135                          | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.230                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |   |           |          |          |                           |           |           |             |        |
| 783014                                | NO. 2 ENGINE INNER FAN DUCT ASSEMBLY    |           |          |          |                           |           |           | Component   | ATA:78 |
| PN:11ND78310-2                        | MOS/MSC                                 | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:A30040139                          | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 78.231                           | AFL                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF             |   |           |          |          |                           |           |           |             |        |
| <b>ATA 79 - OIL</b>                   |   |           |          |          |                           |           |           |             |        |
| 79-20-01-900-801-A01                  | NO. 1 ENGINE - OIL FILTER               |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                                 | MOS/MSC                                 | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS                                     | 0         |          | TSN 0    |                           |           |           |             |        |
|                                       | ENC                                     | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 79-20-01, LMM 79-20-01 |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 79 - OIL                          |  |           |          |          |                           |           |           |             |        |
| 79-20-01-900-801-A01                  | NO. 2 ENGINE - OIL FILTER                    |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                                 | MOS/MSC                                      | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                            | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
|                                       | ENC  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 79-20-01, LMM 79-20-01 |  |           |          |          |                           |           |           |             |        |
| 790110                                | NO. 1 ENGINE - OIL PUMP                      |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:3060785-2                          | MOS/MSC                                      | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:091405700293                       | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.010                           | ENC  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 05-10-01, LMM 79-20-03 |  |           |          |          |                           |           |           |             |        |
| 790110                                | NO. 2 ENGINE - OIL PUMP                      |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:3060785-2                          | MOS/MSC                                      | 08-Nov-11 | O/C      | TSO 0    |                           |           |           |             |        |
| SN:071405701651                       | HRS  | 764       |          | TSO 0    |                           |           |           |             |        |
| WC#: 79.010                           | ENC  | 284       |          | TSO 0    |                           |           |           |             |        |
| PROC. REF: LMM 05-10-01, LMM 79-20-03 |  |           |          |          |                           |           |           |             |        |
| 790130 <sup>S</sup>                   | NO. 1 ENGINE - ANALYZE ENGINE OIL AND FILTER |           |          |          |                           |           |           | Service     | ATA:79 |
|                                       | MOS  | 13-Mar-24 |          |          |                           |           |           |             |        |
|                                       | HRS  | 3877.8    | 250      |          |                           |           |           |             |        |
| WC#: 79.020                           | ENC  | 1467      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 72-00-00               |  |           |          |          |                           |           |           |             |        |
| 790130 <sup>S</sup>                   | NO. 2 ENGINE - ANALYZE ENGINE OIL AND FILTER |           |          |          |                           |           |           | Service     | ATA:79 |
|                                       | MOS  | 13-Mar-24 |          |          |                           |           |           |             |        |
|                                       | HRS  | 3877.8    | 250      |          |                           |           |           |             |        |
| WC#: 79.020                           | ENC  | 1467      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 72-00-00               |  |           |          |          |                           |           |           |             |        |
| 790140 <sup>S</sup>                   | NO. 1 ENGINE - CHANGE OIL                    |           |          |          |                           |           |           | Service     | ATA:79 |
|                                       | MOS  | 04-Dec-17 |          |          |                           |           |           |             |        |
|                                       | HRS  | 2853.82   | 1300     |          |                           |           |           |             |        |
| WC#: 79.030                           | ENC  | 1031      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 72-00-00               |  |           |          |          |                           |           |           |             |        |
| 790140 <sup>S</sup>                   | NO. 2 ENGINE - CHANGE OIL                    |           |          |          |                           |           |           | Service     | ATA:79 |
|                                       | MOS  | 28-Nov-17 |          |          |                           |           |           |             |        |
|                                       | HRS  | 2853.82   | 1300     |          |                           |           |           |             |        |
| WC#: 79.030                           | ENC  | 1031      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 72-00-00               |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                               | Unit   | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------------------|--|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 79 - OIL</b>                   |  |           |          |          |                           |           |           |             |        |
| 790150 <sup>S</sup>                   | NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK |           |          |          |                           |           |           | Service     | ATA:79 |
|                                       | MOS  | 14-May-20 |          |          |                           |           |           |             |        |
|                                       | HRS  | 3324.5    | 650      |          |                           |           |           |             |        |
| WC#: 79.040                           | ENC  | 1210      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 79-10-01, LMM 79-10-01 |  |           |          |          |                           |           |           | PKG:2       |        |
| 790150 <sup>S</sup>                   | NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK |           |          |          |                           |           |           | Service     | ATA:79 |
|                                       | MOS  | 14-May-20 |          |          |                           |           |           |             |        |
|                                       | HRS  | 3324.5    | 650      |          |                           |           |           |             |        |
| WC#: 79.040                           | ENC  | 1210      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 79-10-01, LMM 79-10-01 |  |           |          |          |                           |           |           | PKG:2       |        |
| 790160 <sup>S</sup>                   | NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION   |           |          |          |                           |           |           | Service     | ATA:79 |
|                                       | MOS  | 13-Mar-24 |          |          |                           |           |           |             |        |
|                                       | HRS  | 3877.8    | 250      |          |                           |           |           |             |        |
| WC#: 79.040                           | ENC  | 1467      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 79-10-01, LMM 79-10-01 |  |           |          |          |                           |           |           | PKG:1       |        |
| 790160 <sup>S</sup>                   | NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION   |           |          |          |                           |           |           | Service     | ATA:79 |
|                                       | MOS  | 13-Mar-24 |          |          |                           |           |           |             |        |
|                                       | HRS  | 3877.8    | 250      |          |                           |           |           |             |        |
| WC#: 79.040                           | ENC  | 1467      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 79-10-01, LMM 79-10-01 |  |           |          |          |                           |           |           | PKG:1       |        |
| 792008                                | NO. 1 ENGINE - OIL FLOW REDUCTION VALVE  |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:3060769-1                          | MOS/MSC  | 20-Dec-17 | O/C      |          |                           |           |           |             |        |
| SN:11-182215-11140                    | HRS  | 2888.63   |          |          |                           |           |           |             |        |
| WC#: 79.130                           | ENC  | 1044      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 79-20-08               |  |           |          |          |                           |           |           |             |        |
| 792008                                | NO. 2 ENGINE - OIL FLOW REDUCTION VALVE  |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:3060769-1                          | MOS/MSC  | 20-Dec-17 | O/C      |          |                           |           |           |             |        |
| SN:09-06451-10010                     | HRS  | 2888.63   |          |          |                           |           |           |             |        |
| WC#: 79.130                           | ENC  | 1044      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 79-20-08               |  |           |          |          |                           |           |           |             |        |
| 792144                                | NO. 1 ENGINE OIL LOW PRESSURE SWITCH   |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:HTE690009                          | MOS/MSC  | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:49091183                           | HRS  | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.030                           | AFL  | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 79-33-11               |  |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit                                  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|---------------------------------------|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 79 - OIL</b>     |                                       |           |          |          |                           |           |           |             |        |
| 792145                  | NO. 2 ENGINE OIL LOW PRESSURE SWITCH  |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:HTE690009            | MOS/MSC                               | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:49091181             | HRS                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.030             | AFL                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 79-33-11 |                                       |           |          |          |                           |           |           |             |        |
| 792210                  | NO. 1 ENGINE - UPPER RIGHT OIL COOLER |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:160556-6             | MOS/MSC                               | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:1286                 | HRS                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.050             | ENC                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 79-20-10 |                                       |           |          |          |                           |           |           |             |        |
| 792210                  | NO. 2 ENGINE - UPPER RIGHT OIL COOLER |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:160556-6             | MOS/MSC                               | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:1285                 | HRS                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.050             | ENC                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 79-20-10 |                                       |           |          |          |                           |           |           |             |        |
| 792220                  | NO. 1 ENGINE - UPPER LEFT OIL COOLER  |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:160556-5             | MOS/MSC                               | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:1337                 | HRS                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.060             | ENC                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 79-20-10 |                                       |           |          |          |                           |           |           |             |        |
| 792220                  | NO. 2 ENGINE - UPPER LEFT OIL COOLER  |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:160556-6             | MOS/MSC                               | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:1338                 | HRS                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.060             | ENC                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 79-20-10 |                                       |           |          |          |                           |           |           |             |        |
| 792230                  | NO. 1 ENGINE - LOWER LEFT OIL COOLER  |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:160554-5             | MOS/MSC                               | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3234                 | HRS                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.070             | ENC                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 79-20-10 |                                       |           |          |          |                           |           |           |             |        |
| 792230                  | NO. 2 ENGINE - LOWER LEFT OIL COOLER  |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:160554-5             | MOS/MSC                               | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3236                 | HRS                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.070             | ENC                                   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: LMM 79-20-10 |                                       |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 79 - OIL              |   |           |          |          |                           |           |           |             |        |
| 792240                    | NO. 1 ENGINE - LOWER RIGHT OIL COOLER         |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:160554-6               | MOS/MSC                                       | 18-Feb-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3179                   | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 79.080               | ENC   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 79-20-10   |   |           |          |          |                           |           |           |             |        |
| 792240                    | NO. 2 ENGINE - LOWER RIGHT OIL COOLER         |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:160554-6               | MOS/MSC                                       | 18-Feb-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:3172                   | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 79.080               | ENC   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 79-20-10   |   |           |          |          |                           |           |           |             |        |
| 792250                    | NO. 1 ENGINE - PRESSURE BREATHER VALVE        |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 18-Feb-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 79.090               | ENC   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 79-20-02   |   |           |          |          |                           |           |           |             |        |
| 792250                    | NO. 2 ENGINE - PRESSURE BREATHER VALVE        |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 18-Feb-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 79.090               | ENC   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: LMM 79-20-02   |   |           |          |          |                           |           |           |             |        |
| 792260                    | NO. 1 ENGINE - OIL TEMPERATURE VALVE          |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:158465-6               | MOS/MSC                                       | 18-Feb-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:13594                  | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 79.100               | ENC   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 792260                    | NO. 2 ENGINE - OIL TEMPERATURE VALVE          |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:158465-6               | MOS/MSC                                       | 18-Feb-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:13591                  | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 79.100               | ENC   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 793001                    | NO. 1 ENGINE - ENGINE OIL CHIP DETECTION UNIT |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 18-Feb-10 | O/C      |          | TSN 0                     |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          |          | TSN 0                     |           |           |             |        |
| WC#: 79.140               | ENC   | 0         |          |          | TSN 0                     |           |           |             |        |
| PROC. REF: AMM 79-30-02   |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                   | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|---------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| ATA 79 - OIL              |   |           |          |          |                           |           |           |             |        |
| 793001                    | NO. 1 ENGINE OIL PRESSURE TRANSMITTER         |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.040               | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 79-32-11   |   |           |          |          |                           |           |           |             |        |
| 793001                    | NO. 2 ENGINE - ENGINE OIL CHIP DETECTION UNIT |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.140               | ENC   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 79-30-02   |   |           |          |          |                           |           |           |             |        |
| 793002                    | NO. 2 ENGINE OIL PRESSURE TRANSMITTER         |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.040               | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: AMM 79-32-11   |   |           |          |          |                           |           |           |             |        |
| 793037                    | NO. 1 ENGINE OIL PRESSURE INDICATOR           |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.045               | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 793038                    | NO. 2 ENGINE OIL PRESSURE INDICATOR           |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.045               | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 793049                    | NO. 1 ENGINE OIL TEMPERATURE INDICATOR        |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.050               | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |
| 793050                    | NO. 2 ENGINE OIL TEMPERATURE INDICATOR        |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                     | MOS/MSC                                       | 16-Mar-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN                | HRS   | 0         |          | TSN 0    |                           |           |           |             |        |
| WC#: 79.050               | AFL   | 0         |          | TSN 0    |                           |           |           |             |        |
| PROC. REF: GENERIC NO REF |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



# Status Report

Model: HAWKER 900XP Serial: HA-0161 RegNo: N61HQ HRS: 3908.4 AFL: 1492 As Of: 25-Jul-2024

29-Jul-2024 05:50 PM

| PN & SN                 | Unit  | C/W       | Interval | TSX/Adj. | Next Due<br>(ENG/APU) A/C | Max Limit | Remaining | Disposition |        |
|-------------------------|---|-----------|----------|----------|---------------------------|-----------|-----------|-------------|--------|
| <b>ATA 79 - OIL</b>     |   |           |          |          |                           |           |           |             |        |
| 793310                  | NO. 1 ENGINE - OIL FILTER BYPASS VALVE                                      |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:3060782-2            | MOS/MSC   | 04-Dec-17 | O/C      | TSN 15   |                           |           |           |             |        |
| SN:J13158               | HRS   | 2853.82   | TSN 0    |          |                           |           |           |             |        |
| WC#: 79.110             | ENC   | 1031      | TSN 0    |          |                           |           |           |             |        |
| PROC. REF: LMM 79-30-01 |   |           |          |          |                           |           |           |             |        |
| 793310                  | NO. 2 ENGINE - OIL FILTER BYPASS VALVE                                      |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:PN                   | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:UNKNOWN              | HRS   | 0         | TSN 0    |          |                           |           |           |             |        |
| WC#: 79.110             | ENC   | 0         | TSN 0    |          |                           |           |           |             |        |
| PROC. REF: LMM 79-30-01 |   |           |          |          |                           |           |           |             |        |
| 793315 <sup>S</sup>     | NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH |           |          |          |                           |           |           | Service     | ATA:79 |
| PN:3060782-2            | MOS   | 04-Dec-17 |          |          |                           |           |           |             |        |
| SN:J13158               | HRS   | 2853.82   | 1300     |          |                           |           |           |             |        |
| WC#: 79.110             | ENC   | 1031      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 79-30-01 |   |           |          |          |                           |           |           |             |        |
| 793315 <sup>S</sup>     | NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH |           |          |          |                           |           |           | Service     | ATA:79 |
| PN:PN                   | MOS   | 28-Nov-17 |          |          |                           |           |           |             |        |
| SN:UNKNOWN              | HRS   | 2853.82   | 1300     |          |                           |           |           |             |        |
| WC#: 79.110             | ENC   | 1031      |          |          |                           |           |           |             |        |
| PROC. REF: LMM 79-30-01 |   |           |          |          |                           |           |           |             |        |
| 793320                  | NO. 1 ENGINE - FUEL/OIL COOLER  |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:3060709-4            | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3281                 | HRS   | 0         | TSN 0    |          |                           |           |           |             |        |
| WC#: 79.120             | ENC   | 0         | TSN 0    |          |                           |           |           |             |        |
| PROC. REF: LMM 79-20-07 |   |           |          |          |                           |           |           |             |        |
| 793320                  | NO. 2 ENGINE - FUEL/OIL COOLER  |           |          |          |                           |           |           | Component   | ATA:79 |
| PN:3060709-4            | MOS/MSC   | 18-Feb-10 | O/C      | TSN 0    |                           |           |           |             |        |
| SN:3283                 | HRS   | 0         | TSN 0    |          |                           |           |           |             |        |
| WC#: 79.120             | ENC   | 0         | TSN 0    |          |                           |           |           |             |        |
| PROC. REF: LMM 79-20-07 |   |           |          |          |                           |           |           |             |        |

?-Insufficient Information S-Suppressed Requirement \*-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task